



Cranston totals 1,641,481 square feet and consists of the school type(s) detailed below. School(s) were visited three times during the Statewide Facilities Assessment by teams of specialists from April-June 2016. This report provides LEA summary findings for the statewide assessment program.

School Type by Count



School Type	SqFt
Elementary School	695,228
Middle School	413,258
High School	532,995
Total:	1,641,481

Demographics


Enrollment is projected to decrease by 9.1% over the next 10 years in Cranston. The total LEA enrollment at 24 school(s) is 10,307 students with a total capacity of 11,397 as reported by the LEA. Utilization is calculated by dividing enrollment by capacity, resulting in 90.4% utilization at Cranston.

90.4 % Utilization



Educational Program Space Analysis

In Cranston there are 726 instructional spaces; of these spaces 22.6% meet or exceed the space size standards. Of the total current deficiencies identified, \$13,102,973 are related to the educational program space assessment. Addressing these identified deficiencies will improve the learning environment and bring the school(s) in the district closer to 21st century learning facilities.



Five Year Need Summary

The current deficiencies total \$165,588,929, with 37.0% categorized as Priority 3 and another 29.1% as Priority 4. The building systems with the highest current deficiency costs are Interior and Technology.


School(s) with Greatest Need	Combined 5-Year Need
Cranston High School West	\$25,183,153
Cranston High School East	\$21,785,939
Hugh B. Bain Middle School	\$17,993,738

The projected life cycle need in Years 1 through 5 is \$48,325,997. It is anticipated that the majority of the need will occur in Year 5. School(s) with the greatest need are represented in the adjacent table and make up 30.4% of the combined 5-Year need at Cranston.

Five Year Facility Condition Index (FCI)

For master planning purposes, the total current deficiencies, less new construction, and the first 5 years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-Year FCI was calculated by dividing the 5-Year need by the total replacement cost. The 5-Year need is \$213,914,926 with a district replacement value of \$579,716,134. The resulting 5-Year FCI is 36.9%.

5-Year FCI Ranges




LEA Summary Data

Gross SqFt	Avg Year Built	Current Deficiencies (Less New Construction)	Life Cycle Year 1-5 Total	Total 5-Year Need (Year 1-5 + Current Defs)	5-Year FCI
1,641,481	1955	\$165,588,929	\$48,325,997	\$213,914,926	36.9%



Cranston





Facility Condition Assessment

Cranston - Arlington School

June 2017

155 Princess Avenue, Cranston, RI 02920





Introduction

Arlington School, located at 155 Princess Avenue in Cranston, Rhode Island, was built in 1957. It comprises 18,498 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Arlington School serves grades 1 - 6, has 17 instructional spaces, and has an enrollment of 276. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Arlington School is 278 with a resulting utilization of 99%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Arlington School the 5-year need is \$3,650,764. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Arlington School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Arlington School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Roofing
---------------------	--------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Non-Painted Plaster/Gypsum Board Ceiling
	Painted Ceilings
	Ceramic Tile Wall
	Wood Wall Paneling
	Interior Wall Painting
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
---------------------	----------------------------------



01 - Main Building:	Steam Condensate Receiver, Tank and Pump
	Radiant Steam Heater
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	Window Units
	1 HP or Smaller Pump
	2-Pipe Steam Hydronic Distribution System
	Roof Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	30 Gallon Electric Water Heater
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (1/2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$5,774	\$279,567	\$9,090	\$294,430	9.28 %
Roofing	-	\$250,316	\$2,015	-	-	\$252,331	7.95 %
Structural	\$10,024	-	-	-	-	\$10,024	0.32 %
Exterior	-	\$554,945	-	-	\$107,367	\$662,312	20.87 %
Interior	-	-	\$234,055	\$485,081	\$18,367	\$737,503	23.24 %
Mechanical	-	\$281,834	-	-	\$9,899	\$291,733	9.19 %
Electrical	-	\$58,567	-	-	\$34,062	\$92,629	2.92 %
Plumbing	-	\$14,613	\$165,331	\$27,676	\$9,702	\$217,322	6.85 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$610,944	-	-	\$610,944	19.25 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,619	-	-	\$4,619	0.15 %
Total	\$10,024	\$1,160,274	\$1,022,737	\$792,323	\$188,488	\$3,173,846	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$737,503
Exterior	-	\$662,312
Technology	-	\$610,944

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$48,996	-	\$48,996
Barrier to Accessibility	-	-	\$12,429	-	-	\$12,429
Capital Renewal	\$10,024	\$1,160,274	\$388,971	\$378,347	\$118,959	\$2,056,574
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$4,619	\$41,871	\$69,529	\$116,019
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$323,110	-	\$323,110
Technology	-	-	\$610,944	-	-	\$610,944
Traffic	-	-	\$5,774	-	-	\$5,774
Total	\$10,024	\$1,160,274	\$1,022,737	\$792,323	\$188,488	\$3,173,846

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$294,430	\$0	\$0	\$0	\$6,695	\$9,815	\$16,510	\$310,940
Roofing	\$252,331	\$0	\$0	\$0	\$0	\$0	\$0	\$252,331
Structural	\$10,024	\$0	\$0	\$0	\$0	\$0	\$0	\$10,024
Exterior	\$662,312	\$0	\$0	\$0	\$0	\$0	\$0	\$662,312
Interior	\$737,503	\$0	\$0	\$0	\$37,111	\$332,704	\$369,815	\$1,107,318
Mechanical	\$291,733	\$0	\$0	\$0	\$0	\$0	\$0	\$291,733
Electrical	\$92,629	\$0	\$0	\$0	\$0	\$0	\$0	\$92,629
Plumbing	\$217,322	\$0	\$0	\$0	\$0	\$0	\$0	\$217,322
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$610,944	\$0	\$0	\$0	\$0	\$0	\$0	\$610,944
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$4,619	\$0	\$0	\$0	\$0	\$90,593	\$90,593	\$95,212
Total	\$3,173,846	\$0	\$0	\$0	\$43,806	\$433,112	\$476,918	\$3,650,764

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$9,134,300. For planning purposes, the total 5-year need at the Arlington School is \$3,650,764 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Arlington School facility has a 5-year FCI of 39.97%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 145 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Arlington School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Arlington School comprises 18,498 square feet and was constructed in 1957. Current deficiencies at this school total \$3,173,846. Five year capital renewal costs total \$476,918. The total identified need for the Arlington School (current deficiencies and 5-year capital renewal costs) is \$3,650,764. The 5-year FCI is 39.97%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Arlington School Totals	18,498	1957	\$3,173,846	\$476,918	\$3,650,764	39.97%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Update school zone signs and install flashing beacons on Princess Ave	Traffic	2	Ea.	3	\$5,774	16960
Asphalt Paving Requires Replacement	Capital Renewal	33	CAR	4	\$138,139	16336
Asphalt Paving Requires Resurfacing Location: Asphalt play area	Capital Renewal	14,375	SF	4	\$19,020	12581
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28445
Fencing Requires Replacement (8' Chain Link Fence)	Capital Renewal	1,000	LF	4	\$85,059	16334
Gate Requires Replacement	Capital Renewal	1	Ea.	4	\$1,263	16335
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28716
Play Field Requires Repair Note: Grass play field has boulders and one large hole with a 6" PVC pipe open and exposed. Work orders have been sent in, but have not gotten a response.	Capital Renewal	500	SF	5	\$1,693	12580
Sub Total for System		8	items		\$294,430	
Sub Total for School and Site Level		8	items		\$294,430	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Single-Ply Membrane Roof Covering Requires Replacement Note: Roof membrane has deteriorated, warranty expired 2003.	Capital Renewal	18,498	SF	2	\$250,316	12601
The Metal Downspouts Require Installation or Replacement Note: PVC downspout in southwest corner is broken.	Capital Renewal	30	LF	3	\$2,015	12586
Sub Total for System		2	items		\$252,331	

Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Foundation Study Recommended Note: Cracks in south side foundation, exterior brick veneer and interior plaster in Room 2.	Capital Renewal	1	Job	1	\$10,024	12593
Sub Total for System		1	items		\$10,024	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement	Capital Renewal	3,015	SF	2	\$537,945	12585
The Storefront/Curtain Wall Requires Replacement (Bldg SF)	Capital Renewal	200	SF	2	\$17,000	18987
The Exterior Requires Painting Note: Fascia requires scraping, primer and paint.	Capital Renewal	18,498	SF Wall	5	\$107,367	12584
Sub Total for System		3	items		\$662,312	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Existing Toilet Stall Does Not Meet Minimum ADA Requirements	Barrier to Accessibility	4	Ea.	3	\$12,429	12590
The Interior Door Hardware Requires Replacement	Capital Renewal	67	Door	3	\$221,625	18986
Adhered Acoustical Ceiling Tile Requires Replacement Note: Tiles are damaged.	Capital Renewal	9,249	SF	4	\$105,747	12603
Interior Wood Walls Require Replacement Note: Wood panel walls in kitchen are rotting.	Capital Renewal	150	SF	4	\$1,443	12602
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	9,250	SF	4	\$278,159	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	15	Ea.	4	\$4,511	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	956	LF	4	\$22,998	Rollup



Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	1,740	SF	4	\$17,441	Rollup
Room Is Excessively Reverberant Note: Gym	Acoustics	2,080	SF	4	\$48,996	19816
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	150	SF	4	\$5,785	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,309	Rollup
Sub Total for System		11	items		\$721,445	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent Note: Original unit vents, casing showing signs of deterioration	Capital Renewal	10	Ea.	2	\$178,343	12600
The Steam/Hot Water Radiant Heater Requires Replacement Note: Radiant heaters showing signs of deterioration.	Capital Renewal	19	Ea.	2	\$103,491	12597
Remove Abandoned Equipment Note: Remove old DHW, fuel pump and fuel tank. Oil storage tank is no longer used.	Capital Renewal	3	Ea.	5	\$9,899	12599
Sub Total for System		3	items		\$291,733	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Distribution Panel Requires Replacement	Capital Renewal	1	Ea.	2	\$27,064	12598
The Electrical Disconnect Requires Replacement Note: Main breaker is obsolete - arch flash danger if not maintained regularly.	Capital Renewal	1	Ea.	2	\$1,933	12588
The Panelboard Requires Replacement Note: Panel is obsolete, casing shows signs of rust.	Capital Renewal	1	Ea.	2	\$5,112	12595
The Panelboard Requires Replacement	Capital Renewal	4	Ea.	2	\$24,458	12596
Room Has Insufficient Electrical Outlets	Educational Adequacy	40	Ea.	5	\$20,092	Rollup
Sub Total for System		5	items		\$78,659	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Backflow Preventer Requires Replacement	Capital Renewal	1	Ea.	2	\$14,613	16339
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life Note: Custodian reported brown water, etc. Signs of scaling.	Capital Renewal	18,498	SF	3	\$156,923	12594
The Urinal Plumbing Fixtures Require Replacement Note: Urinals are aging and discolored.	Capital Renewal	6	Ea.	3	\$8,408	12592
Non-Refrigerated Drinking Fountain Requires Replacement Note: No longer functioning.	Capital Renewal	1	Ea.	4	\$10,776	12589
The Classroom Lavatories Plumbing Fixtures Require Replacement Note: Original lavatories showing signs of deterioration.	Capital Renewal	4	Ea.	4	\$11,467	12583
The Custodial Mop Or Service Sink Requires Replacement Note: Does not meet facility's needs, showing signs of deterioration.	Capital Renewal	2	Ea.	4	\$5,433	12591
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		8	items		\$217,322	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$48,114	23323
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	12	Ea.	3	\$120,285	23328
Technology: Instructional spaces do not have local sound reinforcement.	Technology	12	Ea.	3	\$60,143	23333
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23322



Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23320
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23321
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	96	Ea.	3	\$43,303	23326
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	22	Ea.	3	\$9,924	23324
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23331
Technology: Network system inadequate and/or near end of useful life	Technology	10	Ea.	3	\$50,119	23332
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	48	Ea.	3	\$24,057	23325
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	18,498	SF	3	\$33,375	23330
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23327
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23329
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	12	Ea.	3	\$19,246	23334
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23335
Sub Total for System		16	items		\$610,944	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,619	Rollup
Sub Total for System		1	items		\$4,619	
Sub Total for Building 01 - Main Building		50	items		\$2,849,388	

Building: 02 - Portable A

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,294	Rollup
Sub Total for System		1	items		\$2,294	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	4	Ea.	5	\$1,996	Rollup
Sub Total for System		1	items		\$1,996	
Sub Total for Building 02 - Portable A		2	items		\$4,290	

Building: 03 - Portable B

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	2	Ea.	5	\$4,588	Rollup
Sub Total for System		1	items		\$4,588	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$3,991	Rollup
Sub Total for System		1	items		\$3,991	
Sub Total for Building 03 - Portable B		2	items		\$8,579	



Building: 04 - Portable C

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	2	Ea.	5	\$4,588	Rollup
Sub Total for System		1	items		\$4,588	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$3,991	Rollup
Sub Total for System		1	items		\$3,991	
Sub Total for Building 04 - Portable C		2	items		\$8,579	

Building: 05 - Portable D

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	2	Ea.	5	\$4,588	Rollup
Sub Total for System		1	items		\$4,588	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$3,991	Rollup
Sub Total for System		1	items		\$3,991	
Sub Total for Building 05 - Portable D		2	items		\$8,579	
Total for Campus		66	items		\$3,173,846	



Arlington School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Pedestrian Pavement	Sidewalks - Asphalt	774	SF	\$6,695	4
Fences and Gates	Fencing - Chain Link (4 Ft)	150	LF	\$9,815	5
		Sub Total for System		\$16,510	
		Sub Total for Building -		\$16,510	

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	5,549	SF	\$37,111	4
Interior Swinging Doors	Wood	60	Door	\$280,023	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4,049	SF	\$37,015	5
Suspended Plaster and	Painted ceilings	3,700	SF	\$15,666	5
		Sub Total for System		\$369,815	

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	8	Room	\$90,593	5
		Sub Total for System		\$90,593	
		Sub Total for Building 01 - Main Building		\$460,408	
		Total for: Arlington School		\$476,918	



Supporting Photos



Site Aerial



West View



Library In Portable A



Southeast View



Facility Condition Assessment

Cranston - Arlington School




Cafeteria/Gym



Northeast View



Northeast View



Typical Classroom



Typical Classroom



Restroom



Facility Condition Assessment

Cranston - Arlington School



Northwest View



Cafeteria/Gym



East View



Corridor



Southwest View



West View



Facility Condition Assessment

Cranston - Arlington School



West View



Typical Restroom Lavatories



Portable B



Portable A



Portable D



Southeast View



Portable C



Typical Casework



Lobby



Library In Portable A



Custodial Sink



Typical Window



Fascia



PVC Downspout On Southwest Corner



Typical Window



Asphalt Play Area



Cafe/Gym VCT Floor



Large Boulder In Play Area



12" Deep Hole With Exposed Pipe




Damaged Ceiling Tiles



Damaged Ceiling Tiles



Rotted Wood Panel- Kitchen



Rotted Wood Panel- Kitchen



Roof



Roof View



Distribution Panel



Unit Vent



Classroom Lavatories



Radiant Heater



Panelboard



Panelboard



Electrical Disconnect



Drinking Fountain



Toilet Stall



Urinals



Cracks On Southeast Corner



Cracks On Southwest Corner



South Wall Foundation Cracks



Cracks On Southwest Corner



Panelboard



Facility Condition Assessment

Cranston - Chester W. Barrows School

June 2017

9 Beachmont Avenue, Cranston, RI 02905





Introduction

Chester W. Barrows School, located at 9 Beachmont Avenue in Cranston, Rhode Island, was built in 1924. It comprises 27,064 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Chester W. Barrows School serves grades KG - 5, has 16 instructional spaces, and has an enrollment of 190. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Chester W. Barrows School is 283 with a resulting utilization of 67%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Chester W. Barrows School the 5-year need is \$4,768,719. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Chester W. Barrows School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Chester W. Barrows School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Roofing
----------------------------	--------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	FRP Wall Finish
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Quarry Tile Flooring
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	1,275 MBH Cast Iron Water Boiler
----------------------------	----------------------------------



01 - Main Building:	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	36 MBH Steam Unit Heater
	Electronic Heating System Controls
	Window Units
	5 HP VFD
	2-Pipe Hot Water Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	Large Roof Exhaust Fan
	Kitchen Exhaust Hoods
	Wall Exhaust Fan
	4'x8' Ventilator/Relief Vent
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 277/480 100A
	Building Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$8,769	\$85,259	\$72,444	\$166,472	4.46 %
Roofing	-	\$163,251	-	-	-	\$163,251	4.37 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$607,031	-	-	-	\$607,031	16.25 %
Interior	-	-	\$399,540	\$461,464	-	\$861,004	23.05 %
Mechanical	-	\$504,734	-	\$37,221	-	\$541,955	14.51 %
Electrical	-	\$25,332	-	-	\$35,790	\$61,122	1.64 %
Plumbing	-	-	\$366,810	\$13,740	\$11,233	\$391,783	10.49 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$786,664	-	-	\$786,664	21.06 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,238	\$147,213	-	\$156,451	4.19 %
Total	\$0	\$1,300,348	\$1,571,021	\$744,897	\$119,467	\$3,735,733	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$861,004
Technology	-	\$786,664
Exterior	-	\$607,031

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$31,274	-	\$31,274
Barrier to Accessibility	-	-	\$253,320	-	-	\$253,320
Capital Renewal	-	\$1,300,348	\$521,799	\$246,145	\$3,642	\$2,071,934
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$9,238	\$37,288	\$115,824	\$162,351
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$430,190	-	\$430,190
Technology	-	-	\$786,664	-	-	\$786,664
Traffic	-	-	-	-	-	\$0
Total	\$0	\$1,300,348	\$1,571,021	\$744,897	\$119,467	\$3,735,733

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$166,472	\$0	\$0	\$0	\$0	\$182,538	\$182,538	\$349,010
Roofing	\$163,251	\$0	\$0	\$0	\$0	\$0	\$0	\$163,251
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$607,031	\$0	\$0	\$0	\$0	\$38,972	\$38,972	\$646,003
Interior	\$861,004	\$0	\$0	\$0	\$0	\$604,046	\$604,046	\$1,465,050
Mechanical	\$541,955	\$0	\$0	\$0	\$83,927	\$123,503	\$207,430	\$749,385
Electrical	\$61,122	\$0	\$0	\$0	\$0	\$0	\$0	\$61,122
Plumbing	\$391,783	\$0	\$0	\$0	\$0	\$0	\$0	\$391,783
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$786,664	\$0	\$0	\$0	\$0	\$0	\$0	\$786,664
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$156,451	\$0	\$0	\$0	\$0	\$0	\$0	\$156,451
Total	\$3,735,733	\$0	\$0	\$0	\$83,927	\$949,059	\$1,032,986	\$4,768,719

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$9,472,400. For planning purposes, the total 5-year need at the Chester W. Barrows School is \$4,768,719 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Chester W. Barrows School facility has a 5-year FCI of 50.34%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 150 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Chester W. Barrows School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$468,720.



Summary of Findings

The Chester W. Barrows School comprises 27,064 square feet and was constructed in 1924. Current deficiencies at this school total \$3,735,733. Five year capital renewal costs total \$1,032,986. The total identified need for the Chester W. Barrows School (current deficiencies and 5-year capital renewal costs) is \$4,768,719. The 5-year FCI is 50.34%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Chester W. Barrows School Totals	27,064	1924	\$3,735,733	\$1,032,986	\$4,768,719	50.34%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Retaining Wall Requires Repair Note: Concrete retaining wall at exterior northwest stair is damaged.	Capital Renewal	100	SF	3	\$8,769	10976
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$37,288	28432
Fencing Requires Replacement (4' Chain Link Fence)	Capital Renewal	110	LF	4	\$9,297	11586
Fencing Requires Replacement (8' Chain Link Fence)	Capital Renewal	440	LF	4	\$38,673	11587
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,644	28706
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54871
Sub Total for System		6	items		\$166,472	
Sub Total for School and Site Level		6	items		\$166,472	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Single-Ply Membrane Roof Covering Requires Replacement Note: The single ply roof membrane is buckling and insulation moves underfoot. The warranty expired 2013.	Capital Renewal	11,600	SF	2	\$163,251	10995
Sub Total for System		1	items		\$163,251	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Note: Multipurpose room windows are not functioning appropriately.	Capital Renewal	48	SF	2	\$8,907	10978
The Storefront/Curtain Wall Requires Replacement (Bldg SF) Note: Windows are aged with single pane glass. Water and air is infiltrating.	Capital Renewal	6,766	SF	2	\$598,124	10994
Sub Total for System		2	items		\$607,031	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Existing Door Hardware Is Not ADA Compliant	Barrier to Accessibility	81	Door	3	\$253,320	10981
The Vinyl Composition Tile Requires Replacement Note: VCT is cracked, bubbled, and worn.	Capital Renewal	11,624	SF	3	\$146,220	10979
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	11,380	SF	4	\$355,899	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	400	SF	4	\$4,170	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	7	Ea.	4	\$2,189	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	36	LF	4	\$901	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	6,430	SF	4	\$67,031	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) Note: Gym	Acoustics	500	SF	4	\$31,274	19751
Sub Total for System		8	items		\$861,004	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Steam/HW Unit Heater Requires Replacement Note: Unit heaters are original to the building, are obsolete, and are deteriorating.	Capital Renewal	4	Ea.	2	\$7,222	10989
The Cast Iron Water Boiler Requires Replacement Note: Boilers are aged and obsolete.	Capital Renewal	2	Ea.	2	\$68,544	10990
The Fin Tube Water Radiant Heater Requires Replacement Note: Radiators are original to the building and are showing signs of deterioration.	Capital Renewal	109	Ea.	2	\$200,215	10991



Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life Note: Piping is original to the building and should be replaced.	Capital Renewal	27,064	SF	2	\$228,753	10992
Exhaust Fan Ventilation Requires Replacement Note: Basement bathroom exhaust fans are outdated and obsolete.	Capital Renewal	2	Ea.	4	\$5,872	10980
Small HVAC Circulating Pump Requires Replacement Note: Pump bodies are corroded and showing signs of failure.	Capital Renewal	3	Ea.	4	\$31,349	10986
Sub Total for System		6	items		\$541,955	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement Note: Panelboards are outdated and obsolete.	Capital Renewal	3	Ea.	2	\$25,332	10987
Remove Abandoned Equipment Note: 5,000 gallon storage tank	Capital Renewal	1	Ea.	5	\$3,642	10977
Room Has Insufficient Electrical Outlets	Educational Adequacy	64	Ea.	5	\$32,148	Rollup
Sub Total for System		3	items		\$61,122	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life Note: Domestic water piping is original to the 1924 building. There is occasional brown water and signs of scaling.	Capital Renewal	27,064	SF	3	\$238,774	10985
The Sanitary Sewer Piping Requires Replacement Note: Sanitary piping is original to the building and should be replaced.	Capital Renewal	750	LF	3	\$128,036	10993
The Custodial Mop Or Service Sink Requires Replacement Note: Mop sinks are original to the building and are outdated and deteriorating.	Capital Renewal	2	Ea.	4	\$5,650	10983
The Refrigerated Water Cooler Requires Replacement Note: Basement water fountain is non-functional.	Capital Renewal	1	Ea.	4	\$8,090	10984
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	5	Ea.	5	\$5,651	Rollup
Sub Total for System		6	items		\$391,783	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$50,039	23645
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	13	Ea.	3	\$284,594	23650
Technology: Instructional spaces do not have local sound reinforcement.	Technology	13	Ea.	3	\$67,761	23652
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,297	23641
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$46,703	23640
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,903	23643
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	96	Ea.	3	\$45,035	23644
Technology: Network system inadequate and/or near end of useful life	Technology	4	Ea.	3	\$33,359	23653
Technology: Network system inadequate and/or near end of useful life	Technology	14	Ea.	3	\$72,973	23654
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	27,064	SF	3	\$50,784	23649
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$59,421	23646
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,849	23651



Facility Condition Assessment

Cranston - Chester W. Barrows School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,340	23642
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	13	Ea.	3	\$21,683	23648
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,923	23647
Sub Total for System		15	items		\$786,664	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	12	Room	4	\$147,213	11585
Sub Total for System		2	items		\$156,451	
Sub Total for Building 01 - Main Building		43	items		\$3,569,261	
Total for Campus		49	items		\$3,735,733	



Chester W. Barrows School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Pedestrian Pavement	Sidewalks - Concrete	1,300	SF	\$26,895	5
Playfield Areas	ES Playgrounds	1	Ea.	\$45,131	5
Parking Lot Pavement	Asphalt	25	CAR	\$83,721	5
	Note: Paved play area				
Parking Lot Pavement	Asphalt	8	CAR	\$26,791	5
	Note: East side of addition				
	Sub Total for System	4	items	\$182,538	
	Sub Total for Building -	4	items	\$182,538	

Building: 01 - Main Building

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	6	Door	\$38,972	5
	Sub Total for System	1	items	\$38,972	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	18,945	SF	\$173,189	5
Interior Operable Partitions	Foldable partition (Bldg SF)	300	SF Wall	\$35,075	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	18,945	SF	\$227,435	5
Suspended Plaster and	Painted ceilings	5,413	SF	\$22,919	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	18,445	SF	\$123,357	5
Tile Flooring	Ceramic Tile	812	SF	\$22,071	5
	Sub Total for System	6	items	\$604,046	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	4	Ea.	\$68,484	4
Facility Hydronic Distribution	Pump - 1HP or Less (Ea.)	2	Ea.	\$15,443	4
Exhaust Air	Ventilator/Relief Vent (4'x8')	8	Ea.	\$107,344	5
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$16,159	5
	Sub Total for System	4	items	\$207,429	
	Sub Total for Building 01 - Main Building	11	items	\$850,447	
	Total for: Chester W. Barrows School	15	items	\$1,032,985	



Supporting Photos



Corroded Pumps



Library



Aged Panelboard



Aged Radiant Heaters



Facility Condition Assessment

Cranston - Chester W. Barrows School



Exterior Finishes



Non-Functional Water Fountain



Operable Partition Wall



Playground



Restroom Finishes



Art/Music Room



Facility Condition Assessment

Cranston - Chester W. Barrows School



West Elevation



Gymnasium/Cafeteria



Painted Ceilings



Original Unit Heater



Evidence Of Ponding On Roof



Typical Classroom



Facility Condition Assessment

Cranston - Chester W. Barrows School



Northwest Elevation



Damaged Retaining Wall



Worn VCT Bubbled At Seams



Aged Windows



Site Aerial



Cracked VCT



Facility Condition Assessment

Cranston - Chester W. Barrows School



Plaque



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center

June 2017

100 Metropolitan Ave, Cranston, RI 02920





Introduction

Cranston Area Career & Technical Center, located at 100 Metropolitan Ave in Cranston, Rhode Island, was built in 1976. It comprises 43,050 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Cranston Area Career & Technical Center serves grades 9 - 12, has 15 instructional spaces, and enrollment was not provided. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Cranston Area Career & Technical Center is 230 with a resulting utilization of 0%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Cranston Area Career & Technical Center the 5-year need is \$2,505,405. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Cranston Area Career & Technical Center



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Cranston Area Career & Technical Center campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	E.I.F.S. Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors
02 - Greenhouse:	Clear Polycarbonate Exterior Wall
	Steel Exterior Entrance Doors
03 - Quonset Hut 1:	Metal Panel Exterior Wall
	Steel Exterior Entrance Doors
04 - Quonset Hut 2:	Metal Panel Exterior Wall
	Steel Exterior Entrance Doors
05 - Storage:	Vinyl Siding Exterior Wall
	Wood Exterior Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
03 - Quonset Hut 1:	Metal Steep Slope Roofing
04 - Quonset Hut 2:	Metal Steep Slope Roofing
05 - Storage:	Composition Shingle Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Wood Interior Doors
	Steel Interior Doors
	Interior Door Hardware



01 - Main Building:	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Carpet
02 - Greenhouse:	Concrete Flooring
03 - Quonset Hut 1:	Concrete Flooring
04 - Quonset Hut 2:	Concrete Flooring
05 - Storage:	Concrete Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	200 MBH Copper Tube Boiler
	750 MBH Copper Tube Boiler
	Steam/Hot Water Heating Unit Vent
	20 MBH Steam Unit Heater
	DDC Heating System Controls
	3 Ton Ductless Split System
	3 Ton Outside Air Cooled Condenser
	2 Ton Fan Coil - Water Cool/Water Heat
	5 HP VFD
	1 HP or Smaller Pump
	5 HP Pump
	4-Pipe Hydronic Distribution System
	5 Ton DX Gas Roof Top Unit
	Ductwork
	8,000 CFM Energy Recovery Unit
	Supply Fan
	Roof Exhaust Fan
	Kitchen Exhaust Hoods
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	250 Gallon Water Storage Tank
	2" Backflow Preventers



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center

01 - Main Building:	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (1 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	75 kW Emergency Generator
	Automatic Transfer Switch
	1,600 Amp Switchgear
	45 KVA Transformer
	75 KVA Transformer
	Motor Controller
	Panelboard - 120/208 100A
	Panelboard - 120/208 400A
	Panelboard - 120/240 225A
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	-	\$223,570	\$64,800	\$288,370	16.36 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$38,490	\$206,929	\$4,588	\$250,007	14.18 %
Mechanical	-	\$20,452	-	\$22,104	-	\$42,556	2.41 %
Electrical	-	\$100,238	\$8,473	-	\$3,991	\$112,702	6.39 %
Plumbing	-	-	-	\$1,701	\$18,237	\$19,938	1.13 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$858,143	-	-	\$858,143	48.69 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$18,351	\$136,411	\$36,129	\$190,892	10.83 %
Total	\$0	\$120,690	\$923,458	\$590,715	\$127,745	\$1,762,608	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Technology	-	\$858,143
Site	-	\$288,370
Interior	-	\$250,007

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$141,335	-	\$141,335
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$120,690	\$46,964	\$223,570	-	\$391,224
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$35,556	\$224,307	\$127,745	\$387,608
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$1,504	-	\$1,504
Technology	-	-	\$840,939	-	-	\$840,939
Traffic	-	-	-	-	-	\$0
Total	\$0	\$120,690	\$923,458	\$590,715	\$127,745	\$1,762,608

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$288,370	\$0	\$0	\$0	\$0	\$23,194	\$23,194	\$311,564
Roofing	\$0	\$0	\$0	\$0	\$0	\$41,859	\$41,859	\$41,859
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$0	\$375,887	\$375,887	\$375,887
Interior	\$250,007	\$0	\$0	\$0	\$0	\$60,216	\$60,216	\$310,223
Mechanical	\$42,556	\$0	\$0	\$0	\$0	\$0	\$0	\$42,556
Electrical	\$112,702	\$0	\$0	\$0	\$0	\$83,103	\$83,103	\$195,805
Plumbing	\$19,938	\$0	\$0	\$0	\$0	\$0	\$0	\$19,938
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$858,143	\$0	\$0	\$0	\$0	\$0	\$0	\$858,143
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$190,892	\$0	\$0	\$0	\$0	\$158,538	\$158,538	\$349,430
Total	\$1,762,608	\$0	\$0	\$0	\$0	\$742,797	\$742,797	\$2,505,405

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$15,498,000. For planning purposes, the total 5-year need at the Cranston Area Career & Technical Center is \$2,505,405 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Cranston Area Career & Technical Center facility has a 5-year FCI of 16.17%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 210 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Cranston Area Career & Technical Center cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Cranston Area Career & Technical Center comprises 43,050 square feet and was constructed in 1976. Current deficiencies at this school total \$1,762,608. Five year capital renewal costs total \$742,797. The total identified need for the Cranston Area Career & Technical Center (current deficiencies and 5-year capital renewal costs) is \$2,505,405. The 5-year FCI is 16.17%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Cranston Area Career & Technical Center Totals	43,050	1976	\$1,762,608	\$742,797	\$2,505,405	16.17%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Paving Requires Replacement Note: Parking lot pavement is deteriorated with cracks, heaving, and pot holes.	Capital Renewal	41	CAR	4	\$171,628	12109
Asphalt Paving Requires Replacement Note: Roadway asphalt is cracked and weathered.	Capital Renewal	24	CAR	4	\$11,114	12110
Fencing Requires Replacement (8' Chain Link Fence) Note: Fence is rusted and damaged.	Capital Renewal	480	LF	4	\$40,828	13064
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54993
Sub Total for System		4	items		\$288,370	
Sub Total for School and Site Level		4	items		\$288,370	

Building: 01 - Main Building

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceiling Tiles Require Replacement Note: Ceiling tiles are stained and broken.	Capital Renewal	4,042	SF	3	\$38,490	13063
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	4	Ea.	4	\$1,203	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	30	SF	4	\$301	Rollup
Room Is Excessively Reverberant Note: Classrooms without ACT	Acoustics	6,000	SF	4	\$141,335	19832
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	1,673	SF	4	\$64,090	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	2	Ea.	5	\$4,588	Rollup
Sub Total for System		6	items		\$250,007	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Package Roof Top Unit Requires Replacement Note: Roof top unit is rusted and deteriorating.	Capital Renewal	1	Ea.	2	\$20,452	12111
Lab lacks an appropriate fume hood.	Educational Adequacy	1	Ea.	4	\$22,104	Rollup
Sub Total for System		2	items		\$42,556	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Generator Requires Replacement Note: Generator is old and replacement parts are no longer available.	Capital Renewal	1	Ea.	2	\$100,238	12113
Transfer Switch Requires Replacement	Capital Renewal	225	Amps	3	\$8,473	12114
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$3,991	Rollup
Sub Total for System		3	items		\$112,702	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Floor Drains Are Required	Educational Adequacy	2	Ea.	4	\$1,701	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	12	Ea.	5	\$18,237	Rollup
Sub Total for System		2	items		\$19,938	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	3	Ea.	3	\$17,204	Rollup



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	126	Ea.	3	\$63,150	23453
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	1	Ea.	3	\$501	24387
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	264	Ea.	3	\$132,314	24388
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	13	Ea.	3	\$130,309	23457
Technology: Instructional spaces do not have local sound reinforcement.	Technology	20	Ea.	3	\$100,238	24393
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23452
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	24386
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23450
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$22,854	24385
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23451
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	144	Ea.	3	\$64,954	23456
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	24	Ea.	3	\$10,826	23454
Technology: Network system inadequate and/or near end of useful life	Technology	12	Ea.	3	\$60,143	23458
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	24	Ea.	3	\$12,029	23455
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	38,970	SF	3	\$70,313	24392
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	24389
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	25	Ea.	3	\$40,095	24390
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	24391
Sub Total for System		19	items		\$858,143	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$18,351	Rollup
Separate Student Kitchen Stations Are Required	Educational Adequacy	2	Ea.	4	\$7,493	Rollup
Walk In Cooler/Freezer Is Required	Educational Adequacy	1	Ea.	4	\$90,801	Rollup
Welding Bays Are Required	Educational Adequacy	3	Ea.	4	\$16,344	Rollup
Work Tables Are Required	Educational Adequacy	6	Ea.	4	\$21,773	Rollup
Room lacks an appropriate refrigerator.	Educational Adequacy	1	Ea.	5	\$8,602	Rollup
The room lacks a washer and/or dryer.	Educational Adequacy	2	Ea.	5	\$27,527	Rollup
Sub Total for System		7	items		\$190,892	
Sub Total for Building 01 - Main Building		39	items		\$1,474,238	
Total for Campus		43	items		\$1,762,608	



Buildings with no reported deficiencies

- 02 - Greenhouse
- 03 - Quonset Hut 1
- 04 - Quonset Hut 2
- 05 - Storage



Cranston Area Career & Technical Center - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Pedestrian Pavement	Sidewalks - Asphalt	400	SF	\$3,460	5
Fences and Gates	Fencing - Chain Link (8 Ft)	290	LF	\$19,734	5
		Sub Total for System	2 items	\$23,193	
		Sub Total for Building -	2 items	\$23,193	

Building: 01 - Main Building

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	E.I.F.S. - Bldg SF basis	18,001	SF	\$375,887	5
		Sub Total for System	1 items	\$375,887	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Operable Partitions	Foldable partition (Bldg SF)	100	SF Wall	\$11,692	5
Note: Director's office					
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	4,042	SF	\$48,524	5
		Sub Total for System	2 items	\$60,216	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Electrical Service	Switchgear - Main Dist Panel (1600 Amps)	1	Ea.	\$83,103	5
		Sub Total for System	1 items	\$83,103	

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	14	Room	\$158,538	5
		Sub Total for System	1 items	\$158,538	
		Sub Total for Building 01 - Main Building	5 items	\$677,743	

Building: 03 - Quonset Hut 1

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Steep Slope Roofing	Metal (Architectural - Standing Seam)	1,000	SF	\$34,642	5
Note: Corrugated metal					
		Sub Total for System	1 items	\$34,642	
		Sub Total for Building 03 - Quonset Hut 1	1 items	\$34,642	

Building: 05 - Storage

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Steep Slope Roofing	Composition Shingle	250	SF	\$7,217	5
		Sub Total for System	1 items	\$7,217	
		Sub Total for Building 05 - Storage	1 items	\$7,217	
		Total for: Cranston Area Career & Technical Center	9 items	\$742,796	



Supporting Photos



Site Aerial



Southeast Elevation



Robotics Lab



ADA Stall



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center



Typical Classroom



Greenhouse



Greenhouse



Quonset Hut 1



Quonset Hut 1



Quonset Hut 2



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center



CAD Lab



Entry Signage



Green House



Wood Shop



Exterior Brick



Wood Shop



Facility Condition Assessment

Cranston - Cranston Area Career & Technical Center



Corridor Finishes



North Elevation



Rusted Roof Top Unit



Generator



Transfer Switch



Facility Condition Assessment

Cranston - Cranston High School East

June 2017

899 Park Avenue, Cranston, RI 02910





Introduction

Cranston High School East, located at 899 Park Avenue in Cranston, Rhode Island, was built in 1925. It comprises 238,143 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Cranston High School East serves grades 9 - 12, has 86 instructional spaces, and has an enrollment of 1,577. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Cranston High School East is 1,595 with a resulting utilization of 99%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Cranston High School East the 5-year need is \$21,785,939. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Cranston High School East



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Cranston High School East campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	CMU Exterior Wall
	E.I.F.S. Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Storefront / Curtain Wall
	Wood Exterior Doors
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Roofing
----------------------------	--------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Ceramic Tile Wall
	Wood Wall Paneling
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring



01 - Main Building:	Terrazzo Flooring
	Carpet

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	200 MBH Copper Tube Boiler
	400 MBH Copper Tube Boiler
	750 MBH Copper Tube Boiler
	240 GPM Steam to Water Heat Exchanger
	Steam Condensate Receiver, Tank and Pump
	36 MBH Steam Unit Heater
	Steam/Hot Water Heating Unit Vent
	Finned Wall Radiator
	Electronic Heating System Controls
	Pneumatic Heating System Controls
	70 Ton Outdoor Air Cooled Chiller
	10 Ton Condensing Unit
	7.5 Ton Condensing Unit
	1 Ton Fan Coil - Water Cool/Water Heat
	Window Units
	10,000 CFM Energy Recovery Unit
	5 HP VFD
	1 HP or Smaller Pump
	5 HP Pump
	10 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	2,000 CFM Interior AHU
	5,000 CFM Outdoor AHU
	Ductwork
	Kitchen Exhaust Hoods
	Laboratory Fume Hood
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	4'x6' Ventilator/Relief Vent
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	100 Gallon Water Storage Tank
	250 Gallon Water Storage Tank



01 - Main Building:	2" Backflow Preventers
	4" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Air Compressor (1 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	80 KVA UPS
	1,200 Amp Switchgear
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Panelboard - 277/480 100A
	400 Amp Distribution Panel
	600 Amp Distribution Panel
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	-	\$83,526	\$1,301,692	\$1,385,218	7.00 %
Roofing	-	\$914,767	\$87	-	-	\$914,854	4.62 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$2,106,518	\$5,464	\$229	-	\$2,112,212	10.67 %
Interior	-	-	\$2,443,949	\$653,724	\$1,045,583	\$4,143,257	20.93 %
Mechanical	-	\$3,330,034	-	\$1,037,705	-	\$4,367,738	22.06 %
Electrical	\$1,429	\$395,413	-	-	\$122,564	\$519,406	2.62 %
Plumbing	-	-	\$425,387	\$77,174	\$59,835	\$562,396	2.84 %
Fire and Life Safety	\$115,474	-	-	-	-	\$115,474	0.58 %
Technology	-	-	\$4,440,782	-	-	\$4,440,782	22.43 %
Conveyances	-	-	\$24,055	-	-	\$24,055	0.12 %
Specialties	-	-	\$27,714	\$1,084,441	\$100,462	\$1,212,617	6.12 %
Total	\$116,903	\$6,746,732	\$7,367,438	\$2,936,800	\$2,630,135	\$19,798,009	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Technology	-	\$4,440,782
Mechanical	-	\$4,367,738
Interior	-	\$4,143,257

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$292,309	-	\$292,309
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$6,746,732	\$2,898,943	\$2,143,980	\$1,045,583	\$12,835,238
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$116,903	-	\$224,019	\$217,293	\$1,584,552	\$2,142,767
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$283,218	-	\$283,218
Technology	-	-	\$4,244,476	-	-	\$4,244,476
Traffic	-	-	-	-	-	\$0
Total	\$116,903	\$6,746,732	\$7,367,438	\$2,936,800	\$2,630,135	\$19,798,009

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,385,218	\$0	\$0	\$0	\$0	\$550,732	\$550,732	\$1,935,950
Roofing	\$914,854	\$0	\$0	\$0	\$0	\$0	\$0	\$914,854
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$2,112,212	\$0	\$0	\$0	\$0	\$285,876	\$285,876	\$2,398,088
Interior	\$4,143,257	\$0	\$0	\$0	\$121,117	\$311,824	\$432,941	\$4,576,198
Mechanical	\$4,367,738	\$0	\$0	\$0	\$289,939	\$73,896	\$363,835	\$4,731,574
Electrical	\$519,406	\$0	\$0	\$0	\$0	\$0	\$0	\$519,406
Plumbing	\$562,396	\$0	\$0	\$0	\$65,862	\$0	\$65,862	\$628,258
Fire and Life Safety	\$115,474	\$0	\$0	\$0	\$0	\$0	\$0	\$115,474
Technology	\$4,440,782	\$0	\$0	\$0	\$0	\$0	\$0	\$4,440,782
Conveyances	\$24,055	\$0	\$0	\$288,684	\$0	\$0	\$288,684	\$312,739
Specialties	\$1,212,617	\$0	\$0	\$0	\$0	\$0	\$0	\$1,212,617
Total	\$19,798,009	\$0	\$0	\$288,684	\$476,918	\$1,222,328	\$1,987,930	\$21,785,939

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$85,731,480. For planning purposes, the total 5-year need at the Cranston High School East is \$21,785,939 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Cranston High School East facility has a 5-year FCI of 25.41%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 1,287 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Cranston High School East cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$741,830.



Summary of Findings

The Cranston High School East comprises 238,143 square feet and was constructed in 1925. Current deficiencies at this school total \$19,798,009. Five year capital renewal costs total \$1,987,930. The total identified need for the Cranston High School East (current deficiencies and 5-year capital renewal costs) is \$21,785,939. The 5-year FCI is 25.41%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Cranston High School East Totals	238,143	1925	\$19,798,009	\$1,987,930	\$21,785,939	25.41%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Paving Requires Replacement	Capital Renewal	12	CAR	4	\$46,238	11605
Note: Install visitor and handicap parking (exact number depends on available area for visitor/handicap parking. 7 Visitor, 5 Handicap)						
Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$37,288	28434
Note: Backstops Require Replacement						
PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54873
Note: PE / Recess Playfield is Missing and is Needed						
School has insufficient # of tennis courts.	Educational Adequacy	1	Ea.	5	\$212,705	29002
Note: School has insufficient # of tennis courts.						
School has insufficient baseball fields.	Educational Adequacy	1	Ea.	5	\$273,448	28317
Note: School has insufficient baseball fields.						
School has insufficient football/soccer fields.	Educational Adequacy	1	Ea.	5	\$124,295	28187
Note: School has insufficient football/soccer fields.						
School has insufficient softball fields.	Educational Adequacy	1	Ea.	5	\$198,871	28359
Note: School has insufficient softball fields.						
School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$427,573	28233
Note: School lacks a competition track.						
Sub Total for System		8	items		\$1,385,218	
Sub Total for School and Site Level		8	items		\$1,385,218	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Single-Ply Membrane Roof Covering Requires Replacement	Capital Renewal	65,000	SF	2	\$914,767	9701
Note: Ponding, staining, buckling of membrane and insulation feels loose when you walk on it.						
Location: Original building and gym addition						
The Roof Drains Require Cleaning	Capital Renewal	2	Ea.	3	\$87	9671
Note: At the front of the building between the gym addition and original building and on the low roof near the access ladder to the gym roof. Deep standing water in both areas.						
Sub Total for System		2	items		\$914,854	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Storefront/Curtain Wall Requires Replacement (Bldg SF)	Capital Renewal	7,000	SF	2	\$618,810	9695
Note: Storefront windows in 3rd and 4th floor classrooms at rear of building are being kept shut with duct tape.						
The Storefront/Curtain Wall Requires Replacement (Bldg SF)	Capital Renewal	16,829	SF	2	\$1,487,708	9696
Note: Original single pane glass. Do not operate properly and let air in.						
Exterior Metal Door Requires Repainting	Capital Renewal	24	Door	3	\$5,464	9670
Note: All exterior doors need scraping, priming and painting.						
Handrail Requires Repainting	Capital Renewal	20	LF	4	\$229	9680
Note: Paint is peeling at exterior handrail.						
Sub Total for System		4	items		\$2,112,212	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement	Capital Renewal	157	Door	3	\$793,789	9673
Note: Doors and hardware are worn and damaged.						
The Acoustical Ceiling Tiles Require Replacement	Capital Renewal	16,000	SF	3	\$158,455	9672
Location: 4th floor corridor, Nurses' Office, and miscellaneous older classrooms						
The Interior Door Hardware Requires Replacement	Capital Renewal	303	Door	3	\$1,042,366	9681
Note: No master key. Custodian has ring with 20+ keys for all doors in building.						



Facility Condition Assessment

Cranston - Cranston High School East

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Vinyl Composition Tile Requires Replacement	Capital Renewal	35,721	SF	3	\$449,339	9674
Note: VCT in classrooms needs replacement, it's damaged and seams are lifting.						
Adhered Acoustical Ceiling Tile Requires Replacement	Capital Renewal	5,000	SF	4	\$59,453	9703
Note: Adhesive is failing and the tiles are falling in cafe.						
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	130	SF	4	\$4,066	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	76	Ea.	4	\$23,768	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	320	LF	4	\$8,006	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	23,730	SF	4	\$247,378	Rollup
Partitions Provide Insufficient Sound Isolation	Acoustics	1,200	SF	4	\$37,529	19754
Note: Classrooms adjacent to auditorium						
Room Is Excessively Reverberant	Acoustics	10,400	SF	4	\$254,780	19757
Note: Gym						
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	486	SF	4	\$18,744	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	105,542	SF	5	\$764,669	Rollup
The Gypsum Board Ceilings Require Repainting	Capital Renewal	61,243	SF	5	\$280,914	Rollup
	Sub Total for System	14	items		\$4,143,257	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Requires Replacement (SF Basis)	Capital Renewal	26,000	SF	2	\$419,128	9688
Note: Ductwork was installed around the 1950's.						
Replace Unit Vent	Capital Renewal	8	Ea.	2	\$148,381	9700
Note: Cabinet unit heaters are falling apart.						
The Air Handler HVAC Component Requires Replacement	Capital Renewal	4	Ea.	2	\$189,204	9682
Note: Air handling units are outdated and their components are no longer available.						
Location: Boiler room, cafeteria, kitchen, and shop area						
The Boiler HVAC Component Requires Replacement	Capital Renewal	3	Ea.	2	\$560,357	9683
Note: Boilers installed in the early 1970's are inefficient and their components are no longer available.						
The Fin Tube Water Radiant Heater Requires Replacement	Capital Renewal	128	Ea.	2	\$235,115	9687
Note: Fin tube radiator in oldest part of building is in disrepair. Casings show signs of rust and deterioration.						
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	119,071	SF	2	\$1,006,422	9689
Note: HVAC piping in majority of building is original to 1930's install						
The Steam Condensate Receiver Requires Replacement	Capital Renewal	2	Ea.	2	\$771,428	18006
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	119,071	SF	4	\$881,929	9692
Note: Controls are very unreliable, many leaks throughout building per HVAC mechanics.						
Lab lacks an appropriate fume hood.	Educational Adequacy	7	Ea.	4	\$155,776	Rollup
	Sub Total for System	9	items		\$4,367,738	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	1	Ea.	1	\$1,429	Rollup
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$75,725	9690
The Distribution Panel Requires Replacement	Capital Renewal	2	Ea.	2	\$63,883	9691
The Electrical Disconnect Requires Replacement	Capital Renewal	28	Ea.	2	\$56,277	9675
The Panelboard Requires Replacement	Capital Renewal	22	Ea.	2	\$185,768	9684
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$8,444	9685
Note: Panelboard in Shop is missing blanks over bus bar.						
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$5,317	9686
Note: Panelboard is being used as a junction box, is not secured, and poses a hazard.						
Room Has Insufficient Electrical Outlets	Educational Adequacy	244	Ea.	5	\$122,564	Rollup
	Sub Total for System	8	items		\$519,406	



Facility Condition Assessment

Cranston - Cranston High School East

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Gas Water Heater Requires Replacement	Capital Renewal	2	Ea.	3	\$12,818	9699
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	23,814	SF	3	\$210,101	9679
Note: Domestic water piping in original part of building is deteriorating and scaling.						
The Sanitary Sewer Piping Requires Replacement	Capital Renewal	750	LF	3	\$128,036	9694
Note: Sanitary sewer piping is well beyond its anticipated life cycle. District plumber reported backups, etc.						
Water Storage Tank Requires Replacement	Capital Renewal	3	Ea.	3	\$74,432	9702
Note: Storage tanks were installed in 1970's						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	13	Ea.	4	\$36,726	9677
Note: Mop sinks are deteriorating and outdated.						
The Refrigerated Water Cooler Requires Replacement	Capital Renewal	5	Ea.	4	\$40,448	9678
Note: Water fountains outside Room 413, in the gym and adjacent areas are no longer operable.						
Room lacks a drinking fountain.	Educational Adequacy	7	Ea.	5	\$7,814	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	34	Ea.	5	\$52,021	Rollup
	Sub Total for System	8	items		\$562,396	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	10	Ea.	1	\$115,474	Rollup
	Sub Total for System	1	items		\$115,474	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	34	Ea.	3	\$196,305	Rollup
Technology: Auditorium AV/Multimedia system is inadequate.	Technology	1	Room	3	\$364,865	24608
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	816	Ea.	3	\$425,328	24607
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	75	Ea.	3	\$781,853	24610
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	75	Ea.	3	\$781,853	24618
Technology: Gymnasium sound system is nonexistent, inadequate, or near end of useful life.	Technology	1	Ea.	3	\$10,008	24609
Technology: Instructional spaces do not have local sound reinforcement.	Technology	75	Ea.	3	\$390,926	24615
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	6	Ea.	3	\$35,027	24602
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,622	24599
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,622	24600
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,622	24601
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$41,282	24596
Technology: Intermediate Telecommunications Room needs M/E improvements.	Technology	1	Ea.	3	\$26,687	24597
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$18,347	24598
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	3	Ea.	3	\$15,637	24603
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,297	24594
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$46,703	24593



Facility Condition Assessment

Cranston - Cranston High School East

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,903	24595
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	400	Ea.	3	\$187,645	24605
Technology: Network system inadequate and/or near end of useful life	Technology	13	Ea.	3	\$108,417	24613
Technology: Network system inadequate and/or near end of useful life	Technology	38	Ea.	3	\$198,069	24614
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	238,143	SF	3	\$446,862	24612
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,849	24611
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	6	Ea.	3	\$31,274	24604
Technology: Telecommunications Room fiber connectivity infrastructure is outdated and/or inadequate.	Technology	2	Ea.	3	\$13,761	24606
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	75	Ea.	3	\$125,096	24616
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,923	24617
Sub Total for System		27	items		\$4,440,782	

Conveyances

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Dumbwaiter Requires Replacement	Capital Renewal	1	Ea.	3	\$24,055	9693
Sub Total for System		1	items		\$24,055	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	6	Ea.	3	\$27,714	Rollup
The Metal Student Lockers Require Replacement Note: Many lockers are broken and the locks do not function well.	Capital Renewal	2,000	Ea.	4	\$1,078,956	9697
Welding Bays Are Required	Educational Adequacy	1	Ea.	4	\$5,485	Rollup
Room lacks an appropriate refrigerator.	Educational Adequacy	10	Ea.	5	\$86,605	Rollup
The room lacks a washer and/or dryer.	Educational Adequacy	1	Ea.	5	\$13,857	Rollup
Sub Total for System		5	items		\$1,212,617	
Sub Total for Building 01 - Main Building		79	items		\$18,412,791	
Total for Campus		87	items		\$19,798,009	



Cranston High School East - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Landscape Lighting	Ground Mounted Fixtures (Ea.)	8	Ea.	\$14,919	5
	Note: In stone walkway, gym entrance				
Parking Lot Pavement	Asphalt	160	CAR	\$535,813	5
	Note: Shared with fire department and city hall				
	Sub Total for System	2	items	\$550,732	
	Sub Total for Building -	2	items	\$550,732	

Building: 01 - Main Building

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	E.I.F.S. - Bldg SF basis	11,907	SF	\$248,636	5
Exterior Utility Doors	Overhead	1	Door	\$37,240	5
	Sub Total for System	2	items	\$285,876	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Carpeting	Carpet	5,500	SF	\$121,117	4
Interior Operable Partitions	Foldable partition (Bldg SF)	1,200	SF Wall	\$140,300	5
	Note: Rooms 220, 314, 302 & 304.				
Wall Paneling	Wood Panel wall	2,381	SF	\$21,995	5
Resilient Flooring	Vinyl Composition Tile Flooring	11,908	SF	\$138,270	5
Terrazzo Flooring	Terrazzo	150	SF	\$11,259	5
	Sub Total for System	5	items	\$432,941	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	12	Ea.	\$205,451	4
Decentralized Cooling	Window Units	25	Ea.	\$84,488	4
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$16,159	5
Exhaust Air	Laboratory Fume Hood	2	Ea.	\$57,737	5
	Sub Total for System	4	items	\$363,834	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Compressed-Air Systems	Air Compressor (1 hp)	1	Ea.	\$6,124	4
Plumbing Fixtures	Refrigerated Drinking Fountain	8	Ea.	\$59,738	4
	Sub Total for System	2	items	\$65,862	

Conveyances

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Elevators	Hydraulic (Passenger Elev)	1	Ea.	\$288,684	3
	Sub Total for System	1	items	\$288,684	
	Sub Total for Building 01 - Main Building	14	items	\$1,437,198	
	Total for: Cranston High School East	16	items	\$1,987,930	



Supporting Photos



Ponding On Roof



Ponding On Roof



Ponding And Debris On Roof



Weathered Roof Membrane



Facility Condition Assessment

Cranston - Cranston High School East



Site Aerial



Computer Lab



Front



Cafeteria



Rear Of Building



Child Development



Facility Condition Assessment

Cranston - Cranston High School East



Side Of Building




Front



Life Skills



Cafeteria Ceiling



Gymnasium



Interior Entry



Facility Condition Assessment

Cranston - Cranston High School East



Music Room



Music Room



Side Of Building



Auditorium



Band Room



Classroom



Facility Condition Assessment

Cranston - Cranston High School East



Rear Of Building



Front



Front



Wrestling Room



Child Development



Cafeteria



Facility Condition Assessment

Cranston - Cranston High School East



Life Skills



Art Room



Typical Classroom



Gymnasium



Science Lab



Library



Facility Condition Assessment

Cranston - Cranston High School East



Toilet Room Upper Floors



New Wing Typical Classroom



Toilet Room Lower Floor



Art Room



Cabinet Unit Heater



Toilet Room Gym Addition



Facility Condition Assessment

Cranston - Cranston High School East



Weight Room



Cafeteria



Auto Shop



Typical Exterior Metal Door



Art Director's Office Ceiling Tiles



4th Floor Corridor Acoustical Ceiling Tiles



Facility Condition Assessment

Cranston - Cranston High School East



Damaged Interior Wood Door



Damaged VCT In Classrooms



Original Disconnects



Peeling Handrail



Fin Tube Radiant Heater



Single Pane Windows



Facility Condition Assessment

Cranston - Cranston High School East



Storefront Windows



Classroom



Damaged Lockers



Facility Condition Assessment

Cranston - Cranston High School West

June 2017

80 Metropolitan Avenue, Cranston, RI 02920





Introduction

Cranston High School West, located at 80 Metropolitan Avenue in Cranston, Rhode Island, was built in 1958. It comprises 205,632 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Cranston High School West serves grades 9 - 12, has 92 instructional spaces, and has an enrollment of 1,476. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Cranston High School West is 1,494 with a resulting utilization of 99%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Cranston High School West the 5-year need is \$25,183,153. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Cranston High School West



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Cranston High School West campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	E.I.F.S. Exterior Wall
	Aluminum Exterior Windows
	Vinyl on Wood Frame Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors
03 - Auditorium and Music:	Brick Exterior Wall
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors
04 - Gymnasium:	Wood Siding Exterior Wall
	Brick Exterior Wall
	Painted Exterior Wall
	Steel Exterior Entrance Doors
	Storefront Entrance Doors
	Overhead Exterior Utility Doors
05 - E Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
06 - Building 6:	Metal Panel Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Built-Up Roofing With Ballast
	EPDM Roofing
03 - Auditorium and Music:	Composition Shingle Roofing
	EPDM Roofing
04 - Gymnasium:	EPDM Roofing



05 - E Building:	EPDM Roofing
06 - Building 6:	Metal Steep Slope Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Interior Wall Painting
	Quarry Tile Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Carpet
03 - Auditorium and Music:	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Acoustical Wall Paneling
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Carpet
04 - Gymnasium:	Wood Interior Doors
	Steel Interior Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings



04 - Gymnasium:	Ceramic Tile Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Rubber Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
05 - E Building:	Steel Interior Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Interior Wall Painting
	Vinyl Composition Tile Flooring
	Carpet
06 - Building 6:	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Interior Wall Painting
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	1,275 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	36 MBH Steam Unit Heater
	DDC Heating System Controls
	1 Ton Ductless Split System
	Window Units
	Make-up Air Unit
	50 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	15 Ton DX Gas Roof Top Unit
	Ductwork
	Roof Exhaust Fan
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	Laboratory Fume Hood
	4'x6' Ventilator/Relief Vent
	Fire Sprinkler System



03 - Auditorium and Music:	200 MBH Gas Furnace
	DDC Heating System Controls
	2-Pipe Hot Water Hydronic Distribution System
	20,000 CFM Interior AHU
	Ductwork
	Large Roof Exhaust Fan
	Fire Sprinkler System
04 - Gymnasium:	75 MBH Gas Furnace
	DDC Heating System Controls
	2-Pipe Hot Water Hydronic Distribution System
	20,000 CFM Interior AHU
	Ductwork
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	Fire Sprinkler System
05 - E Building:	400 MBH Cast Iron Water Boiler
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	36 MBH Steam Unit Heater
	DDC Heating System Controls
	1 Ton Ductless Split System
	Window Units
	1 HP or Smaller Pump
	5 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	Roof Exhaust Fan
	Fire Sprinkler System
06 - Building 6:	Electronic Heating System Controls
	2,000 CFM Interior AHU
	Roof Exhaust Fan

Plumbing

The plumbing systems for the building(s) at this campus include:

04 - Gymnasium:	500 Gallon Water Storage Tank
01 - Main Building:	4" Backflow Preventers
	Gas Piping System
	200 Gallon Electric Water Heater
05 - E Building:	Gas Piping System
	6.4 GPM Instant Water Heater
04 - Gymnasium:	Gas Piping System
	75 Gallon Gas Water Heater
03 - Auditorium and Music:	Gas Piping System



03 - Auditorium and Music:	40 Gallon Gas Water Heater
01 - Main Building:	Domestic Water Piping System
05 - E Building:	Domestic Water Piping System
04 - Gymnasium:	Domestic Water Piping System
03 - Auditorium and Music:	Domestic Water Piping System
01 - Main Building:	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
05 - E Building:	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
04 - Gymnasium:	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Showers
	Toilets
	Urinals
03 - Auditorium and Music:	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
05 - E Building:	Air Compressor (1/2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	600 Amp Switchgear
	30 KVA Transformer
	45 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 277/480 225A
	Panelboard - 400+ Amps
	Electrical Disconnect
	Light Fixtures



Facility Condition Assessment

Cranston - Cranston High School West

01 - Main Building:	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
03 - Auditorium and Music:	600 Amp Switchgear
	600 Amp Distribution Panel
	Panelboard - 120/208 225A
	Panelboard - 120/240 100A
	Light Fixtures
	Building Mounted Lighting Fixtures
04 - Gymnasium:	100 kW Emergency Generator
	Automatic Transfer Switch
	600 Amp Switchgear
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
05 - E Building:	600 Amp Switchgear
	Panelboard - 120/208 125A
	Panelboard - 120/240 100A
	Building Mounted Lighting Fixtures
	Light Fixtures
06 - Building 6:	Panelboard - 120/208 100A
	Electrical Disconnect
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Cranston - Cranston High School West

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$334,594	\$1,949,868	\$192,456	\$2,476,918	14.91 %
Roofing	-	\$1,281,363	-	-	-	\$1,281,363	7.71 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$160,380	-	\$45,207	-	\$205,587	1.24 %
Interior	-	-	\$1,392,339	\$3,139,026	\$954,531	\$5,485,896	33.03 %
Mechanical	-	\$267,415	-	\$176,287	-	\$443,701	2.67 %
Electrical	\$2,859	\$696,989	\$3,766	-	\$114,010	\$817,625	4.92 %
Plumbing	-	-	\$2,003,601	\$198,382	\$46,767	\$2,248,749	13.54 %
Fire and Life Safety	\$92,379	-	-	-	-	\$92,379	0.56 %
Technology	-	-	\$3,000,351	-	-	\$3,000,351	18.06 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	-	\$460,410	\$96,998	\$557,408	3.36 %
Total	\$95,238	\$2,406,147	\$6,734,651	\$5,969,180	\$1,404,761	\$16,609,978	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$5,485,896
Technology	-	\$3,000,351
Site	-	\$2,476,918

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$527,650	-	\$527,650
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$2,406,147	\$3,566,286	\$2,721,822	\$950,989	\$9,645,244
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$95,238	-	\$161,663	\$208,995	\$453,773	\$919,668
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$2,510,713	-	\$2,510,713
Technology	-	-	\$2,838,688	-	-	\$2,838,688
Traffic	-	-	\$168,014	-	-	\$168,014
Total	\$95,238	\$2,406,147	\$6,734,651	\$5,969,180	\$1,404,761	\$16,609,978

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$2,476,918	\$0	\$0	\$0	\$27,586	\$495,783	\$523,369	\$3,000,287
Roofing	\$1,281,363	\$0	\$0	\$0	\$0	\$241,760	\$241,760	\$1,523,123
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$205,587	\$0	\$0	\$0	\$0	\$620,907	\$620,907	\$826,494
Interior	\$5,485,896	\$0	\$0	\$5,208,110	\$104,845	\$979,417	\$6,292,372	\$11,778,270
Mechanical	\$443,701	\$0	\$0	\$230,947	\$63,933	\$380,176	\$675,056	\$1,118,757
Electrical	\$817,625	\$0	\$0	\$0	\$0	\$0	\$0	\$817,625
Plumbing	\$2,248,749	\$0	\$0	\$0	\$0	\$219,711	\$219,711	\$2,468,461
Fire and Life Safety	\$92,379	\$0	\$0	\$0	\$0	\$0	\$0	\$92,379
Technology	\$3,000,351	\$0	\$0	\$0	\$0	\$0	\$0	\$3,000,351
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$557,408	\$0	\$0	\$0	\$0	\$0	\$0	\$557,408
Total	\$16,609,978	\$0	\$0	\$5,439,057	\$196,364	\$2,937,754	\$8,573,175	\$25,183,153

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$74,387,520. For planning purposes, the total 5-year need at the Cranston High School West is \$25,183,153 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Cranston High School West facility has a 5-year FCI of 33.85%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 1,117 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Cranston High School West cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Cranston High School West comprises 205,632 square feet and was constructed in 1958. Current deficiencies at this school total \$16,609,978. Five year capital renewal costs total \$8,573,175. The total identified need for the Cranston High School West (current deficiencies and 5-year capital renewal costs) is \$25,183,153. The 5-year FCI is 33.85%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Cranston High School West Totals	205,632	1958	\$16,609,978	\$8,573,175	\$25,183,153	33.85%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Walks Require Replacement Note: Asphalt walkways are cracked and uneven.	Capital Renewal	6,507	SF	3	\$70,352	12117
Crosswalk Requires Repainting Note: Repaint crosswalk on Curtis St and crosswalks at intersection of Curtis St and Cranston St	Traffic	3	Ea.	3	\$2,887	16915
Parking Or Roadway Curbs Require Replacement Note: Concrete curbs at the front of the school are cracked and broken and pose a tripping hazard.	Capital Renewal	1,000	LF	3	\$96,228	12120
Sidewalk Requires Replacement Note: Replace sidewalk along Metropolitan Ave and Curtis St from school campus to Cranston St. (920' long x 6' wide)	Traffic	5,520	SF	3	\$159,354	16914
Traffic Signage Is Required Note: Add school zone signage on Curtis St.	Traffic	2	Ea.	3	\$5,774	16913
Asphalt Paving Requires Replacement Note: Asphalt is alligatored and heaving.	Capital Renewal	448	CAR	4	\$1,875,345	12116
Asphalt Paving Requires Resurfacing Note: Roadway surface is weathered.	Capital Renewal	1,850	SF	4	\$2,448	12118
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28447
Fencing Requires Replacement (4' Chain Link Fence) Note: Chain link fence is bent, overgrown, and failing in places.	Capital Renewal	440	LF	4	\$35,989	12115
School has insufficient softball fields. Note: School has insufficient softball fields.	Educational Adequacy	1	Ea.	5	\$192,456	28360
Sub Total for System		10	items		\$2,476,918	
Sub Total for School and Site Level		10	items		\$2,476,918	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Built-up Roofing With Aggregate Ballast Requires Replacement Note: Original roof has some membrane patching and is showing signs of wear and age. Staff reported that it is scheduled to be replaced in the summer of 2016.	Capital Renewal	18,890	SF	2	\$757,395	12127
Sub Total for System		1	items		\$757,395	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement Note: Original wood doors are aged and worn.	Capital Renewal	170	Door	3	\$826,458	12122
The Tectum Decking Requires Repair Note: Tar from roof is leaking into tectum decking in the B wing classrooms.	Capital Renewal	18,890	SF	3	\$146,082	12129
Asbestos 9x9 Tile is Present. Limited Areas of Lifting or Broken Tiles Exist	Hazardous Material	68,003	SF	4	\$2,044,935	Rollup
Caulking - significant areas of broken pieces &/or deteriorating caulk	Hazardous Material	4,134	LF	4	\$82,876	Rollup
Paint (probable pre-1978 in base (layers(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	752	Ea.	4	\$226,136	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	1,731	LF	4	\$41,643	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	11,463	SF	4	\$114,902	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	2	SF	4	\$20	Rollup
Room Is Excessively Reverberant Note: Gym	Acoustics	22,400	SF	4	\$527,650	19833
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	2,610	SF	4	\$100,663	Rollup
Wall/ceiling materials - area < 9 sq. ft. AND in children-accessible area	Hazardous Material	20	SF	4	\$200	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	136,006	SF	5	\$947,487	Rollup
Sub Total for System		12	items		\$5,059,053	



Facility Condition Assessment

Cranston - Cranston High School West

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Lab lacks an appropriate fume hood.	Educational Adequacy	3	Ea.	4	\$66,761	Rollup
The Chemistry Lab Fume Hood(s) Require Replacement Note: Fume hood stack is rusted and deteriorating.	Capital Renewal	2	Ea.	4	\$60,143	12121
The Exhaust Hood Requires Replacement Note: Exhaust fans are outdated and deteriorating.	Capital Renewal	9	Ea.	4	\$49,383	12136
Sub Total for System		3	items		\$176,287	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	2	Ea.	1	\$2,859	Rollup
Switchgear Is Needed Or Requires Replacement Note: Electrical service and distribution switchgear is obsolete.	Capital Renewal	2	Ea.	2	\$40,656	12137
The Electrical Disconnect Requires Replacement Note: Electrical disconnects in the remote vault are heavily corroded and should be replaced.	Capital Renewal	6	Ea.	2	\$121,969	12119
The Panelboard Requires Replacement Note: The panelboards are obsolete.	Capital Renewal	8	Ea.	2	\$40,897	12131
The Panelboard Requires Replacement Note: The panelboards are obsolete.	Capital Renewal	7	Ea.	2	\$42,801	12132
The Panelboard Requires Replacement Note: Panelboards are obsolete.	Capital Renewal	3	Ea.	2	\$56,263	12133
Room Has Insufficient Electrical Outlets	Educational Adequacy	204	Ea.	5	\$102,471	Rollup
Sub Total for System		7	items		\$407,917	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life Note: Water piping is aged with signs of scaling. Staff reports that water runs brown after periods of low use.	Capital Renewal	151,118	SF	3	\$1,281,971	12130
The Urinal Plumbing Fixtures Require Replacement Note: Urinals are aged and stained and should be replaced.	Capital Renewal	39	Ea.	3	\$54,651	12128
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	8	Ea.	4	\$21,731	12126
The Restroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	35	Ea.	4	\$117,388	12124
Room lacks a drinking fountain.	Educational Adequacy	4	Ea.	5	\$4,465	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	23	Ea.	5	\$35,191	Rollup
Sub Total for System		6	items		\$1,515,397	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	8	Ea.	1	\$92,379	Rollup
Sub Total for System		1	items		\$92,379	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	21	Ea.	3	\$121,247	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	624	Ea.	3	\$312,741	23438
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	75	Ea.	3	\$751,781	23449
Technology: Gymnasium sound system is nonexistent, inadequate, or near end of useful life.	Technology	1	Ea.	3	\$9,623	23440
Technology: Instructional spaces do not have local sound reinforcement.	Technology	75	Ea.	3	\$375,891	23446
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23417



Facility Condition Assessment

Cranston - Cranston High School West

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23420
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23424
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23428
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23432
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23436
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$47,713	23431
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23423
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,642	23419
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,642	23427
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,642	23435
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23418
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23421
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23425
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23429
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23433
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23437
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23414
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23416
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23413
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	624	Ea.	3	\$188,547	23439
Technology: Network system inadequate and/or near end of useful life	Technology	12	Ea.	3	\$96,228	23444
Technology: Network system inadequate and/or near end of useful life	Technology	38	Ea.	3	\$190,451	23445
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	237,479	SF	3	\$428,477	23443
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23442
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,019	23415
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23422
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23426



Facility Condition Assessment

Cranston - Cranston High School West

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23430
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23434
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	75	Ea.	3	\$120,285	23447
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23448
Sub Total for System		37	items		\$2,959,935	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Metal Student Lockers Require Replacement Note: Student lockers are damaged. Most are unable to close or lock.	Capital Renewal	720	Ea.	4	\$373,485	12134
Room lacks an appropriate refrigerator.	Educational Adequacy	8	Ea.	5	\$69,284	Rollup
The room lacks a washer and/or dryer.	Educational Adequacy	2	Ea.	5	\$27,714	Rollup
Sub Total for System		3	items		\$470,483	
Sub Total for Building 01 - Main Building		70	items		\$11,438,846	

Building: 03 - Auditorium and Music

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Carpet Flooring Requires Replacement Note: Carpet is worn and according to staff, slated to be replaced during auditorium restoration 2016.	Capital Renewal	4,480	SF	3	\$102,766	12138
The Vinyl Composition Tile Requires Replacement Note: Vinyl composition tile is cracked and worn.	Capital Renewal	4,480	SF	3	\$54,187	12139
Room lacks appropriate sound control.	Educational Adequacy	200	SF	5	\$7,044	Rollup
Sub Total for System		3	items		\$163,997	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Air Handler HVAC Component Requires Replacement Note: Air handling unit is old and should be replaced.	Capital Renewal	1	Ea.	2	\$196,078	12142
Sub Total for System		1	items		\$196,078	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$20,328	18004
The Distribution Panel Requires Replacement Note: The electrical service and distribution panel is obsolete.	Capital Renewal	1	Ea.	2	\$30,713	12145
The Panelboard Requires Replacement Note: Panelboard is obsolete.	Capital Renewal	1	Ea.	2	\$6,114	12143
The Panelboard Requires Replacement Note: Panelboards are obsolete.	Capital Renewal	4	Ea.	2	\$24,458	12144
Remove Abandoned Equipment Note: Abandoned air compressor should be removed.	Capital Renewal	1	Ea.	5	\$3,502	12141
Sub Total for System		5	items		\$85,115	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	2	Ea.	4	\$5,433	12140
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$1,116	Rollup
Sub Total for System		2	items		\$6,549	



Facility Condition Assessment

Cranston - Cranston High School West

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,547	Rollup
Sub Total for System		1	items		\$11,547	
Sub Total for Building 03 - Auditorium and Music		12	items		\$463,286	

Building: 04 - Gymnasium

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF)	Capital Renewal	15,950	SF	2	\$212,639	12156
Note: Roof is buckled and stained with evidence of ponding. The insulation moves when underfoot. Site staff noted that the roof is scheduled for replacment in 2016.						
Sub Total for System		1	items		\$212,639	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Handrail Requires Repainting	Capital Renewal	40	LF	4	\$441	12151
Note: Handrails show chipped paint and require repainting.						
The Exterior Requires Painting (Bldg SF)	Capital Renewal	3,190	SF	4	\$44,766	12155
Note: Wood louvers need to be cleaned, prepped, and painted.						
Sub Total for System		2	items		\$45,207	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Vinyl Composition Tile Requires Replacement	Capital Renewal	160	SF	3	\$1,935	18005
Sub Total for System		1	items		\$1,935	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Generator Requires Replacement	Capital Renewal	1	Ea.	2	\$110,261	12154
Note: The generator is obsolete and should be replaced.						
Switchgear Is Needed Or Requires Replacement	Capital Renewal	3	Ea.	2	\$60,985	12159
The Electrical Disconnect Requires Replacement	Capital Renewal	3	Ea.	2	\$5,798	12146
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$48,715	12152
Note: Power distribution panelboards are obsolete.						
The Panelboard Requires Replacement	Capital Renewal	2	Ea.	2	\$25,220	12153
Transfer Switch Requires Replacement	Capital Renewal	100	Amps	3	\$3,766	12158
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$4,018	Rollup
Sub Total for System		7	items		\$258,763	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Showers Plumbing Fixtures Require Replacement	Capital Renewal	83	Ea.	3	\$665,577	12149
Note: Shower plumbing fixtures are original to the building and should be replaced.						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	2	Ea.	4	\$5,433	12150
The Restroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	12	Ea.	4	\$40,247	12147
Note: The sinks are original to the building and are rusted.						
Room lacks a drinking fountain.	Educational Adequacy	4	Ea.	5	\$4,465	Rollup
Sub Total for System		4	items		\$715,722	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Metal Student Lockers Require Replacement	Capital Renewal	157	Ea.	4	\$81,440	12157
Note: Student lockers are rusting and damaged.						
Sub Total for System		1	items		\$81,440	
Sub Total for Building 04 - Gymnasium		16	items		\$1,315,707	



Building: 05 - E Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF)	Capital Renewal	20,646	SF	2	\$275,244	12165
Note: Warranty for EPDM roofing has expired. The roof is scheduled for replacement in 2016.						
Sub Total for System		1	items		\$275,244	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Carpet Flooring Requires Replacement	Capital Renewal	1,032	SF	3	\$23,673	12160
Note: Carpet is stained and worn.						
The Vinyl Composition Tile Requires Replacement	Capital Renewal	19,614	SF	3	\$237,238	12161
Note: Vinyl composition tile is old, worn, and stained.						
Sub Total for System		2	items		\$260,911	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent	Capital Renewal	4	Ea.	2	\$71,337	12166
Note: The heating equipment unit ventilators are original to the building and should be replaced.						
Sub Total for System		1	items		\$71,337	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$20,328	12167
Note: The electrical service and distribution switchgear is obsolete.						
The Panelboard Requires Replacement	Capital Renewal	5	Ea.	2	\$30,572	12164
Note: The power distribution panelboards are obsolete.						
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$4,018	Rollup
Sub Total for System		3	items		\$54,919	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	1	Ea.	3	\$1,401	12163
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	3	Ea.	4	\$8,149	12162
Note: Original mop sinks should be replaced.						
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	1	Ea.	5	\$1,530	Rollup
Sub Total for System		3	items		\$11,081	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	5	Ea.	3	\$28,868	Rollup
Sub Total for System		1	items		\$28,868	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Welding Bays Are Required	Educational Adequacy	1	Ea.	4	\$5,485	Rollup
Sub Total for System		1	items		\$5,485	
Sub Total for Building 05 - E Building		12	items		\$707,845	

Building: 06 - Building 6

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Metal Roof Architectural Roof Covering Requires Replacement	Capital Renewal	1,000	SF	2	\$36,086	12168
Note: The corrugated roof is rusted. Interior finishes show evidence of leaks.						
Sub Total for System		1	items		\$36,086	



Facility Condition Assessment

Cranston - Cranston High School West

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Metal Panel Exterior Requires Replacement (Bldg SF)	Capital Renewal	1,000	SF	2	\$160,380	12171
Note: The building metal panel walls are rusting and walls have been damaged by snow plows.						
	Sub Total for System	1	items		\$160,380	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electrical Disconnect Requires Replacement	Capital Renewal	3	Ea.	2	\$5,798	12169
Note: The electrical disconnects are obsolete.						
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$5,112	12170
Note: The power distribution panelboard is obsolete.						
	Sub Total for System	2	items		\$10,910	
	Sub Total for Building 06 - Building 6	4	items		\$207,375	
	Total for Campus	124	items		\$16,609,978	



Cranston High School West - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (8 Ft)	290	LF	\$19,734	4
Fences and Gates	Fencing - Chain Link (4 Ft)	120	LF	\$7,852	4
Roadway Pavement	Asphalt	53	CAR	\$177,488	5
Pedestrian Pavement	Sidewalks - Concrete	15,385	SF	\$318,295	5
		Sub Total for System		4 items	\$523,368
		Sub Total for Building -		4 items	\$523,368

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	EPDM - Rubber Roofing Material	18,890	SF	\$241,760	5
		Sub Total for System		1 items	\$241,760

Note: 'A' wing

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Operating Windows	Aluminum - Windows per SF	2,132	SF	\$365,181	5
		Sub Total for System		1 items	\$365,181

Note: 2x4

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Exposed Tectum Ceilings	68,003	SF	\$5,106,776	3
Carpeting	Carpet	4,534	SF	\$99,844	4
Interior Operable Partitions	Foldable partition (Bldg SF)	2,280	SF Wall	\$266,571	5
		Sub Total for System		5 items	\$5,587,324

Note: East cafeteria

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Ventilator/Relief Vent (4'x6')	12	Ea.	\$230,947	3
Air Distribution	Make-up Air Unit	1	Ea.	\$16,093	4
		Sub Total for System		2 items	\$247,040

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 200 Gallon	1	Ea.	\$45,175	5
		Sub Total for System		1 items	\$45,175
		Sub Total for Building 01 - Main Building		10 items	\$6,486,481

Building: 03 - Auditorium and Music

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	16	Door	\$103,926	5
		Sub Total for System		1 items	\$103,926

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Paneling	Acoustical Panel Wall	538	SF	\$5,001	4
Suspended Plaster and	Painted ceilings	5,375	SF	\$22,758	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	17,201	SF	\$115,038	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	12,543	SF	\$114,664	5
		Sub Total for System		4 items	\$257,460



Facility Condition Assessment

Cranston - Cranston High School West

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heat Generation	Furnace - Gas (200 MBH)	1	Ea.	\$7,698	4
Facility Hydronic Distribution	2-Pipe Water System (Hot)	17,918	SF	\$139,798	5
Exhaust Air	Roof Exhaust Fan - Large	3	Ea.	\$42,188	5
Sub Total for System			3 items	\$189,685	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 40 gallon	2	Ea.	\$6,397	5
Sub Total for System			1 items	\$6,397	
Sub Total for Building 03 - Auditorium and Music			9 items	\$557,469	

Building: 04 - Gymnasium

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Utility Doors	Overhead	1	Door	\$37,240	5
Sub Total for System			1 items	\$37,240	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	15,152	SF	\$101,334	3
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	300	SF	\$3,602	5
Tile Flooring	Ceramic Tile	478	SF	\$12,992	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	300	SF	\$2,743	5
Sub Total for System			4 items	\$120,671	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heat Generation	Furnace - Gas (75 MBH)	1	Ea.	\$2,521	4
Facility Hydronic Distribution	2-Pipe Water System (Hot)	15,950	SF	\$124,444	5
Sub Total for System			2 items	\$126,965	
Sub Total for Building 04 - Gymnasium			7 items	\$284,876	

Building: 05 - E Building

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	13	Door	\$84,440	5
Sub Total for System			1 items	\$84,440	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	20,646	SF	\$138,077	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	15,484	SF	\$141,549	5
Sub Total for System			2 items	\$279,627	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Unit Heater Steam/HW (36 MBH)	14	Ea.	\$23,333	4
	Note: Cabinet unit heaters				
Decentralized Cooling	Ductless Split System (1 Ton)	1	Ea.	\$14,288	4
Exhaust Air	Roof Exhaust Fan	13	Ea.	\$68,478	5
Sub Total for System			3 items	\$106,099	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)	20,646	SF	\$168,139	5
Sub Total for System			1 items	\$168,139	
Sub Total for Building 05 - E Building			7 items	\$638,305	

Building: 06 - Building 6

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Operating Windows	Aluminum - Windows per SF	100	SF	\$17,129	5
Exterior Entrance Doors	Steel - Insulated and Painted	2	Door	\$12,991	5
Sub Total for System			2 items	\$30,119	



Facility Condition Assessment

Cranston - Cranston High School West

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Swinging Doors	Wood	1	Door	\$4,667	5
Interior Door Supplementary Components	Door Hardware	1	Door	\$3,176	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	1,000	SF	\$9,142	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	1,000	SF	\$6,688	5
Resilient Flooring	Vinyl Composition Tile Flooring	1,000	SF	\$11,612	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	1,000	SF	\$12,005	5
Sub Total for System		6	items	\$47,289	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Roof Exhaust Fan	1	Ea.	\$5,268	5
Sub Total for System		1	items	\$5,268	
Sub Total for Building 06 - Building 6		9	items	\$82,675	
Total for: Cranston High School West		46	items	\$8,573,175	



Supporting Photos



Site Aerial



Weathered Roadway Asphalt



Cracked And Weathered Sidewalk



E Building Exterior



Facility Condition Assessment

Cranston - Cranston High School West



Rusted Disconnects



Uneven Sidewalk



Damaged Curb At Main Entrance



Corroded Disconnect



East Cafeteria



E Building Entrance



Facility Condition Assessment

Cranston - Cranston High School West




Gymnasium South Entry




Art Room



Library



Vocal Music Room



Gymnasium



E Building Classroom



Facility Condition Assessment


Cranston - Cranston High School West



Science Classroom



West Building Exterior



Exterior Brick



Science Classroom



Original Wood Door



Restroom Finishes



Facility Condition Assessment

Cranston - Cranston High School West



Weathered Roof



9x9 Tile




Worn Vinyl Composition Tile



Damaged Lockers



Southwest Facade



Auditorium Seating



Facility Condition Assessment

Cranston - Cranston High School West



Auditorium Stage



Gymnasium Elevation



Gymnasium



South Elevation Main Entrance



Typical Classroom



Band Classroom



Facility Condition Assessment

Cranston - Cranston High School West



Computer Lab



Auditorium Exterior



East Building Cafeteria



Southwest Elevation



Auditorium Exterior Doors




Chipped Handrail Paint



Facility Condition Assessment

Cranston - Cranston High School West



Wood Louver



Weathered Gym Roofing



Ponding On Roof



Worn And Stained Carpet



Worn And Stained VCT



Damaged Metal Facade



Facility Condition Assessment

Cranston - Cranston High School West



Metal Classroom Building



Damaged Facade



Damaged Facade



Asphalt Parking Pot Holes



Alligator Parking Lot



Aged Panelboard



Facility Condition Assessment


Cranston - Cranston High School West



Aged Electrical Distribution



Aged Shower Fixtures



Rusted Sink



Aged Heating Unit



Aged Panelboard



Aged Urinal



Fume Hood Exhaust Fan Stack



Aged Exhaust Fans



Facility Condition Assessment

Cranston - Daniel D. Waterman School

June 2017

722 Pontiac Avenue, Cranston, RI 02910





Introduction

Daniel D. Waterman School, located at 722 Pontiac Avenue in Cranston, Rhode Island, was built in 1926. It comprises 27,900 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Daniel D. Waterman School serves grades 1 - 6, has 18 instructional spaces, and has an enrollment of 269. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Daniel D. Waterman School is 253 with a resulting utilization of 106%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Daniel D. Waterman School the 5-year need is \$4,945,884. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Daniel D. Waterman School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Daniel D. Waterman School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Roofing
---------------------	--------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Carpet

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	4,488 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	Radiant Water Heater
	DDC Heating System Controls



01 - Main Building:	Window Units
	2-Pipe Hot Water Hydronic Distribution System
	1 HP or Smaller Pump
	Roof Exhaust Fan
	Kitchen Exhaust Hoods
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	75 KVA Transformer
	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Light Fixtures
	Building Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$1,052	\$37,288	\$73,786	\$112,127	3.87 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$266,324	-	-	-	\$266,324	9.19 %
Interior	-	-	\$312,887	\$1,228,996	\$2,309	\$1,544,193	53.28 %
Mechanical	-	-	-	-	-	\$0	0.00 %
Electrical	-	-	-	-	\$36,166	\$36,166	1.25 %
Plumbing	-	-	-	\$123,272	\$4,121	\$127,393	4.40 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$793,461	-	-	\$793,461	27.38 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$18,476	-	-	\$18,476	0.64 %
Total	\$0	\$266,324	\$1,125,876	\$1,389,557	\$116,384	\$2,898,140	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,544,193
Technology	-	\$793,461
Exterior	-	\$266,324

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$31,274	-	\$31,274
Barrier to Accessibility	-	-	\$172,529	\$19,849	-	\$192,377
Capital Renewal	-	\$266,324	\$141,410	\$123,272	-	\$531,006
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$35,797	\$422,353	\$115,041	\$573,191
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$792,809	-	\$792,809
Technology	-	-	\$776,140	-	-	\$776,140
Traffic	-	-	-	-	\$1,342	\$1,342
Total	\$0	\$266,324	\$1,125,876	\$1,389,557	\$116,384	\$2,898,140

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$112,127	\$0	\$0	\$0	\$46,884	\$57,544	\$104,428	\$216,555
Roofing	\$0	\$0	\$0	\$0	\$0	\$120,814	\$120,814	\$120,814
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$266,324	\$0	\$0	\$0	\$0	\$1,262,865	\$1,262,865	\$1,529,189
Interior	\$1,544,193	\$0	\$0	\$0	\$0	\$344,696	\$344,696	\$1,888,889
Mechanical	\$0	\$0	\$0	\$0	\$13,518	\$16,159	\$29,677	\$29,677
Electrical	\$36,166	\$0	\$0	\$0	\$13,597	\$0	\$13,597	\$49,763
Plumbing	\$127,393	\$0	\$0	\$0	\$35,778	\$0	\$35,778	\$163,171
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$793,461	\$0	\$0	\$0	\$0	\$0	\$0	\$793,461
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$18,476	\$0	\$0	\$0	\$0	\$135,889	\$135,889	\$154,365
Total	\$2,898,140	\$0	\$0	\$0	\$109,777	\$1,937,967	\$2,047,744	\$4,945,884

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$9,765,000. For planning purposes, the total 5-year need at the Daniel D. Waterman School is \$4,945,884 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Daniel D. Waterman School facility has a 5-year FCI of 50.65%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 155 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Daniel D. Waterman School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$541,296.



Summary of Findings

The Daniel D. Waterman School comprises 27,900 square feet and was constructed in 1926. Current deficiencies at this school total \$2,898,140. Five year capital renewal costs total \$2,047,744. The total identified need for the Daniel D. Waterman School (current deficiencies and 5-year capital renewal costs) is \$4,945,884. The 5-year FCI is 50.65%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Daniel D. Waterman School Totals	27,900	1926	\$2,898,140	\$2,047,744	\$4,945,884	50.65%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Retaining Wall Requires Repair	Capital Renewal	12	SF	3	\$1,052	8851
Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$37,288	28433
Note: Backstops Require Replacement						
Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,644	28707
Note: Exterior Basketball Goals are Required						
Paving Requires Restriping	Traffic	18	CAR	5	\$1,342	9335
Note: Repaint parking spots in lot						
PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54872
Note: PE / Recess Playfield is Missing and is Needed						
Sub Total for System		5	items		\$112,127	
Sub Total for School and Site Level		5	items		\$112,127	

Building: 01 - Main Building

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement	Capital Renewal	360	SF	2	\$66,801	8852
Note: Single-pane windows						
The Storefront/Curtain Wall Requires Replacement (Bldg SF)	Capital Renewal	2,257	SF	2	\$199,522	9282
Note: Single pane window system						
Sub Total for System		2	items		\$266,324	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Existing Door Hardware Is Not ADA Compliant	Barrier to Accessibility	50	Door	3	\$156,371	8855
The Existing Toilet Stall Does Not Meet Minimum ADA Requirements	Barrier to Accessibility	5	Ea.	3	\$16,158	8856
Note: There is no ADA stall in any restroom.						
The Vinyl Composition Tile Requires Replacement	Capital Renewal	11,158	SF	3	\$140,358	8853
Note: Seams are lifting and tiles are chipped and broken.						
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	15,348	SF	4	\$479,995	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	14	Ea.	4	\$4,378	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	29,587	SF	4	\$308,436	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel)	Acoustics	500	SF	4	\$31,274	19689
Note: Gym						
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	9,984	SF	4	\$385,065	Rollup
The Handrails In The Stair Area Are Not ADA Compliant	Barrier to Accessibility	140	LF	4	\$19,849	8857
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,309	Rollup
Sub Total for System		10	items		\$1,544,193	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	72	Ea.	5	\$36,166	Rollup
Sub Total for System		1	items		\$36,166	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	11	Ea.	4	\$123,272	9287



Facility Condition Assessment

Cranston - Daniel D. Waterman School

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		2	items		\$127,393	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	3	Ea.	3	\$17,321	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$50,039	23678
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	12	Ea.	3	\$262,702	23683
Technology: Instructional spaces do not have local sound reinforcement.	Technology	12	Ea.	3	\$62,548	23685
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,297	23674
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$46,703	23673
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,903	23676
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	96	Ea.	3	\$45,035	23677
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$50,039	23686
Technology: Network system inadequate and/or near end of useful life	Technology	14	Ea.	3	\$72,973	23687
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	27,900	SF	3	\$52,353	23682
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$59,421	23679
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,849	23684
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,340	23675
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	12	Ea.	3	\$20,015	23681
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,923	23680
Sub Total for System		16	items		\$793,461	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$18,476	Rollup
Sub Total for System		1	items		\$18,476	
Sub Total for Building 01 - Main Building		32	items		\$2,786,012	
Total for Campus		37	items		\$2,898,140	



Daniel D. Waterman School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Parking Lot Pavement	Asphalt	14	CAR	\$46,884	4
Pedestrian Pavement	Sidewalks - Concrete	600	SF	\$12,413	5
Playfield Areas	ES Playgrounds	1	Ea.	\$45,131	5
		Sub Total for System		3 items	\$104,428
		Sub Total for Building -		3 items	\$104,428

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Single Ply	9,300	SF	\$120,814	5
		Sub Total for System		1 items	\$120,814

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Brick - Bldg SF basis	27,341	SF	\$1,262,865	5
		Sub Total for System		1 items	\$1,262,865

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Carpeting	Carpet	557	SF	\$12,266	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	25,934	SF	\$237,080	5
Interior Swinging Doors	Steel	22	Door	\$95,350	5
		Sub Total for System		3 items	\$344,696

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Window Units	4	Ea.	\$13,518	4
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$16,159	5
		Sub Total for System		2 items	\$29,677

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)	9	Ea.	\$13,597	4
		Sub Total for System		1 items	\$13,597

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Classroom Lavatories	13	Ea.	\$35,778	4
		Sub Total for System		1 items	\$35,778

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	12	Room	\$135,889	5
		Sub Total for System		1 items	\$135,889
		Sub Total for Building 01 - Main Building		10 items	\$1,943,316
		Total for: Daniel D. Waterman School		13 items	\$2,047,744



Supporting Photos



Site Aerial



Front Elevation



Plaque



Gymnasium / Cafeteria



Facility Condition Assessment

Cranston - Daniel D. Waterman School



Library



Exterior Brick




Plaque



Typical Single-Pane Windows



Typical classroom



Chipped Concrete



Facility Condition Assessment

Cranston - Daniel D. Waterman School



Classroom Cabinetry




Hallway Finishes



Cracked And Lifting VCT



Typical Classroom



Non-Compliant Door Hardware



Chipped And Separating VCT Flooring



Facility Condition Assessment

Cranston - Daniel D. Waterman School



Typical Restroom Stall



Staff Restroom



Peeling Wall Paint



Chipped And Bubbled Ceiling Paint



Facility Condition Assessment

Cranston - Eden Park School

June 2017

180 Oakland Avenue, Cranston, RI 02910





Introduction

Eden Park School, located at 180 Oakland Avenue in Cranston, Rhode Island, was built in 1951. It comprises 39,289 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Eden Park School serves grades 1 - 6, has 17 instructional spaces, and has an enrollment of 352. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Eden Park School is 321 with a resulting utilization of 110%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Eden Park School the 5-year need is \$7,681,721. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Eden Park School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Eden Park School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors
02 - Portable-01:	Wood Siding Exterior Wall
	Vinyl on Wood Frame Exterior Windows
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
02 - Portable-01:	EPDM Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Wood Wall Paneling
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Quarry Tile Flooring
	Rubber Tile Flooring
	Vinyl Composition Tile Flooring
02 - Portable-01:	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile



02 - Portable-01:	Vinyl/Fabric Wall Covering
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	Radiant Steam Heater
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	Pneumatic Heating System Controls
	Window Units
	1 HP or Smaller Pump
	2-Pipe Steam Hydronic Distribution System
	2,000 CFM Interior AHU
	Ductwork
	Roof Exhaust Fan
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	Supply Fan
	Wall Exhaust Fan
02 - Portable-01:	Electric Heating Unit Vent
	Ductwork
	4'x6' Ventilator/Relief Vent

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (1 hp)
	10,000 Gallon Underground Fuel Oil Storage Tank



Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	1,200 Amp Switchgear
	Panelboard - 120/208 225A
	Panelboard - 120/240 100A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
02 - Portable-01:	Panelboard - 120/208 125A
	Building Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$91,728	\$36,086	\$72,198	\$200,011	3.84 %
Roofing	-	\$523,785	-	-	-	\$523,785	10.05 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	\$7,142	\$7,142	0.14 %
Interior	-	-	\$525,104	\$842,141	\$2,309	\$1,369,554	26.28 %
Mechanical	-	\$922,704	\$114,996	\$282,635	-	\$1,320,335	25.33 %
Electrical	-	\$169,205	-	-	\$34,144	\$203,348	3.90 %
Plumbing	-	-	\$345,910	\$259,026	\$104,359	\$709,295	13.61 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$854,946	-	-	\$854,946	16.40 %
Conveyances	-	-	\$23,130	-	-	\$23,130	0.44 %
Specialties	-	-	-	-	-	\$0	0.00 %
Total	\$0	\$1,615,693	\$1,955,814	\$1,419,887	\$220,151	\$5,211,545	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,369,554
Mechanical	-	\$1,320,335
Technology	-	\$854,946

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$100,348	\$70,667	-	\$171,015
Barrier to Accessibility	-	-	\$606,066	-	-	\$606,066
Capital Renewal	-	\$1,615,693	\$391,567	\$586,582	\$107,379	\$2,701,222
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	-	\$221,830	\$112,772	\$334,602
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$540,807	-	\$540,807
Technology	-	-	\$854,946	-	-	\$854,946
Traffic	-	-	\$2,887	-	-	\$2,887
Total	\$0	\$1,615,693	\$1,955,814	\$1,419,887	\$220,151	\$5,211,545

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$200,011	\$0	\$0	\$556,198	\$0	\$387,723	\$943,921	\$1,143,932
Roofing	\$523,785	\$0	\$0	\$15,358	\$0	\$0	\$15,358	\$539,143
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$7,142	\$0	\$0	\$0	\$0	\$244,261	\$244,261	\$251,403
Interior	\$1,369,554	\$0	\$0	\$0	\$0	\$665,614	\$665,614	\$2,035,168
Mechanical	\$1,320,335	\$0	\$28,657	\$5,268	\$16,898	\$140,058	\$190,881	\$1,511,216
Electrical	\$203,348	\$0	\$0	\$0	\$240,826	\$7,217	\$248,043	\$451,392
Plumbing	\$709,295	\$0	\$0	\$0	\$0	\$0	\$0	\$709,295
Fire and Life Safety	\$0	\$0	\$0	\$3,560	\$0	\$0	\$3,560	\$3,560
Technology	\$854,946	\$0	\$0	\$0	\$0	\$0	\$0	\$854,946
Conveyances	\$23,130	\$0	\$0	\$0	\$0	\$0	\$0	\$23,130
Specialties	\$0	\$0	\$0	\$0	\$0	\$158,538	\$158,538	\$158,538
Total	\$5,211,545	\$0	\$28,657	\$580,384	\$257,724	\$1,603,411	\$2,470,176	\$7,681,721

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$14,171,150. For planning purposes, the total 5-year need at the Eden Park School is \$7,681,721 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Eden Park School facility has a 5-year FCI of 54.21%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 225 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Eden Park School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$375,732.



Summary of Findings

The Eden Park School comprises 39,289 square feet and was constructed in 1951. Current deficiencies at this school total \$5,211,545. Five year capital renewal costs total \$2,470,176. The total identified need for the Eden Park School (current deficiencies and 5-year capital renewal costs) is \$7,681,721. The 5-year FCI is 54.21%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Eden Park School Totals	39,289	1951	\$5,211,545	\$2,470,176	\$7,681,721	54.21%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk: Needs to be added Note: Add 2 crosswalks at intersection of Glengrove Ave and Oakland Ave and one crosswalk at intersection of Chestnut Ave and Glengrove Ave	Traffic	3	Ea.	3	\$2,887	11604
Install New Playground Equipment Note: Install New Playground Equipment	Barrier to Accessibility	1	SF	3	\$88,841	54877
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28439
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28711
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54878
Sub Total for System		5	items		\$200,011	
Sub Total for School and Site Level		5	items		\$200,011	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF) Note: Roof is showing signs of wear, tear, and pooling. There are frequent roof leaks.	Capital Renewal	39,289	SF	2	\$523,785	9420
Sub Total for System		1	items		\$523,785	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Cleaning Note: Stone veneer and precast concrete are stained and need cleaning.	Capital Renewal	2,500	SF Wall	5	\$7,142	9396
Sub Total for System		1	items		\$7,142	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Existing Door Hardware Is Not ADA Compliant	Barrier to Accessibility	172	Door	3	\$517,226	9404
Rubber Flooring Requires Replacement Note: Rubber floor is chipped and peeling.	Capital Renewal	400	SF	3	\$7,879	9423
Adhered Acoustical Ceiling Tile Requires Replacement	Capital Renewal	3,929	SF	4	\$44,922	9422
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	16,825	SF	4	\$505,949	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	13	Ea.	4	\$3,909	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	24	LF	4	\$577	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	3,030	SF	4	\$30,372	Rollup
Room Is Excessively Reverberant Note: Gym	Acoustics	3,000	SF	4	\$70,667	19762
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	4,816	SF	4	\$185,744	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,309	Rollup
Sub Total for System		10	items		\$1,369,554	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Requires Replacement (SF Basis)	Capital Renewal	3,000	SF	2	\$46,501	11686
The Air Handler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	2	\$90,964	9409
The Boiler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	2	\$359,203	9410
The Fin Tube Water Radiant Heater Requires Replacement	Capital Renewal	8	Ea.	2	\$14,129	9413



Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	39,289	SF	2	\$319,309	9415
The Steam/Hot Water Radiant Heater Requires Replacement	Capital Renewal	17	Ea.	2	\$92,597	9412
Note: Radiant heaters are beginning to deteriorate.						
The Large Diameter Exhausts/Hoods Require Replacement	Capital Renewal	1	Ea.	3	\$14,649	9399
Unit Ventilators Are Excessively Noisy	Acoustics	15	Ea.	3	\$100,348	19761
Note: All classrooms						
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	1	Ea.	4	\$2,823	9400
Note: Exhaust fan is no longer operable.						
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	39,289	SF	4	\$279,811	9418
Sub Total for System		10	items		\$1,320,335	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$72,813	9416
The Electrical Disconnect Requires Replacement	Capital Renewal	13	Ea.	2	\$25,124	9398
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$36,687	9411
Note: Panelboards are aged and parts are no longer available.						
The Panelboard Requires Replacement	Capital Renewal	3	Ea.	2	\$18,343	11437
Note: Panelboards are aged and parts are no longer available.						
The Panelboard Requires Replacement	Capital Renewal	2	Ea.	2	\$16,238	11438
Note: Panelboards are aged and parts are no longer available.						
Room Has Insufficient Electrical Outlets	Educational Adequacy	64	Ea.	5	\$32,148	Rollup
Sub Total for System		6	items		\$201,353	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	39,289	SF	3	\$333,298	9408
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	9	Ea.	3	\$12,612	9407
Note: Urinals are beginning to fail according to the head custodian.						
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	14	Ea.	4	\$150,857	9403
The Classroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	15	Ea.	4	\$43,002	9394
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	3	Ea.	4	\$8,149	9406
The Restroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	17	Ea.	4	\$57,017	9401
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Underground Fuel/Oil Storage Tank Requires Replacement	Capital Renewal	1	Ea.	5	\$100,238	9417
Sub Total for System		8	items		\$709,295	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$48,114	23663
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	14	Ea.	3	\$294,698	23668
Technology: Instructional spaces do not have local sound reinforcement.	Technology	14	Ea.	3	\$70,166	23670
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23660
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$47,713	23659
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23658
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23661
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23656



Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23655
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	96	Ea.	3	\$43,303	23662
Technology: Network system inadequate and/or near end of useful life	Technology	2	Ea.	3	\$16,038	23671
Technology: Network system inadequate and/or near end of useful life	Technology	18	Ea.	3	\$90,214	23672
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	34,289	SF	3	\$61,867	23667
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23664
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23669
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,019	23657
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	14	Ea.	3	\$22,453	23666
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23665
Sub Total for System		18	items		\$854,946	

Conveyances

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Dumbwaiter Requires Replacement Note: Dumbwaiter is inoperable.	Capital Renewal	1	Ea.	3	\$23,130	11685
Sub Total for System		1	items		\$23,130	
Sub Total for Building 01 - Main Building		55	items		\$5,009,539	

Building: 02 - Portable-01

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	4	Ea.	5	\$1,996	Rollup
Sub Total for System		1	items		\$1,996	
Sub Total for Building 02 - Portable-01		1	items		\$1,996	
Total for Campus		61	items		\$5,211,545	



Eden Park School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	8,500	LF	\$556,198	3
Pedestrian Pavement	Sidewalks - Concrete	10,000	SF	\$206,886	5
Parking Lot Pavement	Asphalt	54	CAR	\$180,837	5
		Sub Total for System	3 items	\$943,921	
		Sub Total for Building -	3 items	\$943,921	

Building: 01 - Main Building

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	32	Door	\$207,852	5
		Sub Total for System	1 items	\$207,852	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Coiling Doors	Overhead	1	Door	\$37,240	5
		Note: Kitchen/cafe			
Suspended Plaster and Wall Paneling	Painted ceilings	35,360	SF	\$149,715	5
Wall Paneling	Wood Panel wall	15,716	SF	\$145,183	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	5,893	SF	\$39,411	5
Tile Flooring	Quarry Tile	300	SF	\$13,828	5
		Note: Slate floor at entrance			
Resilient Flooring	Vinyl Composition Tile Flooring	16,764	SF	\$194,655	5
Interior Swinging Doors	Steel	14	Door	\$60,678	5
		Sub Total for System	7 items	\$640,711	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Roof Exhaust Fan	1	Ea.	\$5,268	3
Decentralized Cooling	Window Units	5	Ea.	\$16,898	4
Exhaust Air	Roof Exhaust Fan - Small	2	Ea.	\$5,339	5
		Sub Total for System	3 items	\$27,504	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	39,289	SF	\$236,294	4
		Sub Total for System	1 items	\$236,294	

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	14	Room	\$158,538	5
		Sub Total for System	1 items	\$158,538	
		Sub Total for Building 01 - Main Building	13 items	\$1,270,898	

Building: 02 - Portable-01

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	EPDM - Rubber Roofing Material	1,200	SF	\$15,358	3
		Sub Total for System	1 items	\$15,358	

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Wood Siding - Bldg SF basis	1,200	SF	\$36,409	5
		Sub Total for System	1 items	\$36,409	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	1,200	SF	\$10,970	5



Facility Condition Assessment

Cranston - Eden Park School

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Vinyl Composition Tile Flooring	1,200	SF	\$13,934	5
Sub Total for System		2	items	\$24,904	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Heating Unit Vent - Electric	2	Ea.	\$28,657	2
Exhaust Air	Ventilator/Relief Vent (4'x6')	7	Ea.	\$134,719	5
Sub Total for System		2	items	\$163,376	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)	3	Ea.	\$4,532	4
Lighting Fixtures	Light Fixtures (Bldg SF)	1,200	SF	\$7,217	5
Sub Total for System		2	items	\$11,749	

Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	1,200	SF	\$3,560	3
Sub Total for System		1	items	\$3,560	
Sub Total for Building 02 - Portable-01		9	items	\$255,356	
Total for: Eden Park School		25	items	\$2,470,175	



Supporting Photos



Site Aerial



Southeast Elevation



Library



Southwest Elevation



Facility Condition Assessment

Cranston - Eden Park School



South Elevation



Entry



Art Room



Typical Drinking Fountain



Aged Panelboard



Weathered Roof



Restroom Finishes



North Elevation



Cafe/Gym



Library



Portable Building



Typical Classroom



Plaque



Typical Windows



Stained Concrete Exterior



Dirty Stone Veneer Wall



Typical Urinals




Damaged Corridor VCT




Worn Gymnasium Floor




Air Handler



Typical Door With Non-Compliant Hardware



Peeling Rubber Flooring



Adhered Ceiling



Aged Boiler



Restroom Lavatories



Exhaust Hood



Inoperable Exhaust Fan



Typical Toilet



Evidence Of Ponding On Roof



Typical Radiant Heater



Switchgear



Typical Mop Sink



Unit Ventilator



Facility Condition Assessment

Cranston - Edgewood Highland School

June 2017

160 Pawtuxet Avenue, Cranston, RI 02905





Introduction

Edgewood Highland School, located at 160 Pawtuxet Avenue in Cranston, Rhode Island, was built in 1970. It comprises 44,239 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Edgewood Highland School serves grades 1 - 6, has 21 instructional spaces, and has an enrollment of 244. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Edgewood Highland School is 324 with a resulting utilization of 75%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Edgewood Highland School the 5-year need is \$9,031,906. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Edgewood Highland School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Edgewood Highland School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	CMU Exterior Wall
	E.I.F.S. Exterior Wall
	Painted Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
----------------------------	--------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Steel Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Non-Painted Plaster/Gypsum Board Ceiling
	Acoustical Wall Paneling
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring



Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,264 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	7 kW Electric Unit Heater
	20 MBH Steam Unit Heater
	Pneumatic Heating System Controls
	130 Ton Metal Cooling Tower
	210 Ton Outdoor Air Cooled Chiller
	1 Ton Fan Coil - Water Cool/Water Heat
	Window Units
	1 HP or Smaller Pump
	5 HP Pump
	4-Pipe Hydronic Distribution System
	Ductwork
	Kitchen Exhaust Hoods
	Roof Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Showers
	Toilets
	Urinals
	Air Compressor (1 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	50 kW Emergency Generator
	Automatic Transfer Switch
	1,200 Amp Switchgear
	225 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A



Facility Condition Assessment

Cranston - Edgewood Highland School

01 - Main Building:	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$192,456	\$333,294	\$72,198	\$597,948	8.18 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$508,163	-	\$625,328	-	\$1,133,491	15.51 %
Interior	-	-	\$398,527	\$1,048,221	\$266,976	\$1,713,725	23.46 %
Mechanical	-	\$2,219,487	\$107,038	\$345,208	-	\$2,671,732	36.57 %
Electrical	-	\$50,019	-	-	\$39,914	\$89,933	1.23 %
Plumbing	-	-	\$112,266	-	\$14,922	\$127,188	1.74 %
Fire and Life Safety	\$33,664	-	-	-	-	\$33,664	0.46 %
Technology	-	-	\$919,974	-	-	\$919,974	12.59 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$18,351	-	-	\$18,351	0.25 %
Total	\$33,664	\$2,777,669	\$1,748,612	\$2,352,051	\$394,010	\$7,306,005	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$2,671,732
Interior	-	\$1,713,725
Exterior	-	\$1,133,491

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$107,038	\$111,301	-	\$218,339
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	\$33,664	\$2,777,669	\$510,793	\$1,555,321	\$260,095	\$5,137,541
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$35,556	\$577,614	\$133,915	\$747,085
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$107,815	-	\$107,815
Technology	-	-	\$902,769	-	-	\$902,769
Traffic	-	-	\$192,456	-	-	\$192,456
Total	\$33,664	\$2,777,669	\$1,748,612	\$2,352,051	\$394,010	\$7,306,005

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$597,948	\$0	\$0	\$0	\$265,956	\$310,866	\$576,822	\$1,174,770
Roofing	\$0	\$0	\$0	\$283,086	\$0	\$0	\$283,086	\$283,086
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$1,133,491	\$0	\$0	\$0	\$0	\$0	\$0	\$1,133,491
Interior	\$1,713,725	\$0	\$0	\$0	\$385,258	\$0	\$385,258	\$2,098,983
Mechanical	\$2,671,732	\$0	\$0	\$0	\$32,341	\$52,675	\$85,016	\$2,756,748
Electrical	\$89,933	\$0	\$0	\$71,755	\$30,317	\$287,523	\$389,595	\$479,528
Plumbing	\$127,188	\$0	\$0	\$0	\$6,124	\$0	\$6,124	\$133,312
Fire and Life Safety	\$33,664	\$0	\$0	\$0	\$0	\$0	\$0	\$33,664
Technology	\$919,974	\$0	\$0	\$0	\$0	\$0	\$0	\$919,974
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$18,351	\$0	\$0	\$0	\$0	\$0	\$0	\$18,351
Total	\$7,306,005	\$0	\$0	\$354,841	\$719,996	\$651,064	\$1,725,901	\$9,031,906

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$15,483,650. For planning purposes, the total 5-year need at the Edgewood Highland School is \$9,031,906 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Edgewood Highland School facility has a 5-year FCI of 58.33%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 246 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Edgewood Highland School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Edgewood Highland School comprises 44,239 square feet and was constructed in 1970. Current deficiencies at this school total \$7,306,005. Five year capital renewal costs total \$1,725,901. The total identified need for the Edgewood Highland School (current deficiencies and 5-year capital renewal costs) is \$9,031,906. The 5-year FCI is 58.33%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Edgewood Highland School Totals	44,239	1970	\$7,306,005	\$1,725,901	\$9,031,906	58.33%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add warning signs for school zone	Traffic	4	Ea.	3	\$192,456	9352
Asphalt Paving Requires Replacement	Capital Renewal	46	CAR	4	\$192,558	9153
Asphalt Paving Requires Replacement	Capital Renewal	25	CAR	4	\$104,651	9229
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28450
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28720
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54884
Sub Total for System		6	items		\$597,948	
Sub Total for School and Site Level		6	items		\$597,948	

Building: 01 - Main Building

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Note: Windows are aged with cracked and broken seals.	Capital Renewal	816	SF	2	\$145,593	9157
The EIFS Exterior Requires Replacement (Bldg SF) Note: EIFS exterior is cracked and peeling.	Capital Renewal	11,060	SF	2	\$240,572	9172
The Storefront/Curtain Wall Requires Replacement Note: Fixed window seals are broken.	Capital Renewal	608	SF Wall	2	\$121,999	9162
The Concrete/CMU Exterior Requires Repair	Capital Renewal	50	LF	4	\$4,511	9156
The Exterior Requires Painting (Bldg SF)	Capital Renewal	44,239	SF	4	\$620,817	9173
Sub Total for System		5	items		\$1,133,491	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceiling Tiles Require Replacement	Capital Renewal	22,120	SF	3	\$210,639	9158
The Ceramic Tile Flooring Requires Replacement	Capital Renewal	6,636	SF	3	\$187,888	9159
Ceiling Grid Requires Replacement	Capital Renewal	22,120	SF	4	\$276,615	9175
Moveable Partitions Require Replacement	Capital Renewal	90	SF Wall	4	\$10,961	9154
Paint (probable pre-1978 in base (layers(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	194	Ea.	4	\$58,338	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	140	LF	4	\$3,368	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	4,600	SF	4	\$46,109	Rollup
Room Is Excessively Reverberant Note: Gym	Acoustics	4,725	SF	4	\$111,301	19691
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	14,136	SF	4	\$541,528	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	3	Ea.	5	\$6,882	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	37,335	SF	5	\$260,095	Rollup
Sub Total for System		11	items		\$1,713,725	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Requires Replacement (SF Basis)	Capital Renewal	44,239	SF	2	\$685,717	9169
Electric Unit Heater Requires Replacement	Capital Renewal	2	Ea.	2	\$4,008	9166
Steam/HW Unit Heater Requires Replacement	Capital Renewal	16	Ea.	2	\$47,505	9177
The Cast Iron Water Boiler Requires Replacement	Capital Renewal	2	Ea.	2	\$381,696	9168



Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Chiller Requires Replacement	Capital Renewal	1	Ea.	2	\$631,496	9165
The Exterior Metal Cooling Tower Requires Replacement	Capital Renewal	1	Ea.	2	\$195,463	9160
The Fan Coil (Chilled Water) HVAC Component Requires Replacement	Capital Renewal	26	Ea.	2	\$121,813	9167
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	44,239	SF	2	\$151,789	9163
Unit Ventilators Are Excessively Noisy	Acoustics	16	Ea.	3	\$107,038	19690
Note: All classrooms						
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	44,239	SF	4	\$315,065	9171
Small HVAC Circulating Pump Requires Replacement	Capital Renewal	3	Ea.	4	\$30,143	9164
Sub Total for System					11 items	\$2,671,732

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement	Capital Renewal	5	Ea.	2	\$25,561	11425
Note: Parts may not be available for all electrical panels throughout the building.						
The Panelboard Requires Replacement	Capital Renewal	4	Ea.	2	\$24,458	11426
Note: Parts may not be available for all electrical panels throughout the building.						
Room Has Insufficient Electrical Outlets	Educational Adequacy	80	Ea.	5	\$39,914	Rollup
Sub Total for System					3 items	\$89,933

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Showers Plumbing Fixtures Require Replacement	Capital Renewal	14	Ea.	3	\$112,266	9161
Room lacks a drinking fountain.	Educational Adequacy	7	Ea.	5	\$7,761	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	6	Ea.	5	\$7,161	Rollup
Sub Total for System					3 items	\$127,188

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Kitchen Exhaust Hood	Capital Renewal	2	Ea.	1	\$33,664	11424
Sub Total for System					1 items	\$33,664

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	3	Ea.	3	\$17,204	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	144	Ea.	3	\$72,171	23631
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	16	Ea.	3	\$336,798	23635
Technology: Instructional spaces do not have local sound reinforcement.	Technology	16	Ea.	3	\$80,190	23637
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23629
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$47,713	23628
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23626
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23625
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	144	Ea.	3	\$64,954	23630
Technology: Network system inadequate and/or near end of useful life	Technology	4	Ea.	3	\$32,076	23638
Technology: Network system inadequate and/or near end of useful life	Technology	14	Ea.	3	\$70,166	23639
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	44,239	SF	3	\$79,819	23634



Facility Condition Assessment

Cranston - Edgewood Highland School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23636
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,019	23627
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	16	Ea.	3	\$25,661	23633
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23632
Sub Total for System		16	items		\$919,974	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$18,351	Rollup
Sub Total for System		1	items		\$18,351	
Sub Total for Building 01 - Main Building		51	items		\$6,708,058	
Total for Campus		57	items		\$7,306,005	



Edgewood Highland School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Playfield Areas	ES Playgrounds	1	Ea.	\$45,131	4
Fences and Gates	Fencing - Chain Link (4 Ft)	1,428	LF	\$93,441	4
Fences and Gates	Fencing - Chain Link (8 Ft)	1,872	LF	\$127,384	4
Pedestrian Pavement	Sidewalks - Concrete	8,824	SF	\$182,556	5
Fences and Gates	Fencing - Ornamental	118	LF	\$128,310	5
Sub Total for System		5	items	\$576,823	
Sub Total for Building -		5	items	\$576,823	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	EPDM - Rubber Roofing Material	22,119	SF	\$283,086	3
Sub Total for System		1	items	\$283,086	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Vinyl Composition Tile Flooring	33,179	SF	\$385,258	4
Sub Total for System		1	items	\$385,258	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Window Units	5	Ea.	\$16,898	4
Facility Hydronic Distribution	Pump - 1HP or Less (Ea.)	2	Ea.	\$15,443	4
Exhaust Air	Roof Exhaust Fan	10	Ea.	\$52,675	5
Sub Total for System		3	items	\$85,016	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Electrical Service	Switchgear - Main Dist Panel (1200 Amps)	1	Ea.	\$69,900	3
Wiring Devices	Electrical Disconnect	1	Ea.	\$1,855	3
Transfer Switches	Automatic Transfer Switch (Amps)	800	Amps	\$28,922	4
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)	1	Ea.	\$1,395	4
Electrical Service	Transformer (225 KVA)	1	Ea.	\$21,459	5
Lighting Fixtures	Light Fixtures (Bldg SF)	44,239	SF	\$266,064	5
Sub Total for System		6	items	\$389,596	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Compressed-Air Systems	Air Compressor (1 hp)	1	Ea.	\$6,124	4
Sub Total for System		1	items	\$6,124	
Sub Total for Building 01 - Main Building		12	items	\$1,149,080	
Total for: Edgewood Highland School		17	items	\$1,725,903	



Supporting Photos



Site Aerial



Aged Panelboard



Aged And Corroded Boiler



Electric Unit Heater



Facility Condition Assessment

Cranston - Edgewood Highland School



Peeling Exterior Paint




Cracked EIFS



Hot Water Unit Heater



Chipped Interior Paint



Hallway Finishes



Typical Classroom



Facility Condition Assessment

Cranston - Edgewood Highland School



Library



Restroom Finishes



Computer Lab



Cafeteria/Gymnasium/Auditorium



North Elevation



Cracked Parking Lot Pavement



Facility Condition Assessment

Cranston - Edgewood Highland School



West Elevation



South Elevation



HVAC Circulating Pump



East Elevation



Main Entrance




Damaged Exterior CMU



Facility Condition Assessment


Cranston - Edgewood Highland School



Typical Aged Window




Stained Acoustical Ceiling Tiles




Damaged Ceramic Floor Tile



Cooling Tower



Typical Shower



Broken Window Seals



Facility Condition Assessment

Cranston - Edward S. Rhodes School

June 2017

160 Shaw Avenue, Cranston, RI 02905





Introduction

Edward S. Rhodes School, located at 160 Shaw Avenue in Cranston, Rhode Island, was built in 1930. It comprises 35,051 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Edward S. Rhodes School serves grades KG - 6, has 21 instructional spaces, and has an enrollment of 248. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Edward S. Rhodes School is 307 with a resulting utilization of 81%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Edward S. Rhodes School the 5-year need is \$7,003,147. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Edward S. Rhodes School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Edward S. Rhodes School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Roofing
---------------------	--------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	1,275 MBH Cast Iron Steam Boiler
	Steam/Hot Water Heating Unit Vent
	Radiant Steam Heater
	36 MBH Steam Unit Heater
	Electronic Heating System Controls
	Window Units



01 - Main Building:	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump
	4'x6' Ventilator/Relief Vent
	Wall Exhaust Fan
	Roof Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	5,000 Gallon Underground Fuel Oil Storage Tank

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	Panelboard - 120/240 100A
	Panelboard - 120/240 225A
	Building Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$8,017	\$286,182	\$72,444	\$366,643	5.95 %
Roofing	-	\$164,433	-	-	-	\$164,433	2.67 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$1,084,509	-	-	-	\$1,084,509	17.59 %
Interior	-	-	\$290,849	\$1,540,539	\$6,928	\$1,838,317	29.81 %
Mechanical	-	\$886,523	-	\$31,410	-	\$917,933	14.89 %
Electrical	-	\$69,533	-	-	\$40,185	\$109,718	1.78 %
Plumbing	-	-	\$437,276	\$13,740	\$93,100	\$544,116	8.82 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$930,853	-	-	\$930,853	15.09 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$13,857	\$196,285	-	\$210,141	3.41 %
Total	\$0	\$2,204,997	\$1,680,852	\$2,068,156	\$212,657	\$6,166,663	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,838,317
Exterior	-	\$1,084,509
Technology	-	\$930,853

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$69,116	-	\$69,116
Barrier to Accessibility	-	-	\$290,849	-	-	\$290,849
Capital Renewal	-	\$2,204,997	\$445,293	\$490,329	\$83,398	\$3,224,017
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$19,631	\$562,973	\$129,260	\$711,863
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$945,739	-	\$945,739
Technology	-	-	\$925,079	-	-	\$925,079
Traffic	-	-	-	-	-	\$0
Total	\$0	\$2,204,997	\$1,680,852	\$2,068,156	\$212,657	\$6,166,663

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$366,643	\$0	\$0	\$0	\$0	\$135,144	\$135,144	\$501,787
Roofing	\$164,433	\$0	\$0	\$0	\$0	\$0	\$0	\$164,433
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$1,084,509	\$0	\$0	\$0	\$0	\$0	\$0	\$1,084,509
Interior	\$1,838,317	\$0	\$0	\$0	\$0	\$504,061	\$504,061	\$2,342,378
Mechanical	\$917,933	\$0	\$0	\$0	\$1,667	\$173,210	\$174,877	\$1,092,810
Electrical	\$109,718	\$0	\$0	\$0	\$0	\$0	\$0	\$109,718
Plumbing	\$544,116	\$0	\$0	\$0	\$22,402	\$0	\$22,402	\$566,518
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$930,853	\$0	\$0	\$0	\$0	\$0	\$0	\$930,853
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$210,141	\$0	\$0	\$0	\$0	\$0	\$0	\$210,141
Total	\$6,166,663	\$0	\$0	\$0	\$24,069	\$812,415	\$836,484	\$7,003,147

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$12,267,850. For planning purposes, the total 5-year need at the Edward S. Rhodes School is \$7,003,147 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Edward S. Rhodes School facility has a 5-year FCI of 57.09%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 195 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Edward S. Rhodes School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$275,940.



Summary of Findings

The Edward S. Rhodes School comprises 35,051 square feet and was constructed in 1930. Current deficiencies at this school total \$6,166,663. Five year capital renewal costs total \$836,484. The total identified need for the Edward S. Rhodes School (current deficiencies and 5-year capital renewal costs) is \$7,003,147. The 5-year FCI is 57.09%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Edward S. Rhodes School Totals	35,051	1930	\$6,166,663	\$836,484	\$7,003,147	57.09%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement Note: Sidewalk is cracked and broken at the front entry.	Capital Renewal	300	SF	3	\$8,017	11183
Asphalt Paving Requires Replacement Note: Asphalt play yard has large cracks.	Capital Renewal	55	CAR	4	\$237,907	11184
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$37,288	28436
Fencing Requires Replacement (4' Chain Link Fence) Note: A portion of the exterior fence is rusting and in disrepair.	Capital Renewal	130	LF	4	\$10,988	11182
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,644	28709
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54875
Sub Total for System		6	items		\$366,643	
Sub Total for School and Site Level		6	items		\$366,643	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Single-Ply Membrane Roof Covering Requires Replacement Note: Roof insulation is failing and moves underfoot. The membrane is buckling and the warranty expired in 2007.	Capital Renewal	11,684	SF	2	\$164,433	11202
Sub Total for System		1	items		\$164,433	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Storefront/Curtain Wall Requires Replacement (Bldg SF) Note: Windows are single pane with air and water infiltration issues.	Capital Renewal	12,268	SF	2	\$1,084,509	11198
Sub Total for System		1	items		\$1,084,509	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Existing Door Hardware Is Not ADA Compliant	Barrier to Accessibility	93	Door	3	\$290,849	11188
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	25,237	SF	4	\$789,264	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	22	Ea.	4	\$6,880	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	360	LF	4	\$9,007	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	13,486	SF	4	\$140,588	Rollup
Partitions Provide Insufficient Sound Isolation Note: Classrooms adjacent to auditorium/cafeteria	Acoustics	800	SF	4	\$25,019	19763
Room Is Excessively Reverberant Note: Gym	Acoustics	1,800	SF	4	\$44,096	19764
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	13,630	SF	4	\$525,684	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	3	Ea.	5	\$6,928	Rollup
Sub Total for System		9	items		\$1,838,317	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent Note: Heating units are antiquated and obsolete.	Capital Renewal	10	Ea.	2	\$185,476	11201
The Boiler HVAC Component Requires Replacement Note: Steam boilers very antiquated and obsolete with poor control.	Capital Renewal	2	Ea.	2	\$163,061	11192



Facility Condition Assessment

Cranston - Edward S. Rhodes School

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	35,501	SF	2	\$300,064	11195
The Steam/Hot Water Radiant Heater Requires Replacement	Capital Renewal	42	Ea.	2	\$237,921	11194
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	5	Ea.	4	\$14,681	11186
Note: Fans are aged and should be replaced.						
Small HVAC Circulating Pump Requires Replacement	Capital Renewal	2	Ea.	4	\$16,730	11203
Note: Fuel oil pumps are aged and obsolete.						
Sub Total for System		6	items		\$917,933	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$63,174	11193
Note: Power distribution in the building is old and obsolete. Service should be updated.						
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$6,359	11551
Note: Power distribution in the building is old and obsolete. Service should be updated.						
Room Has Insufficient Electrical Outlets	Educational Adequacy	80	Ea.	5	\$40,185	Rollup
Sub Total for System		3	items		\$109,718	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	35,051	SF	3	\$309,240	11191
Note: Domestic water piping is aged and should be replaced. Water is brown after periods of low usage and there is evidence of scaling.						
The Sanitary Sewer Piping Requires Replacement	Capital Renewal	750	LF	3	\$128,036	11197
Note: Sanitary piping is original to the building and should be replaced.						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	2	Ea.	4	\$5,650	11189
Note: Original mop sinks should be replaced.						
The Refrigerated Water Cooler Requires Replacement	Capital Renewal	1	Ea.	4	\$8,090	11190
Note: Inoperable drinking fountain on first floor.						
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Underground Fuel/Oil Storage Tank Requires Replacement	Capital Renewal	1	Ea.	5	\$83,398	11196
Note: Tank is very old and should be replaced.						
Sub Total for System		7	items		\$544,116	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	3	\$5,774	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	72	Ea.	3	\$37,529	23615
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	16	Ea.	3	\$350,270	23620
Technology: Instructional spaces do not have local sound reinforcement.	Technology	16	Ea.	3	\$83,398	23622
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,297	23611
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$46,703	23610
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,903	23613
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	144	Ea.	3	\$67,552	23614
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$50,039	23623
Technology: Network system inadequate and/or near end of useful life	Technology	16	Ea.	3	\$83,398	23624



Facility Condition Assessment

Cranston - Edward S. Rhodes School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	35,051	SF	3	\$65,771	23619
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$59,421	23616
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,849	23621
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,340	23612
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	16	Ea.	3	\$26,687	23618
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,923	23617
Sub Total for System		16	items		\$930,853	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	3	Ea.	3	\$13,857	Rollup
Replace Cabinetry In Classes/Labs Note: Cabinetry is aged and functions poorly.	Capital Renewal	16	Room	4	\$196,285	11199
Sub Total for System		2	items		\$210,141	
Sub Total for Building 01 - Main Building		45	items		\$5,800,020	
Total for Campus		51	items		\$6,166,663	



Edward S. Rhodes School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Roadway Pavement	Asphalt	4	CAR	\$13,395	5
Pedestrian Pavement	Sidewalks - Concrete	2,000	SF	\$41,377	5
Parking Lot Pavement	Asphalt	24	CAR	\$80,372	5
		3	items	\$135,145	
		3	items	\$135,145	

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings	8,763	SF	\$37,103	5
Wood Flooring	Wood Flooring - All Types	3,505	SF	\$117,710	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	26,288	SF	\$240,316	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	16,288	SF	\$108,932	5
		4	items	\$504,061	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Unit Heater Steam/HW (36 MBH)	1	Ea.	\$1,667	4
Exhaust Air	Ventilator/Relief Vent (4'x6')	9	Ea.	\$173,210	5
		2	items	\$174,877	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	3	Ea.	\$22,402	4
		1	items	\$22,402	
		7	items	\$701,340	
		10	items	\$836,484	



Supporting Photos



Weathered Roof With Ponding



Aged Boiler



Aged Heating Unit



Aged Pumps



Facility Condition Assessment

Cranston - Edward S. Rhodes School



Aged Wall Exhaust



Cracked And Spalled Sidewalk



Cracked Play Area



Gym



Site Aerial



Cafeteria



Facility Condition Assessment

Cranston - Edward S. Rhodes School



Typical Classroom



Typical Toilet Fixture




Exterior Finishes



Typical Windows



Library



Non-Compliant Door Hardware



Facility Condition Assessment

Cranston - Edward S. Rhodes School



VCT Lifting At Seams



Aged Window System



Radiators



Peeling Paint



Aged Cabinetry




Single Ply Roofing



Facility Condition Assessment

Cranston - Edward S. Rhodes School



Weathered Roof Membrane



Facility Condition Assessment

Cranston - Garden City School

June 2017

70 Plantations Drive, Cranston, RI 02920





Introduction

Garden City School, located at 70 Plantations Drive in Cranston, Rhode Island, was built in 1953. It comprises 33,186 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Garden City School serves grades PK - 6, has 18 instructional spaces, and has an enrollment of 350. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Garden City School is 310 with a resulting utilization of 113%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Garden City School the 5-year need is \$6,382,209. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Garden City School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Garden City School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Storefront Entrance Doors
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
	Canopy Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Ceramic Tile Wall
	Vinyl/Fabric Wall Covering
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
----------------------------	----------------------------------



01 - Main Building:	Steam Condensate Receiver, Tank and Pump
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	Window Units
	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump
	Roof Exhaust Fan
	Supply Fan

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	100 Gallon Gas Water Heater
	Domestic Water Piping System
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Toilets
	Urinals

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	-	\$36,086	\$72,198	\$108,283	2.48 %
Roofing	-	-	\$30,071	-	-	\$30,071	0.69 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$47,817	-	-	-	\$47,817	1.09 %
Interior	-	-	\$43,002	\$1,123,276	\$2,294	\$1,168,572	26.73 %
Mechanical	-	\$910,684	\$121,686	-	-	\$1,032,370	23.61 %
Electrical	-	\$82,924	-	-	\$36,153	\$119,077	2.72 %
Plumbing	-	-	\$415,847	\$237,152	\$5,238	\$658,237	15.05 %
Fire and Life Safety	\$52,841	-	-	-	-	\$52,841	1.21 %
Technology	-	-	\$862,935	-	-	\$862,935	19.74 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,238	\$283,103	-	\$292,341	6.69 %
Total	\$52,841	\$1,041,426	\$1,482,780	\$1,679,616	\$115,882	\$4,372,544	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,168,572
Mechanical	-	\$1,032,370
Technology	-	\$862,935

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$107,038	\$69,164	-	\$176,201
Barrier to Accessibility	-	-	\$43,002	-	-	\$43,002
Capital Renewal	\$52,841	\$1,041,426	\$460,567	\$766,883	-	\$2,321,717
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$66,975	\$36,086	\$115,882	\$218,942
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$807,483	-	\$807,483
Technology	-	-	\$805,198	-	-	\$805,198
Traffic	-	-	-	-	-	\$0
Total	\$52,841	\$1,041,426	\$1,482,780	\$1,679,616	\$115,882	\$4,372,544

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$108,283	\$0	\$0	\$0	\$155,642	\$103,443	\$259,085	\$367,368
Roofing	\$30,071	\$0	\$0	\$0	\$0	\$436,272	\$436,272	\$466,343
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$47,817	\$0	\$0	\$0	\$0	\$0	\$0	\$47,817
Interior	\$1,168,572	\$0	\$99,876	\$0	\$42,802	\$106,180	\$248,858	\$1,417,430
Mechanical	\$1,032,370	\$0	\$0	\$0	\$739,123	\$47,408	\$786,531	\$1,818,901
Electrical	\$119,077	\$0	\$0	\$0	\$12,904	\$199,589	\$212,493	\$331,570
Plumbing	\$658,237	\$0	\$0	\$0	\$22,402	\$44,024	\$66,426	\$724,663
Fire and Life Safety	\$52,841	\$0	\$0	\$0	\$0	\$0	\$0	\$52,841
Technology	\$862,935	\$0	\$0	\$0	\$0	\$0	\$0	\$862,935
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$292,341	\$0	\$0	\$0	\$0	\$0	\$0	\$292,341
Total	\$4,372,544	\$0	\$99,876	\$0	\$972,873	\$936,916	\$2,009,665	\$6,382,209

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$12,455,100. For planning purposes, the total 5-year need at the Garden City School is \$6,382,209 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Garden City School facility has a 5-year FCI of 51.24%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 198 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Garden City School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$313,740.



Summary of Findings

The Garden City School comprises 33,186 square feet and was constructed in 1953. Current deficiencies at this school total \$4,372,544. Five year capital renewal costs total \$2,009,665. The total identified need for the Garden City School (current deficiencies and 5-year capital renewal costs) is \$6,382,209. The 5-year FCI is 51.24%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Garden City School Totals	33,186	1953	\$4,372,544	\$2,009,665	\$6,382,209	51.24%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28441
Note: Backstops Require Replacement						
Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28713
Note: Exterior Basketball Goals are Required						
PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54880
Note: PE / Recess Playfield is Missing and is Needed						
Sub Total for System		3	items		\$108,283	
Sub Total for School and Site Level		3	items		\$108,283	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Awning Or Canopy Metal Roofing System Requires Replacement	Capital Renewal	500	SF	3	\$30,071	9011
Note: Canopy deteriorating						
Sub Total for System		1	items		\$30,071	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement	Capital Renewal	268	SF	2	\$47,817	9004
Sub Total for System		1	items		\$47,817	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Interior Door Hardware Requires Replacement	Barrier to Accessibility	13	Door	3	\$43,002	9013
Note: Door knobs to be replaced with ADA levers.						
9x9 Asbestos Tile Present and In Active Use, Greater than 25 Percent has Significant Deterioration	Hazardous Material	26,549	SF	4	\$798,362	Rollup
Adhered Acoustical Ceiling Tile Requires Replacement	Capital Renewal	21,571	SF	4	\$246,629	9023
Note: Tiles are cracking and falling down						
Paint (probable pre-1978 in base (layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	18	Ea.	4	\$5,413	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	100	LF	4	\$2,406	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	130	SF	4	\$1,303	Rollup
Partitions Provide Insufficient Sound Isolation	Acoustics	1,500	SF	4	\$45,107	19695
Note: All classrooms & offices						
Room Is Excessively Reverberant (Install Fiberglass Wall Panel)	Acoustics	400	SF	4	\$24,057	19697
Note: Gym						
Sub Total for System		8	items		\$1,166,278	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent	Capital Renewal	5	Ea.	2	\$89,171	9021
Note: Unit heaters visually deteriorating and require constant attention per building operator						
The Boiler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	2	\$359,203	9016
Note: Boilers obsolete						
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	33,186	SF	2	\$269,709	9017
Note: Based on condition of mechanical equipment, piping is passed is expected life. Reco,mend replacement						
The Radiant Heat HVAC Component Requires Replacement	Capital Renewal	24	Ea.	2	\$192,600	9022
The Large Diameter Exhausts/Hoods Require Replacement	Capital Renewal	1	Ea.	3	\$14,649	9006
Note: Boiler fan obsolete.						
Unit Ventilators Are Excessively Noisy	Acoustics	16	Ea.	3	\$107,038	19696



Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Note: All classrooms						
Sub Total for System		6	items		\$1,032,370	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Distribution Panel Requires Replacement	Capital Renewal	1	Ea.	2	\$27,064	9268
The Electrical Disconnect Requires Replacement	Capital Renewal	1	Ea.	2	\$1,933	9273
The Panelboard Requires Replacement	Capital Renewal	4	Ea.	2	\$32,477	9018
The Panelboard Requires Replacement	Capital Renewal	3	Ea.	2	\$15,336	9271
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$6,114	9272
Room Has Insufficient Electrical Outlets	Educational Adequacy	68	Ea.	5	\$34,157	Rollup
Sub Total for System		6	items		\$117,082	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	33,186	SF	3	\$281,525	9015
Note: Piping has surpassed expected life cycle. Based on condition of other mech equipment piping is ready to be replaced						
The Sanitary Sewer Piping Requires Replacement	Capital Renewal	750	LF	3	\$123,112	9019
Note: Piping is outdated and should be replaced. Sewage backups have occurred in the past						
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	8	Ea.	3	\$11,211	9014
Note: Urinals outdated and obsolete						
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	21	Ea.	4	\$226,286	9008
Note: Outdated and obsolete.						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	4	Ea.	4	\$10,866	9010
Note: Mop sinks original to building, visually deteriorating						
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$1,116	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		7	items		\$658,237	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Emergency Lighting Is Inadequate Or Not Present And Should be Installed	Capital Renewal	33,186	SF	1	\$52,841	9012
Note: Throughout building						
Sub Total for System		1	items		\$52,841	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	10	Ea.	3	\$57,737	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	72	Ea.	3	\$36,086	23466
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	15	Ea.	3	\$150,356	23471
Technology: Instructional spaces do not have local sound reinforcement.	Technology	15	Ea.	3	\$75,178	23476
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23463
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23462
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23464
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23461
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23459



Facility Condition Assessment

Cranston - Garden City School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23460
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	160	Ea.	3	\$72,171	23469
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	30	Ea.	3	\$13,532	23467
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23474
Technology: Network system inadequate and/or near end of useful life	Technology	18	Ea.	3	\$90,214	23475
Technology: Network system inadequate and/or near end of useful life	Technology	33,186	SF	3	\$9,979	24943
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	48	Ea.	3	\$24,057	23468
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	33,186	SF	3	\$59,877	23473
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23470
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23472
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23465
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	15	Ea.	3	\$24,057	23477
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23478
Sub Total for System		22	items		\$862,935	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	24	Room	4	\$283,103	9020
Sub Total for System		2	items		\$292,341	
Sub Total for Building 01 - Main Building		54	items		\$4,259,971	

Building: 02 - Portable

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,294	Rollup
Sub Total for System		1	items		\$2,294	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	4	Ea.	5	\$1,996	Rollup
Sub Total for System		1	items		\$1,996	
Sub Total for Building 02 - Portable		2	items		\$4,290	
Total for Campus		59	items		\$4,372,544	



Garden City School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Roadway Pavement	Asphalt	33	CAR	\$110,511	4
Playfield Areas	ES Playgrounds	1	Ea.	\$45,131	4
Pedestrian Pavement	Sidewalks - Concrete	5,000	SF	\$103,443	5
		Sub Total for System	3 items	\$259,085	
		Sub Total for Building -	3 items	\$259,085	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Canopy Roofing	Canopies	200	SF	\$11,547	5
Low-Slope Roofing	EPDM - Rubber Roofing Material	33,186	SF	\$424,725	5
		Sub Total for System	2 items	\$436,273	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	14,934	SF	\$99,876	2
Wall Coverings	Vinyl/Fabric Wall Covering	1,659	SF	\$11,973	4
Resilient Flooring	Vinyl Composition Tile Flooring	2,655	SF	\$30,829	4
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	11,615	SF	\$106,180	5
		Sub Total for System	4 items	\$248,858	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heat Generation	Steam Condensate Receiver, Tank and Pump	2	Ea.	\$712,087	4
Decentralized Cooling	Window Units	8	Ea.	\$27,036	4
Exhaust Air	Roof Exhaust Fan	9	Ea.	\$47,408	5
		Sub Total for System	3 items	\$786,531	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)	3	Ea.	\$4,532	4
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)	6	Ea.	\$8,372	4
Lighting Fixtures	Light Fixtures (Bldg SF)	33,186	SF	\$199,589	5
		Sub Total for System	3 items	\$212,493	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	3	Ea.	\$22,402	4
Domestic Water Equipment	Water Heater - Gas - 100 Gallon	1	Ea.	\$5,387	5
Plumbing Fixtures	Lavatories	12	Ea.	\$38,637	5
		Sub Total for System	3 items	\$66,426	
		Sub Total for Building 01 - Main Building	15 items	\$1,750,581	
		Total for: Garden City School	18 items	\$2,009,667	



Supporting Photos



North Elevation



South Elevation



Site Aerial



Courtyard Elevation



Facility Condition Assessment

Cranston - Garden City School



Main Entrance



West Elevation



North Elevation



Broken Window Seals



East Elevation



Boiler Exhaust Fan



Patched/Broken Tile



Custodial Sink



Drinking Fountain



Canopy



Custodial Sink



Boiler



Urinals



Electrical Panel



Electric Panel



Worn Casework



Electric Panel



Radiant Heater



Unit Heater



Ceiling Tiles - Falling Down



Radiant Heater




Entrance Lobby




Typical Classroom



Typical Restroom



Cafeteria/Gym



Entrance Lobby



Library



Library



Portable Interior



Elevation



Portable Exterior



Portable Side View



Elevation



Portable Front Elevation



Facility Condition Assessment

Cranston - George J. Peters School

June 2017

15 Mayberry Street, Cranston, RI 02920





Introduction

George J. Peters School, located at 15 Mayberry Street in Cranston, Rhode Island, was built in 1957. It comprises 38,800 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

George J. Peters School serves grades 1 - 6, has 18 instructional spaces, and has an enrollment of 347. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for George J. Peters School is 307 with a resulting utilization of 113%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For George J. Peters School the 5-year need is \$7,257,028. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of George J. Peters School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the George J. Peters School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Built-Up Roofing With Ballast
	Canopy Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	CMU Wall
	Interior Wall Painting
	Quarry Tile Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	Steam Condensate Receiver, Tank and Pump



01 - Main Building:	36 MBH Steam Unit Heater
	Radiant Steam Heater
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	DDC Heating System Controls
	Window Units
	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	10 HP Pump
	2,000 CFM Interior AHU
	Kitchen Exhaust Hoods
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (1/2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/240 100A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$5,774	\$36,086	\$7,398	\$49,257	0.76 %
Roofing	-	\$1,555,686	-	-	-	\$1,555,686	24.03 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$719,505	\$1,271,121	\$6,928	\$1,997,554	30.86 %
Mechanical	-	\$1,513,536	\$58,595	-	-	\$1,572,131	24.29 %
Electrical	-	\$71,798	-	-	\$46,672	\$118,470	1.83 %
Plumbing	-	-	-	\$2,716	\$9,702	\$12,419	0.19 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$969,738	-	-	\$969,738	14.98 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,238	\$188,735	-	\$197,973	3.06 %
Total	\$0	\$3,141,020	\$1,762,849	\$1,498,658	\$70,701	\$6,473,228	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,997,554
Mechanical	-	\$1,572,131
Roofing	-	\$1,555,686

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$169,602	-	\$169,602
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$3,141,020	\$778,100	\$191,452	\$10,506	\$4,121,077
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$9,238	\$70,797	\$60,195	\$140,229
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$1,066,808	-	\$1,066,808
Technology	-	-	\$969,738	-	-	\$969,738
Traffic	-	-	\$5,774	-	-	\$5,774
Total	\$0	\$3,141,020	\$1,762,849	\$1,498,658	\$70,701	\$6,473,228

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$49,257	\$0	\$0	\$0	\$361,674	\$0	\$361,674	\$410,931
Roofing	\$1,555,686	\$0	\$0	\$0	\$0	\$0	\$0	\$1,555,686
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Interior	\$1,997,554	\$0	\$0	\$0	\$0	\$115,341	\$115,341	\$2,112,895
Mechanical	\$1,572,131	\$0	\$0	\$0	\$0	\$306,785	\$306,785	\$1,878,916
Electrical	\$118,470	\$0	\$0	\$0	\$0	\$0	\$0	\$118,471
Plumbing	\$12,419	\$0	\$0	\$0	\$0	\$0	\$0	\$12,419
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$969,738	\$0	\$0	\$0	\$0	\$0	\$0	\$969,738
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$197,973	\$0	\$0	\$0	\$0	\$0	\$0	\$197,973
Total	\$6,473,228	\$0	\$0	\$0	\$361,674	\$422,126	\$783,800	\$7,257,028

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$13,580,000. For planning purposes, the total 5-year need at the George J. Peters School is \$7,257,028 (Life Cycle Years 1-5 plus the FCI deficiency cost). The George J. Peters School facility has a 5-year FCI of 53.44%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 216 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the George J. Peters School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$423,360.



Summary of Findings

The George J. Peters School comprises 38,800 square feet and was constructed in 1957. Current deficiencies at this school total \$6,473,228. Five year capital renewal costs total \$783,800. The total identified need for the George J. Peters School (current deficiencies and 5-year capital renewal costs) is \$7,257,028. The 5-year FCI is 53.44%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
George J. Peters School Totals	38,800	1957	\$6,473,228	\$783,800	\$7,257,028	53.44%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add school zone signage with speed limitations	Traffic	2	Ea.	3	\$5,774	16925
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28446
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28717
Sub Total for System		3	items		\$49,257	
Sub Total for School and Site Level		3	items		\$49,257	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Built-up Roofing With Aggregate Ballast Requires Replacement Note: The roof is original to the building. There are multiple locations of ponding and leaks at flashing.	Capital Renewal	38,800	SF	2	\$1,555,686	12288
Sub Total for System		1	items		\$1,555,686	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement Note: Interior wood doors are aged and chipped with non-compliant hardware. They should be replaced.	Capital Renewal	148	Door	3	\$719,505	12281
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	34,920	SF	4	\$1,050,088	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	30	Ea.	4	\$9,021	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	320	LF	4	\$7,698	Rollup
Room Is Excessively Reverberant Location: Cafeteria	Acoustics	7,200	SF	4	\$169,602	27943
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	900	SF	4	\$34,711	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	3	Ea.	5	\$6,928	Rollup
Sub Total for System		7	items		\$1,997,554	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent Note: Unit vents are original to the building and obsolete with damaged casings.	Capital Renewal	17	Ea.	2	\$303,182	12300
Steam/HW Unit Heater Requires Replacement Note: Unit heaters are obsolete and should be replaced.	Capital Renewal	2	Ea.	2	\$3,472	12294
The Boiler HVAC Component Requires Replacement Note: Boilers are aged and should be replaced.	Capital Renewal	2	Ea.	2	\$359,203	12291
The Fin Tube Water Radiant Heater Requires Replacement Note: Fin tube heaters are original to the building with deteriorating casings.	Capital Renewal	76	Ea.	2	\$134,230	12297
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	38,800	SF	2	\$315,335	13480
The Steam Condensate Receiver Requires Replacement Note: Condensate receiver, tank, and pump are original to the building and heavily corroded. They should be replaced.	Capital Renewal	1	Ea.	2	\$370,879	12295
The Steam/Hot Water Radiant Heater Requires Replacement Note: Radiant heaters are original to the building and should be replaced.	Capital Renewal	5	Ea.	2	\$27,235	12296
The Large Diameter Exhausts/Hoods Require Replacement Note: Original exhaust fans are rusted and non-functional.	Capital Renewal	4	Ea.	3	\$58,595	12284
Sub Total for System		8	items		\$1,572,131	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Distribution Panel Requires Replacement	Capital Renewal	1	Ea.	2	\$27,064	12298



Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electrical Disconnect Requires Replacement	Capital Renewal	1	Ea.	2	\$1,933	12283
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$6,114	12292
Note: Panelboard is obsolete and should be replaced.						
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$36,687	12293
Note: Panelboards are aged and obsolete.						
Remove Abandoned Equipment	Capital Renewal	1	Ea.	5	\$3,502	12289
Note: Water heater						
Remove Abandoned Equipment	Capital Renewal	2	Ea.	5	\$7,004	12290
Note: Fuel oil pumps						
Room Has Insufficient Electrical Outlets	Educational Adequacy	72	Ea.	5	\$36,166	Rollup
	Sub Total for System	7	items		\$118,470	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	1	Ea.	4	\$2,716	12287
Note: Service sink is aged and stained.						
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
	Sub Total for System	3	items		\$12,419	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	120	Ea.	3	\$60,143	23361
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	21	Ea.	3	\$210,499	23366
Technology: Instructional spaces do not have local sound reinforcement.	Technology	21	Ea.	3	\$105,249	23371
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23359
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23358
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23360
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23357
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23355
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23356
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	99	Ea.	3	\$44,656	23364
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	63	Ea.	3	\$28,417	23362
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23369
Technology: Network system inadequate and/or near end of useful life	Technology	16	Ea.	3	\$80,190	23370
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	168	Ea.	3	\$84,200	23363
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	38,800	SF	3	\$70,006	23368
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23365
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23367



Facility Condition Assessment

Cranston - George J. Peters School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	21	Ea.	3	\$33,680	23372
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23373
Sub Total for System		19	items		\$969,738	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Replace Cabinetry In Classes/Labs Note: Cabinets are original and in disrepair.	Capital Renewal	16	Room	4	\$188,735	12299
Sub Total for System		2	items		\$197,973	
Sub Total for Building 01 - Main Building		47	items		\$6,423,971	
Total for Campus		50	items		\$6,473,228	



George J. Peters School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Roadway Pavement	Asphalt	108	CAR	\$361,674	4
Sub Total for System		1	items	\$361,674	
Sub Total for Building -		1	items	\$361,674	

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Operable Partitions	Foldable partition (Bldg SF)	128	SF Wall	\$14,965	5
Interior Coiling Doors	Overhead	1	Door	\$37,240	5
Suspended Plaster and	Painted ceilings	3,880	SF	\$16,428	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	6,984	SF	\$46,708	5
Sub Total for System		4	items	\$115,342	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Roof Exhaust Fan - Large	1	Ea.	\$14,063	5
Exhaust Air	Roof Exhaust Fan - Large	4	Ea.	\$56,251	5
Heating System Supplementary Components	Controls - DDC (Bldg,SF)	38,800	SF	\$236,471	5
Sub Total for System		3	items	\$306,784	
Sub Total for Building 01 - Main Building		7	items	\$422,126	
Total for: George J. Peters School		8	items	\$783,800	



Supporting Photos



Aged Unit Heater



Aged Boilers



Obsolete Panelboard



Restroom Finishes And Fixtures



Facility Condition Assessment

Cranston - George J. Peters School



Site Aerial



Exterior Finishes



Cafeteria/Gym



West Elevation



Library



Typical Classroom



Facility Condition Assessment

Cranston - George J. Peters School



Cafetorium Exterior



Main Office



South Elevation



Kindergarten Toilet



Plaque



Worn 9x9 Flooring



Facility Condition Assessment

Cranston - George J. Peters School



Chipped And Worn Wood Door



Vegetation Growing On Roof



Ponding At Roof Edge



Original Radiant Heater



Ponding At Roof Drain



Radiant Heater



Corroded Condensate Receiver



Aged Distribution Panel



Aged Unit Vent



Typical Aged Casework



Aged Service Sink



Rusted Exhaust Fan



Facility Condition Assessment

Cranston - Gladstone Street School

June 2017

50 Gladstone Street, Cranston, RI 02920





Introduction

Gladstone Street School, located at 50 Gladstone Street in Cranston, Rhode Island, was built in 1952. It comprises 95,925 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Gladstone Street School serves grades 1 - 6, has 33 instructional spaces, and has an enrollment of 565. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Gladstone Street School is 520 with a resulting utilization of 109%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Gladstone Street School the 5-year need is \$14,477,893. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Gladstone Street School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Gladstone Street School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Painted Gypsum Soffit
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors
02 - Greenhouse:	Clear Polycarbonate Exterior Wall
	Wood Exterior Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Composition Shingle Roofing
	Single Ply Roofing
	Canopy Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Ceramic Tile Wall
	Wood Wall Paneling
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring



01 - Main Building:	Terrazzo Flooring
----------------------------	-------------------

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	400 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	250 MBH Steam Unit Heater
	50 MBH Steam Unit Heater
	Pneumatic Heating System Controls
	1 Ton Ductless Split System
	Window Units
	1 HP or Smaller Pump
	5 HP Pump
	10 HP Pump
	25 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	2,000 CFM Interior AHU
	Kitchen Exhaust Hoods
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	100 Gallon Water Storage Tank
	Gas Piping System
	100 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (2 hp)
	10,000 Gallon Underground Fuel Oil Storage Tank



Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	300 kW Emergency Generator
	Automatic Transfer Switch
	600 Amp Switchgear
	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$5,774	\$870,688	\$72,198	\$948,659	7.88 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$2,861,484	-	\$1,654	\$378,369	\$3,241,507	26.92 %
Interior	-	-	\$1,122,102	\$1,928,695	\$914,503	\$3,965,300	32.93 %
Mechanical	-	\$313,743	-	\$706,939	-	\$1,020,682	8.48 %
Electrical	-	\$42,902	-	-	\$60,277	\$103,179	0.86 %
Plumbing	-	-	\$818,936	\$154,719	\$25,314	\$998,969	8.30 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$1,699,823	-	-	\$1,699,823	14.12 %
Conveyances	-	-	\$50,119	-	-	\$50,119	0.42 %
Specialties	-	-	\$13,857	-	-	\$13,857	0.12 %
Total	\$0	\$3,218,129	\$3,710,610	\$3,662,694	\$1,450,660	\$12,042,094	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$3,965,300
Exterior	-	\$3,241,507
Technology	-	\$1,699,823

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$270,731	-	\$270,731
Barrier to Accessibility	-	-	\$843,499	-	-	\$843,499
Capital Renewal	-	\$3,218,129	\$1,147,659	\$1,457,344	\$1,287,040	\$7,110,171
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$25,404	\$159,002	\$163,620	\$348,027
Functional Deficiency	-	-	-	\$240,570	-	\$240,570
Hazardous Material	-	-	-	\$1,535,047	-	\$1,535,047
Technology	-	-	\$1,688,275	-	-	\$1,688,275
Traffic	-	-	\$5,774	-	-	\$5,774
Total	\$0	\$3,218,129	\$3,710,610	\$3,662,694	\$1,450,660	\$12,042,094

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$948,659	\$0	\$0	\$0	\$134,796	\$12,109	\$146,905	\$1,095,564
Roofing	\$0	\$0	\$0	\$0	\$725,290	\$297,755	\$1,023,045	\$1,023,045
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$3,241,507	\$0	\$0	\$0	\$0	\$1,925	\$1,925	\$3,243,432
Interior	\$3,965,300	\$0	\$0	\$0	\$0	\$25,031	\$25,031	\$3,990,332
Mechanical	\$1,020,682	\$0	\$0	\$0	\$625,430	\$585,606	\$1,211,036	\$2,231,718
Electrical	\$103,179	\$0	\$0	\$0	\$0	\$0	\$0	\$103,179
Plumbing	\$998,969	\$0	\$0	\$0	\$27,857	\$0	\$27,857	\$1,026,826
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$1,699,823	\$0	\$0	\$0	\$0	\$0	\$0	\$1,699,823
Conveyances	\$50,119	\$0	\$0	\$0	\$0	\$0	\$0	\$50,119
Specialties	\$13,857	\$0	\$0	\$0	\$0	\$0	\$0	\$13,857
Total	\$12,042,094	\$0	\$0	\$0	\$1,513,373	\$922,426	\$2,435,799	\$14,477,893

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$33,573,748. For planning purposes, the total 5-year need at the Gladstone Street School is \$14,477,893 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Gladstone Street School facility has a 5-year FCI of 43.12%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 662 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Gladstone Street School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$1,612,170.



Summary of Findings

The Gladstone Street School comprises 95,925 square feet and was constructed in 1952. Current deficiencies at this school total \$12,042,094. Five year capital renewal costs total \$2,435,799. The total identified need for the Gladstone Street School (current deficiencies and 5-year capital renewal costs) is \$14,477,893. The 5-year FCI is 43.12%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Gladstone Street School Totals	95,925	1952	\$12,042,094	\$2,435,799	\$14,477,893	43.12%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add school zone signs	Traffic	2	Ea.	3	\$5,774	11670
Asphalt Paving Requires Replacement Note: Back parking lot is splitting and cracking.	Capital Renewal	13	CAR	4	\$54,419	11501
Asphalt Paving Requires Replacement Note: The south parking lot is weathered and cracked.	Capital Renewal	6	CAR	4	\$25,116	11502
Asphalt Paving Requires Replacement Note: Roadway asphalt is weathered with alligator cracking and potholes.	Capital Renewal	30	CAR	4	\$125,581	11503
Asphalt Paving Requires Replacement Note: Paved play area has large cracks and a weathered surface.	Capital Renewal	89	CAR	4	\$372,557	11504
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28440
Fencing Requires Replacement (4' Chain Link Fence) Note: A portion of the fence is rusting and should be replaced.	Capital Renewal	200	LF	4	\$16,359	11500
Site Requires Regrading And Gravel Fill Note: The south end of the parking lot floods. The custodian places a large board over the water for teachers to walk on to exit lot.	Functional Deficiency	10,000	SF	4	\$240,570	11530
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28712
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54879
Sub Total for System		10	items		\$948,659	
Sub Total for School and Site Level		10	items		\$948,659	

Building: 01 - Main Building

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Storefront/Curtain Wall Requires Replacement (Bldg SF) Note: Original single pane windows are aged with snow, air, and water infiltrating.	Capital Renewal	33,556	SF	2	\$2,852,307	11528
Handrail Requires Repainting Note: Exterior handrails are weathered and should be repainted.	Capital Renewal	150	LF	4	\$1,654	11519
The Exterior Requires Cleaning	Capital Renewal	95,875	SF Wall	5	\$273,893	11507
The Exterior Requires Painting Note: Exposed painted concrete foundation, soffit dentil moulding, cupola and six roof dormers need to be painted.	Capital Renewal	18,000	SF Wall	5	\$104,476	11508
Sub Total for System		4	items		\$3,232,330	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Interior Door Hardware Requires Replacement Note: Interior doors are not keyed for safe lockdown procedures and are not ADA compliant.	Barrier to Accessibility	255	Door	3	\$843,499	11515
The Vinyl Composition Tile Requires Replacement Note: VCT is cracked, peeling, scratched, and worn.	Capital Renewal	23,034	SF	3	\$278,604	11509
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	46,766	SF	4	\$1,406,312	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	27	Ea.	4	\$8,119	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	3,620	LF	4	\$87,086	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	3,345	SF	4	\$33,529	Rollup
Partitions Provide Insufficient Sound Isolation Note: Classrooms adjacent to gym/cafeteria	Acoustics	2,000	SF	4	\$60,143	19771



Facility Condition Assessment

Cranston - Gladstone Street School

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Is Excessively Reverberant Note: Gym	Acoustics	5,340	SF	4	\$125,788	19772
Room Is Excessively Reverberant Note: Music Space	Acoustics	3,600	SF	4	\$84,801	19773
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	3,187	SF	4	\$122,917	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,309	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	67,112	SF	5	\$467,536	Rollup
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,522	Rollup
The Concrete Flooring Requires Repair Or Repainting Note: Auditorium flooring paint is chipped and worn.	Capital Renewal	3,600	SF	5	\$28,868	11510
The Gypsum Board Ceilings Require Repainting	Capital Renewal	93,475	SF	5	\$412,267	Rollup
Sub Total for System		15	items		\$3,965,300	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Air Handler HVAC Component Requires Replacement Note: Interior AHU's (blower coils) are re-built as needed and still operate, but they are antiquated and do not introduce any outside air. The systems should be updated given that they serve places of assembly.	Capital Renewal	4	Ea.	2	\$181,927	11521
The Cast Iron Water Boiler Requires Replacement Note: Boilers are corroded and non-functional. 272 MBH	Capital Renewal	4	Ea.	2	\$131,816	11526
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls Note: Controls system is outdated and erratic with hot and cold areas throughout.	Capital Renewal	95,875	SF	4	\$682,810	11527
Small HVAC Circulating Pump Requires Replacement Note: Fuel oil pumps are aged and deteriorating.	Capital Renewal	3	Ea.	4	\$24,129	11529
Sub Total for System		4	items		\$1,020,682	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement Note: Original panelboards should be replaced.	Capital Renewal	6	Ea.	2	\$30,673	11523
The Panelboard Requires Replacement Note: Original panelboards should be replaced.	Capital Renewal	2	Ea.	2	\$12,229	11525
Room Has Insufficient Electrical Outlets	Educational Adequacy	120	Ea.	5	\$60,277	Rollup
Sub Total for System		3	items		\$103,179	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life Note: Domestic water comes out brown after long weekends or periods of low use. There are signs of scaling in the pipes.	Capital Renewal	95,875	SF	3	\$813,331	11518
The Urinal Plumbing Fixtures Require Replacement Note: Original urinals should be replaced.	Capital Renewal	4	Ea.	3	\$5,605	11516
The Classroom Lavatories Plumbing Fixtures Require Replacement Note: Classroom lavatories are outdated and aged.	Capital Renewal	32	Ea.	4	\$91,737	11505
The Custodial Mop Or Service Sink Requires Replacement Note: Service sinks are aged and should be replaced.	Capital Renewal	8	Ea.	4	\$21,731	11514
The Refrigerated Water Cooler Requires Repair Note: Drinking fountain is missing front part of casing. Location: Outside gym	Capital Renewal	1	Ea.	4	\$1,002	11517
The Restroom Lavatories Plumbing Fixtures Require Replacement Note: Original restroom lavatories should be replaced.	Capital Renewal	12	Ea.	4	\$40,247	11511
Room lacks a drinking fountain.	Educational Adequacy	13	Ea.	5	\$14,511	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	10	Ea.	5	\$10,803	Rollup
Sub Total for System		8	items		\$998,969	



Facility Condition Assessment

Cranston - Gladstone Street School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,547	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	168	Ea.	3	\$84,200	23342
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	44	Ea.	3	\$441,045	23347
Technology: Instructional spaces do not have local sound reinforcement.	Technology	44	Ea.	3	\$220,523	23352
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23340
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23339
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23341
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23338
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23336
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23337
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	168	Ea.	3	\$75,780	23345
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	168	Ea.	3	\$75,780	23343
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23350
Technology: Network system inadequate and/or near end of useful life	Technology	42	Ea.	3	\$210,499	23351
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	168	Ea.	3	\$84,200	23344
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	95,875	SF	3	\$172,985	23349
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23346
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23348
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	44	Ea.	3	\$70,567	23353
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23354
Sub Total for System		20	items		\$1,699,823	

Conveyances

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Elevator Finishes Require Replacement	Capital Renewal	1	Ea.	3	\$50,119	11520
Note: Flooring and wall laminate in elevator cab is worn and should be replaced.						
Sub Total for System		1	items		\$50,119	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	3	Ea.	3	\$13,857	Rollup
Sub Total for System		1	items		\$13,857	
Sub Total for Building 01 - Main Building		56	items		\$11,084,258	

Building: 02 - Greenhouse

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Greenhouse (polycarbonate) Walls Require Replacement (Bldg SF)	Capital Renewal	10	SF	2	\$401	11533
Note: There are four missing panels.						



Facility Condition Assessment

Cranston - Gladstone Street School

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Wood Exterior Door Requires Replacement	Capital Renewal	1	Door	2	\$8,776	11532
	Sub Total for System	2	items		\$9,177	
	Sub Total for Building 02 - Greenhouse	2	items		\$9,177	
	Total for Campus	68	items		\$12,042,094	



Gladstone Street School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	1,230	LF	\$80,485	4
Fences and Gates	Fencing - Chain Link (4 Ft)	830	LF	\$54,311	4
Pedestrian Pavement	Sidewalks - Asphalt	1,400	SF	\$12,109	5
Sub Total for System		3	items	\$146,905	
Sub Total for Building -		3	items	\$146,905	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Steep Slope Roofing	Composition Shingle	25,124	SF	\$725,290	4
Low-Slope Roofing	Single Ply	22,476	SF	\$291,981	5
Canopy Roofing	Canopies	100	SF	\$5,774	5
Sub Total for System		3	items	\$1,023,044	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	800	SF	\$7,313	5
Note: Restrooms					
Wall Paneling	Wood Panel wall	1,918	SF	\$17,718	5
Sub Total for System		2	items	\$25,032	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Facility Hydronic Distribution	Pump - 5HP	2	Ea.	\$19,292	4
Decentralized Heating Equipment	Unit Heater Steam/HW (250 MBH)	17	Ea.	\$58,270	4
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	32	Ea.	\$547,868	4
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$16,159	5
Heat Generation	Boiler - Cast Iron - Water (400 MBH)	18	Ea.	\$569,447	5
Note: 272 MBH					
Sub Total for System		5	items	\$1,211,035	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	2	Ea.	\$14,935	4
Compressed-Air Systems	Air Compressor (2 hp)	2	Ea.	\$12,922	4
Sub Total for System		2	items	\$27,856	
Sub Total for Building 01 - Main Building		12	items	\$2,286,967	

Building: 02 - Greenhouse

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Clear Polycarbonate (Greenhouse) walls	50	SF	\$1,925	5
Sub Total for System		1	items	\$1,925	
Sub Total for Building 02 - Greenhouse		1	items	\$1,925	
Total for: Gladstone Street School		16	items	\$2,435,797	



Supporting Photos



Typical Classroom Cabinetry



Southwest Elevation



Original Panelboard



Elevator Floor



Facility Condition Assessment

Cranston - Gladstone Street School



Chipped Ceiling Paint



Aged Windows



Typical Aged Windows



Northwest Elevation



Greenhouse



Typical Classroom



Facility Condition Assessment

Cranston - Gladstone Street School



Peeling Exterior Paint



Dirty Exterior Walls



Cupola



Dentil Molding At Soffit Worn Paint



Aged VCT Flooring



Scratched And Worn VCT



Facility Condition Assessment

Cranston - Gladstone Street School



Library




Worn Painted Auditorium Floor



Vandalized Exterior Wall



Non-Compliant Door Hardware



Gymnasium



Weathered Asphalt Roadway



Facility Condition Assessment

Cranston - Gladstone Street School



Large Cracks In Play Area Paving




Aged Classroom Sink



Auditorium



Abandoned Pool Area



Worn Handrails




Restroom Fixtures And Finishes



Facility Condition Assessment

Cranston - Gladstone Street School



Site Aerial



Kindergarten Exterior



West Side Entry



Typical Classroom



Plaque



Drinking Fountain Missing Front Casing



Facility Condition Assessment

Cranston - Gladstone Street School



Aged Service Sink



Facility Condition Assessment

Cranston - Glen Hills School

June 2017

50 Glen Hills Drive, Cranston, RI 02920





Introduction

Glen Hills School, located at 50 Glen Hills Drive in Cranston, Rhode Island, was built in 1964. It comprises 40,800 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Glen Hills School serves grades PK - 6, has 19 instructional spaces, and has an enrollment of 347. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Glen Hills School is 334 with a resulting utilization of 104%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Glen Hills School the 5-year need is \$7,849,445. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Glen Hills School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Glen Hills School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
	Canopy Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Ceramic Tile Wall
	Wood Wall Paneling
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Carpet



Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	1,275 MBH Cast Iron Water Boiler
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	36 MBH Steam Unit Heater
	Electronic Heating System Controls
	Window Units
	5 HP VFD
	2-Pipe Hot Water Hydronic Distribution System
	5 HP Pump
	Roof Mounted Exhaust Fan
	Kitchen Exhaust Hoods

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	Gas Piping System
	100 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Toilets
	Urinals

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$56,414	\$730,968	\$7,398	\$794,779	11.77 %
Roofing	-	\$543,929	-	-	-	\$543,929	8.06 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$1,064,827	-	\$902	-	\$1,065,729	15.79 %
Interior	-	-	\$346,734	\$1,583,324	\$113,693	\$2,043,752	30.27 %
Mechanical	-	\$311,308	\$120,417	-	-	\$431,725	6.39 %
Electrical	-	\$67,616	\$200,635	\$13,081	\$38,176	\$319,508	4.73 %
Plumbing	-	-	\$123,112	-	\$10,819	\$133,930	1.98 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$1,129,917	-	-	\$1,129,917	16.74 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,619	\$283,103	-	\$287,722	4.26 %
Total	\$0	\$1,987,680	\$1,981,848	\$2,611,378	\$170,085	\$6,750,991	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$2,043,752
Technology	-	\$1,129,917
Exterior	-	\$1,065,729

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$120,417	\$30,071	-	\$150,489
Barrier to Accessibility	-	-	\$145,545	-	-	\$145,545
Capital Renewal	-	\$1,987,680	\$380,714	\$1,475,056	\$113,693	\$3,957,143
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$4,619	\$36,086	\$56,392	\$97,096
Functional Deficiency	-	-	\$200,635	-	-	\$200,635
Hazardous Material	-	-	-	\$1,070,166	-	\$1,070,166
Technology	-	-	\$1,129,917	-	-	\$1,129,917
Traffic	-	-	-	-	-	\$0
Total	\$0	\$1,987,680	\$1,981,848	\$2,611,378	\$170,085	\$6,750,991

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$794,779	\$0	\$0	\$0	\$24,342	\$114,450	\$138,792	\$933,571
Roofing	\$543,929	\$0	\$0	\$0	\$0	\$17,321	\$17,321	\$561,250
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$1,065,729	\$0	\$0	\$0	\$0	\$0	\$0	\$1,065,729
Interior	\$2,043,752	\$0	\$17,275	\$0	\$0	\$0	\$17,275	\$2,061,027
Mechanical	\$431,725	\$0	\$0	\$0	\$0	\$369,718	\$369,718	\$801,443
Electrical	\$319,508	\$0	\$0	\$0	\$24,172	\$0	\$24,172	\$343,680
Plumbing	\$133,930	\$0	\$5,387	\$0	\$0	\$525,789	\$531,176	\$665,106
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$1,129,917	\$0	\$0	\$0	\$0	\$0	\$0	\$1,129,917
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$287,722	\$0	\$0	\$0	\$0	\$0	\$0	\$287,722
Total	\$6,750,991	\$0	\$22,662	\$0	\$48,514	\$1,027,278	\$1,098,454	\$7,849,445

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$14,280,000. For planning purposes, the total 5-year need at the Glen Hills School is \$7,849,445 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Glen Hills School facility has a 5-year FCI of 54.97%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 227 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Glen Hills School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$388,584.



Summary of Findings

The Glen Hills School comprises 40,800 square feet and was constructed in 1964. Current deficiencies at this school total \$6,750,991. Five year capital renewal costs total \$1,098,454. The total identified need for the Glen Hills School (current deficiencies and 5-year capital renewal costs) is \$7,849,445. The 5-year FCI is 54.97%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Glen Hills School Totals	40,800	1964	\$6,750,991	\$1,098,454	\$7,849,445	54.97%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Playground Equipment Requires Replacement Note: Cracked and broken pavement, ponding.	Capital Renewal	1	Ea.	3	\$56,414	8978
Asphalt Paving Requires Replacement Note: Cracked and broken pavement	Capital Renewal	92	CAR	4	\$385,116	8979
Asphalt Paving Requires Replacement Note: Cracked and broken, ponding along edges, needs to be repaved.	Capital Renewal	74	CAR	4	\$309,767	8980
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28449
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28719
Sub Total for System		5 items			\$794,779	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Pole Lighting Is Missing And Needed Note: All around the building perimeter	Functional Deficiency	8	Ea.	3	\$200,635	8981
Sub Total for System		1 items			\$200,635	
Sub Total for School and Site Level		6 items			\$995,414	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF) Note: Roof has many leaks per building operator. Shows wear and tear	Capital Renewal	40,800	SF	2	\$543,929	8996
Sub Total for System		1 items			\$543,929	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement	Capital Renewal	5,952	SF	2	\$1,061,972	8983
The Aluminum Window Requires Replacement	Capital Renewal	16	SF	2	\$2,855	8984
The Concrete/CMU Exterior Requires Repair Note: Natural stone pier in front of building is leaning and should be repaired.	Capital Renewal	10	LF	4	\$902	8982
Sub Total for System		3 items			\$1,065,729	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceiling Tiles Require Replacement	Capital Renewal	4,080	SF	3	\$38,852	8985
The Carpet Flooring Requires Replacement	Capital Renewal	2,041	SF	3	\$46,818	8987
The Ceramic Tile Flooring Requires Replacement	Capital Renewal	4,080	SF	3	\$115,519	8989
The Interior Door Hardware Requires Replacement Note: 95% of door hardware is knobs, not levers, not ADA compliant.	Barrier to Accessibility	44	Door	3	\$145,545	8990
9x9 Asbestos Tile Present and In Active Use, Greater than 25 Percent has Significant Deterioration	Hazardous Material	33,047	SF	4	\$993,765	Rollup
Adhered Acoustical Ceiling Tile Requires Replacement Note: Tiles cracked/missing/falling down, Comment: (null)	Capital Renewal	32,640	SF	4	\$373,184	9003
Ceiling Grid Requires Replacement	Capital Renewal	4,080	SF	4	\$51,021	8999
Interior Wood Walls Require Replacement Note: Remove/replace paneling.	Capital Renewal	6,119	SF	4	\$58,882	9001
Paint (probable pre-1978 in base (layers(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	130	Ea.	4	\$39,093	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	1,330	LF	4	\$31,996	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	530	SF	4	\$5,313	Rollup



Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Is Excessively Reverberant (Install Fiberglass Wall Panel)	Acoustics	500	SF	4	\$30,071	19700
Note: Gym						
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	16,320	SF	5	\$113,693	Rollup
	Sub Total for System	13	items		\$2,043,752	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent	Capital Renewal	5	Ea.	2	\$89,171	9000
Note: Univents are original to building and obsolete. Constantly failing per principal						
Steam/HW Unit Heater Requires Replacement	Capital Renewal	8	Ea.	2	\$13,889	8991
Note: Unit heater original to building and past expected life. Equipment is obsolete in event of failure						
The Cast Iron Water Boiler Requires Replacement	Capital Renewal	2	Ea.	2	\$158,794	8992
Note: Boilers are original to building and obsolete and wrapped in asbestos insulation						
The Fin Tube Water Radiant Heater Requires Replacement	Capital Renewal	28	Ea.	2	\$49,453	8993
Note: Fin tube heater is original to building and past expected life. Equipment is obsolete in event of failure						
Unit Ventilators Are Excessively Noisy	Acoustics	18	Ea.	3	\$120,417	19699
Note: Some classrooms						
	Sub Total for System	5	items		\$431,725	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electrical Disconnect Requires Replacement	Capital Renewal	2	Ea.	2	\$3,865	10958
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$36,687	8994
Note: Every electrical distribution panel throughout building is past it's lifetime and parts may not be available, installed in 1964						
The Panelboard Requires Replacement	Capital Renewal	4	Ea.	2	\$20,448	10956
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$6,616	10957
The Canopy Lighting Requires Replacement	Capital Renewal	9	Ea.	4	\$13,081	9002
Note: Canopy lights at every entry						
Room Has Insufficient Electrical Outlets	Educational Adequacy	76	Ea.	5	\$38,176	Rollup
	Sub Total for System	6	items		\$118,873	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Sanitary Sewer Piping Requires Replacement	Capital Renewal	750	LF	3	\$123,112	8995
Note: Waste water is constantly backing up and slow drainage per building operator						
Room lacks a drinking fountain.	Educational Adequacy	6	Ea.	5	\$6,697	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
	Sub Total for System	3	items		\$133,930	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	84	Ea.	3	\$42,100	23485
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	16	Ea.	3	\$160,380	23490
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	16	Ea.	3	\$336,798	23499
Technology: Instructional spaces do not have local sound reinforcement.	Technology	16	Ea.	3	\$80,190	23495
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23482
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,642	23481
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23483
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23480



Facility Condition Assessment

Cranston - Glen Hills School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23479
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	144	Ea.	3	\$64,954	23488
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	16	Ea.	3	\$7,217	23486
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23493
Technology: Network system inadequate and/or near end of useful life	Technology	18	Ea.	3	\$90,214	23494
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	48	Ea.	3	\$24,057	23487
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	40,800	SF	3	\$73,614	23492
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23489
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23491
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23484
Technology: Telecommunications Room fiber connectivity infrastructure is outdated and/or inadequate.	Technology	1	Ea.	3	\$6,616	23498
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	16	Ea.	3	\$25,661	23496
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23497
Sub Total for System		21	items		\$1,129,917	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,619	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	24	Room	4	\$283,103	8997
Sub Total for System		2	items		\$287,722	
Sub Total for Building 01 - Main Building		54	items		\$5,755,577	
Total for Campus		60	items		\$6,750,991	



Glen Hills School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	372	LF	\$24,342	4
Pedestrian Pavement	Sidewalks - Concrete	5,532	SF	\$114,450	5
Sub Total for System		2	items	\$138,791	
Sub Total for Building -		2	items	\$138,791	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Canopy Roofing	Canopies	300	SF	\$17,321	5
Sub Total for System		1	items	\$17,321	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings	4,080	SF	\$17,275	2
Sub Total for System		1	items	\$17,275	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Exhaust Fan - Roof Mounted (CFM)	13	CFM	\$35,233	5
Facility Hydronic Distribution	2-Pipe Water System (Hot)	40,800	SF	\$318,326	5
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$16,159	5
Sub Total for System		3	items	\$369,718	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)	16	Ea.	\$24,172	4
Sub Total for System		1	items	\$24,172	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 100 Gallon	1	Ea.	\$5,387	2
Plumbing Fixtures	Urinals	7	Ea.	\$9,417	5
Plumbing Fixtures	Classroom Lavatories	23	Ea.	\$63,299	5
Plumbing Fixtures	Lavatories	16	Ea.	\$51,517	5
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)	40,800	SF	\$332,272	5
Plumbing Fixtures	Toilets	24	Ea.	\$69,284	5
Sub Total for System		6	items	\$531,175	
Sub Total for Building 01 - Main Building		12	items	\$959,661	
Total for: Glen Hills School		14	items	\$1,098,453	



Supporting Photos



Site Aerial



North Elevation



East Elevation



Roof



Facility Condition Assessment

Cranston - Glen Hills School



South Elevation



West elevation



East Side Building Lighting



Leaning Stone Pier



Windows (Broken Seals)



Floor Tile



Damaged Ceramic Tile



Boiler



Pavement Crack



Cracked and Damaged Pavement



Casework Requires Replacement



Main Entrance



Classroom Heating




Missing Ceiling Tiles



Canopy Lighting



Damaged Wood Panel Wall



Typical Restroom



Canopy Lighting



Library



Computer Lab



Cafeteria



Typical Classroom



Electrical Panels



Electric Panel



Roof



Facility Condition Assessment

Cranston - Hope Highlands Elementary School

June 2017

300 Hope Road, Cranston, RI 02921





Introduction

Hope Highlands Elementary School, located at 300 Hope Road in Cranston, Rhode Island, was built in 1991. It comprises 68,700 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Hope Highlands Elementary School serves grades PK - 6, has 30 instructional spaces, and has an enrollment of 363. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Hope Highlands Elementary School is 417 with a resulting utilization of 87%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Hope Highlands Elementary School the 5-year need is \$6,993,849. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Hope Highlands Elementary School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Hope Highlands Elementary School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Brick Pedestrian Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Composition Shingle Roofing
	EPDM Roofing
	Fabric Canopy Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Non-Painted Plaster/Gypsum Board Ceiling
	Ceramic Tile Wall
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring



01 - Main Building:	Carpet
	Athletic/Sport Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,264 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	Radiant Water Heater
	DDC Heating System Controls
	210 Ton Outdoor Air Cooled Chiller
	3 Ton Outside Air Cooled Condenser
	Window Units
	Make-up Air Unit
	15 HP VFD
	1 HP or Smaller Pump
	10 HP Pump
	4-Pipe Hydronic Distribution System
	5,000 CFM Interior AHU
	10,000 CFM Interior AHU
	15,000 CFM Interior AHU
	Ductwork
	Roof Mounted Exhaust Fan
	Wall Exhaust Fan
	Laboratory Fume Hood
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	Gas Piping System
	100 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals



Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	1,600 Amp Switchgear
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Cranston - Hope Highlands Elementary School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$288,684	\$1,181,644	\$72,198	\$1,542,525	27.02 %
Roofing	-	\$745,444	-	-	-	\$745,444	13.06 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	\$8,921	-	-	\$8,921	0.16 %
Interior	-	-	\$740,488	\$218,518	\$410,307	\$1,369,313	23.99 %
Mechanical	-	-	-	\$2,823	-	\$2,823	0.05 %
Electrical	-	-	-	-	-	\$0	0.00 %
Plumbing	-	-	\$16,712	\$577	\$20,387	\$37,676	0.66 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$1,592,507	-	-	\$1,592,507	27.90 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	-	\$401,062	\$8,602	\$409,664	7.18 %
Total	\$0	\$745,444	\$2,647,311	\$1,804,624	\$511,494	\$5,708,873	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Technology	-	\$1,592,507
Site	-	\$1,542,525
Interior	-	\$1,369,313

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$111,264	\$218,518	-	\$329,781
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$745,444	\$654,857	\$1,549,444	\$406,809	\$3,356,554
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$63,083	\$36,662	\$104,685	\$204,430
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	-	-	\$0
Technology	-	-	\$1,529,424	-	-	\$1,529,424
Traffic	-	-	\$288,684	-	-	\$288,684
Total	\$0	\$745,444	\$2,647,311	\$1,804,624	\$511,494	\$5,708,873

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,542,525	\$0	\$0	\$0	\$0	\$172,893	\$172,893	\$1,715,418
Roofing	\$745,444	\$0	\$0	\$0	\$0	\$0	\$0	\$745,444
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$8,921	\$0	\$0	\$0	\$0	\$0	\$0	\$8,921
Interior	\$1,369,313	\$0	\$0	\$0	\$478,627	\$545,504	\$1,024,131	\$2,393,444
Mechanical	\$2,823	\$0	\$0	\$0	\$0	\$0	\$0	\$2,823
Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Plumbing	\$37,676	\$0	\$0	\$0	\$0	\$0	\$0	\$37,676
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$1,592,507	\$0	\$0	\$0	\$0	\$0	\$0	\$1,592,507
Conveyances	\$0	\$0	\$0	\$0	\$0	\$48,114	\$48,114	\$48,114
Specialties	\$409,664	\$0	\$0	\$0	\$0	\$39,838	\$39,838	\$449,503
Total	\$5,708,873	\$0	\$0	\$0	\$478,627	\$806,349	\$1,284,976	\$6,993,849

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$24,045,000. For planning purposes, the total 5-year need at the Hope Highlands Elementary School is \$6,993,849 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Hope Highlands Elementary School facility has a 5-year FCI of 29.09%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 409 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Hope Highlands Elementary School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Hope Highlands Elementary School comprises 68,700 square feet and was constructed in 1991. Current deficiencies at this school total \$5,708,873. Five year capital renewal costs total \$1,284,976. The total identified need for the Hope Highlands Elementary School (current deficiencies and 5-year capital renewal costs) is \$6,993,849. The 5-year FCI is 29.09%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Hope Highlands Elementary School Totals	68,700	1991	\$5,708,873	\$1,284,976	\$6,993,849	29.09%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Install signs for school zone	Traffic	4	Ea.	3	\$192,456	9341
Traffic Signage Is Required Note: Add flashing beacons to school zone speed limit signs	Traffic	2	Ea.	3	\$96,228	9342
Asphalt Paving Requires Replacement	Capital Renewal	118	CAR	4	\$493,953	8949
Asphalt Paving Requires Replacement	Capital Renewal	143	CAR	4	\$598,603	8950
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28451
Fencing Requires Replacement (4' Chain Link Fence) Note: Fence was knocked over by snow plow and needs to be replaced.	Capital Renewal	648	LF	4	\$53,002	8948
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28722
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54885
Sub Total for System		8	items		\$1,542,525	
Sub Total for School and Site Level		8	items		\$1,542,525	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF) Note: Roof is patched and leaking and should be replaced.	Capital Renewal	17,175	SF	2	\$228,970	8960
Shingle Roof Requires Replacement Note: Shingles are falling off and need to be replaced.	Capital Renewal	17,175	SF	2	\$516,474	8953
Sub Total for System		2	items		\$745,444	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Repair Note: Seals of windows are broken and windows should be replaced.	Capital Renewal	3	Ea.	3	\$3,308	8951
The Brick Exterior Requires Repair Note: Large crack in front column brick.	Capital Renewal	80	SF Wall	3	\$5,613	8954
Sub Total for System		2	items		\$8,921	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Interior Doors Provide Insufficient Sound Isolation Note: All classrooms	Acoustics	12	Ea.	3	\$111,264	19703
The Athletic Sport Flooring Requires Replacement Note: Gym flooring is cracking and should be replaced.	Capital Renewal	5,496	SF	3	\$198,326	8959
The Carpet Flooring Requires Replacement Note: Carpet is worn, faded, and wrinkled and needs to be replaced.	Capital Renewal	10,305	SF	3	\$236,385	8955
The Ceramic Tile Flooring Requires Replacement Note: Tile is dirty and cracked and should be replaced.	Capital Renewal	6,870	SF	3	\$194,514	8956
Room Is Excessively Reverberant Note: Gym	Acoustics	8,000	SF	4	\$188,447	19705
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) Note: Music Space	Acoustics	500	SF	4	\$30,071	19706
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	58,395	SF	5	\$406,809	Rollup
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,498	Rollup
Sub Total for System		8	items		\$1,369,313	



Facility Condition Assessment

Cranston - Hope Highlands Elementary School

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	1	Ea.	4	\$2,823	19897
Sub Total for System		1	items		\$2,823	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Non-Refrigerated Drinking Fountain Requires Repair	Capital Renewal	10	Ea.	3	\$16,712	8957
Note: Classrooms						
Floor Drains Are Required	Educational Adequacy	1	Ea.	4	\$577	Rollup
Room lacks a drinking fountain.	Educational Adequacy	11	Ea.	5	\$12,196	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	7	Ea.	5	\$8,191	Rollup
Sub Total for System		4	items		\$37,676	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	11	Ea.	3	\$63,083	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$48,114	23539
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	27	Ea.	3	\$270,641	23531
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	27	Ea.	3	\$568,347	23538
Technology: Instructional spaces do not have local sound reinforcement.	Technology	27	Ea.	3	\$135,321	23535
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23529
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$22,854	23528
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	96	Ea.	3	\$43,303	23540
Technology: Network system inadequate and/or near end of useful life	Technology	12	Ea.	3	\$96,228	23533
Technology: Network system inadequate and/or near end of useful life	Technology	22	Ea.	3	\$110,261	23534
Technology: Special Space AV/Multimedia system is inadequate.	Technology	2	Ea.	3	\$114,271	23530
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23543
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23541
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	27	Ea.	3	\$43,303	23536
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23537
Sub Total for System		15	items		\$1,592,507	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Cabinetry In Classes/Labs	Capital Renewal	34	Room	4	\$401,062	8961
Note: Casework in classrooms and toilet rooms is delaminating.						
Room lacks an appropriate refrigerator.	Educational Adequacy	1	Ea.	5	\$8,602	Rollup
Sub Total for System		2	items		\$409,664	
Sub Total for Building 01 - Main Building		34	items		\$4,166,348	
Total for Campus		42	items		\$5,708,873	



Hope Highlands Elementary School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Ornamental	159	LF	\$172,893	5
		Sub Total for System		\$172,893	
		Sub Total for Building -		\$172,893	

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Vinyl Composition Tile Flooring	41,220	SF	\$478,627	4
Interior Coiling Doors	Overhead	2	Door	\$74,480	5
Note: In cafeteria					
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	51,525	SF	\$471,024	5
		Sub Total for System		\$1,024,131	

Conveyances

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Elevators	Passenger elevator cab finishes	1	Ea.	\$48,114	5
		Sub Total for System		\$48,114	

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Lockers	80	Ea.	\$39,838	5
		Sub Total for System		\$39,838	
		Sub Total for Building 01 - Main Building		\$1,112,083	
		Total for: Hope Highlands Elementary School		\$1,284,976	



Supporting Photos



Site Aerial



Cracked Paving



East Elevation



Loading Dock



Facility Condition Assessment

Cranston - Hope Highlands Elementary School



North Elevation



Historic Cemetary



West Elevation



Main Entrance



South Elevation



North Elevation



Facility Condition Assessment


Cranston - Hope Highlands Elementary School



Windows With Broken Seals



Roof Shingles



Front Column Brick Cracking



Auditorium Carpet



Classroom Drinking Fountain



Gym Flooring



Facility Condition Assessment

Cranston - Hope Highlands Elementary School



Delaminating Laminate



Delaminating Laminate



Peeling/chipped Paint Throughout School



Kindergarten Playground



Cafeteria



Gymnasium



Facility Condition Assessment

Cranston - Hope Highlands Elementary School



Music



Computer Lab



Art



Library



Playground



Typical Classroom



Facility Condition Assessment

Cranston - Hope Highlands Elementary School



Typical Classroom



Auditorium



Entry Lobby



Typical Restroom



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School

June 2017

135 Gansett Avenue, Cranston, RI 02910





Introduction

Hugh B. Bain Middle School, located at 135 Gansett Avenue in Cranston, Rhode Island, was built in 1929. It comprises 132,813 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Hugh B. Bain Middle School serves grades 7 - 8, has 49 instructional spaces, and has an enrollment of 479. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Hugh B. Bain Middle School is 726 with a resulting utilization of 66%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Hugh B. Bain Middle School the 5-year need is \$17,993,738. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Hugh B. Bain Middle School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Hugh B. Bain Middle School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
----------------------------	--------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Carpet



Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	200 MBH Copper Tube Boiler
	120 GPM Steam to Water Heat Exchanger
	Steam Condensate Receiver, Tank and Pump
	36 MBH Steam Unit Heater
	Steam/Hot Water Heating Unit Vent
	Radiant Steam Heater
	Pneumatic Heating System Controls
	2 Ton Ductless Split System
	25 Ton DX Cool w/Electric Heat Fan Coil
	20 Ton Condensing Unit
	Window Units
	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	2,000 CFM Interior AHU
	Ductwork
	Roof Exhaust Fan
	Large Roof Exhaust Fan
	Kitchen Exhaust Hoods
	Laboratory Fume Hood
	Wall Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	4" Backflow Preventers
	Gas Piping System
	40 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Air Compressor (2 hp)



Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	1,200 Amp Switchgear
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$23,865	\$638,543	\$506,431	\$1,168,838	7.39 %
Roofing	-	\$610,053	-	-	-	\$610,053	3.86 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$2,394,276	\$5,692	-	\$38,624	\$2,438,592	15.42 %
Interior	-	-	\$1,946,246	\$1,230,880	\$880,023	\$4,057,149	25.66 %
Mechanical	-	\$1,151,131	-	\$1,104,001	\$6,864	\$2,261,996	14.31 %
Electrical	\$1,429	\$191,927	-	-	\$86,397	\$279,754	1.77 %
Plumbing	-	-	\$1,463,644	\$45,014	\$19,226	\$1,527,884	9.66 %
Fire and Life Safety	\$86,789	-	-	-	-	\$86,789	0.55 %
Technology	-	-	\$2,484,264	-	-	\$2,484,264	15.71 %
Conveyances	-	-	\$312,741	-	-	\$312,741	1.98 %
Specialties	-	-	\$9,238	\$516,350	\$57,159	\$582,747	3.69 %
Total	\$88,219	\$4,347,388	\$6,245,689	\$3,534,788	\$1,594,724	\$15,810,807	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$4,057,149
Technology	-	\$2,484,264
Exterior	-	\$2,438,592

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$56,835	-	\$56,835
Barrier to Accessibility	-	-	\$312,741	-	-	\$312,741
Capital Renewal	\$17,505	\$4,347,388	\$3,415,581	\$2,510,289	\$906,288	\$11,197,052
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$70,714	-	\$38,106	\$217,679	\$688,435	\$1,014,935
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$749,984	-	\$749,984
Technology	-	-	\$2,455,396	-	-	\$2,455,396
Traffic	-	-	\$23,865	-	-	\$23,865
Total	\$88,219	\$4,347,388	\$6,245,689	\$3,534,788	\$1,594,724	\$15,810,807

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,168,838	\$0	\$0	\$0	\$0	\$127,442	\$127,442	\$1,296,280
Roofing	\$610,053	\$0	\$0	\$0	\$0	\$0	\$0	\$610,053
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$2,438,592	\$0	\$0	\$0	\$0	\$0	\$0	\$2,438,592
Interior	\$4,057,149	\$0	\$0	\$0	\$0	\$209,143	\$209,143	\$4,266,292
Mechanical	\$2,261,996	\$0	\$0	\$0	\$1,173,227	\$70,420	\$1,243,647	\$3,505,643
Electrical	\$279,754	\$0	\$0	\$0	\$0	\$0	\$0	\$279,754
Plumbing	\$1,527,884	\$0	\$0	\$233,930	\$0	\$6,397	\$240,327	\$1,768,211
Fire and Life Safety	\$86,789	\$0	\$0	\$0	\$0	\$0	\$0	\$86,789
Technology	\$2,484,264	\$0	\$0	\$0	\$0	\$0	\$0	\$2,484,264
Conveyances	\$312,741	\$0	\$0	\$0	\$0	\$0	\$0	\$312,741
Specialties	\$582,747	\$0	\$0	\$0	\$0	\$362,372	\$362,372	\$945,119
Total	\$15,810,807	\$0	\$0	\$233,930	\$1,173,227	\$775,774	\$2,182,931	\$17,993,738

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$43,828,288. For planning purposes, the total 5-year need at the Hugh B. Bain Middle School is \$17,993,738 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Hugh B. Bain Middle School facility has a 5-year FCI of 41.06%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 734 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Hugh B. Bain Middle School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$741,312.



Summary of Findings

The Hugh B. Bain Middle School comprises 132,813 square feet and was constructed in 1929. Current deficiencies at this school total \$15,810,807. Five year capital renewal costs total \$2,182,931. The total identified need for the Hugh B. Bain Middle School (current deficiencies and 5-year capital renewal costs) is \$17,993,738. The 5-year FCI is 41.06%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Hugh B. Bain Middle School Totals	132,813	1929	\$15,810,807	\$2,182,931	\$17,993,738	41.06%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add school zone signage on adjacent streets	Traffic	4	Ea.	3	\$11,932	11677
Traffic Signage Is Required Note: Add school zone signage on adjacent streets	Traffic	4	Ea.	3	\$11,932	16936
Asphalt Paving Requires Replacement	Capital Renewal	27	CAR	4	\$116,790	12536
Asphalt Paving Requires Replacement Note: Asphalt parking is weathered, alligatored, and breaking.	Capital Renewal	112	CAR	4	\$484,464	12537
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$37,288	28435
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,644	28708
Paving Requires Restriping Note: Repaint parking spaces on campus (quantity provided is an estimate)	Capital Renewal	43	CAR	5	\$3,207	11676
Paving Requires Restriping Note: Repaint parking spaces on campus (quantity provided is an estimate)	Capital Renewal	43	CAR	5	\$3,207	16935
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54874
School lacks a competition track. Note: School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$427,573	28234
Sub Total for System		10	items		\$1,168,838	
Sub Total for School and Site Level		10	items		\$1,168,838	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF) Note: Membrane is buckling and insulation is deteriorating and feels soft underfoot. The warranty expired in 1998.	Capital Renewal	44,000	SF	2	\$610,053	12562
Sub Total for System		1	items		\$610,053	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Note: Single pane windows allow water and air infiltration.	Capital Renewal	12,903	SF	2	\$2,394,276	12542
Exterior Metal Door Requires Repainting Note: Exterior doors are weathered, faded, and have chipped paint.	Capital Renewal	25	Door	3	\$5,692	12541
The Exterior Requires Cleaning Note: Limestone exterior is stained and should be cleaned.	Capital Renewal	13,000	SF Wall	5	\$38,624	12540
Sub Total for System		3	items		\$2,438,592	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement Note: Wood doors are aged, stained, and chipped.	Capital Renewal	280	Door	3	\$1,415,674	12543
The Carpet Flooring Requires Replacement Note: Carpet is aged and worn. Location: Library and music rooms	Capital Renewal	3,984	SF	3	\$95,044	12544
The Vinyl Composition Tile Requires Replacement Note: Tile is chipped, worn, and lifting at the seams.	Capital Renewal	34,623	SF	3	\$435,527	12545
Adhered Acoustical Ceiling Tile Requires Replacement Note: Tiles are separating from the ceiling.	Capital Renewal	13,281	SF	4	\$157,920	12568
Interior Toilet Partition Requires Repair	Capital Renewal	36	Ea.	4	\$20,641	12552



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	9,205	SF	4	\$287,878	Rollup
Moveable Partitions Require Replacement	Capital Renewal	648	SF Wall	4	\$82,076	12567
Note: Partition opens, but is extremely difficult to close.						
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	123	Ea.	4	\$38,467	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	30	LF	4	\$751	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	40,566	SF	4	\$422,888	Rollup
Room Is Excessively Reverberant	Acoustics	2,320	SF	4	\$56,835	19775
Note: Gym						
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	2,227	SF	4	\$85,891	Rollup
The Terrazzo Flooring Requires Repair	Capital Renewal	1,328	SF	4	\$77,533	12554
Note: Cracks in restrooms.						
Classroom Door Requires Vision Panel	Educational Adequacy	5	Ea.	5	\$11,547	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	70,038	SF	5	\$507,437	Rollup
Room lacks appropriate sound control.	Educational Adequacy	400	SF	5	\$14,088	Rollup
The Gypsum Board Ceilings Require Repainting	Capital Renewal	75,640	SF	5	\$346,951	Rollup
Sub Total for System		17	items		\$4,057,149	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent	Capital Renewal	14	Ea.	2	\$259,667	12566
Note: Unit vents are no longer functional.						
The Air Handler HVAC Component Requires Replacement	Capital Renewal	7	Ea.	2	\$331,107	12556
The Boiler HVAC Component Requires Replacement	Capital Renewal	3	Ea.	2	\$560,357	12557
Note: Steam boilers and antiquated and should be replaced.						
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls	Capital Renewal	132,813	SF	4	\$983,713	12561
Lab lacks an appropriate fume hood.	Educational Adequacy	4	Ea.	4	\$89,015	Rollup
The Chemistry Lab Fume Hood(s) Require Replacement	Capital Renewal	1	Ea.	4	\$31,274	12539
Remove Abandoned Equipment	Capital Renewal	2	Ea.	5	\$6,864	13481
Note: Hot water storage tanks						
Sub Total for System		7	items		\$2,261,996	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	1	Ea.	1	\$1,429	Rollup
Switchgear Is Needed Or Requires Replacement	Capital Renewal	2	Ea.	2	\$151,450	12560
The Electrical Disconnect Requires Replacement	Capital Renewal	1	Ea.	2	\$2,010	12546
The Panelboard Requires Replacement	Capital Renewal	9	Ea.	2	\$38,467	12558
Note: Electrical distribution is obsolete and should be replaced.						
Room Has Insufficient Electrical Outlets	Educational Adequacy	172	Ea.	5	\$86,397	Rollup
Sub Total for System		5	items		\$279,754	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	132,813	SF	3	\$1,171,752	12555
Note: The custodian reported occasional brown water and signs of scaling in the pipes.						
The Showers Plumbing Fixtures Require Replacement	Capital Renewal	35	Ea.	3	\$291,892	12548
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	2	Ea.	4	\$22,413	12549
Note: Water fountains are not functional.						
Location: Second floor						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	8	Ea.	4	\$22,601	12553
Note: Service sinks are aged and corroded and should be replaced.						



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks a drinking fountain.	Educational Adequacy	9	Ea.	5	\$10,046	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	6	Ea.	5	\$9,180	Rollup
Sub Total for System		6	items		\$1,527,884	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Kitchen Exhaust Hood	Capital Renewal	1	Ea.	1	\$17,505	12559
Note: Exhaust hood performs poorly according to staff and should be replaced.						
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	6	Ea.	1	\$69,284	Rollup
Sub Total for System		2	items		\$86,789	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	5	Ea.	3	\$28,868	Rollup
Technology: Auditorium AV/Multimedia system is in need of minor improvements.	Technology	1	Room	3	\$104,247	23580
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	478	Ea.	3	\$249,150	23579
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	46	Ea.	3	\$1,007,026	23584
Technology: Instructional spaces do not have local sound reinforcement.	Technology	46	Ea.	3	\$239,768	23586
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,838	23573
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,838	23576
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,622	23572
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,622	23575
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,212	23571
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,212	23574
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,212	23577
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,297	23569
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$46,703	23568
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	322	Ea.	3	\$151,054	23578
Technology: Network system inadequate and/or near end of useful life	Technology	8	Ea.	3	\$66,718	23587
Technology: Network system inadequate and/or near end of useful life	Technology	18	Ea.	3	\$93,822	23588
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	132,813	SF	3	\$249,216	23583
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,849	23585
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,340	23570
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	46	Ea.	3	\$76,726	23582



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,923	23581
Sub Total for System		22	items		\$2,484,264	

Conveyances

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Elevator Cab Requires Replacement	Barrier to Accessibility	1	Ea.	3	\$312,741	12547
Note: Elevator is obsolete and not ADA compliant. It is difficult to get replacement parts when necessary.						
Sub Total for System		1	items		\$312,741	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	4	Room	4	\$49,071	12564
Note: Science wing cabinetry is in disrepair with doors falling off.						
The Metal Student Lockers Require Replacement	Capital Renewal	856	Ea.	4	\$461,793	12563
Note: Lockers are aged and rusted with poorly functioning locks.						
Welding Bays Are Required	Educational Adequacy	1	Ea.	4	\$5,485	Rollup
Room lacks an appropriate refrigerator.	Educational Adequacy	5	Ea.	5	\$43,303	Rollup
The room lacks a washer and/or dryer.	Educational Adequacy	1	Ea.	5	\$13,857	Rollup
Sub Total for System		6	items		\$582,747	
Sub Total for Building 01 - Main Building		70	items		\$14,641,969	
Total for Campus		80	items		\$15,810,807	



Hugh B. Bain Middle School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Pedestrian Pavement	Sidewalks - Concrete	6,160	SF	\$127,442	5
Sub Total for System		1	items	\$127,442	
Sub Total for Building -		1	items	\$127,442	

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	13,281	SF	\$121,410	5
Carpeting	Carpet	3,984	SF	\$87,733	5
Sub Total for System		2	items	\$209,143	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heat Generation	Steam Condensate Receiver, Tank and Pump	3	Ea.	\$1,068,131	4
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	2	Ea.	\$34,242	4
Decentralized Heating Equipment	Unit Heater Steam/HW (36 MBH)	2	Ea.	\$3,333	4
Facility Hydronic Distribution	Pump - 5HP	7	Ea.	\$67,521	4
Exhaust Air	Roof Exhaust Fan	7	Ea.	\$36,873	5
Exhaust Air	Roof Exhaust Fan - Large	2	Ea.	\$28,126	5
Exhaust Air	Wall Exhaust Fan	2	Ea.	\$5,421	5
Sub Total for System		7	items	\$1,243,646	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Classroom Lavatories	85	Ea.	\$233,930	3
Domestic Water Equipment	Water Heater - Gas - 40 gallon	2	Ea.	\$6,397	5
Sub Total for System		2	items	\$240,328	

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	32	Room	\$362,372	5
Sub Total for System		1	items	\$362,372	
Sub Total for Building 01 - Main Building		12	items	\$2,055,488	
Total for: Hugh B. Bain Middle School		13	items	\$2,182,930	



Supporting Photos



Weathered Exterior Doors



Damaged Wood Door



Damaged Interior Door



Frayed Carpet



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Worn Carpet



Aged Steam Boilers



Chipped, Mismatched, And Missing VCT



Chipped And Worn VCT



Typical Single Pane Windows



Weathered Exterior Doors



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Peeling Ceiling Paint



Aged Elevator



Cracked Terrazzo



Toilet Partitions



Non-Functional Unit Vent



Buckled EPDM



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Obsolete Panelboard



Aged Air Handling Unit



Deteriorated Asphalt Parking



Weathered Asphalt



Site Aerial



Typical Built-In Casework



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Cafeteria



Science Room



Art Room



Gym



Exterior Finishes




Typical Classroom



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Auditorium




Exterior Finishes



Music Room



Weight Room



Band Room



Main Entry



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Site Signage



Dirty Exterior



Stained Roof Membrane



Aged Lockers



Damaged Science Cabinetry



Peeling Classroom Paint



Facility Condition Assessment

Cranston - Hugh B. Bain Middle School



Peeling Classroom Paint



Facility Condition Assessment

Charter - Nel/CPS Construction Career Academy

June 2017

4 Sharpe Dr, Cranston, RI 02920





Introduction

Nel/CPS Construction Career Academy, located at 4 Sharpe Dr in Cranston, Rhode Island, was built in 1980. It comprises 46,170 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Nel/CPS Construction Career Academy serves grades 9 - 12, has 23 instructional spaces, and has an enrollment of 170. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Nel/CPS Construction Career Academy is 192 with a resulting utilization of 89%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Nel/CPS Construction Career Academy the 5-year need is \$5,416,948. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Nel/CPS Construction Career Academy



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Nel/CPS Construction Career Academy campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Painted Exterior Wall
	Metal Panel Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors
	Overhead Exterior Utility Doors
02 - Building 02:	Metal Panel Exterior Wall
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Built-Up Roofing With Ballast
02 - Building 02:	Metal Steep Slope Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Vinyl/Fabric Wall Covering
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring



01 - Main Building:	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Carpet
02 - Building 02:	Exposed Metal Structure Ceiling
	Vinyl/Fabric Wall Covering
	Interior Wall Painting
	Concrete Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	20 kW Electric Unit Heater
	5 kW Electric Unit Heater
	Electronic Heating System Controls
	5 Ton Package DX Unit
	10 Ton Package DX Unit
	Ductwork
	Wall Exhaust Fan
	Fire Sprinkler System
02 - Building 02:	20 kW Electric Unit Heater
	Wall Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	4" Backflow Preventers
	40 Gallon Gas Water Heater
	Domestic Water Piping System
02 - Building 02:	Domestic Water Piping System
01 - Main Building:	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	50 kW Emergency Generator
	1,200 Amp Switchgear



Facility Condition Assessment

Charter - Nel/CPS Construction Career Academy

01 - Main Building:	500 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	400 Amp Distribution Panel
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
02 - Building 02:	75 KVA Transformer
	Panelboard - 120/208 225A
	Panelboard - 277/480 100A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Charter - Nel/CPS Construction Career Academy

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$5,774	\$504,922	\$1,055,948	\$1,566,644	51.18 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	\$164,063	-	\$164,063	5.36 %
Interior	-	-	\$299,766	\$514,778	\$228,657	\$1,043,201	34.08 %
Mechanical	-	-	-	-	-	\$0	0.00 %
Electrical	-	-	\$30,071	-	\$43,906	\$73,977	2.42 %
Plumbing	-	-	-	-	\$24,958	\$24,958	0.82 %
Fire and Life Safety	\$11,470	-	-	-	-	\$11,470	0.37 %
Technology	-	-	\$28,674	-	-	\$28,674	0.94 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$18,351	\$129,755	-	\$148,107	4.84 %
Total	\$11,470	\$0	\$382,636	\$1,313,518	\$1,353,469	\$3,061,093	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Site	-	\$1,566,644
Interior	-	\$1,043,201
Exterior	-	\$164,063

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	-	-	\$0
Barrier to Accessibility	-	-	\$238,164	-	-	\$238,164
Capital Renewal	-	-	\$61,601	\$843,551	\$231,221	\$1,136,373
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$11,470	-	\$47,025	\$469,967	\$1,122,248	\$1,650,711
Functional Deficiency	-	-	\$30,071	-	-	\$30,071
Hazardous Material	-	-	-	-	-	\$0
Technology	-	-	-	-	-	\$0
Traffic	-	-	\$5,774	-	-	\$5,774
Total	\$11,470	\$0	\$382,636	\$1,313,518	\$1,353,469	\$3,061,093

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,566,644	\$0	\$0	\$0	\$0	\$0	\$0	\$1,566,644
Roofing	\$0	\$0	\$0	\$0	\$1,500,002	\$0	\$1,500,002	\$1,500,002
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$164,063	\$0	\$0	\$0	\$0	\$0	\$0	\$164,063
Interior	\$1,043,201	\$0	\$0	\$0	\$53,503	\$21,315	\$74,818	\$1,118,019
Mechanical	\$0	\$0	\$0	\$0	\$750,001	\$0	\$750,001	\$750,001
Electrical	\$73,977	\$0	\$0	\$0	\$0	\$0	\$0	\$73,977
Plumbing	\$24,958	\$0	\$0	\$0	\$0	\$31,034	\$31,034	\$55,992
Fire and Life Safety	\$11,470	\$0	\$0	\$0	\$0	\$0	\$0	\$11,470
Technology	\$28,674	\$0	\$0	\$0	\$0	\$0	\$0	\$28,674
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$148,107	\$0	\$0	\$0	\$0	\$0	\$0	\$148,107
Total	\$3,061,093	\$0	\$0	\$0	\$2,303,506	\$52,349	\$2,355,855	\$5,416,948

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$16,621,200. For planning purposes, the total 5-year need at the Nel/CPS Construction Career Academy is \$5,416,948 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Nel/CPS Construction Career Academy facility has a 5-year FCI of 32.59%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 225 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Nel/CPS Construction Career Academy cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$276,048.



Summary of Findings

The Nel/CPS Construction Career Academy comprises 46,170 square feet and was constructed in 1980. Current deficiencies at this school total \$3,061,093. Five year capital renewal costs total \$2,355,855. The total identified need for the Nel/CPS Construction Career Academy (current deficiencies and 5-year capital renewal costs) is \$5,416,948. The 5-year FCI is 32.59%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Nel/CPS Construction Career Academy Totals	46,170	1980	\$3,061,093	\$2,355,855	\$5,416,948	32.59%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add school zone signs on East Street / Pontiac Avenue.	Traffic	2	Ea.	3	\$5,774	9324
Asphalt Paving Requires Replacement Note: Paving is cracked and in need of replacement.	Capital Renewal	112	CAR	4	\$468,836	8758
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28652
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54981
School has insufficient baseball fields. Note: School has insufficient baseball fields.	Educational Adequacy	1	Ea.	5	\$264,627	28339
School has insufficient football/soccer fields. Note: School has insufficient football/soccer fields.	Educational Adequacy	1	Ea.	5	\$120,285	28207
School has insufficient softball fields. Note: School has insufficient softball fields.	Educational Adequacy	1	Ea.	5	\$192,456	28382
School lacks a competition track. Note: School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$413,780	28291
Sub Total for System		8	items		\$1,566,644	
Sub Total for School and Site Level		8	items		\$1,566,644	

Building: 01 - Main Building

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Requires Painting (Bldg SF) Note: Metal panels require repainting.	Capital Renewal	11,691	SF	4	\$164,063	8762
Sub Total for System		1	items		\$164,063	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceiling Tiles Require Replacement Note: Cracked/sagging/stained tiles.	Capital Renewal	6,469	SF	3	\$61,601	8759
The Interior Door Hardware Requires Replacement Note: Non-ADA compliant door knobs.	Barrier to Accessibility	72	Door	3	\$238,164	8761
Ceiling Grid Requires Replacement Note: Sagging grid. Needs to be replaced.	Capital Renewal	6,469	SF	4	\$80,896	8764
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	11,326	SF	4	\$433,882	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	5	Ea.	5	\$11,470	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	31,176	SF	5	\$217,188	Rollup
Sub Total for System		6	items		\$1,043,201	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electrical Receptacles Are Inadequate And More are Needed	Functional Deficiency	50	Ea.	3	\$30,071	8765
Room Has Insufficient Electrical Outlets	Educational Adequacy	88	Ea.	5	\$43,906	Rollup
Sub Total for System		2	items		\$73,977	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks a drinking fountain.	Educational Adequacy	3	Ea.	5	\$3,326	Rollup



Facility Condition Assessment

Charter - Nel/CPS Construction Career Academy

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	5	Ea.	5	\$7,599	Rollup
The Custodial Mop Or Service Sink Is Missing And Should Be Installed	Capital Renewal	2	Ea.	5	\$14,033	8760
Note: Both floors						
Sub Total for System		3	items		\$24,958	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	1	Ea.	1	\$11,470	Rollup
Sub Total for System		1	items		\$11,470	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	5	Ea.	3	\$28,674	Rollup
Sub Total for System		1	items		\$28,674	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$18,351	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	11	Room	4	\$129,755	8763
Note: Base cabinets are delaminating and broken.						
Sub Total for System		2	items		\$148,107	
Sub Total for Building 01 - Main Building		16	items		\$1,494,449	
Total for Campus		24	items		\$3,061,093	

Buildings with no reported deficiencies

02 - Building 02



Nel/CPS Construction Career Academy - Life Cycle Summary Yrs 1-5

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Built-Up Roofing (BUR) w/ballast	38,970	SF	\$1,500,002	4
Sub Total for System		1	items	\$1,500,002	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Coverings	Vinyl/Fabric Wall Covering	5,845	SF	\$42,184	4
Carpeting	Carpet	514	SF	\$11,319	4
Suspended Plaster and	Painted ceilings	3,897	SF	\$16,500	5
Sub Total for System		3	items	\$70,003	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Water-Based Fire-Suppression	Fire Sprinkler System (Bldg.SF)	38,970	SF	\$750,001	4
Sub Total for System		1	items	\$750,001	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Non-Refrigerated Drinking Fountain	3	Ea.	\$31,034	5
Sub Total for System		1	items	\$31,034	
Sub Total for Building 01 - Main Building		6	items	\$2,351,040	

Building: 02 - Building 02

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	720	SF	\$4,815	5
Note: Painted metal structure.					
Sub Total for System		1	items	\$4,815	
Sub Total for Building 02 - Building 02		1	items	\$4,815	
Total for: Nel/CPS Construction Career Academy		7	items	\$2,355,855	



Supporting Photos



Site Aerial



Cracked Asphalt Pavement



Main Building West Elevation



Building 2 East Elevation



Main Building Front Entrance



Main Building East Elevation



Building 2 West Elevation



Building 2 North Elevation



Main Building South Elevation



Building 2 South Elevation




Main Building North Elevation



Delaminating Wood Base Cabinet



Art Room



Computer Lab



Cafeteria



Restroom



Fitness Room



Classroom



Stained and Sagging Ceiling Tiles



Exterior Door



Interior



Main Building Front Entrance



Facility Condition Assessment

Cranston - Oak Lawn School

June 2017

36 Stoneham Street, Cranston, RI 02920





Introduction

Oak Lawn School, located at 36 Stoneham Street in Cranston, Rhode Island, was built in 1950. It comprises 30,102 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Oak Lawn School serves grades 1 - 6, has 20 instructional spaces, and has an enrollment of 249. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Oak Lawn School is 297 with a resulting utilization of 84%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Oak Lawn School the 5-year need is \$4,288,623. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Oak Lawn School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Oak Lawn School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	CMU Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Roofing
----------------------------	--------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Vinyl/Fabric Wall Covering
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring



Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	1,200 MBH Copper Tube Boiler
	100 MBH Gas Furnace
	Radiant Water Heater
	10 kW Electric Unit Heater
	Electronic Heating System Controls
	3 Ton Ductless Split System
	15 Ton Condensing Unit
	Window Units
	5 Ton Package DX Unit
	10 Ton Package DX Unit
	Make-up Air Unit
	2-Pipe Hot Water Hydronic Distribution System
	1 HP or Smaller Pump
	5,000 CFM Interior AHU
	Roof Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Sump Pump
	Air Compressor (1/2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	225 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Panelboard - 400+ Amps



Facility Condition Assessment

Cranston - Oak Lawn School

01 - Main Building:	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$108,257	\$111,434	\$161,362	\$381,053	11.17 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$393,823	-	-	-	\$393,823	11.55 %
Interior	-	-	\$273,648	\$1,103,443	\$9,714	\$1,386,805	40.67 %
Mechanical	-	-	\$120,417	\$16,086	-	\$136,503	4.00 %
Electrical	-	-	\$33,078	-	\$40,185	\$73,263	2.15 %
Plumbing	-	-	-	-	\$8,711	\$8,711	0.26 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$1,020,662	-	-	\$1,020,662	29.93 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,238	-	-	\$9,238	0.27 %
Total	\$0	\$393,823	\$1,565,300	\$1,230,963	\$219,972	\$3,410,058	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,386,805
Technology	-	\$1,020,662
Exterior	-	\$393,823

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$120,417	\$30,071	-	\$150,489
Barrier to Accessibility	-	-	\$285,677	-	-	\$285,677
Capital Renewal	-	\$393,823	-	\$91,435	\$160,156	\$645,414
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$15,012	\$328,432	\$59,816	\$403,260
Functional Deficiency	-	-	\$33,078	-	-	\$33,078
Hazardous Material	-	-	-	\$781,025	-	\$781,025
Technology	-	-	\$1,014,888	-	-	\$1,014,888
Traffic	-	-	\$96,228	-	-	\$96,228
Total	\$0	\$393,823	\$1,565,300	\$1,230,963	\$219,972	\$3,410,058

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$381,053	\$0	\$0	\$0	\$0	\$0	\$0	\$381,053
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$393,823	\$0	\$0	\$0	\$0	\$0	\$0	\$393,823
Interior	\$1,386,805	\$0	\$0	\$0	\$0	\$841,864	\$841,864	\$2,228,669
Mechanical	\$136,503	\$0	\$0	\$0	\$0	\$0	\$0	\$136,503
Electrical	\$73,263	\$0	\$0	\$0	\$11,932	\$0	\$11,932	\$85,195
Plumbing	\$8,711	\$0	\$0	\$0	\$24,769	\$0	\$24,769	\$33,480
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$1,020,662	\$0	\$0	\$0	\$0	\$0	\$0	\$1,020,662
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$9,238	\$0	\$0	\$0	\$0	\$0	\$0	\$9,238
Total	\$3,410,058	\$0	\$0	\$0	\$36,701	\$841,864	\$878,565	\$4,288,623

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$10,535,700. For planning purposes, the total 5-year need at the Oak Lawn School is \$4,288,623 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Oak Lawn School facility has a 5-year FCI of 40.71%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 167 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Oak Lawn School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Oak Lawn School comprises 30,102 square feet and was constructed in 1950. Current deficiencies at this school total \$3,410,058. Five year capital renewal costs total \$878,565. The total identified need for the Oak Lawn School (current deficiencies and 5-year capital renewal costs) is \$4,288,623. The 5-year FCI is 40.71%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Oak Lawn School Totals	30,102	1950	\$3,410,058	\$878,565	\$4,288,623	40.71%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add flashing beacons to school zone speed limit signs	Traffic	2	Ea.	3	\$96,228	9334
Asphalt Paving Requires Replacement Note: Asphalt roadways have cracks and patched potholes that are deteriorating.	Capital Renewal	18	CAR	4	\$75,349	8842
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28438
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28710
Paved Play Requires Recoating And Resurfacing Note: Large cracks in play area asphalt.	Capital Renewal	4,000	SF	5	\$153,965	8841
Sub Total for System		5 items			\$369,025	
Sub Total for School and Site Level		5 items			\$369,025	

Building: 01 - Main Building

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Access Is Not ADA Compliant And Requires An ADA Compliant Ramp	Barrier to Accessibility	1	Ea.	3	\$12,029	8847
Sub Total for System		1 items			\$12,029	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Note: Single-pane windows should be replaced.	Capital Renewal	48	SF	2	\$8,564	8843
The Storefront/Curtain Wall Requires Replacement	Capital Renewal	1,920	SF Wall	2	\$385,258	8848
Sub Total for System		2 items			\$393,823	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Existing Door Hardware Is Not ADA Compliant	Barrier to Accessibility	91	Door	3	\$273,648	8846
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	25,587	SF	4	\$769,433	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	19	Ea.	4	\$5,714	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	36	LF	4	\$866	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	500	SF	4	\$5,012	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) Note: Gym	Acoustics	500	SF	4	\$30,071	19717
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	7,580	SF	4	\$292,347	Rollup
Interior Doors Require Repainting Note: Wood doors are worn and need to be sanded and refinished.	Capital Renewal	87	Door	5	\$6,192	8844
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,522	Rollup
Sub Total for System		9 items			\$1,386,805	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Unit Ventilators Are Excessively Noisy Note: All classrooms	Acoustics	18	Ea.	3	\$120,417	19716
Small HVAC Circulating Pump Requires Replacement	Capital Renewal	2	Ea.	4	\$16,086	9265
Sub Total for System		2 items			\$136,503	



Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electrical Receptacles Are Inadequate And More are Needed	Functional Deficiency	55	Ea.	3	\$33,078	8849
Room Has Insufficient Electrical Outlets	Educational Adequacy	80	Ea.	5	\$40,185	Rollup
Sub Total for System		2	items		\$73,263	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	7	Ea.	5	\$8,711	Rollup
Sub Total for System		1	items		\$8,711	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	3	\$5,774	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	48	Ea.	3	\$24,057	23502
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	18	Ea.	3	\$180,428	23506
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	18	Ea.	3	\$378,898	23515
Technology: Instructional spaces do not have local sound reinforcement.	Technology	18	Ea.	3	\$90,214	23511
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23501
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23500
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23504
Technology: Network system inadequate and/or near end of useful life	Technology	5	Ea.	3	\$40,095	23509
Technology: Network system inadequate and/or near end of useful life	Technology	12	Ea.	3	\$60,143	23510
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	30,102	SF	3	\$54,312	23508
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23505
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23507
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23503
Technology: Telecommunications Room fiber connectivity infrastructure is outdated and/or inadequate.	Technology	1	Ea.	3	\$6,616	23514
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	18	Ea.	3	\$28,868	23512
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23513
Sub Total for System		17	items		\$1,020,662	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Sub Total for System		1	items		\$9,238	
Sub Total for Building 01 - Main Building		35	items		\$3,041,034	
Total for Campus		40	items		\$3,410,058	



Oak Lawn School - Life Cycle Summary Yrs 1-5

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Operable Partitions	Foldable partition (Bldg SF)	1,600	SF Wall	\$187,067	5
	Note: 4 @ 400 sf				
Interior Coiling Doors	Overhead	1	Door	\$37,240	5
Suspended Plaster and	Painted ceilings	3,010	SF	\$12,744	5
Wall Coverings	Vinyl/Fabric Wall Covering	1,505	SF	\$10,862	5
Stone Facing	CMU Wall	12,041	SF	\$442,616	5
	Note: Glazed block				
Wall Painting and Coating	Painting/Staining (Bldg SF)	13,546	SF	\$90,594	5
Flooring Treatment	Concrete Floor - Finished	1,505	SF	\$19,834	5
Tile Flooring	Ceramic Tile	1,505	SF	\$40,907	5
	Sub Total for System	8	items	\$841,865	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Panelboard - 120/208 400A	1	Ea.	\$6,351	4
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)	4	Ea.	\$5,581	4
	Sub Total for System	2	items	\$11,932	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Classroom Lavatories	9	Ea.	\$24,769	4
	Sub Total for System	1	items	\$24,769	
	Sub Total for Building 01 - Main Building	11	items	\$878,566	
	Total for: Oak Lawn School	11	items	\$878,566	



Supporting Photos



Patched Asphalt Roadway Deteriorating



Signage



Site Aerial



Worn Paved Play Area



Facility Condition Assessment

Cranston - Oak Lawn School



Music Classroom



Exterior Brick



Restroom Finishes



Typical Classroom



Art Classroom



Playground Equipment



Library



Gymnasium / Cafeteria



Worn Finish On Wood Door



Plaque



Typical Non-Compliant Hardware



Typical Aged VCT



Single-Pane Windows



Main Entry Without ADA Access



Facility Condition Assessment

Cranston - Orchard Farms Elementary School

June 2017

1555 Scituate Avenue, Cranston, RI 02921





Introduction

Orchard Farms Elementary School, located at 1555 Scituate Avenue in Cranston, Rhode Island, was built in 2002. It comprises 67,600 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Orchard Farms Elementary School serves grades PK - 6, has 30 instructional spaces, and has an enrollment of 304. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Orchard Farms Elementary School is 364 with a resulting utilization of 84%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Orchard Farms Elementary School the 5-year need is \$5,203,273. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Orchard Farms Elementary School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Orchard Farms Elementary School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Composition Shingle Roofing
	Single Ply Roofing
	Canopy Roofing

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Moveable Interior Partition
	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Interior Wall Painting
	Quarry Tile Flooring
	Ceramic Tile Flooring
	Rubber Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Carpet
	Athletic/Sport Flooring



Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	14,000 MBH Cast Iron Boiler
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	50 MBH Steam Unit Heater
	Electronic Heating System Controls
	2 Ton Ductless Split System
	Window Units
	2-Pipe Hot Water Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	75 HP Pump
	10 HP Pump
	15 Ton DX Gas Roof Top Unit
	25 Ton DX Gas Roof Top Unit
	Ductwork
	Kitchen Exhaust Hoods
	Roof Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	4" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (1 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	300 kW Emergency Generator
	Automatic Transfer Switch
	800 Amp Switchgear
	112.5 KVA Transformer



Facility Condition Assessment

Cranston - Orchard Farms Elementary School

01 - Main Building:	225 KVA Transformer
	30 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/240 400A
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Cranston - Orchard Farms Elementary School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$96,228	\$948,425	\$64,800	\$1,109,453	24.58 %
Roofing	-	-	\$2,456	-	-	\$2,456	0.05 %
Structural	\$10,024	-	-	-	-	\$10,024	0.22 %
Exterior	-	\$2,855	-	-	-	\$2,855	0.06 %
Interior	-	-	\$664,645	\$1,101,542	-	\$1,766,187	39.14 %
Mechanical	-	-	-	\$25,583	-	\$25,583	0.57 %
Electrical	-	-	\$64,834	-	\$55,880	\$120,714	2.67 %
Plumbing	-	-	-	-	\$11,882	\$11,882	0.26 %
Fire and Life Safety	\$48,659	-	-	-	-	\$48,659	1.08 %
Technology	-	-	\$1,410,554	-	-	\$1,410,554	31.26 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,588	-	-	\$4,588	0.10 %
Total	\$58,683	\$2,855	\$2,243,304	\$2,075,550	\$132,562	\$4,512,954	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,766,187
Technology	-	\$1,410,554
Site	-	\$1,109,453

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$240,971	-	\$240,971
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	\$58,683	\$2,855	\$828,162	\$956,167	-	\$1,845,867
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$61,936	\$878,412	\$132,562	\$1,072,910
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	-	-	\$0
Technology	-	-	\$1,353,206	-	-	\$1,353,206
Traffic	-	-	-	-	-	\$0
Total	\$58,683	\$2,855	\$2,243,304	\$2,075,550	\$132,562	\$4,512,954

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,109,453	\$0	\$0	\$0	\$0	\$170,131	\$170,131	\$1,279,584
Roofing	\$2,456	\$0	\$0	\$0	\$0	\$0	\$0	\$2,456
Structural	\$10,024	\$0	\$0	\$0	\$0	\$0	\$0	\$10,024
Exterior	\$2,855	\$0	\$0	\$0	\$0	\$0	\$0	\$2,855
Interior	\$1,766,187	\$0	\$0	\$0	\$0	\$514,272	\$514,272	\$2,280,459
Mechanical	\$25,583	\$0	\$0	\$0	\$0	\$0	\$0	\$25,583
Electrical	\$120,714	\$0	\$0	\$0	\$0	\$0	\$0	\$120,714
Plumbing	\$11,882	\$0	\$0	\$0	\$0	\$5,916	\$5,916	\$17,798
Fire and Life Safety	\$48,659	\$0	\$0	\$0	\$0	\$0	\$0	\$48,659
Technology	\$1,410,554	\$0	\$0	\$0	\$0	\$0	\$0	\$1,410,554
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$4,588	\$0	\$0	\$0	\$0	\$0	\$0	\$4,588
Total	\$4,512,954	\$0	\$0	\$0	\$0	\$690,319	\$690,319	\$5,203,273

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$23,660,000. For planning purposes, the total 5-year need at the Orchard Farms Elementary School is \$5,203,273 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Orchard Farms Elementary School facility has a 5-year FCI of 21.99%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 402 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Orchard Farms Elementary School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



Summary of Findings

The Orchard Farms Elementary School comprises 67,600 square feet and was constructed in 2002. Current deficiencies at this school total \$4,512,954. Five year capital renewal costs total \$690,319. The total identified need for the Orchard Farms Elementary School (current deficiencies and 5-year capital renewal costs) is \$5,203,273. The 5-year FCI is 21.99%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Orchard Farms Elementary School Totals	67,600	2002	\$4,512,954	\$690,319	\$5,203,273	21.99%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Parking Or Roadway Curbs Require Replacement Note: Asphalt curb is crumbled and deteriorated.	Capital Renewal	1,000	LF	3	\$96,228	9828
Asphalt Paving Requires Replacement Note: Asphalt approaching end of useful life with cracks throughout, and striping no longer visible	Capital Renewal	115	CAR	4	\$481,394	9823
Asphalt Paving Requires Replacement	Capital Renewal	102	CAR	4	\$426,976	9824
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28452
Concrete Sidewalks Require Repair Note: Concrete walkway in front of building has some cracking.	Capital Renewal	50	LF	4	\$3,969	9825
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54886
Sub Total for System		6	items		\$1,109,453	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Pole Lighting Requires Repair Note: Pole lighting is no longer operable due to water infiltration. The infiltration issue should be resolved and the short repaired.	Capital Renewal	14	Ea.	3	\$64,834	9826
Sub Total for System		1	items		\$64,834	
Sub Total for School and Site Level		7	items		\$1,174,287	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Column Requires Repair Note: Column base at kindergarten entrance is spalling.	Capital Renewal	1	Ea.	3	\$2,456	9834
Sub Total for System		1	items		\$2,456	

Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Foundation Study Recommended Note: There are cracks in the CMU wall in the corridor and main entry lobby.	Capital Renewal	1	Job	1	\$10,024	9832
Sub Total for System		1	items		\$10,024	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Location: Room 128	Capital Renewal	16	SF	2	\$2,855	9829
Sub Total for System		1	items		\$2,855	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Rubber Flooring Requires Replacement Note: Seams have lifted and flooring is no longer adhered to the floor. Location: Ramp in cafeteria	Capital Renewal	160	SF	3	\$3,151	9837
The Vinyl Composition Tile Requires Replacement Note: Seams are separating and tiles are chipped and cracked.	Capital Renewal	54,690	SF	3	\$661,493	9830
Room Is Excessively Reverberant Note: Gym	Acoustics	6,400	SF	4	\$150,757	19792
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) Note: Music Space	Acoustics	1,500	SF	4	\$90,214	19793
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	21,988	SF	4	\$842,327	Rollup
The Terrazzo Flooring Requires Repair Note: There is a large crack in the terrazzo floor in girl's restroom room of the library wing.	Capital Renewal	325	SF	4	\$18,245	9831
Sub Total for System		6	items		\$1,766,187	



Facility Condition Assessment

Cranston - Orchard Farms Elementary School

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Small HVAC Circulating Pump Requires Replacement Note: Domestic water booster pumps have bad seals and are rusting and deteriorating prematurely.	Capital Renewal	2	Ea.	4	\$20,096	9833
The Exhaust Hood Requires Replacement Note: Fan is not functional. Location: Kitchen staff bathroom	Capital Renewal	1	Ea.	4	\$5,487	9836
Sub Total for System		2	items		\$25,583	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	112	Ea.	5	\$55,880	Rollup
Sub Total for System		1	items		\$55,880	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks a drinking fountain.	Educational Adequacy	7	Ea.	5	\$7,761	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		2	items		\$11,882	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Pump Requires Repair Note: Fire pump has a bad seal.	Capital Renewal	1	Ea.	1	\$48,659	9835
Sub Total for System		1	items		\$48,659	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	10	Ea.	3	\$57,348	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	148	Ea.	3	\$74,176	23527
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	26	Ea.	3	\$260,618	23519
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	26	Ea.	3	\$547,297	23526
Technology: Instructional spaces do not have local sound reinforcement.	Technology	26	Ea.	3	\$130,309	23523
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23517
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$22,854	23516
Technology: Network system inadequate and/or near end of useful life	Technology	8	Ea.	3	\$64,152	23521
Technology: Network system inadequate and/or near end of useful life	Technology	28	Ea.	3	\$140,333	23522
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23518
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	26	Ea.	3	\$41,699	23524
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23525
Sub Total for System		12	items		\$1,410,554	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,588	Rollup
Sub Total for System		1	items		\$4,588	
Sub Total for Building 01 - Main Building		28	items		\$3,338,668	
Total for Campus		35	items		\$4,512,954	



Orchard Farms Elementary School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Wood	680	LF	\$170,131	5
		Sub Total for System		\$170,131	
		1	items		
		Sub Total for Building -		\$170,131	
		1	items		

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings	3,380	SF	\$14,311	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	64,220	SF	\$429,493	5
Carpeting	Carpet	3,200	SF	\$70,468	5
		Sub Total for System		\$514,273	
		3	items		

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 75 Gallons	1	Ea.	\$5,916	5
		Sub Total for System		\$5,916	
		1	items		
		Sub Total for Building 01 - Main Building		\$520,189	
		4	items		
		Total for: Orchard Farms Elementary School		\$690,320	
		5	items		



Supporting Photos



Cracked Concrete Walkway



Restroom Fixtures And Finishes



Gymnasium



Chipped And Separating VCT



Facility Condition Assessment

Cranston - Orchard Farms Elementary School



VCT Flooring Lifting At Seams



Elevation



Cracked CMU



Cracked Terrazzo Flooring



Entrance



Deteriorated Asphalt Curb



Facility Condition Assessment

Cranston - Orchard Farms Elementary School



Art Room



Library



Spalled Column Base



Entry Elevation



Cafeteria



Typical Classroom



Facility Condition Assessment

Cranston - Orchard Farms Elementary School



Damaged Window



Building Signage



Plaque



Cracked Asphalt



Site Aerial



Cracked CMU



Facility Condition Assessment

Cranston - Orchard Farms Elementary School



Library



Leaking Pumps



Cracked CMU



Leaking Pump



Lifting Rubber Floor



Facility Condition Assessment

Cranston - Park View Middle School

June 2017

25 Park View Boulevard, Cranston, RI 02910





Introduction

Park View Middle School, located at 25 Park View Boulevard in Cranston, Rhode Island, was built in 1954. It comprises 151,200 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Park View Middle School serves grades 7 - 8, has 47 instructional spaces, and has an enrollment of 531. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Park View Middle School is 841 with a resulting utilization of 63%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Park View Middle School the 5-year need is \$14,650,394. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Park View Middle School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Park View Middle School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	CMU Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Stucco Exterior Wall
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Membrane Ballasted Roofing
----------------------------	---------------------------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Wood Wall Paneling
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring



01 - Main Building:	Terrazzo Flooring
	Carpet

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	400 MBH Cast Iron Steam Boiler
	400 MBH Cast Iron Water Boiler
	120 GPM Steam to Water Heat Exchanger
	Steam Condensate Receiver, Tank and Pump
	36 MBH Steam Unit Heater
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	Radiant Steam Heater
	DDC Heating System Controls
	3 Ton Ductless Split System
	1 Ton Heat Pump
	3 Ton Heat Pump
	50,000 CFM Interior AHU
	5 Ton Package DX Unit
	5 HP VFD
	1 HP or Smaller Pump
	2-Pipe Steam Hydronic Distribution System
	Ductwork
	Kitchen Exhaust Hoods
	Roof Exhaust Fan
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	Wall Exhaust Fan

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	200 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories



01 - Main Building:	Showers
	Toilets
	Urinals
	Sump Pump
	Air Compressor (1/2 hp)
	Air Compressor (2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	300 kW Emergency Generator
	2,000 Amp Switchgear
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	400 Amp Distribution Panel
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$78,835	\$533,006	-	\$611,840	8.31 %
Roofing	-	\$433,012	\$5,413	-	-	\$438,425	5.95 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	\$1,323	-	\$1,323	0.02 %
Interior	-	-	\$1,373,435	\$1,199,005	\$29,853	\$2,602,293	35.33 %
Mechanical	-	\$50,049	-	-	\$3,300	\$53,348	0.72 %
Electrical	\$8,577	\$235,859	-	-	\$82,379	\$326,815	4.44 %
Plumbing	-	-	\$173,269	\$2,005	\$47,369	\$222,643	3.02 %
Fire and Life Safety	\$69,284	-	-	-	-	\$69,284	0.94 %
Technology	-	-	\$2,509,546	-	-	\$2,509,546	34.07 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,619	\$451,610	\$74,480	\$530,709	7.20 %
Total	\$77,861	\$718,920	\$4,145,117	\$2,186,948	\$237,381	\$7,366,227	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$2,602,293
Technology	-	\$2,509,546
Site	-	\$611,840

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$161,122	-	\$161,122
Barrier to Accessibility	-	-	\$896,424	-	-	\$896,424
Capital Renewal	-	\$718,920	\$728,754	\$951,858	\$22,587	\$2,422,119
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$77,861	-	\$85,450	\$36,086	\$214,794	\$414,191
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$1,037,883	-	\$1,037,883
Technology	-	-	\$2,428,715	-	-	\$2,428,715
Traffic	-	-	\$5,774	-	-	\$5,774
Total	\$77,861	\$718,920	\$4,145,117	\$2,186,948	\$237,381	\$7,366,227

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$611,840	\$0	\$0	\$0	\$0	\$9,298	\$9,298	\$621,138
Roofing	\$438,425	\$0	\$0	\$0	\$0	\$615,821	\$615,821	\$1,054,246
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$1,323	\$0	\$0	\$0	\$0	\$0	\$0	\$1,323
Interior	\$2,602,293	\$0	\$0	\$595,144	\$0	\$136,925	\$732,069	\$3,334,362
Mechanical	\$53,348	\$0	\$0	\$5,509,994	\$149,812	\$5,421	\$5,665,227	\$5,718,576
Electrical	\$326,815	\$0	\$0	\$73,220	\$0	\$0	\$73,220	\$400,035
Plumbing	\$222,643	\$0	\$25,758	\$51,896	\$104,417	\$6,461	\$188,532	\$411,175
Fire and Life Safety	\$69,284	\$0	\$0	\$0	\$0	\$0	\$0	\$69,284
Technology	\$2,509,546	\$0	\$0	\$0	\$0	\$0	\$0	\$2,509,546
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$530,709	\$0	\$0	\$0	\$0	\$0	\$0	\$530,709
Total	\$7,366,227	\$0	\$25,758	\$6,230,254	\$254,229	\$773,926	\$7,284,167	\$14,650,394

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$49,896,000. For planning purposes, the total 5-year need at the Park View Middle School is \$14,650,394 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Park View Middle School facility has a 5-year FCI of 29.36%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 831 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Park View Middle School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$2,491,592.



Summary of Findings

The Park View Middle School comprises 151,200 square feet and was constructed in 1954. Current deficiencies at this school total \$7,366,227. Five year capital renewal costs total \$7,284,167. The total identified need for the Park View Middle School (current deficiencies and 5-year capital renewal costs) is \$14,650,394. The 5-year FCI is 29.36%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Park View Middle School Totals	151,200	1954	\$7,366,227	\$7,284,167	\$14,650,394	29.36%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement Location: Front entry	Capital Renewal	200	SF	3	\$5,172	11361
Crosswalk Requires Repainting Note: Repaint crosswalks at intersection of Park View Blvd and Park Ave	Traffic	4	Ea.	3	\$3,849	11655
Crosswalk: Needs to be added Note: Add crosswalks at intersection of Park View Blvd and Eldorado St	Traffic	2	Ea.	3	\$1,925	11654
Retaining Wall Requires Repair Note: Bricks retaining wall is buckling. Mortar and bricks are missing in various locations.	Capital Renewal	800	SF	3	\$67,889	11375
Asphalt Paving Requires Replacement Note: Pavement is cracked with potholes and substantial pooling of water.	Capital Renewal	73	CAR	4	\$305,581	11359
Asphalt Paving Requires Replacement Note: Asphalt roadway is cracked and deteriorated with potholes and curb damage.	Capital Renewal	30	CAR	4	\$125,581	11360
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28443
Fencing Requires Replacement (4' Chain Link Fence) Note: Fence is rusted and falling.	Capital Renewal	180	LF	4	\$14,723	11358
Fencing Requires Replacement (8' Chain Link Fence) Note: Fence is rusted and falling.	Capital Renewal	600	LF	4	\$51,035	11357
Sub Total for System		9	items		\$611,840	
Sub Total for School and Site Level		9	items		\$611,840	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Single-Ply Membrane Roof Covering Requires Replacement Note: There is excessive ponding on roof. The membrane is aged and worn. Warranty expired 2013.	Capital Renewal	31,999	SF	2	\$433,012	11365
Concrete Column Requires Repair Location: Exterior west side at maintenance garage entrance	Capital Renewal	2	Ea.	3	\$4,912	11374
The Roof Drains Require Cleaning Note: Roof drains are full of debris. Some have vegetation growing in them.	Capital Renewal	12	Ea.	3	\$501	11364
Sub Total for System		3	items		\$438,425	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Handrail Requires Repainting Location: Pool area and front entry exterior	Capital Renewal	120	LF	4	\$1,323	11372
Sub Total for System		1	items		\$1,323	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Hardware Requires Re-Keying Note: There is no master key for interior doors. Other 271 doors rekeyed with hardware replacement.	Capital Renewal	33	Ea.	3	\$14,885	11373
The Interior Door Hardware Requires Replacement Note: Door hardware is poorly functioning and non-compliant.	Barrier to Accessibility	271	Door	3	\$896,424	11370
The Vinyl Composition Tile Requires Replacement	Capital Renewal	38,207	SF	3	\$462,126	11367
Asbestos 9x9 Tile is Present. Limited Areas of Lifting or Broken Tiles Exist	Hazardous Material	25,316	SF	4	\$761,284	Rollup
Caulking - significant areas of broken pieces &/or deteriorating caulk	Hazardous Material	320	LF	4	\$6,415	Rollup
Paint (probable pre-1978 in base (layers(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	363	Ea.	4	\$109,159	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	3,271	LF	4	\$78,690	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	6,292	SF	4	\$63,069	Rollup



Facility Condition Assessment

Cranston - Park View Middle School

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - linear feet)	Hazardous Material	80	LF	4	\$1,925	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	80	SF	4	\$802	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	1	SF	4	\$10	Rollup
Paint (probable pre-1978 in base layer(s)) -large areas (> 10 sq. ft.)of peeling/damage & area in active use-adults only (measurement unit - square feet)	Hazardous Material	1,608	SF	4	\$16,118	Rollup
Room Is Excessively Reverberant Note: Gym	Acoustics	6,840	SF	4	\$161,122	19795
Wall/ceiling materials - area < 9 sq. ft. AND in children-accessible area	Hazardous Material	1	SF	4	\$10	Rollup
Wall/ceiling materials -large areas (> 10 sq. ft.) of damage & area in active use-adults only	Hazardous Material	40	SF	4	\$401	Rollup
Interior Doors Require Repainting Note: Finish on wood doors is worn. They should be sanded and refinished.	Capital Renewal	271	Door	5	\$19,287	11366
Room lacks appropriate sound control.	Educational Adequacy	300	SF	5	\$10,566	Rollup
Sub Total for System		17 items			\$2,602,293	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Steam Heat Exchanger Requires Replacement	Capital Renewal	1	Ea.	2	\$6,014	11376
Steam/HW Unit Heater Requires Replacement	Capital Renewal	4	Ea.	2	\$6,944	11581
The Fin Tube Water Radiant Heater Requires Replacement	Capital Renewal	21	Ea.	2	\$37,090	11580
Remove Abandoned Equipment Note: Old boiler fuel pump should be removed. Location: Boiler room	Capital Renewal	1	Ea.	5	\$3,300	11378
Sub Total for System		4 items			\$53,348	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	6	Ea.	1	\$8,577	Rollup
The Distribution Panel Requires Replacement	Capital Renewal	2	Ea.	2	\$54,128	11582
The Panelboard Requires Replacement	Capital Renewal	20	Ea.	2	\$102,242	11583
The Panelboard Requires Replacement	Capital Renewal	13	Ea.	2	\$79,488	11584
Room Has Insufficient Electrical Outlets	Educational Adequacy	164	Ea.	5	\$82,379	Rollup
Sub Total for System		5 items			\$326,815	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Sump Pump Requires Replacement	Capital Renewal	1	Ea.	3	\$1,528	11579
The Non-Refrigerated Drinking Fountain Requires Repair Location: Main entry and swimming pool area	Capital Renewal	2	Ea.	3	\$3,342	11369
The Showers Plumbing Fixtures Require Replacement	Capital Renewal	21	Ea.	3	\$168,399	11578
The Refrigerated Water Cooler Requires Repair Location: Second floor	Capital Renewal	2	Ea.	4	\$2,005	11371
Room lacks a drinking fountain.	Educational Adequacy	3	Ea.	5	\$3,349	Rollup
Room lacks a private shower area.	Educational Adequacy	1	Ea.	5	\$10,360	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	22	Ea.	5	\$33,661	Rollup
Sub Total for System		7 items			\$222,643	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	6	Ea.	1	\$69,284	Rollup
Sub Total for System		1 items			\$69,284	



Facility Condition Assessment

Cranston - Park View Middle School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	14	Ea.	3	\$80,832	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	456	Ea.	3	\$228,542	23560
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	52	Ea.	3	\$1,094,594	23563
Technology: Instructional spaces do not have local sound reinforcement.	Technology	52	Ea.	3	\$260,618	23564
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23548
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23551
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23555
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23558
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23554
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,642	23557
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23549
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23552
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23545
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23547
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23550
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23544
Technology: Network system inadequate and/or near end of useful life	Technology	10	Ea.	3	\$80,190	23566
Technology: Network system inadequate and/or near end of useful life	Technology	26	Ea.	3	\$130,309	23567
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	151,200	SF	3	\$272,806	23565
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,019	23546
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23553
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23556
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,012	23559
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	52	Ea.	3	\$83,398	23562
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23561
Sub Total for System		25	items		\$2,509,546	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,619	Rollup



Facility Condition Assessment

Cranston - Park View Middle School

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Bleachers Require Replacement Note: Concrete risers and steel brackets have deteriorated from humidity in the pool area.	Capital Renewal	150	Seat	4	\$97,732	11362
Replace Cabinetry In Classes/Labs Note: Cabinetry is worn, chipped, and peeling.	Capital Renewal	30	Room	4	\$353,878	11377
Room lacks an appropriate refrigerator.	Educational Adequacy	7	Ea.	5	\$60,624	Rollup
The room lacks a washer and/or dryer.	Educational Adequacy	1	Ea.	5	\$13,857	Rollup
	Sub Total for System	5	items		\$530,709	
	Sub Total for Building 01 - Main Building	68	items		\$6,754,387	
	Total for Campus	77	items		\$7,366,227	



Park View Middle School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Pedestrian Pavement	Sidewalks - Asphalt	1,075	SF	\$9,298	5
Sub Total for System		1	items	\$9,298	
Sub Total for Building -		1	items	\$9,298	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Single Ply Membrane Ballasted Roof	15,999	SF	\$615,821	5
Sub Total for System		1	items	\$615,821	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings	25,925	SF	\$109,767	3
Wall Painting and Coating	Painting/Staining (Bldg SF)	72,576	SF	\$485,377	3
Interior Coiling Doors	Overhead	1	Door	\$37,240	5
Interior Swinging Doors	Steel	23	Door	\$99,685	5
Sub Total for System		4	items	\$732,069	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$16,159	3
Decentralized Heating Equipment	Radiant Heater - Radiator Steam	2	Ea.	\$10,458	3
Heat Generation	Boiler - Cast Iron - Steam (400 MBH)	2	Ea.	\$62,644	3
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	112	Ea.	\$1,917,539	3
Decentralized Cooling	AHU 50,000 CFM Interior	12	Ea.	\$3,503,194	3
Exhaust Air	Roof Exhaust Fan	9	Ea.	\$47,408	4
Decentralized Cooling	Ductless Split System (3 Ton)	13	Ea.	\$102,404	4
Exhaust Air	Wall Exhaust Fan	2	Ea.	\$5,421	5
Note: Kitchen					
Sub Total for System		8	items	\$5,665,227	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Electrical Service	Switchgear - Main Dist Panel (2000 Amps)	1	Ea.	\$73,220	3
Note: 208/120 V					
Sub Total for System		1	items	\$73,220	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Lavatories	8	Ea.	\$25,758	2
Plumbing Fixtures	Mop/Service Sinks	8	Ea.	\$20,862	3
Plumbing Fixtures	Non-Refrigerated Drinking Fountain	3	Ea.	\$31,034	3
Plumbing Fixtures	Restroom Lavatories	30	Ea.	\$96,594	4
Plumbing Fixtures	Mop/Service Sinks	3	Ea.	\$7,823	4
Note: Kitchen					
Compressed-Air Systems	Air Compressor (2 hp)	1	Ea.	\$6,461	5
Sub Total for System		6	items	\$188,532	
Sub Total for Building 01 - Main Building		20	items	\$7,274,868	
Total for: Park View Middle School		21	items	\$7,284,166	



Supporting Photos



Damaged Bleachers



Vegetation In Roof Drain



Conductor Box With Debris



Weathered Roof With Ponding



Facility Condition Assessment

Cranston - Park View Middle School



Ponding On Roof



Interior Wood Door



Site Aerial



Auditorium



Small Gym



Music Room



Facility Condition Assessment

Cranston - Park View Middle School



Large Gym



Lobby Finishes



Typical Classroom



Exterior Finishes



Library



Cafeteria



Facility Condition Assessment

Cranston - Park View Middle School



Restroom Finishes



Art Room



Pool



Computer Lab



Hallway Finishes




Main Entry




Exterior Windows



Science Room



Separating VCT Flooring



Non-Compliant Door Hardware



Chipped And Worn Handrail



Damaged Column



Facility Condition Assessment

Cranston - Park View Middle School



Retaining Wall



Typical Aged And Chipped Cabinetry



Abandoned Fuel Pump



Rusted Exhaust Fan



Plaque



Asphalt Cracks And Potholes



Facility Condition Assessment

Cranston - Park View Middle School



Cracked And Spalled Concrete



Parking Lot Pavement



Deteriorated Asphalt Roadway



Drinking Fountain



Art Room Sink



Service Sink



Facility Condition Assessment

Cranston - Park View Middle School



Classroom Lavatory



Aged Panel



Damaged Heater



Aged Panelboard



Drinking Fountain



Facility Condition Assessment

Cranston - Stadium School

June 2017

100 Crescent Avenue, Cranston, RI 02910





Introduction

Stadium School, located at 100 Crescent Avenue in Cranston, Rhode Island, was built in 1955. It comprises 34,412 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Stadium School serves grades PK - 6, has 18 instructional spaces, and has an enrollment of 349. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Stadium School is 303 with a resulting utilization of 115%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Stadium School the 5-year need is \$5,055,371. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Stadium School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Stadium School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
----------------------------	--------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	Steam Condensate Receiver, Tank and Pump
	Steam/Hot Water Heating Unit Vent
	Radiant Steam Heater
	Pneumatic Heating System Controls
	Window Units
	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump



01 - Main Building:	2,000 CFM Interior AHU
	Roof Exhaust Fan
	Supply Fan
	Wall Exhaust Fan

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Sump Pump
	Air Compressor (1/2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Panelboard - 400+ Amps
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$5,774	\$182,837	\$72,198	\$260,808	6.01 %
Roofing	-	-	\$334	-	-	\$334	0.01 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$330,439	-	-	-	\$330,439	7.62 %
Interior	-	-	-	\$1,237,610	\$145,634	\$1,383,244	31.88 %
Mechanical	-	\$846,901	\$101,617	\$280,983	\$3,300	\$1,232,800	28.41 %
Electrical	-	\$56,372	-	-	\$34,130	\$90,502	2.09 %
Plumbing	-	-	\$14,140	\$8,149	\$4,121	\$26,410	0.61 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$844,321	-	-	\$844,321	19.46 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,619	\$165,143	-	\$169,762	3.91 %
Total	\$0	\$1,233,711	\$970,804	\$1,874,722	\$259,382	\$4,338,620	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,383,244
Mechanical	-	\$1,232,800
Technology	-	\$844,321

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$86,968	-	-	\$86,968
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$1,233,711	\$29,122	\$876,433	\$146,639	\$2,285,906
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$10,393	\$36,086	\$112,743	\$159,221
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$962,204	-	\$962,204
Technology	-	-	\$838,548	-	-	\$838,548
Traffic	-	-	\$5,774	-	-	\$5,774
Total	\$0	\$1,233,711	\$970,804	\$1,874,722	\$259,382	\$4,338,620

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$260,808	\$0	\$0	\$0	\$0	\$139,545	\$139,545	\$400,353
Roofing	\$334	\$0	\$0	\$0	\$0	\$440,416	\$440,416	\$440,750
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$330,439	\$0	\$0	\$0	\$0	\$0	\$0	\$330,439
Interior	\$1,383,244	\$0	\$0	\$0	\$0	\$115,071	\$115,071	\$1,498,315
Mechanical	\$1,232,800	\$0	\$0	\$0	\$0	\$15,803	\$15,803	\$1,248,603
Electrical	\$90,502	\$0	\$0	\$0	\$0	\$0	\$0	\$90,502
Plumbing	\$26,410	\$0	\$0	\$0	\$0	\$5,916	\$5,916	\$32,326
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$844,321	\$0	\$0	\$0	\$0	\$0	\$0	\$844,321
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$169,762	\$0	\$0	\$0	\$0	\$0	\$0	\$169,762
Total	\$4,338,620	\$0	\$0	\$0	\$0	\$716,751	\$716,751	\$5,055,371

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$12,534,200. For planning purposes, the total 5-year need at the Stadium School is \$5,055,371 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Stadium School facility has a 5-year FCI of 40.33%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 199 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Stadium School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$366,660.



Summary of Findings

The Stadium School comprises 34,412 square feet and was constructed in 1955. Current deficiencies at this school total \$4,338,620. Five year capital renewal costs total \$716,751. The total identified need for the Stadium School (current deficiencies and 5-year capital renewal costs) is \$5,055,371. The 5-year FCI is 40.33%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Stadium School Totals	34,412	1955	\$4,338,620	\$716,751	\$5,055,371	40.33%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add school zone signs on adjacent street if none were added with other recent improvements	Traffic	2	Ea.	3	\$5,774	16942
Asphalt Paving Requires Replacement Note: Deteriorated parking lot pavement.	Capital Renewal	29	CAR	4	\$121,395	13003
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28444
Fencing Requires Replacement (4' Chain Link Fence) Note: Parking lot fence is deteriorating.	Capital Renewal	280	LF	4	\$22,902	13001
Fencing Requires Replacement (4' Chain Link Fence) Note: Rusted fence by stairs.	Capital Renewal	30	LF	4	\$2,454	13002
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28715
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54882
Sub Total for System		7	items		\$260,808	
Sub Total for School and Site Level		7	items		\$260,808	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Roof Drains Require Cleaning	Capital Renewal	8	Ea.	3	\$334	13006
Sub Total for System		1	items		\$334	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Note: Single pane glass and kalwall, poorly functioning.	Capital Renewal	1,852	SF	2	\$330,439	13005
Sub Total for System		1	items		\$330,439	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Adhered Acoustical Ceiling Tile Requires Replacement Note: Tiles falling from ceiling, require frequent replacement	Capital Renewal	24,088	SF	4	\$275,406	13025
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	30,971	SF	4	\$931,337	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	32	Ea.	4	\$9,623	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	406	LF	4	\$9,767	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	1,145	SF	4	\$11,477	Rollup
Interior Doors Require Repair Note: Wood doors need refinishing.	Capital Renewal	143	Door	5	\$143,340	13007
Sub Total for System		6	items		\$1,380,950	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent Note: Unit vent is outdated and obsolete.	Capital Renewal	4	Ea.	2	\$71,337	13024
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	2	\$45,482	13015
The Boiler HVAC Component Requires Replacement Note: The boiler is obsolete.	Capital Renewal	2	Ea.	2	\$359,203	13016
The Steam Condensate Receiver Requires Replacement	Capital Renewal	1	Ea.	2	\$370,879	13020
The Large Diameter Exhausts/Hoods Require Replacement Note: Supply fan requires replacement.	Capital Renewal	1	Ea.	3	\$14,649	13010



Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Unit Ventilators Are Excessively Noisy Location: All learning spaces	Acoustics	13	Ea.	3	\$86,968	27973
Exhaust Fan Ventilation Requires Replacement Note: Wall exhaust fan is obsolete.	Capital Renewal	3	Ea.	4	\$8,470	13011
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls Note: Controls are obsolete.	Capital Renewal	34,412	SF	4	\$245,078	13021
The Exhaust Hood Requires Replacement Note: The exhaust hood is deteriorated and outdated.	Capital Renewal	5	Ea.	4	\$27,435	13023
Remove Abandoned Equipment Note: Remove vacuum.	Capital Renewal	1	Ea.	5	\$3,300	16328
Sub Total for System		10	items		\$1,232,800	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electrical Disconnect Requires Replacement	Capital Renewal	1	Ea.	2	\$1,933	13009
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$5,112	13017
The Panelboard Requires Replacement	Capital Renewal	5	Ea.	2	\$30,572	13018
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$18,754	13019
Room Has Insufficient Electrical Outlets	Educational Adequacy	60	Ea.	5	\$30,139	Rollup
Sub Total for System		5	items		\$86,510	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Sump Pump Requires Replacement Note: Sump pump is deteriorated.	Capital Renewal	1	Ea.	3	\$1,528	13014
The Urinal Plumbing Fixtures Require Replacement Note: Outdated urinals require replacement.	Capital Renewal	9	Ea.	3	\$12,612	13013
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	3	Ea.	4	\$8,149	13012
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		4	items		\$26,410	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	3	\$5,774	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$48,114	23307
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	22	Ea.	3	\$220,523	23312
Technology: Instructional spaces do not have local sound reinforcement.	Technology	22	Ea.	3	\$110,261	23317
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23306
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23304
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23305
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	96	Ea.	3	\$43,303	23310
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	22	Ea.	3	\$9,924	23308
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23315
Technology: Network system inadequate and/or near end of useful life	Technology	16	Ea.	3	\$80,190	23316
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	48	Ea.	3	\$24,057	23309
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	35,756	SF	3	\$64,514	23314



Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23311
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23313
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	22	Ea.	3	\$35,284	23318
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23319
Sub Total for System		17	items		\$844,321	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,619	Rollup
Replace Cabinetry In Classes/Labs Note: Cabinets are damaged.	Capital Renewal	14	Room	4	\$165,143	13022
Sub Total for System		2	items		\$169,762	
Sub Total for Building 01 - Main Building		46	items		\$4,071,526	

Building: 02 - Portable A

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,294	Rollup
Sub Total for System		1	items		\$2,294	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$3,991	Rollup
Sub Total for System		1	items		\$3,991	
Sub Total for Building 02 - Portable A		2	items		\$6,285	
Total for Campus		55	items		\$4,338,620	



Stadium School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Pedestrian Pavement	Sidewalks - Concrete	6,745	SF	\$139,545	5
Sub Total for System		1	items	\$139,545	
Sub Total for Building -		1	items	\$139,545	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	EPDM - Rubber Roofing Material	34,412	SF	\$440,416	5
Sub Total for System		1	items	\$440,416	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	17,206	SF	\$115,071	5
Sub Total for System		1	items	\$115,071	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exhaust Air	Roof Exhaust Fan	3	Ea.	\$15,803	5
Sub Total for System		1	items	\$15,803	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 75 Gallons	1	Ea.	\$5,916	5
Sub Total for System		1	items	\$5,916	
Sub Total for Building 01 - Main Building		4	items	\$577,206	
Total for: Stadium School		5	items	\$716,750	



Supporting Photos



Boiler



Roof Drain




Obsolete Panelboard



Air Handling Unit



Electrical Disconnect



Roof Exhaust Fan



Wall Exhaust Fan



Unit Vent



Outdated Urinals



Custodial Sink



Obsolete Panelboard



Sump Pump



Site Aerial



Supply Fan



Typical Restroom



Front Entry



Facility Condition Assessment

Cranston - Stadium School



Northwest View



Auditorium



West View



North View



ADA Stall



Southeast View



Facility Condition Assessment

Cranston - Stadium School



South View



Typical Classroom



Northeast View



East View



North View



Cafeteria/Gym



Auditorium



Library



Typical Classroom



Cafeteria/Gym



Roof Drain



Roof Drain



Interior Doors Require Refinishing



Vinyl Flooring In Classrooms



Vinyl Flooring In Cafe



Classroom Cabinets



Classroom Cabinets



Acoustical Tiles Require Replacement



Pneumatic Controls



Facility Condition Assessment

Cranston - Stone Hill School

June 2017

21 Village Avenue, Cranston, RI 02920





Introduction

Stone Hill School, located at 21 Village Avenue in Cranston, Rhode Island, was built in 1962. It comprises 36,960 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Stone Hill School serves grades PK - 6, has 19 instructional spaces, and has an enrollment of 312. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Stone Hill School is 251 with a resulting utilization of 124%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Stone Hill School the 5-year need is \$5,184,037. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Stone Hill School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Stone Hill School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
---------------------	--------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Ceramic Tile Wall
	Wood Wall Paneling
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	Finned Wall Radiator



01 - Main Building:	Steam/Hot Water Heating Unit Vent
	20 MBH Steam Unit Heater
	DDC Heating System Controls
	Window Units
	5 HP VFD
	1 HP or Smaller Pump
	5 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	Roof Exhaust Fan
	Kitchen Exhaust Hoods

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 120/240 225A
	Panelboard - 277/480 100A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$15,396	\$174,383	\$72,198	\$261,977	6.47 %
Roofing	-	\$66,658	-	-	-	\$66,658	1.65 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$586,637	-	-	-	\$586,637	14.50 %
Interior	-	-	\$393,629	\$532,575	\$8,151	\$934,354	23.09 %
Mechanical	-	\$715,888	-	-	-	\$715,888	17.69 %
Electrical	-	-	-	-	\$38,176	\$38,176	0.94 %
Plumbing	-	-	-	\$5,433	\$9,702	\$15,135	0.37 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$1,423,098	-	-	\$1,423,098	35.17 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,619	-	-	\$4,619	0.11 %
Total	\$0	\$1,369,183	\$1,836,742	\$712,391	\$128,226	\$4,046,542	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Technology	-	\$1,423,098
Interior	-	\$934,354
Mechanical	-	\$715,888

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$72,171	-	\$72,171
Barrier to Accessibility	-	-	\$16,936	-	-	\$16,936
Capital Renewal	-	\$1,369,183	\$376,693	\$542,252	\$8,151	\$2,296,278
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$16,166	\$36,086	\$120,076	\$172,327
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$61,883	-	\$61,883
Technology	-	-	\$1,411,551	-	-	\$1,411,551
Traffic	-	-	\$15,396	-	-	\$15,396
Total	\$0	\$1,369,183	\$1,836,742	\$712,391	\$128,226	\$4,046,542

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$261,977	\$0	\$0	\$0	\$90,418	\$495,627	\$586,045	\$848,022
Roofing	\$66,658	\$0	\$0	\$0	\$0	\$0	\$0	\$66,658
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$586,637	\$0	\$0	\$0	\$0	\$0	\$0	\$586,637
Interior	\$934,354	\$0	\$0	\$0	\$123,591	\$320,495	\$444,086	\$1,378,440
Mechanical	\$715,888	\$0	\$0	\$0	\$17,102	\$0	\$17,102	\$732,990
Electrical	\$38,176	\$0	\$0	\$0	\$0	\$90,262	\$90,262	\$128,438
Plumbing	\$15,135	\$0	\$0	\$0	\$0	\$0	\$0	\$15,135
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$1,423,098	\$0	\$0	\$0	\$0	\$0	\$0	\$1,423,098
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$4,619	\$0	\$0	\$0	\$0	\$0	\$0	\$4,619
Total	\$4,046,542	\$0	\$0	\$0	\$231,111	\$906,384	\$1,137,495	\$5,184,037

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$12,936,000. For planning purposes, the total 5-year need at the Stone Hill School is \$5,184,037 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Stone Hill School facility has a 5-year FCI of 40.07%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 205 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Stone Hill School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$388,584.



Summary of Findings

The Stone Hill School comprises 36,960 square feet and was constructed in 1962. Current deficiencies at this school total \$4,046,542. Five year capital renewal costs total \$1,137,495. The total identified need for the Stone Hill School (current deficiencies and 5-year capital renewal costs) is \$5,184,037. The 5-year FCI is 40.07%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Stone Hill School Totals	36,960	1962	\$4,046,542	\$1,137,495	\$5,184,037	40.07%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk: Needs to be added Note: Add crosswalks in surrounding area	Traffic	4	Ea.	3	\$3,849	16956
Traffic Signage Is Required Note: Add school zone signs and flashing beacon on adjacent street	Traffic	4	Ea.	3	\$11,547	16955
Asphalt Paving Requires Resurfacing Note: Roadway, parking and play area surfaces have many cracks.	Capital Renewal	61,250	SF	4	\$81,042	13027
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28448
Fencing Requires Replacement (4' Chain Link Fence)	Capital Renewal	700	LF	4	\$57,256	13026
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28718
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54883
Sub Total for System		7	items		\$261,977	
Sub Total for School and Site Level		7	items		\$261,977	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF) Note: Cafe roof is deteriorating, evidence of leaks in ceiling tile. Warranty expired 2004.	Capital Renewal	5,000	SF	2	\$66,658	13035
Sub Total for System		1	items		\$66,658	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement Note: Window is single pane glass. Extreme heat and air infiltration. Aluminum is corroding and glass is cloudy. Some glass has been replaced with plexiglass panels.	Capital Renewal	3,018	SF	2	\$538,480	13028
The Storefront/Curtain Wall Requires Replacement Note: Storefront frame is corroded at sill.	Capital Renewal	240	SF Wall	2	\$48,157	13033
Sub Total for System		2	items		\$586,637	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceiling Tiles Require Replacement Note: Cafe/gym ceiling tiles are damaged from roof leak.	Capital Renewal	1,000	SF	3	\$9,523	13029
The Interior Door Hardware Requires Replacement	Capital Renewal	111	Door	3	\$367,170	13030
Toilet Stall Not Compliant	Barrier to Accessibility	4	Ea.	3	\$16,936	13032
Adhered Acoustical Ceiling Tile Requires Replacement	Capital Renewal	29,568	SF	4	\$338,061	13038
Interior Wood Walls Require Replacement Note: Panels are damaged.	Capital Renewal	6,283	SF	4	\$60,460	13037
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	1,490	SF	4	\$44,806	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	27	Ea.	4	\$8,119	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	24	LF	4	\$577	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	836	SF	4	\$8,380	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) Note: Cafeteria	Acoustics	1,200	SF	4	\$72,171	19870
The Gypsum Board Ceilings Require Repainting	Capital Renewal	1,848	SF	5	\$8,151	Rollup
Sub Total for System		11	items		\$934,354	



Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent	Capital Renewal	20	Ea.	2	\$356,685	13036
The Boiler HVAC Component Requires Replacement	Capital Renewal	2	Ea.	2	\$359,203	13034
Note: Boilers are outdated.						
Sub Total for System		2	items		\$715,888	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	76	Ea.	5	\$38,176	Rollup
Sub Total for System		1	items		\$38,176	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	2	Ea.	4	\$5,433	13031
Note: Damaged custodial sink.						
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		3	items		\$15,135	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,547	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	120	Ea.	3	\$60,143	23381
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	69	Ea.	3	\$691,639	23386
Technology: Instructional spaces do not have local sound reinforcement.	Technology	23	Ea.	3	\$115,273	23391
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23378
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23377
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23379
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23376
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23374
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23375
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	99	Ea.	3	\$44,656	23384
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	46	Ea.	3	\$20,749	23382
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23389
Technology: Network system inadequate and/or near end of useful life	Technology	16	Ea.	3	\$80,190	23390
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	72	Ea.	3	\$36,086	23383
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	36,920	SF	3	\$66,614	23388
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23385
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23387
Technology: Telecommunications Room fiber connectivity infrastructure is outdated and/or inadequate.	Technology	1	Ea.	3	\$6,616	23380



Facility Condition Assessment

Cranston - Stone Hill School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	23	Ea.	3	\$36,887	23392
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23393
Sub Total for System		21	items		\$1,423,098	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,619	Rollup
Sub Total for System		1	items		\$4,619	
Sub Total for Building 01 - Main Building		42	items		\$3,784,565	
Total for Campus		49	items		\$4,046,542	



Stone Hill School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Roadway Pavement	Asphalt	27	CAR	\$90,418	4
Parking Lot Pavement	Asphalt	148	CAR	\$495,627	5
Note: 33,175 SF (95 CAR) Paved play area					
		Sub Total for System		2 items	\$586,045
		Sub Total for Building -		2 items	\$586,045

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	18,480	SF	\$123,591	4
Resilient Flooring	Vinyl Composition Tile Flooring	24,024	SF	\$278,955	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4,544	SF	\$41,540	5
		Sub Total for System		3 items	\$444,086

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Unit Heater Steam/HW (20 MBH)	6	Ea.	\$17,102	4
		Sub Total for System		1 items	\$17,102

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Distribution Panels (400 Amps)	1	Ea.	\$25,982	5
Power Distribution	Panelboard - 277/480 100A	7	Ea.	\$54,561	5
Power Distribution	Panelboard - 120/240 225A	1	Ea.	\$9,719	5
		Sub Total for System		3 items	\$90,262
		Sub Total for Building 01 - Main Building		7 items	\$551,450
		Total for: Stone Hill School		9 items	\$1,137,495



Supporting Photos



Play Yard



Damaged Fence



Roadway



Play Yard



Facility Condition Assessment

Cranston - Stone Hill School



Site Aerial



Parking Lot



Northwest View



Restroom



Restroom Lavatories



Cafeteria/Gym



Facility Condition Assessment

Cranston - Stone Hill School



East View



Northeast View



Library



East Entry



West Play Yard



Typical Classroom



Facility Condition Assessment

Cranston - Stone Hill School



Library



Typical Casework



Cafeteria/Gym



North Play Yard



Typical Classroom



South View



Facility Condition Assessment

Cranston - Stone Hill School



North View



Southeast View



Southeast View



West View



Southwest View




Aluminum Windows



Aluminum Windows



Cafe/Gym Ceiling Tiles



Door Hardware



Custodial Sink



Typical Toilet Stall



Corroding Storefront Window Frame




Roof View



Roof View



Unit Vent



Wood Panel Wall



Classroom Acoustical Tile Ceiling



Facility Condition Assessment

Cranston - Western Hills Middle School

June 2017

400 Phenix Avenue, Cranston, RI 02920





Introduction

Western Hills Middle School, located at 400 Phenix Avenue in Cranston, Rhode Island, was built in 1970. It comprises 129,245 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Western Hills Middle School serves grades 7 - 8, has 58 instructional spaces, and has an enrollment of 656. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Western Hills Middle School is 841 with a resulting utilization of 78%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Western Hills Middle School the 5-year need is \$14,631,451. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Western Hills Middle School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Western Hills Middle School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Stucco Exterior Wall
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
---------------------	--------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Foldable Interior Partition
	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Quarry Tile Flooring
	Vinyl Composition Tile Flooring
	Carpet
	Athletic/Sport Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	4,488 MBH Cast Iron Water Boiler
---------------------	----------------------------------



01 - Main Building:	400 MBH Copper Tube Boiler
	Steam/Hot Water Heating Unit Vent
	Finned Wall Radiator
	Fin Tube Water Radiant Heater
	36 MBH Steam Unit Heater
	DDC Heating System Controls
	Pneumatic Heating System Controls
	2 Ton Ductless Split System
	3 Ton Outside Air Cooled Condenser
	5 Ton Package DX Unit
	20 Ton Package DX Unit
	Window Units
	1 HP or Smaller Pump
	10 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	2,000 CFM Interior AHU
	Ductwork
	Roof Exhaust Fan
	Supply Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	500 Gallon Water Storage Tank
	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	300 kW Emergency Generator
	Automatic Transfer Switch
	1,600 Amp Switchgear
	600 Amp Distribution Panel



Facility Condition Assessment

Cranston - Western Hills Middle School

01 - Main Building:	Panelboard - 120/208 225A
	Panelboard - 277/480 100A
	Panelboard - 277/480 400A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$480,847	\$753,487	\$421,178	\$1,655,511	13.23 %
Roofing	-	\$757,234	\$125	-	-	\$757,359	6.05 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$2,559,761	\$1,751	-	-	\$2,561,512	20.47 %
Interior	-	-	\$1,398,839	\$2,482,113	\$33,865	\$3,914,817	31.28 %
Mechanical	-	\$867,377	\$47,801	-	-	\$915,178	7.31 %
Electrical	-	-	-	-	\$95,794	\$95,794	0.77 %
Plumbing	-	-	\$2,940	\$19,502	\$11,212	\$33,653	0.27 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$2,431,177	-	-	\$2,431,177	19.42 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,588	\$133,023	\$13,764	\$151,375	1.21 %
Total	\$0	\$4,184,372	\$4,368,069	\$3,388,125	\$575,813	\$12,516,378	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$3,914,817
Exterior	-	\$2,561,512
Technology	-	\$2,431,177

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$176,669	-	\$176,669
Barrier to Accessibility	-	-	\$2,940	-	-	\$2,940
Capital Renewal	-	\$4,184,372	\$1,862,677	\$2,892,106	\$17,579	\$8,956,734
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$79,140	\$577	\$558,234	\$637,951
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$318,773	-	\$318,773
Technology	-	-	\$2,356,625	-	-	\$2,356,625
Traffic	-	-	\$66,686	-	-	\$66,686
Total	\$0	\$4,184,372	\$4,368,069	\$3,388,125	\$575,813	\$12,516,378

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,655,511	\$0	\$0	\$0	\$0	\$0	\$0	\$1,655,511
Roofing	\$757,359	\$0	\$0	\$0	\$0	\$0	\$0	\$757,360
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$2,561,512	\$0	\$0	\$0	\$0	\$0	\$0	\$2,561,512
Interior	\$3,914,817	\$0	\$0	\$0	\$0	\$941,805	\$941,805	\$4,856,623
Mechanical	\$915,178	\$0	\$0	\$0	\$0	\$712,884	\$712,884	\$1,628,063
Electrical	\$95,794	\$0	\$0	\$0	\$0	\$308,894	\$308,894	\$404,688
Plumbing	\$33,653	\$0	\$0	\$0	\$12,922	\$138,568	\$151,490	\$185,143
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Technology	\$2,431,177	\$0	\$0	\$0	\$0	\$0	\$0	\$2,431,177
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$151,375	\$0	\$0	\$0	\$0	\$0	\$0	\$151,375
Total	\$12,516,378	\$0	\$0	\$0	\$12,922	\$2,102,151	\$2,115,073	\$14,631,451

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$44,333,848. For planning purposes, the total 5-year need at the Western Hills Middle School is \$14,631,451 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Western Hills Middle School facility has a 5-year FCI of 33.00%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 738 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Western Hills Middle School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$665,399.



Summary of Findings

The Western Hills Middle School comprises 129,245 square feet and was constructed in 1970. Current deficiencies at this school total \$12,516,378. Five year capital renewal costs total \$2,115,073. The total identified need for the Western Hills Middle School (current deficiencies and 5-year capital renewal costs) is \$14,631,451. The 5-year FCI is 33.00%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Western Hills Middle School Totals	129,245	1970	\$12,516,378	\$2,115,073	\$14,631,451	33.00%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement Note: Concrete walkways are cracked and uneven throughout the campus.	Capital Renewal	16,015	SF	3	\$414,161	13041
New Sidewalk Is Required Note: Add sidewalk along school driveway adjacent to baseball field (6' wide x 385' long)	Traffic	2,310	SF	3	\$66,686	16946
Asphalt Paving Requires Replacement Note: Roadway asphalt is weathered, cracked, and alligatored.	Capital Renewal	70	CAR	4	\$293,023	13039
Asphalt Paving Requires Replacement Note: Asphalt paving is cracked and weathered.	Capital Renewal	110	CAR	4	\$460,464	16874
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28721
School lacks a competition track. Note: School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$413,780	28235
Sub Total for System		6 items			\$1,655,511	
Sub Total for School and Site Level		6 items			\$1,655,511	

Building: 01 - Main Building

Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
EPDM Roofing Requires Replacement (Bldg SF) Note: Membrane on the concrete canopy is weathered with significant ponding.	Capital Renewal	1,800	SF	2	\$23,997	13051
EPDM Roofing Requires Replacement (Bldg SF) Note: EPDM roofing shows signs of ponding. The membrane is buckled and stained with evidence of water infiltration inside of the building.	Capital Renewal	55,000	SF	2	\$733,237	13056
The Roof Drains Require Cleaning Note: Debris is collecting around the roof drain cages.	Capital Renewal	3	Ea.	3	\$125	13044
Sub Total for System		3 items			\$757,359	

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Storefront/Curtain Wall Requires Replacement (Bldg SF) Note: Single pane windows are rusted and leaking. Many are secured shut to keep water from infiltrating.	Capital Renewal	19,387	SF	2	\$1,647,922	13055
The Stucco Exterior Wall Requires Replacement (Bldg SF) Note: Stucco exterior is deteriorated and stained.	Capital Renewal	25,849	SF	2	\$911,838	13057
Exterior Metal Door Requires Repainting Note: Exterior door finishes are faded, peeling, or rusted. They should be repainted.	Capital Renewal	8	Door	3	\$1,751	13043
Sub Total for System		3 items			\$2,561,512	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Carpet Flooring Requires Replacement	Capital Renewal	6,462	SF	3	\$148,231	16875
The Vinyl Composition Tile Requires Replacement Note: VCT tiles are worn and separating at the seams.	Capital Renewal	103,396	SF	3	\$1,250,608	13046
Ceiling Grid Requires Replacement Note: Ceiling grid is rusted and discolored throughout.	Capital Renewal	113,990	SF	4	\$1,425,469	13060
Moveable Partitions Require Replacement Note: Partitions are aged, worn, stained, and poorly functioning. Location: Rooms 200, 202, 204, 205, 207, 209, 211, 213, 216, 218, 220, 222, 223, 225, 227, 229	Capital Renewal	4,608	SF Wall	4	\$561,202	13062
Paint (probable pre-1978 in base (layers(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	497	Ea.	4	\$149,454	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	3,922	LF	4	\$94,352	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	6,238	SF	4	\$62,528	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	1,238	SF	4	\$12,409	Rollup



Facility Condition Assessment

Cranston - Western Hills Middle School

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Is Excessively Reverberant	Acoustics	7,500	SF	4	\$176,669	27979
Location: Gym						
Wall/ceiling materials - area < 9 sq. ft. AND in children-accessible area	Hazardous Material	3	SF	4	\$30	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,294	Rollup
Interior Doors Require Repainting	Capital Renewal	247	Door	5	\$17,579	13045
Note: Wood doors are chipped and worn and should be refinished.						
Room lacks appropriate sound control.	Educational Adequacy	400	SF	5	\$13,993	Rollup
Sub Total for System		13 items			\$3,914,817	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Package DX Unit Requires Replacement	Capital Renewal	5	Ea.	2	\$76,000	13053
Note: Rooftop units are aged, weathered, and rusted.						
Replace Unit Vent	Capital Renewal	41	Ea.	2	\$731,205	13061
Note: Unit vents are aged and rusting with cases deteriorating.						
Steam/HW Unit Heater Requires Replacement	Capital Renewal	10	Ea.	2	\$17,361	13054
Note: Unit heaters are rusting out with deteriorating casings.						
The Exterior Condenser Requires Replacement	Capital Renewal	5	Ea.	2	\$42,811	13047
Note: Condensers are weathered and rusting out with deteriorated casing.						
Large HVAC Circulating Pump Requires Replacement	Capital Renewal	3	Ea.	3	\$47,801	13052
Note: Pumps are aged and corroding with visible leaks and standing water.						
Sub Total for System		5 items			\$915,178	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	192	Ea.	5	\$95,794	Rollup
Sub Total for System		1 items			\$95,794	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Restroom Is Not ADA Compliant	Barrier to Accessibility	10	SF	3	\$2,940	13049
Floor Drains Are Required	Educational Adequacy	1	Ea.	4	\$577	Rollup
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	1	Ea.	4	\$10,776	13048
Note: Drinking fountain in the girl's locker room is not functioning.						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	3	Ea.	4	\$8,149	13050
Note: Service sinks are aged and deteriorating.						
Room lacks a drinking fountain.	Educational Adequacy	6	Ea.	5	\$6,652	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	3	Ea.	5	\$4,559	Rollup
Sub Total for System		6 items			\$33,653	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	13	Ea.	3	\$74,552	Rollup
Technology: Auditorium AV/Multimedia system is inadequate.	Technology	1	Room	3	\$350,831	23601
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	196	Ea.	3	\$98,233	23600
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	45	Ea.	3	\$947,244	23605
Technology: Instructional spaces do not have local sound reinforcement.	Technology	45	Ea.	3	\$225,534	23607
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23594



Facility Condition Assessment

Cranston - Western Hills Middle School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23597
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$47,713	23593
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,642	23596
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23592
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23595
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23598
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23590
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,906	23589
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	128	Ea.	3	\$57,737	23599
Technology: Network system inadequate and/or near end of useful life	Technology	14	Ea.	3	\$112,266	23608
Technology: Network system inadequate and/or near end of useful life	Technology	16	Ea.	3	\$80,190	23609
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	129,245	SF	3	\$233,194	23604
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23606
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,019	23591
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	45	Ea.	3	\$72,171	23603
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23602
Sub Total for System		22	items		\$2,431,177	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,588	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	6	Room	4	\$70,776	13059
The Metal Student Lockers Require Replacement Note: Original lockers are aged, worn, and should be replaced.	Capital Renewal	120	Ea.	4	\$62,247	13058
The room lacks a washer and/or dryer.	Educational Adequacy	1	Ea.	5	\$13,764	Rollup
Sub Total for System		4	items		\$151,375	
Sub Total for Building 01 - Main Building		57	items		\$10,860,867	
Total for Campus		63	items		\$12,516,378	

Buildings with no reported deficiencies

- 02 - Portable A
- 03 - Portable B
- 04 - Portable C



Western Hills Middle School - Life Cycle Summary Yrs 1-5

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	51,698	SF	\$345,748	5
Suspended Plaster and	Painted ceilings	7,755	SF	\$32,835	5
Acoustical Suspended Ceilings	Exposed Tectum Ceilings	7,500	SF	\$563,222	5
Sub Total for System		3	items	\$941,806	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Package DX Unit (5 Ton)	2	Ea.	\$29,184	5
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	100,000	SF	\$683,700	5
Sub Total for System		2	items	\$712,884	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Distribution Panels (600 Amps)	2	Ea.	\$58,969	5
Wiring Devices	Electrical Disconnect	24	Ea.	\$44,527	5
Power Distribution	Panelboard - 120/208 225A	17	Ea.	\$99,788	5
Power Distribution	Panelboard - 277/480 400A	5	Ea.	\$90,021	5
Power Distribution	Panelboard - 277/480 100A	2	Ea.	\$15,589	5
Sub Total for System		5	items	\$308,894	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Compressed-Air Systems	Air Compressor (2 hp)	2	Ea.	\$12,922	4
Plumbing Fixtures	Toilets	48	Ea.	\$138,568	5
Sub Total for System		2	items	\$151,490	
Sub Total for Building 01 - Main Building		12	items	\$2,115,073	
Total for: Western Hills Middle School		12	items	\$2,115,073	



Supporting Photos



Leaking Pump



Rusting Unit Heater



Cracked Concrete Walkway



Rusted Condenser



Facility Condition Assessment

Cranston - Western Hills Middle School



Rusting Heater



Weathered And Rusted Rooftop Unit



Deteriorated Curbs



Asphalt Parking



Weathered And Rusted Rooftop Unit



Alligatored Roadway Paving



Facility Condition Assessment

Cranston - Western Hills Middle School



Weathered Exterior Doors



Building Signage



Site Aerial



Band Room



Gymnasium



Exterior Brick



Facility Condition Assessment

Cranston - Western Hills Middle School



North Elevation



Typical Classroom



Plaque



Chipped Gym Floor Paint



Typical Restroom



Shop Classroom



Facility Condition Assessment

Cranston - Western Hills Middle School



Portable A



Art Room




Cafeteria



Library




Auditorium



Paint Peeling On Door



Debris At Roof Drain



Worn Interior Door Finish




Chipped VCT



Aged Unit Vent



Aged Unit Vent



VCT Separating At Seams



Facility Condition Assessment

Cranston - Western Hills Middle School



Ponding On Canopy



Broken Window



Aged Windows



Ponding And Vegetation On Roof



Buckled EPDM




Deteriorated And Stained Stucco



Facility Condition Assessment

Cranston - Western Hills Middle School



Original Lockers



Rusted Grid



Stained Ceiling Grid



Partition Wall



Aged Service Sink



Facility Condition Assessment

Cranston - William R. Dutemple School

June 2017

32 Garden Street, Cranston, RI 02910





Introduction

William R. Dutemple School, located at 32 Garden Street in Cranston, Rhode Island, was built in 1931. It comprises 34,215 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

William R. Dutemple School serves grades 1 - 6, has 20 instructional spaces, and has an enrollment of 309. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for William R. Dutemple School is 324 with a resulting utilization of 95%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For William R. Dutemple School the 5-year need is \$5,739,530. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of William R. Dutemple School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the William R. Dutemple School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Single Ply Membrane Ballasted Roofing
----------------------------	---------------------------------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	Painted Ceilings
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Carpet

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,264 MBH Cast Iron Water Boiler
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent



01 - Main Building:	20 MBH Steam Unit Heater
	Electronic Heating System Controls
	Window Units
	5 HP VFD
	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	Roof Exhaust Fan
	Kitchen Exhaust Hoods
	4'x6' Ventilator/Relief Vent
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	4" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	10,000 Gallon Underground Fuel Oil Storage Tank

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Building Mounted Lighting Fixtures
	Light Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Facility Condition Assessment

Cranston - William R. Dutemple School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$5,966	\$79,847	\$64,800	\$150,613	3.51 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$302,510	-	\$138	-	\$302,647	7.04 %
Interior	-	-	\$692,134	\$607,528	\$14,611	\$1,314,273	30.59 %
Mechanical	-	\$1,052,079	-	\$61,418	-	\$1,113,497	25.92 %
Electrical	-	\$60,046	-	-	\$40,185	\$100,231	2.33 %
Plumbing	-	-	\$182,011	\$87,484	\$117,010	\$386,505	9.00 %
Fire and Life Safety	\$49,024	-	-	-	-	\$49,024	1.14 %
Technology	-	-	\$870,541	-	-	\$870,541	20.26 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,238	-	-	\$9,238	0.22 %
Total	\$49,024	\$1,414,635	\$1,759,891	\$836,415	\$236,605	\$4,296,569	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,314,273
Mechanical	-	\$1,113,497
Technology	-	\$870,541

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$66,145	-	\$66,145
Barrier to Accessibility	-	-	\$575,097	-	-	\$575,097
Capital Renewal	\$49,024	\$1,414,635	\$299,048	\$191,598	\$114,239	\$2,068,544
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$15,012	\$91,901	\$122,366	\$229,279
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$486,771	-	\$486,771
Technology	-	-	\$864,767	-	-	\$864,767
Traffic	-	-	\$5,966	-	-	\$5,966
Total	\$49,024	\$1,414,635	\$1,759,891	\$836,415	\$236,605	\$4,296,569

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$150,613	\$0	\$0	\$0	\$23,816	\$0	\$23,816	\$174,429
Roofing	\$0	\$0	\$0	\$0	\$0	\$404,158	\$404,158	\$404,158
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$302,647	\$0	\$0	\$0	\$0	\$0	\$0	\$302,647
Interior	\$1,314,273	\$0	\$0	\$0	\$0	\$419,715	\$419,715	\$1,733,988
Mechanical	\$1,113,497	\$0	\$0	\$0	\$254,205	\$153,965	\$408,170	\$1,521,667
Electrical	\$100,231	\$0	\$0	\$0	\$0	\$0	\$0	\$100,231
Plumbing	\$386,505	\$0	\$0	\$0	\$0	\$5,916	\$5,916	\$392,421
Fire and Life Safety	\$49,024	\$0	\$0	\$0	\$0	\$0	\$0	\$49,024
Technology	\$870,541	\$0	\$0	\$0	\$0	\$0	\$0	\$870,541
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$9,238	\$0	\$0	\$0	\$0	\$181,186	\$181,186	\$190,424
Total	\$4,296,569	\$0	\$0	\$0	\$278,021	\$1,164,940	\$1,442,961	\$5,739,530

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$11,975,250. For planning purposes, the total 5-year need at the William R. Dutemple School is \$5,739,530 (Life Cycle Years 1-5 plus the FCI deficiency cost). The William R. Dutemple School facility has a 5-year FCI of 47.93%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 190 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the William R. Dutemple School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$375,732.



Summary of Findings

The William R. Dutemple School comprises 34,215 square feet and was constructed in 1931. Current deficiencies at this school total \$4,296,569. Five year capital renewal costs total \$1,442,961. The total identified need for the William R. Dutemple School (current deficiencies and 5-year capital renewal costs) is \$5,739,530. The 5-year FCI is 47.93%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
William R. Dutemple School Totals	34,215	1931	\$4,296,569	\$1,442,961	\$5,739,530	47.93%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Traffic Signage Is Required Note: Add school zone signs	Traffic	2	Ea.	3	\$5,966	11642
Asphalt Paving Requires Replacement Note: Play area asphalt is weathered with large cracks.	Capital Renewal	6	CAR	4	\$23,119	10017
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$37,288	28437
Fencing Requires Replacement (4' Chain Link Fence) Note: Fence is in disrepair with much of it damaged and rusted.	Capital Renewal	230	LF	4	\$19,440	10016
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54876
Sub Total for System		5 items			\$150,613	
Sub Total for School and Site Level		5 items			\$150,613	

Building: 01 - Main Building

Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Storefront/Curtain Wall Requires Replacement (Bldg SF) Note: Original single pane windows allow air and water in. The glass is cloudy and glazing is deteriorating.	Capital Renewal	3,422	SF	2	\$302,510	10040
Handrail Requires Repainting Location: Outside south cafe/gym entrance.	Capital Renewal	12	LF	4	\$138	10032
Sub Total for System		2 items			\$302,647	

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Existing Door Hardware Is Not ADA Compliant	Barrier to Accessibility	135	Door	3	\$422,200	10026
The Carpet Flooring Requires Replacement Note: Carpet is worn and frayed.	Capital Renewal	1,036	SF	3	\$24,715	10022
The Terrazzo Flooring Requires Replacement Note: Terrazzo is cracked and worn. Location: Restrooms	Capital Renewal	1,711	SF	3	\$139,126	10029
The Vinyl Composition Tile Requires Replacement Note: Tile is worn and cracking.	Capital Renewal	8,434	SF	3	\$106,092	10023
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	12,770	SF	4	\$399,370	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	16	Ea.	4	\$5,004	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	160	LF	4	\$4,003	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	7,520	SF	4	\$78,394	Rollup
Room Is Excessively Reverberant Note: Gym	Acoustics	2,700	SF	4	\$66,145	19808
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	1,416	SF	4	\$54,613	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	2	Ea.	5	\$4,619	Rollup
Interior Doors Require Repainting Note: Interior wood door finishes are worn.	Capital Renewal	135	Door	5	\$9,992	10021
Sub Total for System		12 items			\$1,314,273	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent	Capital Renewal	5	Ea.	2	\$92,738	10042
Steam/HW Unit Heater Requires Replacement	Capital Renewal	4	Ea.	2	\$12,351	11687
The Cast Iron Water Boiler Requires Replacement	Capital Renewal	2	Ea.	2	\$396,964	10034



Facility Condition Assessment

Cranston - William R. Dutemple School

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Fin Tube Water Radiant Heater Requires Replacement Note: Radiant heater casing is deteriorating.	Capital Renewal	142	Ea.	2	\$260,830	10036
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life Note: Piping is deteriorating. There were leaks observed in boiler room and teachers report leaks throughout the building.	Capital Renewal	34,215	SF	2	\$289,195	10037
Small HVAC Circulating Pump Requires Replacement Note: Pump is deteriorating and has bad seals and rust.	Capital Renewal	1	Ea.	4	\$10,450	10031
Small HVAC Circulating Pump Requires Replacement	Capital Renewal	2	Ea.	4	\$16,730	10043
The Exhaust Hood Requires Replacement	Capital Renewal	6	Ea.	4	\$34,239	10041
Sub Total for System		8	items		\$1,113,497	

Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Distribution Panel Requires Replacement	Capital Renewal	1	Ea.	2	\$28,147	10038
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$31,900	10033
Room Has Insufficient Electrical Outlets	Educational Adequacy	80	Ea.	5	\$40,185	Rollup
Sub Total for System		3	items		\$100,231	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life Note: Original water piping should be replaced.	Capital Renewal	3,300	SF	3	\$29,114	10030
The Restroom Is Not ADA Compliant Note: Staff, boy's, and girl's rooms are not ADA compliant.	Barrier to Accessibility	500	SF	3	\$152,897	10027
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	6	Ea.	4	\$67,239	10025
The Classroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	3	Ea.	4	\$8,944	10020
The Custodial Mop Or Service Sink Requires Replacement Note: Mop sinks are deteriorating.	Capital Renewal	4	Ea.	4	\$11,300	10019
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	6	Ea.	5	\$7,181	Rollup
Underground Fuel/Oil Storage Tank Requires Replacement	Capital Renewal	1	Ea.	5	\$104,247	10039
Sub Total for System		8	items		\$386,505	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Emergency Lighting System Requires Replacement	Capital Renewal	34,215	SF	1	\$31,519	10018
Replace Kitchen Exhaust Hood	Capital Renewal	1	Ea.	1	\$17,505	10035
Sub Total for System		2	items		\$49,024	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	3	\$5,774	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	120	Ea.	3	\$62,548	23693
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	16	Ea.	3	\$350,270	23698
Technology: Instructional spaces do not have local sound reinforcement.	Technology	16	Ea.	3	\$83,398	23700
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,297	23689
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$46,703	23688
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,903	23691



Facility Condition Assessment

Cranston - William R. Dutemple School

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	1	Ea.	3	\$469	23692
Technology: Network system inadequate and/or near end of useful life	Technology	4	Ea.	3	\$33,359	23701
Technology: Network system inadequate and/or near end of useful life	Technology	16	Ea.	3	\$83,398	23702
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	34,215	SF	3	\$64,203	23697
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$59,421	23694
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,849	23699
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,340	23690
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	16	Ea.	3	\$26,687	23696
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,923	23695
Sub Total for System		16	items		\$870,541	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Sub Total for System		1	items		\$9,238	
Sub Total for Building 01 - Main Building		52	items		\$4,145,956	
Total for Campus		57	items		\$4,296,569	



William R. Dutemple School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (8 Ft)	350	LF	\$23,816	4
		Sub Total for System		\$23,816	
		1	items		
		Sub Total for Building -		\$23,816	
		1	items		

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Single Ply Membrane Ballasted Roof	10,500	SF	\$404,158	5
		Sub Total for System		\$404,158	
		1	items		

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Swinging Doors	Steel	16	Door	\$69,346	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	4,000	SF	\$48,020	5
Acoustical Suspended Ceilings	Ceilings - Adhered acoustical tiles	10,264	SF	\$112,658	5
Suspended Plaster and	Painted ceilings	19,951	SF	\$84,473	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	10,265	SF	\$68,651	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	4,000	SF	\$36,567	5
		Sub Total for System		\$419,714	
		6	items		

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - Electronic (Bldg,SF)	34,215	SF	\$233,928	4
Decentralized Cooling	Window Units	6	Ea.	\$20,277	4
Exhaust Air	Ventilator/Relief Vent (4'x6')	8	Ea.	\$153,965	5
Note: 12"					
		Sub Total for System		\$408,170	
		3	items		

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 75 Gallons	1	Ea.	\$5,916	5
		Sub Total for System		\$5,916	
		1	items		

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	16	Room	\$181,186	5
		Sub Total for System		\$181,186	
		1	items		
		Sub Total for Building 01 - Main Building		\$1,419,143	
		12	items		
		Total for: William R. Dutemple School		\$1,442,960	
		13	items		



Supporting Photos



Fin Tube Radiant Heater



Heating And Ventilating Unit



Typical Exhaust Hood



Distribution Panel



Facility Condition Assessment

Cranston - William R. Dutemple School



Typical Rusted Fence



Classroom Lavatory



South Elevation



Typical Interior Doors



West Elevation



Art Room



Facility Condition Assessment

Cranston - William R. Dutemple School



East Elevation



Restroom Finishes



Worn Finish On Interior Door



Frayed Carpet



Site Aerial



Cracked And Weathered Play Area



Facility Condition Assessment

Cranston - William R. Dutemple School



Library



North Elvation



Typical Classroom



Library



Northwest Elevation



Cafe/Gym



Facility Condition Assessment

Cranston - William R. Dutemple School



Hallway Finishes



Cafe/Gym



Chipped VCT



Non-Compliant Door Hardware



Peeling Ceiling Paint



Stained And Peeling Paint



Facility Condition Assessment

Cranston - William R. Dutemple School



Cracking Terrazzo



Circulating Pump



Chipped Handrail Painting



Typical Boiler



HVAC Piping




Typical Window



Facility Condition Assessment

Cranston - William R. Dutemple School



Typical Toilet



Facility Condition Assessment

Cranston - Woodridge School

June 2017

401 Budlong Road, Cranston, RI 02920





Introduction

Woodridge School, located at 401 Budlong Road in Cranston, Rhode Island, was built in 1953. It comprises 22,487 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Woodridge School serves grades 1 - 6, has 21 instructional spaces, and has an enrollment of 344. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Woodridge School is 285 with a resulting utilization of 121%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Woodridge School the 5-year need is \$6,234,499. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Woodridge School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Woodridge School campus, identified by discipline and building.

Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	EPDM Roofing
----------------------------	--------------

Interior

The interior systems for the building(s) at this campus include:

01 - Main Building:	Steel Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Adhered Acoustical Ceiling Tiles
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Quarry Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	3,060 MBH Cast Iron Steam Boiler
	Steam to Water Heat Exchanger
	Steam Condensate Receiver, Tank and Pump



01 - Main Building:	36 MBH Steam Unit Heater
	Steam/Hot Water Heating Unit Vent
	Finned Wall Radiator
	Pneumatic Heating System Controls
	Window Units
	2-Pipe Steam Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	Small Roof Exhaust Fan
	Kitchen Exhaust Hoods
	4'x8' Ventilator/Relief Vent
	Supply Fan

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	2" Backflow Preventers
	Gas Piping System
	80 Gallon Electric Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (1/2 hp)

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	400 Amp Distribution Panel
	Panelboard - 120/240 100A
	Panelboard - 120/240 225A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$38,828	\$747,712	\$72,198	\$858,738	20.35 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$7,819	\$745,853	\$2,309	\$755,981	17.92 %
Mechanical	-	\$601,000	\$214,075	-	-	\$815,075	19.32 %
Electrical	-	\$28,912	-	-	\$30,139	\$59,050	1.40 %
Plumbing	-	-	\$2,803	\$7,778	\$9,702	\$20,284	0.48 %
Fire and Life Safety	\$16,832	-	-	-	-	\$16,832	0.40 %
Technology	-	-	\$1,684,227	-	-	\$1,684,227	39.92 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,238	-	-	\$9,238	0.22 %
Total	\$16,832	\$629,912	\$1,956,989	\$1,501,343	\$114,348	\$4,219,424	

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Technology	-	\$1,684,227
Site	-	\$858,738
Mechanical	-	\$815,075

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$214,075	-	-	\$214,075
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	\$16,832	\$629,912	\$45,263	\$912,228	-	\$1,604,235
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$43,880	\$86,083	\$114,348	\$244,311
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$503,032	-	\$503,032
Technology	-	-	\$1,649,585	-	-	\$1,649,585
Traffic	-	-	\$4,186	-	-	\$4,186
Total	\$16,832	\$629,912	\$1,956,989	\$1,501,343	\$114,348	\$4,219,424

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$858,738	\$0	\$0	\$0	\$78,522	\$150,717	\$229,239	\$1,087,977
Roofing	\$0	\$0	\$0	\$0	\$0	\$287,796	\$287,796	\$287,796
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$0	\$77,945	\$77,945	\$77,945
Interior	\$755,981	\$0	\$0	\$0	\$0	\$324,076	\$324,076	\$1,080,057
Mechanical	\$815,075	\$0	\$0	\$0	\$402,818	\$416,346	\$819,164	\$1,634,239
Electrical	\$59,050	\$0	\$0	\$0	\$0	\$135,242	\$135,242	\$194,292
Plumbing	\$20,284	\$0	\$0	\$0	\$0	\$5,724	\$5,724	\$26,008
Fire and Life Safety	\$16,832	\$0	\$0	\$0	\$0	\$0	\$0	\$16,832
Technology	\$1,684,227	\$0	\$0	\$0	\$0	\$0	\$0	\$1,684,227
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$9,238	\$0	\$0	\$0	\$0	\$135,889	\$135,889	\$145,127
Total	\$4,219,424	\$0	\$0	\$0	\$481,340	\$1,533,735	\$2,015,075	\$6,234,499

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$9,550,450. For planning purposes, the total 5-year need at the Woodridge School is \$6,234,499 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Woodridge School facility has a 5-year FCI of 65.28%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 152 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Woodridge School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$459,270.



Summary of Findings

The Woodridge School comprises 22,487 square feet and was constructed in 1953. Current deficiencies at this school total \$4,219,424. Five year capital renewal costs total \$2,015,075. The total identified need for the Woodridge School (current deficiencies and 5-year capital renewal costs) is \$6,234,499. The 5-year FCI is 65.28%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Woodridge School Totals	22,487	1953	\$4,219,424	\$2,015,075	\$6,234,499	65.28%

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk Requires Repainting Note: Repaint crosswalks at intersection of Harwich Rd and Budlong Rd	Traffic	2	Ea.	3	\$1,925	16916
Crosswalk: Needs to be added Note: Add crosswalk on Budlong Rd at the north end of school property	Traffic	1	Ea.	3	\$962	16919
Parking Or Roadway Curbs Require Replacement Note: Replace curb along Harwich Rd	Capital Renewal	360	LF	3	\$34,642	16917
Sidewalk Requires Replacement Note: Replace badly cracked section of sidewalk on Harwich Rd (6' long x 7.5' wide)	Traffic	45	SF	3	\$1,299	16918
Asphalt Paving Requires Replacement	Capital Renewal	91	CAR	4	\$380,929	12409
Asphalt Paving Requires Replacement	Capital Renewal	79	CAR	4	\$330,697	13482
Backstops Require Replacement Note: Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$36,086	28442
Exterior Basketball Goals are Required Note: Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$7,398	28714
PE / Recess Playfield is Missing and is Needed Note: PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,800	54881
Sub Total for System		9	items		\$858,738	
Sub Total for School and Site Level		9	items		\$858,738	

Building: 01 - Main Building

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Terrazzo Flooring Requires Replacement Note: Substantial cracking in terrazzo in the girl's restroom.	Capital Renewal	100	SF	3	\$7,819	12411
Adhered Acoustical Ceiling Tile Requires Replacement Note: Adhered tiles are aged and stained and should be replaced.	Capital Renewal	16,865	SF	4	\$192,823	12422
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	16,476	SF	4	\$495,454	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	17	Ea.	4	\$5,112	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	40	LF	4	\$962	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	150	SF	4	\$1,504	Rollup
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	462	SF	4	\$17,819	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,309	Rollup
Sub Total for System		8	items		\$723,802	

Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent Note: Unit vents are aged and showing signs of potential failure.	Capital Renewal	9	Ea.	2	\$160,508	12420
Steam Heat Exchanger Requires Replacement Note: Heat exchanger is original to the building and should be replaced.	Capital Renewal	1	Ea.	2	\$50,119	12419
The Boiler HVAC Component Requires Replacement Note: Boiler is aged and obsolete.	Capital Renewal	1	Ea.	2	\$179,602	12414
The Fin Tube Water Radiant Heater Requires Replacement	Capital Renewal	16	Ea.	2	\$28,259	13483
The Mechanical / HVAC Piping / System Is Beyond Its Useful Life Note: Visible piping observed deteriorating.	Capital Renewal	22,457	SF	2	\$182,512	12418
Unit Ventilators Are Excessively Noisy Location: Classrooms	Acoustics	32	Ea.	3	\$214,075	27980
Sub Total for System		6	items		\$815,075	



Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Push Button Switch Requires Replacement Note: Push button controllers are aged and should be replaced.	Capital Renewal	2	Ea.	2	\$444	12421
The Panelboard Requires Replacement Note: Obsolete panelboard should be replaced.	Capital Renewal	1	Ea.	2	\$10,124	12415
The Panelboard Requires Replacement Note: Obsolete panelboards should be replaced.	Capital Renewal	3	Ea.	2	\$18,343	12416
Room Has Insufficient Electrical Outlets	Educational Adequacy	60	Ea.	5	\$30,139	Rollup
Sub Total for System		4	items		\$59,050	

Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	2	Ea.	3	\$2,803	12412
The Refrigerated Water Cooler Requires Replacement Note: Drinking fountain in the north wing is not functional.	Capital Renewal	1	Ea.	4	\$7,778	12413
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,581	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	4	Ea.	5	\$4,121	Rollup
Sub Total for System		4	items		\$20,284	

Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Kitchen Exhaust Hood	Capital Renewal	1	Ea.	1	\$16,832	12417
Sub Total for System		1	items		\$16,832	

Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	6	Ea.	3	\$34,642	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	72	Ea.	3	\$36,086	23400
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	69	Ea.	3	\$691,639	23405
Technology: Instructional spaces do not have local sound reinforcement.	Technology	69	Ea.	3	\$345,819	23410
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,613	23398
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$39,694	23397
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,012	23399
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,017	23396
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$52,925	23394
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$9,523	23395
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	95	Ea.	3	\$42,852	23403
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	51	Ea.	3	\$23,005	23401
Technology: Network system inadequate and/or near end of useful life	Technology	6	Ea.	3	\$48,114	23408
Technology: Network system inadequate and/or near end of useful life	Technology	14	Ea.	3	\$70,166	23409
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	72	Ea.	3	\$36,086	23402
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	22,487	SF	3	\$40,573	23407



Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$57,135	23404
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$20,048	23406
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	69	Ea.	3	\$110,662	23411
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,618	23412
Sub Total for System		20	items		\$1,684,227	

Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,238	Rollup
Sub Total for System		1	items		\$9,238	
Sub Total for Building 01 - Main Building		44	items		\$3,328,508	

Building: 02 - Portable A

Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	840	SF	4	\$32,179	Rollup
Sub Total for System		1	items		\$32,179	
Sub Total for Building 02 - Portable A		1	items		\$32,179	
Total for Campus		54	items		\$4,219,424	

Buildings with no reported deficiencies

03 - Portable B

04 - Portable C



Woodridge School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	1,200	LF	\$78,522	4
Pedestrian Pavement	Sidewalks - Concrete	7,285	SF	\$150,717	5
		Sub Total for System	2 items	\$229,239	
		Sub Total for Building -	2 items	\$229,239	

Building: 01 - Main Building

Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	EPDM - Rubber Roofing Material	22,487	SF	\$287,796	5
Note: Some staining, but no leaks. Warranty expires in 2017.					
		Sub Total for System	1 items	\$287,796	

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	12	Door	\$77,945	5
		Sub Total for System	1 items	\$77,945	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	13,492	SF	\$90,232	5
Resilient Flooring	Vinyl Composition Tile Flooring	20,139	SF	\$233,844	5
		Sub Total for System	2 items	\$324,077	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Window Units	6	Ea.	\$20,277	4
Decentralized Heating Equipment	Unit Heater Steam/HW (36 MBH)	2	Ea.	\$3,333	4
Facility Hydronic Distribution	Pump - 1HP or Less (Ea.)	3	Ea.	\$23,164	4
Heat Generation	Steam Condensate Receiver, Tank and Pump	1	Ea.	\$356,044	4
Decentralized Heating Equipment	Finned Wall Radiator - (Ea.)	52	Ea.	\$88,168	5
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	22,487	SF	\$153,744	5
Exhaust Air	Ventilator/Relief Vent (4'x8')	13	Ea.	\$174,434	5
		Sub Total for System	7 items	\$819,164	

Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	22,487	SF	\$135,242	5
		Sub Total for System	1 items	\$135,242	

Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 80 gallon	1	Ea.	\$5,724	5
		Sub Total for System	1 items	\$5,724	

Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	12	Room	\$135,889	5
		Sub Total for System	1 items	\$135,889	
		Sub Total for Building 01 - Main Building	14 items	\$1,785,837	
		Total for: Woodridge School	16 items	\$2,015,075	



Supporting Photos



Weathered Parking



Aged Panelboard



Site Aerial



Cracked Play Area



Facility Condition Assessment

Cranston - Woodridge School



Northeast Elevation



Cracked Asphalt Play Area



Exterior Finishes



Typical Cabinetry



Library



East Elevation




Plaque



Typical Classroom



Exterior Finishes



Hallway Finishes



Aged Unit Vent



Gym/Cafe



Cracked Terrazzo



Stained Adhered Tiles



Non-Functional Drinking Fountain



Aged Boiler