




South Kingstown totals 683,619 square feet and consists of the school type(s) detailed below. School(s) were visited three times during the Statewide Facilities Assessment by teams of specialists from April-May 2016. This report provides LEA summary findings for the statewide assessment program.

### School Type by Count



School Type	SqFt
Pre-K	37,350
Elementary School	207,388
Middle School	177,478
High School	261,403
<b>Total:</b>	<b>683,619</b>

### Demographics

Enrollment is projected to decrease by 12.1% over the next 10 years in South Kingstown. The total LEA enrollment at 9 school (s) is 3,231 students with a total capacity of 5,043 as reported by the LEA. Utilization is calculated by dividing enrollment by capacity, resulting in 64.1% utilization at South Kingstown.


### 64.1 % Utilization



### Educational Program Space Analysis

In South Kingstown there are 333 instructional spaces; of these spaces 27.9% meet or exceed the space size standards. Of the total current deficiencies identified, \$5,829,632 are related to the educational program space assessment. Addressing these identified deficiencies will improve the learning environment and bring the school(s) in the district closer to 21st century learning facilities.

### Total Current Deficiencies



### Five Year Need Summary

The current deficiencies total \$62,223,053, with 36.7% categorized as Priority 2 and another 25.8% as Priority 3. The building systems with the highest current deficiency costs are Mechanical and Interior.

School(s) with Greatest Need	Combined 5-Year Need
South Kingstown High School	\$24,701,149
Curtis Corner Middle School	\$15,663,052
Peace Dale Elementary School	\$9,604,036

The projected life cycle need in Years 1 through 5 is \$27,751,270. It is anticipated that the majority of the need will occur in Year 5. School(s) with the greatest need are represented in the adjacent table and make up 55.5% of the combined 5-Year need at South Kingstown.

### Five Year Facility Condition Index (FCI)

For master planning purposes, the total current deficiencies, less new construction, and the first 5 years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-Year FCI was calculated by dividing the 5-Year need by the total replacement cost. The 5-Year need is \$89,974,323 with a district replacement value of \$238,331,120. The resulting 5-Year FCI is 37.8%.

### 5-Year FCI Ranges




### LEA Summary Data

Gross SqFt	Avg Year Built	Current Deficiencies (Less New Construction)	Life Cycle Year 1-5 Total	Total 5-Year Need (Year 1-5 + Current Defs)	5-Year FCI
683,619	1960	\$62,223,053	\$27,751,270	\$89,974,323	37.8%



# South Kingstown





# Facility Condition Assessment

South Kingstown - Academic Success Academy

June 2017

153 School Street, Wakefield, RI 02879





## Introduction

Academic Success Academy, located at 153 School Street in Wakefield, Rhode Island, was built in 1920. It comprises 26,503 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Academic Success Academy serves grades HS, has 7 instructional spaces, and enrollment was not provided. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Academic Success Academy is 112 with a resulting utilization of 0%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Academic Success Academy the 5-year need is \$3,678,702. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Academic Success Academy



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Academic Success Academy campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	Painted Exterior Wall
	Stucco Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Composition Shingle Roofing
----------------------------	-----------------------------

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Non-Painted Plaster/Gypsum Board Ceiling
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Vinyl Composition Tile Flooring
	Carpet
	Athletic/Sport Flooring

### Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	1,275 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent



<b>01 - Main Building:</b>	Fin Tube Water Radiant Heater
	Pneumatic Heating System Controls
	1 Ton Ductless Split System
	2 Ton Ductless Split System
	5 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	5,000 CFM Interior AHU
	Roof Exhaust Fan
	Fire Sprinkler System

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Air Compressor (2 hp)

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	400 Amp Distribution Panel
	Panelboard - 120/208 225A
	Panelboard - 120/240 225A
	Panelboard - 120/240 400A
	Electrical Disconnect
	Light Fixtures
	Building Mounted Lighting Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.





# Facility Condition Assessment

South Kingstown - Academic Success Academy

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$6,043	\$264,938	\$1,003,716	\$1,274,698	50.49 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	\$47,215	-	-	-	-	\$47,215	1.87 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$257,923	\$750,828	\$15,864	\$1,024,615	40.59 %
Mechanical	-	-	-	\$18,931	-	\$18,931	0.75 %
Electrical	-	-	-	-	\$13,802	\$13,802	0.55 %
Plumbing	-	-	-	\$2,559	-	\$2,559	0.10 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$110,860	-	-	\$110,860	4.39 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$31,728	-	-	\$31,728	1.26 %
<b>Total</b>	\$47,215	\$0	\$406,555	\$1,037,256	\$1,033,382	\$2,524,409	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Site	-	\$1,274,698
Interior	-	\$1,024,615
Technology	-	\$110,860

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$205,044	-	\$205,044
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	\$47,215	-	\$257,923	\$333,046	-	\$638,185
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$71,389	\$303,668	\$1,033,382	\$1,408,439
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$195,497	-	\$195,497
Technology	-	-	\$71,200	-	-	\$71,200
Traffic	-	-	\$6,043	-	-	\$6,043
<b>Total</b>	\$47,215	\$0	\$406,555	\$1,037,256	\$1,033,382	\$2,524,409

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,274,698	\$0	\$0	\$0	\$44,588	\$168,165	\$212,753	\$1,487,451
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Structural	\$47,215	\$0	\$0	\$0	\$0	\$0	\$0	\$47,215
Exterior	\$0	\$0	\$117,592	\$0	\$0	\$0	\$117,592	\$117,592
Interior	\$1,024,615	\$0	\$0	\$0	\$0	\$0	\$0	\$1,024,615
Mechanical	\$18,931	\$0	\$0	\$0	\$329,652	\$194,632	\$524,284	\$543,215
Electrical	\$13,802	\$0	\$0	\$0	\$8,956	\$157,477	\$166,433	\$180,235
Plumbing	\$2,559	\$0	\$0	\$0	\$35,893	\$0	\$35,893	\$38,452
Fire and Life Safety	\$0	\$0	\$0	\$77,680	\$0	\$0	\$77,680	\$77,680
Technology	\$110,860	\$0	\$0	\$0	\$0	\$0	\$0	\$110,860
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$31,728	\$0	\$0	\$0	\$0	\$0	\$0	\$31,728
<b>Total</b>	<b>\$2,524,409</b>	<b>\$0</b>	<b>\$117,592</b>	<b>\$77,680</b>	<b>\$419,089</b>	<b>\$520,274</b>	<b>\$1,134,635</b>	<b>\$3,659,044</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$9,541,080. For planning purposes, the total 5-year need at the Academic Success Academy is \$3,678,702 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Academic Success Academy facility has a 5-year FCI of 38.35%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 129 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Academic Success Academy cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



### Summary of Findings

The Academic Success Academy comprises 26,503 square feet and was constructed in 1920. Current deficiencies at this school total \$2,544,067. Five year capital renewal costs total \$1,134,635. The total identified need for the Academic Success Academy (current deficiencies and 5-year capital renewal costs) is \$3,678,702. The 5-year FCI is 38.35%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
<b>Academic Success Academy Totals</b>	<b>26,503</b>	<b>1920</b>	<b>\$2,544,067</b>	<b>\$1,134,635</b>	<b>\$3,678,702</b>	<b>38.35%</b>

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

### Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk Requires Repainting <b>Note:</b> Repaint crosswalks on north and east sides of school in circular driveway.	Traffic	2	Ea.	3	\$1,511	9300
Traffic Signage Is Required <b>Note:</b> Add flashing beacons to school zone speed limit signs.	Traffic	2	Ea.	3	\$4,533	9299
Asphalt Paving Requires Replacement <b>Note:</b> Cracked & alligating.	Capital Renewal	72	CAR	4	\$236,609	4596
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28663
PE / Recess Playfield is Missing and is Needed <b>Note:</b> PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,020	54992
School has insufficient # of tennis courts. <b>Note:</b> School has insufficient # of tennis courts.	Educational Adequacy	1	Ea.	5	\$161,597	29072
School has insufficient baseball fields. <b>Note:</b> School has insufficient baseball fields.	Educational Adequacy	1	Ea.	5	\$207,745	28345
School has insufficient football/soccer fields. <b>Note:</b> School has insufficient football/soccer fields.	Educational Adequacy	1	Ea.	5	\$94,430	28213
School has insufficient softball fields. <b>Note:</b> School has insufficient softball fields.	Educational Adequacy	1	Ea.	5	\$151,087	28388
School lacks a competition track. <b>Note:</b> School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$324,837	28298
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$1,274,698</b>	
<b>Sub Total for School and Site Level</b>		<b>10</b>	<b>items</b>		<b>\$1,274,698</b>	

## Building: 01 - Main Building

### Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Structural Condition Exists <b>Note:</b> There are cracks on walls on the second floor, north of the building by both stairwells and on the perimeter foundation walls in the basement. Plaster at the columns is dissolving due to water damage. Investigate further to address structural condition.	Capital Renewal	1	Job	1	\$47,215	8352
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$47,215</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Athletic Sport Flooring Requires Replacement	Capital Renewal	1,040	SF	3	\$35,354	8717
The Carpet Flooring Requires Replacement <b>Note:</b> Existing carpet frayed, faded, and stained.	Capital Renewal	2,280	SF	3	\$49,270	8350
The Vinyl Composition Tile Requires Replacement <b>Note:</b> VCT throughout building is chipped, faded or lifting.	Capital Renewal	15,209	SF	3	\$173,299	8351
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	20,703	SF	4	\$195,497	Rollup
Room Is Excessively Reverberant <b>Location:</b> Weight room	Acoustics	1,440	SF	4	\$31,955	27934
Room Is Excessively Reverberant <b>Location:</b> Gym	Acoustics	7,800	SF	4	\$173,089	27937
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	7,275	SF	4	\$275,339	Rollup
The Gypsum Board Ceilings Require Replacement <b>Note:</b> Holes in ceiling at basement.	Capital Renewal	6,614	SF	4	\$74,947	8349





# Facility Condition Assessment

South Kingstown - Academic Success Academy

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Door Requires Vision Panel	Educational Adequacy	7	Ea.	5	\$15,864	Rollup
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$1,024,615</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Small HVAC Circulating Pump Requires Replacement <b>Note:</b> Pumps and seals are corroded.	Capital Renewal	2	Ea.	4	\$18,931	4598
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$18,931</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets	Educational Adequacy	28	Ea.	5	\$13,802	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$13,802</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Custodial sink is original to the building and is rusted and leaking.	Capital Renewal	1	Ea.	4	\$2,559	4597
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$2,559</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	7	Ea.	3	\$39,660	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	72	Ea.	3	\$33,995	13136
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,610	13134
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	72	Ea.	3	\$30,595	13135
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>		<b>\$110,860</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	7	Ea.	3	\$31,728	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$31,728</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>18</b>	<b>items</b>		<b>\$1,249,711</b>	
<b>Total for Campus</b>		<b>28</b>	<b>items</b>		<b>\$2,524,409</b>	



## Academic Success Academy - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Playfield Areas	ES Playgrounds	1	Ea.	\$44,588	4
Parking Lot Lighting	Pole Mounted Fixtures (Ea.)	8	Ea.	\$61,879	5
Pedestrian Pavement	Sidewalks - Concrete	5,200	SF	\$106,286	5
		<b>Sub Total for System</b>		<b>\$212,753</b>	
		<b>Sub Total for Building -</b>		<b>\$212,753</b>	

### Building: 01 - Main Building

#### Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Exterior Painting - Bldg SF basis	8,835	SF	\$117,592	2
		<b>Sub Total for System</b>		<b>\$117,592</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	13	Ea.	\$219,892	4
Decentralized Cooling	Ductless Split System (2 Ton)	14	Ea.	\$95,644	4
Decentralized Cooling	Ductless Split System (1 Ton)	1	Ea.	\$14,116	4
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	26,503	SF	\$179,020	5
Exhaust Air	Roof Exhaust Fan	3	Ea.	\$15,612	5
		<b>Sub Total for System</b>		<b>\$524,285</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)	6	Ea.	\$8,956	4
Lighting Fixtures	Light Fixtures (Bldg SF)	26,503	SF	\$157,477	5
		<b>Sub Total for System</b>		<b>\$166,433</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Compressed-Air Systems	Air Compressor (2 hp)	1	Ea.	\$6,383	4
Plumbing Fixtures	Refrigerated Drinking Fountain	4	Ea.	\$29,510	4
		<b>Sub Total for System</b>		<b>\$35,893</b>	

#### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	26,503	SF	\$77,680	3
		<b>Sub Total for System</b>		<b>\$77,680</b>	
		<b>Sub Total for Building 01 - Main Building</b>		<b>\$921,882</b>	
		<b>Total for: Academic Success Academy</b>		<b>\$1,134,634</b>	



## Supporting Photos



Site Aerial



Renovation Plaque



Elevation East



Elevation



# Facility Condition Assessment

South Kingstown - Academic Success Academy



Weight Room



Typical Classroom



Science Lab



Elevation North



School Signage



Holes In Gypsum Board Ceiling



# Facility Condition Assessment

South Kingstown - Academic Success Academy



Elevation West



Chipped VCT Flooring



Frayed Carpet



Water Damaged Basement Wall



Water Damage At Basement Windows



Damaged Basement Wall



# Facility Condition Assessment

South Kingstown - Academic Success Academy




Crack At Stairwell Wall



Cracked Parking Lot Pavement



Peeling Paint



Corroded Pump



Rusted And Leaking Custodial Sink



# Facility Condition Assessment

South Kingstown - Broad Rock Middle School

June 2017

351 Broad Rock Road, Wakefield, RI 02879





## Introduction

Broad Rock Middle School, located at 351 Broad Rock Road in Wakefield, Rhode Island, was built in 2001. It comprises 77,781 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Broad Rock Middle School serves grades 5 - 6, has 48 instructional spaces, and has an enrollment of 526. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Broad Rock Middle School is 672 with a resulting utilization of 78%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Broad Rock Middle School the 5-year need is \$8,264,829. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Broad Rock Middle School





## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Broad Rock Middle School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	CMU Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Built-Up Roofing With Ballast
	Canopy Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Foldable Interior Partition
	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Non-Painted Plaster/Gypsum Board Ceiling
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Rubber Tile Flooring
	Epoxy Coated Flooring
	Carpet



<b>01 - Main Building:</b>	Athletic/Sport Flooring
----------------------------	-------------------------

## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	1,275 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	DDC Heating System Controls
	1 Ton Ductless Split System
	3 Ton Ductless Split System
	5 Ton Package DX Unit
	10 Ton Package DX Unit
	2 Ton Thru-Wall A/C
	Make-up Air Unit
	5 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	2,000 CFM Interior AHU
	Ductwork
	Laboratory Fume Hood
	Roof Exhaust Fan
	Wall Exhaust Fan

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	250 Gallon Water Storage Tank
	2" Backflow Preventers
	4" Backflow Preventers
	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals



## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	50 kW Emergency Generator
	480v Switch
	800 Amp Switchgear
	225 KVA Transformer
	45 KVA Transformer
	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Panelboard - 277/480 400A
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



# Facility Condition Assessment

South Kingstown - Broad Rock Middle School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$100,473	\$1,194,944	\$330,645	\$1,626,062	47.86 %
Roofing	-	-	-	\$1,439	-	\$1,439	0.04 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$165,326	\$82,815	\$109,774	\$357,915	10.54 %
Mechanical	-	-	-	-	-	\$0	0.00 %
Electrical	\$2,806	-	\$42,994	-	-	\$45,799	1.35 %
Plumbing	-	-	-	-	\$24,995	\$24,995	0.74 %
Fire and Life Safety	\$22,663	-	-	-	-	\$22,663	0.67 %
Technology	-	-	\$1,284,436	-	-	\$1,284,436	37.81 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	-	-	\$33,995	\$33,995	1.00 %
<b>Total</b>	\$25,469	\$0	\$1,593,229	\$1,279,198	\$499,409	\$3,397,305	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Site	-	\$1,626,062
Technology	-	\$1,284,436
Interior	-	\$357,915

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	-	-	\$0
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	-	\$208,320	\$1,250,869	\$106,318	\$1,565,508
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$25,469	-	\$11,332	\$28,329	\$393,091	\$458,220
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	-	-	\$0
Technology	-	-	\$1,273,104	-	-	\$1,273,104
Traffic	-	-	\$100,473	-	-	\$100,473
<b>Total</b>	\$25,469	\$0	\$1,593,229	\$1,279,198	\$499,409	\$3,397,305

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority





### Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,626,062	\$0	\$0	\$0	\$398,736	\$329,598	\$728,334	\$2,354,396
Roofing	\$1,439	\$0	\$0	\$0	\$0	\$0	\$0	\$1,439
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Interior	\$357,915	\$0	\$0	\$33,626	\$1,041,393	\$149,701	\$1,224,720	\$1,582,635
Mechanical	\$0	\$0	\$0	\$0	\$1,271,250	\$853,036	\$2,124,286	\$2,124,286
Electrical	\$45,799	\$0	\$0	\$0	\$11,028	\$538,220	\$549,248	\$595,047
Plumbing	\$24,995	\$0	\$0	\$0	\$7,377	\$0	\$7,377	\$32,372
Fire and Life Safety	\$22,663	\$0	\$0	\$227,976	\$0	\$0	\$227,976	\$250,639
Technology	\$1,284,436	\$0	\$0	\$0	\$0	\$0	\$0	\$1,284,436
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$33,995	\$0	\$0	\$0	\$0	\$0	\$0	\$33,995
<b>Total</b>	<b>\$3,397,305</b>	<b>\$0</b>	<b>\$0</b>	<b>\$261,602</b>	<b>\$2,729,784</b>	<b>\$1,870,555</b>	<b>\$4,861,941</b>	<b>\$8,259,246</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



### Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$25,667,730. For planning purposes, the total 5-year need at the Broad Rock Middle School is \$8,264,829 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Broad Rock Middle School facility has a 5-year FCI of 32.18%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 409 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Broad Rock Middle School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$807,959.



## Summary of Findings

The Broad Rock Middle School comprises 77,781 square feet and was constructed in 2001. Current deficiencies at this school total \$3,402,888. Five year capital renewal costs total \$4,861,941. The total identified need for the Broad Rock Middle School (current deficiencies and 5-year capital renewal costs) is \$8,264,829. The 5-year FCI is 32.18%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
<b>Broad Rock Middle School Totals</b>	<b>77,781</b>	<b>2001</b>	<b>\$3,402,888</b>	<b>\$4,861,941</b>	<b>\$8,264,829</b>	<b>32.18%</b>

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk Requires Repainting <b>Note:</b> Repaint crosswalk on Broad Rock Rd and crosswalk on south side of campus	Traffic	2	Ea.	3	\$1,511	9323
Pavement Markings: Words/Symbols Are Required <b>Note:</b> Change flow of buses and parents around campus to be counterclockwise to allow for safer drop off/pick up (paint arrows on pavement to show direction of flow)	Traffic	14	Ea.	3	\$5,288	9322
Traffic Signage Is Required <b>Note:</b> Add signs to show where parents/buses drop off/pick up (2), one way signs around campus (4), and do not enter signs (2)	Traffic	8	Ea.	3	\$18,130	9320
Traffic Signage Is Required <b>Note:</b> Add flashing beacons to school zone speed limit signs	Traffic	2	Ea.	3	\$75,544	9321
Asphalt Paving Requires Replacement <b>Note:</b> Roadway asphalt top is splitting and alligating.	Capital Renewal	177	CAR	4	\$581,665	8818
Asphalt Paving Requires Replacement <b>Note:</b> Parking asphalt top is splitting and alligating.	Capital Renewal	178	CAR	4	\$584,951	8819
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28595
Exterior Basketball Goals are Required <b>Note:</b> Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$5,807	28809
School lacks a competition track. <b>Note:</b> School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$324,837	28275
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$1,626,062</b>	
<b>Sub Total for School and Site Level</b>		<b>9</b>	<b>items</b>		<b>\$1,626,062</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Canopies Require Painting	Capital Renewal	120	SF	4	\$1,439	8823
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$1,439</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Carpet Flooring Requires Replacement <b>Location:</b> Offices and library	Capital Renewal	5,668	SF	3	\$122,484	8820
The Wood Flooring Requires Replacement <b>Note:</b> Wood floor is scratched and worn. <b>Location:</b> Stage	Capital Renewal	1,300	SF	3	\$42,843	8821
Epoxy Flooring Requires Repair Or Replacement <b>Location:</b> Kitchen and locker rooms	Capital Renewal	4,000	SF	4	\$75,544	8825
Stair Treads Require Replacement <b>Note:</b> Stair treads at rubber tiles are worn and should be replaced.	Capital Renewal	175	LF	4	\$7,271	8827
Interior Walls Require Repainting (Bldg SF) Room lacks appropriate sound control.	Capital Renewal	16,200	SF	5	\$106,318	Rollup
	Educational Adequacy	100	SF	5	\$3,456	Rollup
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$357,915</b>	

### Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	2	Ea.	1	\$2,806	Rollup
The Mounted Building Lighting Requires Replacement <b>Note:</b> Fixtures are damaged or clouded.	Capital Renewal	29	Ea.	3	\$42,994	8822
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$45,799</b>	



# Facility Condition Assessment

South Kingstown - Broad Rock Middle School

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks a drinking fountain.	Educational Adequacy	5	Ea.	5	\$5,477	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	13	Ea.	5	\$19,519	Rollup
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$24,995</b>	

## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	2	Ea.	1	\$22,663	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$22,663</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,332	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	264	Ea.	3	\$124,647	13184
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	26	Ea.	3	\$515,585	13186
Technology: Gymnasium sound system is nonexistent, inadequate, or near end of useful life.	Technology	1	Ea.	3	\$9,065	13189
Technology: Instructional spaces do not have local sound reinforcement.	Technology	34	Ea.	3	\$160,530	13194
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1	Ea.	3	\$5,288	13181
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$16,620	13180
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$4,721	13182
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,610	13179
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$42,304	13178
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	32	Ea.	3	\$13,598	13188
Technology: Network system inadequate and/or near end of useful life	Technology	21	Ea.	3	\$99,151	13193
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	48	Ea.	3	\$22,663	13187
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	77,781	SF	3	\$132,207	13190
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$53,825	13185
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$4,721	13183
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	36	Ea.	3	\$54,391	13192
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,177	13191
<b>Sub Total for System</b>		<b>18</b>	<b>items</b>		<b>\$1,284,436</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks an appropriate refrigerator.	Educational Adequacy	4	Ea.	5	\$33,995	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$33,995</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>31</b>	<b>items</b>		<b>\$1,771,242</b>	
<b>Total for Campus</b>		<b>40</b>	<b>items</b>		<b>\$3,397,305</b>	



## Broad Rock Middle School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	830	LF	\$53,657	4
Fences and Gates	Fencing - Chain Link (8 Ft)	80	LF	\$5,378	4
Playfield Areas	MS Athletic Components	1	Ea.	\$339,701	4
Fences and Gates	Wood	150	LF	\$37,077	5
Pedestrian Pavement	Sidewalks - Concrete	6,743	SF	\$137,824	5
Parking Lot Lighting	Pole Mounted Fixtures (Ea.)	20	Ea.	\$154,697	5
<b>Note:</b> Parking and tennis courts					
		<b>Sub Total for System</b>		<b>6 items</b>	<b>\$728,336</b>
		<b>Sub Total for Building -</b>		<b>6 items</b>	<b>\$728,336</b>

### Building: 01 - Main Building

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Rubber Tile Flooring	1,800	SF	\$33,626	3
Resilient Flooring	Vinyl Composition Tile Flooring	55,725	SF	\$639,263	4
Wall Painting and Coating	Painting/Staining (Bldg SF)	60,861	SF	\$402,130	4
Interior Operable Partitions	Foldable partition (Bldg SF)	1,296	SF Wall	\$149,701	5
		<b>Sub Total for System</b>		<b>4 items</b>	<b>\$1,224,719</b>

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	53	Ea.	\$896,484	4
Decentralized Cooling	Thru-Wall AC (2 Ton)	1	Ea.	\$7,081	4
Decentralized Cooling	Ductless Split System (3 Ton)	2	Ea.	\$15,565	4
Facility Hydronic Distribution	Pump - 5HP	2	Ea.	\$19,060	4
Air Distribution	Make-up Air Unit	10	Ea.	\$158,995	4
Decentralized Cooling	Ductless Split System (1 Ton)	3	Ea.	\$42,348	4
Decentralized Cooling	Package DX Unit (10 Ton)	4	Ea.	\$88,468	4
<b>Note:</b> 1 @ 7.5 ton, 3 @ 10 ton					
Decentralized Cooling	Package DX Unit ( 5 Ton)	3	Ea.	\$43,249	4
Heating System Supplementary Components	Controls - DDC (Bldg.SF)	77,781	SF	\$468,338	5
Exhaust Air	Laboratory Fume Hood	4	Ea.	\$114,084	5
Exhaust Air	Roof Exhaust Fan	52	Ea.	\$270,614	5
		<b>Sub Total for System</b>		<b>11 items</b>	<b>\$2,124,285</b>

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)	8	Ea.	\$11,028	4
Packaged Generator Assemblies	Emergency Generator (50 KW)	1	Ea.	\$76,056	5
<b>Note:</b> 25 kw					
Lighting Fixtures	Light Fixtures (Bldg SF)	77,781	SF	\$462,164	5
		<b>Sub Total for System</b>		<b>3 items</b>	<b>\$549,247</b>

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	1	Ea.	\$7,377	4
		<b>Sub Total for System</b>		<b>1 items</b>	<b>\$7,377</b>

#### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	77,781	SF	\$227,976	3
		<b>Sub Total for System</b>		<b>1 items</b>	<b>\$227,976</b>
		<b>Sub Total for Building 01 - Main Building</b>		<b>20 items</b>	<b>\$4,133,605</b>
		<b>Total for: Broad Rock Middle School</b>		<b>26 items</b>	<b>\$4,861,940</b>



## Supporting Photos



Cracked Asphalt Paving



Elevation



Site Aerial



Alligatored Asphalt





# Facility Condition Assessment

South Kingstown - Broad Rock Middle School



Kitchen



Hallway Finishes



Gymnasium



Front Entrance



Music Room



Computer Lab



# Facility Condition Assessment

South Kingstown - Broad Rock Middle School



Library



Typical Classroom



Stage



Plaque



Science Room



Cafeteria



# Facility Condition Assessment


South Kingstown - Broad Rock Middle School




Marquee



Typical Classroom With Partition



Worn Wood Floor At Stage



Worn Carpet



Canopy




Aged Building Light



# Facility Condition Assessment

South Kingstown - Broad Rock Middle School



Worn Wall Paint



Roof



Worn Stair Treads



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

June 2017

301 Curtis Corner Road, Wakefield, RI 02879





## Introduction

Curtis Corner Middle School, located at 301 Curtis Corner Road in Wakefield, Rhode Island, was built in 1964. It comprises 99,697 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Curtis Corner Middle School serves grades 7 - 8, has 49 instructional spaces, and has an enrollment of 511. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Curtis Corner Middle School is 729 with a resulting utilization of 70%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Curtis Corner Middle School the 5-year need is \$15,663,052. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Curtis Corner Middle School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Curtis Corner Middle School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	CMU Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Storefront Entrance Doors
	Steel Exterior Entrance Doors
<b>02 - Concessions:</b>	CMU Exterior Wall
	Wood Siding Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Wood Exterior Doors
<b>03 - Storage:</b>	Wood Siding Exterior Wall
	Steel Exterior Entrance Doors
<b>04 - Greenhouse :</b>	Clear Polycarbonate Exterior Wall
	Storefront Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Built-Up Roofing With Ballast
	Modified Bitumen Roofing
	Canopy Roofing
<b>02 - Concessions:</b>	Composition Shingle Roofing
<b>03 - Storage:</b>	Composition Shingle Roofing
<b>04 - Greenhouse :</b>	Clear Polycarbonate Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors





<b>01 - Main Building:</b>	Interior Door Hardware
	Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	CMU Wall
	Interior Wall Painting
	Ceramic Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Carpet
	Athletic/Sport Flooring
<b>02 - Concessions:</b>	Steel Interior Doors
	Interior Door Hardware
	Painted Ceilings
	Wood Ceilings
	FRP Wall Finish
	Brick/Stone Veneer
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Rubber Tile Flooring
	Epoxy Coated Flooring
<b>03 - Storage:</b>	Wood Ceilings
	Wood Wall Paneling
	Concrete Flooring
<b>04 - Greenhouse :</b>	Concrete Flooring

## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	400 MBH Cast Iron Water Boiler
	4,488 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	DDC Heating System Controls
	Pneumatic Heating System Controls
	2 Ton Ductless Split System
	3 Ton Ductless Split System
	5 Ton Package DX Unit
	10 Ton Package DX Unit
	Window Units



<b>01 - Main Building:</b>	Make-up Air Unit
	2-Pipe Hot Water Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	10 HP Pump
	Ductwork
	Kitchen Exhaust Hoods
	Laboratory Fume Hood
	Roof Exhaust Fan
	Supply Fan
	Wall Exhaust Fan
<b>02 - Concessions:</b>	10 kW Electric Unit Heater
	Electronic Heating System Controls
	Roof Exhaust Fan
<b>04 - Greenhouse :</b>	100 MBH Gas Furnace
	10 kW Electric Unit Heater
	5,000 CFM Interior AHU
	Ductwork
	Wall Exhaust Fan

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	2" Backflow Preventers
	Gas Piping System
	50 Gallon Gas Water Heater
	60 Gallon Gas Water Heater
<b>02 - Concessions:</b>	2" Backflow Preventers
	30 Gallon Electric Water Heater
<b>01 - Main Building:</b>	Domestic Water Piping System
<b>02 - Concessions:</b>	Domestic Water Piping System
<b>04 - Greenhouse :</b>	Domestic Water Piping System
<b>01 - Main Building:</b>	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
<b>02 - Concessions:</b>	Lavatories
	Mop/Service Sinks



<b>02 - Concessions:</b>	Non-Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
<b>01 - Main Building:</b>	Sump Pump
	Air Compressor (2 hp)
	Air Compressor (5 hp)
<b>04 - Greenhouse :</b>	550 Gallon Above Ground Fuel Oil Storage Tank

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	75 kW Emergency Generator
	Automatic Transfer Switch
	600 Amp Switchgear
	800 Amp Switchgear
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures
<b>02 - Concessions:</b>	Panelboard - 120/208 225A
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures
<b>03 - Storage:</b>	Panelboard - 120/208 100A
	Light Fixtures
<b>04 - Greenhouse :</b>	Panelboard - 120/208 225A
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$263,009	\$1,080,135	\$69,827	\$1,412,971	13.61 %
Roofing	-	\$1,388,018	-	-	-	\$1,388,018	13.37 %
Structural	\$1,365	-	-	-	-	\$1,365	0.01 %
Exterior	-	\$342,437	\$415	-	\$199,646	\$542,499	5.23 %
Interior	-	-	\$611,442	\$1,115,142	\$637,218	\$2,363,803	22.77 %
Mechanical	-	\$1,963,441	\$172,888	\$292,627	\$15,648	\$2,444,605	23.55 %
Electrical	\$7,061	\$139,787	\$46,270	\$45,491	\$35,082	\$273,692	2.64 %
Plumbing	-	-	\$213,063	\$193,684	\$25,802	\$432,548	4.17 %
Fire and Life Safety	\$84,414	-	-	-	-	\$84,414	0.81 %
Technology	-	-	\$1,286,535	-	-	\$1,286,535	12.39 %
Conveyances	-	-	\$47,535	-	-	\$47,535	0.46 %
Specialties	-	-	\$13,690	\$30,995	\$59,894	\$104,579	1.01 %
<b>Total</b>	<b>\$92,841</b>	<b>\$3,833,683</b>	<b>\$2,654,847</b>	<b>\$2,758,074</b>	<b>\$1,043,119</b>	<b>\$10,382,564</b>	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$2,444,605
Interior	-	\$2,363,803
Site	-	\$1,412,971

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$85,563	-	\$85,563
Barrier to Accessibility	-	-	\$65,218	-	-	\$65,218
Capital Renewal	\$17,329	\$3,833,683	\$1,286,383	\$2,237,178	\$868,517	\$8,243,089
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$75,511	-	\$25,098	\$28,329	\$174,602	\$303,541
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$407,005	-	\$407,005
Technology	-	-	\$1,275,127	-	-	\$1,275,127
Traffic	-	-	\$3,022	-	-	\$3,022
<b>Total</b>	<b>\$92,841</b>	<b>\$3,833,683</b>	<b>\$2,654,847</b>	<b>\$2,758,074</b>	<b>\$1,043,119</b>	<b>\$10,382,564</b>

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,412,971	\$0	\$0	\$0	\$339,701	\$30,939	\$370,640	\$1,783,611
Roofing	\$1,388,018	\$0	\$0	\$2,308,178	\$0	\$11,408	\$2,319,586	\$3,707,604
Structural	\$1,365	\$0	\$0	\$0	\$0	\$0	\$0	\$1,365
Exterior	\$542,499	\$0	\$0	\$0	\$0	\$21,391	\$21,391	\$563,890
Interior	\$2,363,803	\$0	\$0	\$3,651	\$421,044	\$0	\$424,695	\$2,788,498
Mechanical	\$2,444,605	\$0	\$0	\$0	\$57,240	\$706,425	\$763,665	\$3,208,270
Electrical	\$273,692	\$0	\$574,560	\$0	\$0	\$41,308	\$615,868	\$889,560
Plumbing	\$432,548	\$0	\$1,867	\$0	\$0	\$5,246	\$7,113	\$439,661
Fire and Life Safety	\$84,414	\$0	\$0	\$288,109	\$0	\$0	\$288,109	\$372,523
Technology	\$1,286,535	\$0	\$0	\$0	\$0	\$0	\$0	\$1,286,535
Conveyances	\$47,535	\$0	\$0	\$47,535	\$0	\$0	\$47,535	\$95,070
Specialties	\$104,579	\$0	\$0	\$418,188	\$0	\$0	\$418,188	\$522,767
<b>Total</b>	<b>\$10,382,564</b>	<b>\$0</b>	<b>\$576,427</b>	<b>\$3,065,661</b>	<b>\$817,985</b>	<b>\$816,717</b>	<b>\$5,276,790</b>	<b>\$15,659,354</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast





## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$32,900,010. For planning purposes, the total 5-year need at the Curtis Corner Middle School is \$15,663,052 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Curtis Corner Middle School facility has a 5-year FCI of 47.60%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 570 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Curtis Corner Middle School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$635,461.



## Summary of Findings

The Curtis Corner Middle School comprises 99,697 square feet and was constructed in 1964. Current deficiencies at this school total \$10,386,262. Five year capital renewal costs total \$5,276,790. The total identified need for the Curtis Corner Middle School (current deficiencies and 5-year capital renewal costs) is \$15,663,052. The 5-year FCI is 47.60%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Curtis Corner Middle School Totals	99,697	1964	\$10,386,262	\$5,276,790	\$15,663,052	47.60%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement <b>Note:</b> Concrete is cracked and spalling.	Capital Renewal	12,806	SF	3	\$259,987	9278
Crosswalk Requires Repainting <b>Note:</b> Repaint crosswalks on campus.	Traffic	4	Ea.	3	\$3,022	9344
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt is cracking and heaving.	Capital Renewal	134	CAR	4	\$440,356	9276
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt paving is alligating and heaving.	Capital Renewal	140	CAR	4	\$460,074	9277
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28594
Fencing Requires Replacement (4' Chain Link Fence)	Capital Renewal	340	LF	4	\$21,832	9275
Fencing Requires Replacement (8' Chain Link Fence) <b>Note:</b> Fence is damaged and falling.	Capital Renewal	1,940	LF	4	\$129,544	9274
Exterior Basketball Goals are Required <b>Note:</b> Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$5,807	28808
PE / Recess Playfield is Missing and is Needed <b>Note:</b> PE / Recess Playfield is Missing and is Needed	Educational Adequacy	1	Ea.	5	\$64,020	54953
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$1,412,971</b>	
<b>Sub Total for School and Site Level</b>		<b>9</b>	<b>items</b>		<b>\$1,412,971</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Built-up Roofing With Aggregate Ballast Requires Replacement <b>Note:</b> Roof leaks at science wing.	Capital Renewal	12,000	SF	2	\$456,335	9108
The Modified Roof Covering Requires Replacement <b>Note:</b> Water leak at north addition.	Capital Renewal	24,000	SF	2	\$912,669	9088
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$1,369,004</b>	

### Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Foundation Requires Minor Repairs <b>Note:</b> Concrete slab is cracked in two locations. One crack is near the new addition and runs from Room 507 to 516. The other crack is near the Science wing near Room 405.	Capital Renewal	2	Ea.	1	\$1,365	11449
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$1,365</b>	

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement <b>Note:</b> Single pane windows. Some are broken with paint peeling.	Capital Renewal	1,728	SF	2	\$292,419	9087
The Exterior Soffit Requires Repainting <b>Location:</b> Original building	Capital Renewal	60,000	SF	5	\$199,646	9086
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$492,066</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Acoustical Ceiling Tiles Require Replacement <b>Note:</b> Stained ceiling tiles.	Capital Renewal	50,697	SF	3	\$457,876	9089
The Carpet Flooring Requires Replacement <b>Note:</b> Carpet is worn in the library and Rooms 111, 112, and 109 at the original building.	Capital Renewal	4,500	SF	3	\$97,903	9091
The Existing Toilet Stall Does Not Meet Minimum ADA Requirements <b>Location:</b> Faculty restrooms	Barrier to Accessibility	2	Ea.	3	\$5,894	9105



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Wood Flooring Requires Replacement <b>Note:</b> Stage flooring is worn out and scratched.	Capital Renewal	1,500	SF	3	\$49,769	9093
Ceiling Grid Requires Replacement <b>Note:</b> Bent and stained ceiling grid at the original building.	Capital Renewal	50,697	SF	4	\$601,292	9130
Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	12,000	SF	4	\$342,251	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	500	SF	4	\$4,753	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	107	Ea.	4	\$30,517	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	678	LF	4	\$15,470	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	1,474	SF	4	\$14,013	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) <b>Note:</b> Gym	Acoustics	1,500	SF	4	\$85,563	19688
Interior Doors Require Repainting <b>Note:</b> Paint on metal doors throughout the building is scratched and worn.	Capital Renewal	80	Door	5	\$5,400	9090
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	95,097	SF	5	\$628,339	Rollup
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,480	Rollup
<b>Sub Total for System</b>		<b>14 items</b>			<b>\$2,342,520</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductless Split System AC Requires Replacement <b>Note:</b> Aged units with damaged coils.	Capital Renewal	4	Ea.	2	\$27,327	9126
Ductless Split System AC Requires Replacement <b>Note:</b> Aged unit with damaged coil.	Capital Renewal	1	Ea.	2	\$7,782	9127
Package DX Unit Requires Replacement <b>Note:</b> Units are aged and rusted with damaged coils.	Capital Renewal	2	Ea.	2	\$28,833	9123
Package DX Unit Requires Replacement <b>Note:</b> Units are aged and rusted with damaged coils.	Capital Renewal	3	Ea.	2	\$66,351	9124
Replace Unit Vent <b>Note:</b> Unit vents are aged with non-functional motors and clogged coils.	Capital Renewal	30	Ea.	2	\$507,444	9132
Replace Unit Vent <b>Note:</b> Unit vents are aged with non-functional motors and clogged coils.	Capital Renewal	50	Ea.	2	\$845,740	9133
The Cast Iron Water Boiler Requires Replacement <b>Note:</b> Per LEA review feedback - school needs new boiler.	Capital Renewal	1	Ea.	2	\$31,255	54849
The Radiant Heat HVAC Component Requires Replacement <b>Note:</b> Radiant heaters are aged with corroded connections and clogged coils.	Capital Renewal	44	Ea.	2	\$334,896	9134
The Large Diameter Exhausts/Hoods Require Replacement <b>Note:</b> Supply fan is rusted with broken connections.	Capital Renewal	1	Ea.	3	\$13,893	9097
The Make Up Air Equipment Requires Replacement <b>Note:</b> Units are aged with rusted and worn heat exchangers.	Capital Renewal	5	Ea.	3	\$79,497	9109
The Make Up Air Equipment Requires Replacement <b>Note:</b> Units are aged with broken connections. Some are non-functional.	Capital Renewal	5	Ea.	3	\$79,497	9110
Exhaust Fan Ventilation Requires Replacement <b>Note:</b> Wall exhaust fans are old and bearings are seizing.	Capital Renewal	5	Ea.	4	\$13,388	9098
Small HVAC Circulating Pump Requires Replacement <b>Note:</b> Pumps are old and leaking.	Capital Renewal	2	Ea.	4	\$19,060	9117
The Chemistry Lab Fume Hood(s) Require Replacement <b>Note:</b> Wood shop paint hood	Capital Renewal	1	Ea.	4	\$28,521	9084
The Exhaust Hood Requires Replacement <b>Note:</b> Units are rusted and bearings seizing. They have been painted and patched multiple times.	Capital Renewal	44	Ea.	4	\$228,981	9131
Remove Abandoned Equipment <b>Note:</b> Fuel oil equipment (pump, filter, and line set) needs to be removed.	Capital Renewal	3	Ea.	5	\$9,389	9113
Remove Abandoned Equipment <b>Note:</b> Incinerator	Capital Renewal	1	Ea.	5	\$3,130	9114



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Remove Abandoned Equipment	Capital Renewal	1	Ea.	5	\$3,130	9115
<b>Note:</b> Abandoned water storage tank						
<b>Sub Total for System</b>		<b>18</b>	<b>items</b>		<b>\$2,328,115</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	5	Ea.	1	\$7,061	Rollup
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$19,280	9135
<b>Note:</b> Switchgear is aged and replacement parts are no longer manufactured.						
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$23,482	9136
<b>Note:</b> Switchgear is aged and replacement parts are no longer manufactured.						
The Electrical Disconnect Requires Replacement	Capital Renewal	2	Ea.	2	\$3,666	9096
The Panelboard Requires Replacement	Capital Renewal	6	Ea.	2	\$29,091	9120
<b>Note:</b> Kelek panelboards are aged and replacement parts are no longer available.						
The Panelboard Requires Replacement	Capital Renewal	9	Ea.	2	\$52,193	9121
<b>Note:</b> 200 amps. Kelek panelboards are aged and replacement parts are no longer available.						
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$6,275	9122
<b>Note:</b> 250 amps. Kelek panelboards are aged and replacement parts are no longer available.						
The Mounted Building Lighting Requires Replacement	Capital Renewal	30	Ea.	3	\$44,778	9095
The Canopy Lighting Requires Replacement	Capital Renewal	25	Ea.	4	\$34,463	9094
Remove Abandoned Equipment	Capital Renewal	1	Ea.	5	\$3,321	9116
<b>Note:</b> Generator						
Room Has Insufficient Electrical Outlets	Educational Adequacy	64	Ea.	5	\$31,761	Rollup
<b>Sub Total for System</b>		<b>11</b>	<b>items</b>		<b>\$255,372</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Existing Lavatory/Sink Is Not ADA Compliant	Barrier to Accessibility	2	Ea.	3	\$11,789	9106
<b>Location:</b> At faculty restroom						
The Gas Water Heater Requires Replacement	Capital Renewal	1	Ea.	3	\$3,160	9118
<b>Note:</b> Gas water heater is aged and the connections are corroded.						
The Showers Plumbing Fixtures Require Replacement	Capital Renewal	25	Ea.	3	\$190,139	9102
<b>Note:</b> Showers are old with corroded nozzles.						
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	6	Ea.	3	\$7,974	9111
<b>Note:</b> Urinal fixtures are aged and stained and wall mounts are cracked.						
Non-Refrigerated Drinking Fountain Requires Replacement	Capital Renewal	7	Ea.	4	\$71,540	9103
<b>Note:</b> Drinking fountains are old with corroded nozzles.						
The Classroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	2	Ea.	4	\$5,438	9085
<b>Note:</b> Lavatories are aged, stained, and corroded.						
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	5	Ea.	4	\$12,882	9107
<b>Note:</b> Service sinks are stained, corroded, and rusted.						
The Refrigerated Water Cooler Requires Replacement	Capital Renewal	2	Ea.	4	\$14,755	9112
<b>Note:</b> Refrigerated drinking fountains are aged and rusted and compressors are non-functional.						
The Restroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	18	Ea.	4	\$57,259	9099
<b>Note:</b> Restroom lavatories are aged and stained with rusted valves.						
The Restroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	10	Ea.	4	\$31,810	9100
<b>Note:</b> Lavatories are aged, stained, and corroded.						
Room lacks a drinking fountain.	Educational Adequacy	6	Ea.	5	\$6,617	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	2	Ea.	5	\$3,023	Rollup
<b>Sub Total for System</b>		<b>12</b>	<b>items</b>		<b>\$416,386</b>	



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Kitchen Exhaust Hood	Capital Renewal	1	Ea.	1	\$15,964	9125
<b>Note:</b> Kitchen exhaust hood is aged with clogged filters.						
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	6	Ea.	1	\$68,450	Rollup
	<b>Sub Total for System</b>	<b>2</b>	<b>items</b>		<b>\$84,414</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,408	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	336	Ea.	3	\$159,717	13228
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	33	Ea.	3	\$313,730	13231
Technology: Gymnasium sound system is nonexistent, inadequate, or near end of useful life.	Technology	1	Ea.	3	\$9,127	13235
Technology: Instructional spaces do not have local sound reinforcement.	Technology	35	Ea.	3	\$166,372	13236
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$45,253	13217
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$45,253	13221
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$45,253	13225
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$4,753	13219
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$4,753	13223
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13215
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13218
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13222
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13226
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$50,197	13214
Technology: Network system inadequate and/or near end of useful life	Technology	1	Ea.	3	\$7,606	13232
Technology: Network system inadequate and/or near end of useful life	Technology	23	Ea.	3	\$109,330	13234
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	96	Ea.	3	\$45,633	13229
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	96,697	SF	3	\$165,473	13233
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$54,190	13230
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$7,606	13216
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$4,753	13220
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$4,753	13224
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$4,753	13227
	<b>Sub Total for System</b>	<b>24</b>	<b>items</b>		<b>\$1,286,535</b>	



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

## Conveyances

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Access Is Not ADA Compliant And Requires A Platform Lift	Barrier to Accessibility	1	Ea.	3	\$47,535	9104
<b>Note:</b> Lift by the nurse's office is not functional.						
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$47,535</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	3	Ea.	3	\$13,690	Rollup
The Metal Student Lockers Require Replacement	Capital Renewal	63	Ea.	4	\$30,995	9128
<b>Note:</b> Boy's locker room lockers are dented and showing signs of wear.						
Room lacks an appropriate refrigerator.	Educational Adequacy	7	Ea.	5	\$59,894	Rollup
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$104,579</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>90</b>	<b>items</b>		<b>\$8,727,890</b>	

## Building: 02 - Concessions

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Epoxy Flooring Requires Repair Or Replacement	Capital Renewal	640	SF	4	\$12,169	9140
<b>Note:</b> Epoxy flooring is cracking.						
<b>Location:</b> Restrooms						
The Concrete Flooring Requires Replacement	Capital Renewal	700	SF	4	\$9,114	9137
<b>Note:</b> Concrete finish is faded and worn.						
<b>Location:</b> First floor						
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$21,283</b>	

### Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Electric Unit Heater Requires Replacement	Capital Renewal	1	Ea.	2	\$2,476	9141
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$2,476</b>	

### Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Mounted Building Lighting Requires Replacement	Capital Renewal	1	Ea.	3	\$1,493	9139
The Canopy Lighting Requires Replacement	Capital Renewal	8	Ea.	4	\$11,028	9138
<b>Note:</b> Canopy fixtures are broken.						
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$12,521</b>	
<b>Sub Total for Building 02 - Concessions</b>		<b>5</b>	<b>items</b>		<b>\$36,279</b>	

## Building: 03 - Storage

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Exterior Wood Requires Replacement (Bldg SF)	Capital Renewal	400	SF	2	\$11,990	9143
<b>Note:</b> Exterior wood is molding and should be replaced.						
Exterior Metal Door Requires Repainting	Capital Renewal	2	Door	3	\$415	9142
<b>Note:</b> Paint is peeling at exterior double doors.						
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$12,405</b>	
<b>Sub Total for Building 03 - Storage</b>		<b>2</b>	<b>items</b>		<b>\$12,405</b>	

## Building: 04 - Greenhouse

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Plexiglass/Polycarbonate Sheet Roof Requires Replacement	Capital Renewal	1,000	SF	2	\$19,014	9145
<b>Note:</b> Polycarbonate roof sheets are missing or broken.						
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$19,014</b>	





# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School

## Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Greenhouse (polycarbonate) Walls Require Replacement (Bldg SF)	Capital Renewal	1,000	SF	2	\$38,028	9150
<b>Note:</b> Polycarbonate is broken or missing.						
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$38,028</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Electric Unit Heater Requires Replacement	Capital Renewal	3	Ea.	2	\$7,427	9146
The Air Handler HVAC Component Requires Replacement	Capital Renewal	1	Ea.	2	\$101,258	9288
The Gas Furnace HVAC Component Requires Replacement	Capital Renewal	1	Ea.	2	\$2,652	9148
<b>Note:</b> Vent is broken and rusting.						
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	1	Ea.	4	\$2,678	9144
<b>Note:</b> Exhaust fan is rusted and non-functional.						
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>		<b>\$114,015</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$5,799	9147
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$5,799</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Above Ground Fuel/Oil Storage Tank Requires Replacement	Capital Renewal	1	Ea.	5	\$16,162	9149
<b>Note:</b> Tank is rusting and there is no secondary containment or protection.						
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$16,162</b>	
<b>Sub Total for Building 04 - Greenhouse</b>		<b>8</b>	<b>items</b>		<b>\$193,018</b>	
<b>Total for Campus</b>		<b>114</b>	<b>items</b>		<b>\$10,382,564</b>	



## Curtis Corner Middle School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Playfield Areas	MS Athletic Components	1	Ea.	\$339,701	4
Parking Lot Lighting	Pole Mounted Fixtures (Ea.)	4	Ea.	\$30,939	5
		<b>Sub Total for System</b>	<b>2 items</b>	<b>\$370,641</b>	
		<b>Sub Total for Building -</b>	<b>2 items</b>	<b>\$370,641</b>	

#### Building: 01 - Main Building

#### Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Built-Up Roofing (BUR) w/ballast	60,697	SF	\$2,308,178	3
		<b>Sub Total for System</b>	<b>1 items</b>	<b>\$2,308,178</b>	

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Vinyl Composition Tile Flooring	36,000	SF	\$412,983	4
		<b>Sub Total for System</b>	<b>1 items</b>	<b>\$412,983</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Facility Hydronic Distribution	Pump - 1HP or Less (Ea.)	5	Ea.	\$38,142	4
<b>Note:</b> Booster pumps					
Decentralized Cooling	Window Units	1	Ea.	\$3,339	4
Exhaust Air	Laboratory Fume Hood	2	Ea.	\$57,042	5
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	77,358	SF	\$522,530	5
Heating System Supplementary Components	Controls - DDC (Bldg.SF)	19,339	SF	\$116,445	5
		<b>Sub Total for System</b>	<b>5 items</b>	<b>\$737,498</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	96,697	SF	\$574,560	2
<b>Note:</b> T5 bulbs					
Electrical Service	Switchgear - Main Dist Panel (800 Amps)	1	Ea.	\$23,482	5
		<b>Sub Total for System</b>	<b>2 items</b>	<b>\$598,042</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 60 gallon	1	Ea.	\$3,797	5
Building Support Plumbing System Supplementary Components	Sump Pump	1	Ea.	\$1,449	5
		<b>Sub Total for System</b>	<b>2 items</b>	<b>\$5,246</b>	

#### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	96,697	SF	\$283,419	3
		<b>Sub Total for System</b>	<b>1 items</b>	<b>\$283,419</b>	

#### Conveyances

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lifts	ADA Wheelchair lift	1	Ea.	\$47,535	3
		<b>Sub Total for System</b>	<b>1 items</b>	<b>\$47,535</b>	

#### Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Lockers	850	Ea.	\$418,188	3
		<b>Sub Total for System</b>	<b>1 items</b>	<b>\$418,188</b>	
		<b>Sub Total for Building 01 - Main Building</b>	<b>14 items</b>	<b>\$4,811,088</b>	



## Building: 02 - Concessions

### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	1,220	SF	\$8,061	4
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$8,061</b>	

### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Unit Heater Electric (10 KW)	2	Ea.	\$4,951	4
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)	1,600	SF	\$10,808	4
Exhaust Air	Roof Exhaust Fan	2	Ea.	\$10,408	5
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$26,167</b>	

### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	1,600	SF	\$9,507	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$9,507</b>	

### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 30 gallon	1	Ea.	\$1,867	2
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$1,867</b>	

### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	1,600	SF	\$4,690	3
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$4,690</b>	
<b>Sub Total for Building 02 - Concessions</b>		<b>7</b>	<b>items</b>	<b>\$50,292</b>	

## Building: 03 - Storage

### Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Steep Slope Roofing	Composition Shingle	400	SF	\$11,408	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$11,408</b>	

### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Paneling	Wood Panel wall	400	SF	\$3,651	3
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$3,651</b>	

### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	400	SF	\$2,377	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$2,377</b>	
<b>Sub Total for Building 03 - Storage</b>		<b>3</b>	<b>items</b>	<b>\$17,436</b>	

## Building: 04 - Greenhouse

### Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum	3	Door	\$21,391	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$21,391</b>	

### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	1,000	SF	\$5,942	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$5,942</b>	
<b>Sub Total for Building 04 - Greenhouse</b>		<b>2</b>	<b>items</b>	<b>\$27,333</b>	
<b>Total for: Curtis Corner Middle School</b>		<b>28</b>	<b>items</b>	<b>\$5,276,789</b>	



## Supporting Photos



Paint Peeling



Damaged Lockers



Aged Heating Unit



Roof Exhaust



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Worn Floor Coating



Switchgear



Exterior Drinking Fountain



Unit Heater



Pressbox Interior



Concessions Rear Elevation



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School




Paint Peeling On Exterior Door



Concessions Front Elevation



Storage Exterior



Molding Exterior



Damaged Chain Link Fence



Damaged Chain Link



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Alligatored And Patched Asphalt Parking



Storage Interior



Rusted Wall Exhaust



Greenhouse Interior



Unit Heater



Greenhouse Panelboard



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Greenhouse AHU



Greenhouse Exterior



Exterior



Typical Classroom



Gym



Science Room





# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Bleachers



Addition Plaque



Gym 2



Cafeteria



Marquee



Athletic Field Signage



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Library



Music Room



Spalling Concrete Walkway



Alligatored Asphalt Paving



Site Aerial



Lab Exhaust Hood



# Facility Condition Assessment


South Kingstown - Curtis Corner Middle School



Classroom Lavatory



Peeling Exterior Paint



Broken Single-Pane Glass



Aged Windows



North Addition Roof



Stained And Broken Ceiling Tiles



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Stained Ceiling Grid




Scratched Door Paint



Worn Carpet



9x9 Tile



VCT Curling



Worn Wood Floor At Stage



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Damaged Canopy Light



Aged Building Mounted Light



Disconnect



Supply Fan



Typical Restroom Lavatory



Typical Toilet Fixture



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School



Typical Showers



Drinking Fountain



ADA Lift



Evidence Of Ponding On Roof



MUA



Typical Urinal Fixtures



# Facility Condition Assessment

South Kingstown - Curtis Corner Middle School




Drinking Fountains




Water Storage



Generator



Pumps



Water Heater



Cracked And Chipped VCT



100 Amp Panel



DX Unit



Kitchen Hood





# Facility Condition Assessment

South Kingstown - Matunuck School

June 2017

380 Matunuck Beach Road, Wakefield, RI 02879





## Introduction

Matunuck School, located at 380 Matunuck Beach Road in Wakefield, Rhode Island, was built in 1975. It comprises 44,332 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Matunuck School serves grades KG - 4, has 26 instructional spaces, and has an enrollment of 202. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Matunuck School is 400 with a resulting utilization of 51%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Matunuck School the 5-year need is \$7,358,769. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of Matunuck School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Matunuck School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	CMU Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors
<b>02 - Storage:</b>	Wood Siding Exterior Wall
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Metal Steep Slope Roofing
	Modified Bitumen Roofing
<b>02 - Storage:</b>	Composition Shingle Roofing
<b>03 - Pavillion:</b>	Composition Shingle Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Foldable Interior Partition
	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Door Hardware
	Painted Ceilings
	Wood Wall Paneling
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring



<b>01 - Main Building:</b>	Epoxy Coated Flooring
	Carpet
	Athletic/Sport Flooring
<b>02 - Storage:</b>	Wood Ceilings
	Concrete Flooring

## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Electric Heating Unit Vent
	Fin Tube Water Radiant Heater
	5 kW Electric Unit Heater
	Pneumatic Heating System Controls
	2 Ton Ductless Split System
	Window Units
	Make-up Air Unit
	5,000 CFM Interior AHU
	Ductwork
	Kitchen Exhaust Hoods
	Wall Exhaust Fan

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	2" Backflow Preventers
	Gas Piping System
	100 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Air Compressor (5 hp)
	550 Gallon Above Ground Fuel Oil Storage Tank

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	800 Amp Switchgear
----------------------------	--------------------



# Facility Condition Assessment

South Kingstown - Matunuck School

<b>01 - Main Building:</b>	112.5 KVA Transformer
	800 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Panelboard - 120/240 400A
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Panelboard - 277/480 400A
	Light Fixtures
	Building Mounted Lighting Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$387,552	\$623,139	\$5,807	\$1,016,498	16.29 %
Roofing	-	\$151,087	-	-	-	\$151,087	2.42 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$310,356	-	-	-	\$310,356	4.98 %
Interior	-	-	\$317,005	\$115,676	\$299,300	\$731,982	11.73 %
Mechanical	-	\$1,847,529	\$157,924	\$316,002	-	\$2,321,455	37.21 %
Electrical	-	\$441,500	\$51,487	-	\$3,943	\$496,931	7.97 %
Plumbing	-	-	\$19,435	\$153,871	\$25,775	\$199,082	3.19 %
Fire and Life Safety	\$158,446	-	-	-	-	\$158,446	2.54 %
Technology	-	-	\$820,741	-	-	\$820,741	13.16 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$31,728	-	-	\$31,728	0.51 %
<b>Total</b>	\$158,446	\$2,750,473	\$1,785,873	\$1,208,688	\$334,826	\$6,238,306	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$2,321,455
Site	-	\$1,016,498
Technology	-	\$820,741

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies





## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$33,995	-	\$33,995
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	\$31,713	\$2,750,473	\$841,346	\$1,064,683	\$311,897	\$5,000,112
Code Compliance	\$126,733	-	-	-	-	\$126,733
Educational Adequacy	-	-	\$54,391	\$28,329	\$22,929	\$105,649
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$81,682	-	\$81,682
Technology	-	-	\$798,078	-	-	\$798,078
Traffic	-	-	\$92,057	-	-	\$92,057
<b>Total</b>	<b>\$158,446</b>	<b>\$2,750,473</b>	<b>\$1,785,873</b>	<b>\$1,208,688</b>	<b>\$334,826</b>	<b>\$6,238,306</b>

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



### Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,016,498	\$0	\$0	\$0	\$44,588	\$0	\$44,588	\$1,061,086
Roofing	\$151,087	\$0	\$0	\$0	\$0	\$0	\$0	\$151,087
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$310,356	\$0	\$0	\$0	\$0	\$102,675	\$102,675	\$413,031
Interior	\$731,982	\$0	\$0	\$413,350	\$0	\$522,338	\$935,688	\$1,667,670
Mechanical	\$2,321,455	\$0	\$0	\$0	\$23,526	\$0	\$23,526	\$2,344,981
Electrical	\$496,931	\$0	\$0	\$0	\$0	\$0	\$0	\$496,931
Plumbing	\$199,082	\$0	\$0	\$5,322	\$7,377	\$0	\$12,699	\$211,781
Fire and Life Safety	\$158,446	\$0	\$0	\$0	\$0	\$0	\$0	\$158,446
Technology	\$820,741	\$0	\$0	\$0	\$0	\$0	\$0	\$820,741
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$31,728	\$0	\$0	\$0	\$0	\$0	\$0	\$31,728
<b>Total</b>	<b>\$6,238,306</b>	<b>\$0</b>	<b>\$0</b>	<b>\$418,672</b>	<b>\$75,491</b>	<b>\$625,013</b>	<b>\$1,119,176</b>	<b>\$7,357,482</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$15,516,200. For planning purposes, the total 5-year need at the Matunuck School is \$7,358,769 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Matunuck School facility has a 5-year FCI of 47.42%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 246 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Matunuck School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



## Summary of Findings

The Matunuck School comprises 44,332 square feet and was constructed in 1975. Current deficiencies at this school total \$6,239,593. Five year capital renewal costs total \$1,119,176. The total identified need for the Matunuck School (current deficiencies and 5-year capital renewal costs) is \$7,358,769. The 5-year FCI is 47.42%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
<b>Matunuck School Totals</b>	<b>44,332</b>	<b>1975</b>	<b>\$6,239,593</b>	<b>\$1,119,176</b>	<b>\$7,358,769</b>	<b>47.42%</b>

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement <b>Note:</b> Cracked and spalling concrete sidewalks.	Capital Renewal	14,555	SF	3	\$295,495	4506
New Sidewalk Is Required <b>Note:</b> Install sidewalks from crosswalk at the front of the school to the intersection crosswalk (6' wide)	Traffic	4,062	SF	3	\$92,057	9290
Asphalt Paving Requires Replacement <b>Note:</b> Parking lot is cracked and alligatored.	Capital Renewal	83	CAR	4	\$272,758	4503
Asphalt Paving Requires Replacement <b>Note:</b> Pavement is cracked and alligatored.	Capital Renewal	89	CAR	4	\$292,475	4504
Asphalt Paving Requires Replacement <b>Note:</b> Paved play area is depressed and cracked.	Capital Renewal	9	CAR	4	\$29,576	4505
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28592
Exterior Basketball Goals are Required <b>Note:</b> Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$5,807	28807
<b>Sub Total for System</b>		<b>7</b>	<b>items</b>		<b>\$1,016,498</b>	

### Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Pole Lighting Requires Replacement <b>Note:</b> Old sodium vapor lighting is insufficient.	Capital Renewal	4	Ea.	3	\$30,731	4507
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$30,731</b>	
<b>Sub Total for School and Site Level</b>		<b>8</b>	<b>items</b>		<b>\$1,047,230</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Modified Roof Covering Requires Replacement <b>Note:</b> Roof leaks at two classroom wings. Updated per LEA review feedback. Replaced all but 4,000 SF of roof during summer 2016.	Capital Renewal	4,000	SF	2	\$151,087	4752
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$151,087</b>	

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement <b>Note:</b> Windows have rusting frames with exterior caulk failing and air leaking in. All exterior windows should be replaced.	Capital Renewal	1,088	SF	2	\$182,876	4510
The Metal Exterior Door Requires Replacement <b>Note:</b> Doors at the south side of the main building and east wing are rusted and faded and need to be replaced.	Capital Renewal	20	Door	2	\$127,480	4509
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$310,356</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement <b>Note:</b> Laminate is scratched and chipped on doors throughout the main building.	Capital Renewal	20	Door	3	\$91,597	4511
The Acoustical Ceiling Tiles Require Replacement <b>Location:</b> Main building and kitchen	Capital Renewal	18,382	SF	3	\$164,901	4533
The Carpet Flooring Requires Replacement	Capital Renewal	2,800	SF	3	\$60,507	4755
Caulking - significant areas of broken pieces &/or deteriorating caulk	Hazardous Material	250	LF	4	\$4,721	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	245	Ea.	4	\$69,406	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	800	SF	4	\$7,554	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) <b>Note:</b> Gym	Acoustics	600	SF	4	\$33,995	19712
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	43,352	SF	5	\$284,513	Rollup
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,456	Rollup



# Facility Condition Assessment

South Kingstown - Matunuck School

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Concrete Flooring Requires Repair Or Repainting <b>Note:</b> Painted concrete floor has chipped and faded paint.	Capital Renewal	1,500	SF	5	\$11,332	4754
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$731,982</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Requires Replacement (SF Basis) <b>Note:</b> Replace with MUA units.	Capital Renewal	13,060	SF	2	\$190,704	9238
Electric Unit Heater Requires Replacement <b>Note:</b> Fans are non-functional.	Capital Renewal	1	Ea.	2	\$1,349	4527
Replace Unit Vent <b>Note:</b> Unit vent is aged with clogged coils.	Capital Renewal	23	Ea.	2	\$323,393	4534
Replace Unit Vent <b>Note:</b> Unit is old with clogged coils.	Capital Renewal	2	Ea.	2	\$28,121	4535
Replace Unit Vent <b>Note:</b> Oil-filled electric heat.	Capital Renewal	2	Ea.	2	\$33,602	4756
The Air Handler HVAC Component Requires Replacement <b>Note:</b> AHUs are old with very noisy bearings and blowers.	Capital Renewal	10	Ea.	2	\$1,005,759	4521
The Radiant Heat HVAC Component Requires Replacement <b>Note:</b> Units are aged and fins are packed and not effectively dissipating heat.	Capital Renewal	35	Ea.	2	\$264,601	4536
The Make Up Air Equipment Requires Replacement	Capital Renewal	10	Ea.	3	\$157,924	9239
Exhaust Fan Ventilation Requires Replacement <b>Note:</b> Bearings and blowers are worn out.	Capital Renewal	9	Ea.	4	\$23,936	4513
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls <b>Note:</b> Pneumatic system is aged with numerous patches and leaks.	Capital Renewal	43,532	SF	4	\$292,066	4532
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$2,321,455</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Switchgear Is Needed Or Requires Replacement <b>Note:</b> Switchgear is old and running excessively hot.	Capital Renewal	1	Ea.	2	\$23,324	4537
The Distribution Panel Requires Replacement	Capital Renewal	1	Ea.	2	\$28,971	9237
The Lighting Fixtures Require Replacement <b>Note:</b> Aged, low efficiency ballasted fixtures.	Capital Renewal	43,532	SF	2	\$256,919	4529
The Panelboard Requires Replacement <b>Note:</b> Panels are aged and breakers are cracked.	Capital Renewal	2	Ea.	2	\$15,298	4522
The Panelboard Requires Replacement <b>Note:</b> 150 amp single breaker panelboard with cracking breakers.	Capital Renewal	3	Ea.	2	\$17,281	4523
The Panelboard Requires Replacement <b>Note:</b> Panel has multiple defective breakers.	Capital Renewal	1	Ea.	2	\$6,232	4524
The Panelboard Requires Replacement	Capital Renewal	5	Ea.	2	\$59,396	4525
The Panelboard Requires Replacement	Capital Renewal	3	Ea.	2	\$34,080	4526
The Mounted Building Lighting Requires Replacement <b>Note:</b> Building mounted lights are old, low efficiency units with broken lenses.	Capital Renewal	14	Ea.	3	\$20,756	4512
Room Has Insufficient Electrical Outlets	Educational Adequacy	8	Ea.	5	\$3,943	Rollup
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$466,199</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Showers Plumbing Fixtures Require Replacement <b>Note:</b> Shower is no longer functional. <b>Location:</b> Nurse's office	Capital Renewal	1	Ea.	3	\$7,554	4517
The Urinal Plumbing Fixtures Require Replacement <b>Note:</b> Urinal fixtures are aged and stained.	Capital Renewal	9	Ea.	3	\$11,881	4519
The Classroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Sinks are old and stained.	Capital Renewal	15	Ea.	4	\$40,510	4508





# Facility Condition Assessment

South Kingstown - Matunuck School

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Concrete service sinks are aged, stained, and leaking.	Capital Renewal	4	Ea.	4	\$10,236	4518
The Refrigerated Water Cooler Requires Replacement <b>Note:</b> Compressors are non-functional.	Capital Renewal	2	Ea.	4	\$14,655	4520
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Sinks are aged, stained, and pitted.	Capital Renewal	10	Ea.	4	\$31,596	4514
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Restroom lavatories are aged and stained.	Capital Renewal	18	Ea.	4	\$56,873	4515
Above Ground Fuel/Oil Storage Tank Requires Replacement <b>Note:</b> Tank is old and has no testing or monitoring performed.	Capital Renewal	1	Ea.	5	\$16,053	4531
Room lacks a drinking fountain.	Educational Adequacy	1	Ea.	5	\$1,095	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	8	Ea.	5	\$8,627	Rollup
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$199,082</b>	

## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Alarm Is Missing Or Inadequate (NFPA 72 and NFPA 101, Section 9.6) <b>Note:</b> Per LEA review feedback - fire alarm system should be replaced.	Code Compliance	43,532	SF	1	\$126,733	54850
Replace Kitchen Exhaust Hood <b>Note:</b> Hoods are aged and clogged.	Capital Renewal	2	Ea.	1	\$31,713	4528
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$158,446</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	4	Ea.	3	\$22,663	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	144	Ea.	3	\$67,989	13123
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	20	Ea.	3	\$188,859	13128
Technology: Instructional spaces do not have local sound reinforcement.	Technology	23	Ea.	3	\$108,594	13133
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,610	13122
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$21,530	13121
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	60	Ea.	3	\$25,496	13124
Technology: Network system inadequate and/or near end of useful life	Technology	2	Ea.	3	\$15,109	13131
Technology: Network system inadequate and/or near end of useful life	Technology	25	Ea.	3	\$118,037	13132
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	96	Ea.	3	\$45,326	13125
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	43,532	SF	3	\$73,993	13130
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$53,825	13126
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$53,825	13127
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	1	Room	3	\$18,886	13129
<b>Sub Total for System</b>		<b>14</b>	<b>items</b>		<b>\$820,741</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	7	Ea.	3	\$31,728	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$31,728</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>60</b>	<b>items</b>		<b>\$5,191,077</b>	
<b>Total for Campus</b>		<b>68</b>	<b>items</b>		<b>\$6,238,306</b>	



## Buildings with no reported deficiencies

02 - Building-02

03 - Pavillion



## Matunuck School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Playfield Areas	ES Playgrounds	1	Ea.	\$44,588	4
		<b>Sub Total for System</b>		<b>\$44,588</b>	
		<b>Sub Total for Building -</b>		<b>\$44,588</b>	

### Building: 01 - Main Building

#### Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	16	Door	\$102,675	5
		<b>Sub Total for System</b>		<b>\$102,675</b>	

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Vinyl Composition Tile Flooring	36,032	SF	\$413,350	3
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	18,382	SF	\$218,020	5
Interior Swinging Doors	Wood	66	Door	\$304,318	5
		<b>Sub Total for System</b>		<b>\$935,688</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Window Units	5	Ea.	\$16,694	4
Decentralized Cooling	Ductless Split System (2 Ton)	1	Ea.	\$6,832	4
		<b>Sub Total for System</b>		<b>\$23,526</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 100 Gallon	1	Ea.	\$5,322	3
Plumbing Fixtures	Refrigerated Drinking Fountain	1	Ea.	\$7,377	4
		<b>Sub Total for System</b>		<b>\$12,699</b>	
		<b>Sub Total for Building 01 - Main Building</b>		<b>\$1,074,588</b>	
		<b>Total for: Matunuck School</b>		<b>\$1,119,176</b>	



**Supporting Photos**



Cracked And Worn Parking



Alligatored Parking Lot Paving



Cracked Concrete Walkway



Sinking And Cracking Pavement



# Facility Condition Assessment

South Kingstown - Matunuck School



Site Aerial



Old Pole Lights



Entrance



Cafeteria



Music Room



School Signage



# Facility Condition Assessment

South Kingstown - Matunuck School



Gymnasium




Building Entrance



Typical Classroom



Hallway Finishes



Typical Classroom Lavatory



Exterior Door Rusting



Faded And Worn Exterior Door



Failed Window Caulking



Rusting Window



Chipped Laminate Wood Door



Low Efficiency Building Mounted Light



Exhaust Fan



# Facility Condition Assessment

South Kingstown - Matunuck School



Handwashing Kitchen Sink




Stainless Kitchen Sinks




Aged And Stained Restroom Lavatory



Nurse's Office Shower



Stained And Leaking Service Sink



Typical Urinals





# Facility Condition Assessment

South Kingstown - Matunuck School



Refrigerated Drinking Fountain With Non-Functional Compressor



Aged Air Handling Unit



Air Handling Unit



Aged Panel



Panelboards



400 Amp Panel



Non-Functional Electric Unit Heater



Kitchen Exhaust Hood




Kitchen Exhaust Hood



Aged Fuel Storage Tank



Pneumatics System



stained ceiling



# Facility Condition Assessment

South Kingstown - Matunuck School



Unit Vent



1991 Fan Coil



Radiant Heater



Switchgear



Library



Rusted Window Frame



# Facility Condition Assessment

South Kingstown - Matunuck School



Classroom Cabinetry



Storage Building



Storage Building



Pavilion



# Facility Condition Assessment

South Kingstown - Peace Dale Elementary School

June 2017

109 Kersey Road, Peace Dale, RI 02879





## Introduction

Peace Dale Elementary School, located at 109 Kersey Road in Peace Dale, Rhode Island, was built in 1924. It comprises 85,500 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Peace Dale Elementary School serves grades KG - 4, has 42 instructional spaces, and has an enrollment of 360. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Peace Dale Elementary School is 560 with a resulting utilization of 64%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Peace Dale Elementary School the 5-year need is \$9,604,036. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Peace Dale Elementary School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Peace Dale Elementary School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	CMU Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Composition Shingle Roofing
	Slate Roofing
	Modified Bitumen Roofing
	Built-Up Roofing With Ballast
	Canopy Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring





<b>01 - Main Building:</b>	Wood Flooring
	Vinyl Composition Tile Flooring
	Rubber Tile Flooring
	Carpet

## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	3,264 MBH Cast Iron Water Boiler
	400 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	Pneumatic Heating System Controls
	2 Ton Ductless Split System
	Make-up Air Unit
	10 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	10,000 CFM Interior AHU
	10,000 CFM Outdoor AHU
	Ductwork
	10 Ton DX Gas Roof Top Unit
	5 Ton DX Gas Roof Top Unit
	Wall Exhaust Fan
	Roof Exhaust Fan
	Fire Sprinkler System

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	4" Backflow Preventers
	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Sump Pump
	Air Compressor (10 hp)



## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	150 kW Emergency Generator
	Automatic Transfer Switch
	800 Amp Switchgear
	30 KVA Transformer
	45 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 277/480 225A
	Panelboard - 277/480 400A
	Building Mounted Lighting Fixtures
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



# Facility Condition Assessment

South Kingstown - Peace Dale Elementary School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$2,644	\$1,027,314	\$5,807	\$1,035,765	20.15 %
Roofing	-	\$926,930	-	-	-	\$926,930	18.04 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$694,728	\$14,519	\$564,134	\$1,273,381	24.78 %
Mechanical	-	\$451,406	\$51,673	\$84,567	-	\$587,647	11.43 %
Electrical	-	-	\$43,658	-	\$75,432	\$119,091	2.32 %
Plumbing	-	-	-	\$11,164	\$13,372	\$24,537	0.48 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$1,171,922	-	-	\$1,171,922	22.80 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	-	-	-	\$0	0.00 %
<b>Total</b>	\$0	\$1,378,336	\$1,964,625	\$1,137,565	\$658,746	\$5,139,272	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$1,273,381
Technology	-	\$1,171,922
Site	-	\$1,035,765

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	-	-	\$0
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$1,378,336	\$790,059	\$1,094,716	\$557,175	\$3,820,287
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$5,704	\$34,197	\$101,571	\$141,472
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$8,651	-	\$8,651
Technology	-	-	\$1,166,218	-	-	\$1,166,218
Traffic	-	-	\$2,644	-	-	\$2,644
<b>Total</b>	\$0	\$1,378,336	\$1,964,625	\$1,137,565	\$658,746	\$5,139,272

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,035,765	\$0	\$0	\$0	\$44,588	\$141,873	\$186,461	\$1,222,227
Roofing	\$926,930	\$0	\$0	\$0	\$0	\$555,968	\$555,968	\$1,482,898
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Interior	\$1,273,381	\$0	\$0	\$0	\$0	\$1,010,163	\$1,010,163	\$2,283,545
Mechanical	\$587,647	\$0	\$0	\$0	\$659,677	\$580,205	\$1,239,882	\$1,827,529
Electrical	\$119,091	\$0	\$0	\$0	\$0	\$678,584	\$678,584	\$797,675
Plumbing	\$24,537	\$0	\$0	\$0	\$35,033	\$2,898	\$37,931	\$62,468
Fire and Life Safety	\$0	\$0	\$0	\$250,600	\$0	\$0	\$250,600	\$250,600
Technology	\$1,171,922	\$0	\$0	\$0	\$0	\$0	\$0	\$1,171,922
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$0	\$0	\$503,451	\$503,451	\$503,451
<b>Total</b>	<b>\$5,139,272</b>	<b>\$0</b>	<b>\$0</b>	<b>\$250,600</b>	<b>\$739,298</b>	<b>\$3,473,142</b>	<b>\$4,463,040</b>	<b>\$9,602,312</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$29,925,000. For planning purposes, the total 5-year need at the Peace Dale Elementary School is \$9,604,036 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Peace Dale Elementary School facility has a 5-year FCI of 32.09%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.





## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 574 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Peace Dale Elementary School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$352,296.



### Summary of Findings

The Peace Dale Elementary School comprises 85,500 square feet and was constructed in 1924. Current deficiencies at this school total \$5,140,996. Five year capital renewal costs total \$4,463,040. The total identified need for the Peace Dale Elementary School (current deficiencies and 5-year capital renewal costs) is \$9,604,036. The 5-year FCI is 32.09%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Peace Dale Elementary School Totals	85,500	1924	\$5,140,996	\$4,463,040	\$9,604,036	32.09%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

### Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk Requires Repainting <b>Note:</b> Repaint crosswalks on school campus	Traffic	1	Ea.	3	\$755	9332
Pavement Markings: Words/Symbols Are Required <b>Note:</b> Repaint arrows on campus	Traffic	5	Ea.	3	\$1,889	9333
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt is cracked and alligating	Capital Renewal	137	CAR	4	\$450,215	8880
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt cracked, splitting, and alligating	Capital Renewal	79	CAR	4	\$259,613	8881
Asphalt Paving Requires Replacement <b>Note:</b> Play area pavement.	Capital Renewal	34	CAR	4	\$111,732	9261
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28589
Exterior Basketball Goals Require Replacement	Capital Renewal	4	Ea.	4	\$30,520	8882
Fencing Requires Replacement (8' Chain Link Fence) <b>Note:</b> Fence falling and rusted	Capital Renewal	2,200	LF	4	\$146,905	8879
Exterior Basketball Goals are Required <b>Note:</b> Exterior Basketball Goals are Required	Educational Adequacy	1	Ea.	5	\$5,807	28806
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$1,035,765</b>	
<b>Sub Total for School and Site Level</b>		<b>9</b>	<b>items</b>		<b>\$1,035,765</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Slate Roof Requires Replacement <b>Note:</b> Slate Shingle requires replacement.	Capital Renewal	15,000	SF	2	\$926,930	8883
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$926,930</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior CMU Walls Require Repair <b>Note:</b> Interior CMU wall has cracks at the northwest stairwell and the southwest stairs at the basement.	Capital Renewal	40	SF	3	\$1,574	8891
Rubber Flooring Requires Replacement <b>Note:</b> Worn out at all stairs	Capital Renewal	1,500	SF	3	\$30,357	8897
The Vinyl Composition Tile Requires Replacement <b>Note:</b> Cracked and fading, throughout building	Capital Renewal	51,836	SF	3	\$644,203	8884
The Vinyl Composition Tile Requires Replacement <b>Note:</b> Replace elevator floor	Capital Renewal	50	SF	3	\$621	8890
The Wood Flooring Requires Replacement <b>Note:</b> Worn out at stage	Capital Renewal	500	SF	3	\$17,972	8885
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	7	Ea.	4	\$2,163	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	200	LF	4	\$4,944	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	150	SF	4	\$1,545	Rollup
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	154	SF	4	\$5,868	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	77,840	SF	5	\$557,175	Rollup
Room lacks appropriate sound control.	Educational Adequacy	200	SF	5	\$6,959	Rollup
<b>Sub Total for System</b>		<b>11</b>	<b>items</b>		<b>\$1,273,381</b>	



# Facility Condition Assessment

South Kingstown - Peace Dale Elementary School

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductless Split System AC Requires Replacement <b>Note:</b> Condenser rusted and coils damaged	Capital Renewal	2	Ea.	2	\$14,802	8894
Outdoor Air Handler HVAC Component Required Replacement <b>Note:</b> Rusted.	Capital Renewal	1	Ea.	2	\$308,977	8893
Package Roof Top Unit Requires Replacement <b>Note:</b> Unit rusting & coils damaged	Capital Renewal	3	Ea.	2	\$63,044	8887
Package Roof Top Unit Requires Replacement <b>Note:</b> Rusted with damaged coils	Capital Renewal	2	Ea.	2	\$64,584	8892
The Make Up Air Equipment Requires Replacement <b>Note:</b> Heat exchangers and units rusted	Capital Renewal	3	Ea.	3	\$51,673	8889
The Exhaust Hood Requires Replacement <b>Note:</b> Units rusted and bearings bad	Capital Renewal	15	Ea.	4	\$84,567	8896
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$587,647</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Mounted Building Lighting Requires Replacement <b>Note:</b> Fixtures broken or damaged	Capital Renewal	27	Ea.	3	\$43,658	8886
Room Has Insufficient Electrical Outlets	Educational Adequacy	152	Ea.	5	\$75,432	Rollup
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$119,091</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Stained and rusting	Capital Renewal	4	Ea.	4	\$11,164	8888
Room lacks a drinking fountain.	Educational Adequacy	2	Ea.	5	\$2,206	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	10	Ea.	5	\$11,167	Rollup
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$24,537</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	1	Ea.	3	\$5,704	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	192	Ea.	3	\$98,872	13206
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	31	Ea.	3	\$319,276	13209
Technology: Instructional spaces do not have local sound reinforcement.	Technology	33	Ea.	3	\$169,937	13213
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,024	13198
Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$49,024	13202
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,150	13200
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1	Ea.	3	\$5,150	13204
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,209	13196
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,209	13199
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$7,209	13203
Technology: Main Telecommunications Room is not dedicated and/or inadequate.	Technology	1	Ea.	3	\$54,380	13195
Technology: Network system inadequate and/or near end of useful life	Technology	1	Ea.	3	\$8,239	13210
Technology: Network system inadequate and/or near end of useful life	Technology	21	Ea.	3	\$108,142	13212



# Facility Condition Assessment

South Kingstown - Peace Dale Elementary School

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	96	Ea.	3	\$49,436	13207
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	81,298	SF	3	\$150,715	13211
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$58,706	13208
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$8,239	13197
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,150	13201
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$5,150	13205
	<b>Sub Total for System</b>	<b>20</b>	<b>items</b>		<b>\$1,171,922</b>	
	<b>Sub Total for Building 01 - Main Building</b>	<b>43</b>	<b>items</b>		<b>\$4,103,507</b>	
	<b>Total for Campus</b>	<b>52</b>	<b>items</b>		<b>\$5,139,272</b>	



## Peace Dale Elementary School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Playfield Areas	ES Playgrounds	1	Ea.	\$44,588	4
Parking Lot Lighting	Pole Mounted Fixtures (Ea.)	12	Ea.	\$92,818	5
Pedestrian Pavement	Sidewalks - Concrete	2,400	SF	\$49,055	5
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$186,461</b>	
<b>Sub Total for Building -</b>		<b>3</b>	<b>items</b>	<b>\$186,461</b>	

### Building: 01 - Main Building

#### Roofing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Low-Slope Roofing	Modified Bitumen	14,620	SF	\$555,968	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$555,968</b>	

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings	1,600	SF	\$6,693	5
	<b>Note:</b> Restrooms				
Carpeting	Carpet	14,474	SF	\$314,899	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	76,240	SF	\$688,571	5
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$1,010,163</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	39	Ea.	\$659,677	4
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	85,500	SF	\$577,527	5
Exhaust Air	Wall Exhaust Fan	1	Ea.	\$2,678	5
	<b>Note:</b> Gym Exhaust				
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$1,239,882</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Electrical Service	Switchgear - Main Dist Panel (800 Amps)	1	Ea.	\$23,482	5
Electrical Service	Switchgear - Main Dist Panel (800 Amps)	1	Ea.	\$23,482	5
Packaged Generator Assemblies	Emergency Generator (150 KW)	1	Ea.	\$123,591	5
Lighting Fixtures	Light Fixtures (Bldg SF)	85,500	SF	\$508,029	5
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>	<b>\$678,584</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	2	Ea.	\$14,755	4
Compressed-Air Systems	Air Compressor (10 hp)	1	Ea.	\$20,278	4
Building Support Plumbing System Supplementary Components	Sump Pump	2	Ea.	\$2,898	5
	<b>Note:</b> 64 gpm				
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$37,931</b>	

#### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	85,500	SF	\$250,600	3
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$250,600</b>	

#### Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	45	Room	\$503,451	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$503,451</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>16</b>	<b>items</b>	<b>\$4,276,579</b>	
<b>Total for: Peace Dale Elementary School</b>		<b>19</b>	<b>items</b>	<b>\$4,463,040</b>	



**Supporting Photos**



Roadway Alligator Cracking



Falling Fence



Basketball Goals



Parking Alligator Cracking



# Facility Condition Assessment

South Kingstown - Peace Dale Elementary School



Site Aerial




Library



Cafeteria



West Elevation



Front Elevation



Music





# Facility Condition Assessment

South Kingstown - Peace Dale Elementary School



Front Elevation



Typical Classroom



Gym



Marquee



Playground



Computer Room



Slate With Mold



Mold



Typical VCT Damage



Stage Flooring



Building Mounted Fixtures




DX Unit



Mop Sink




Make Up Air Unit



VCT At Elevator



First Floor Northwest CMU Crack



Southwest Basement Stairway Crack



DX Unit



Outdoor AHU



Ductless System



Typical Paint



Exhaust



Worn Rubber Flooring



# Facility Condition Assessment

South Kingstown - South Kingstown High School

June 2017

215 Columbia Street, Wakefield, RI 02879





## Introduction

South Kingstown High School, located at 215 Columbia Street in Wakefield, Rhode Island, was built in 1954. It comprises 234,900 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

South Kingstown High School serves grades 9 - 12, has 90 instructional spaces, and has an enrollment of 1,004. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for South Kingstown High School is 1,703 with a resulting utilization of 59%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For South Kingstown High School the 5-year need is \$24,701,149. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of South Kingstown High School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the South Kingstown High School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	Metal Panel Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Storefront Entrance Doors
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors
<b>02 - Small Shed:</b>	Wood Siding Exterior Wall
	Aluminum Exterior Windows
	Wood Exterior Doors
<b>03 - Building 03:</b>	Wood Siding Exterior Wall
	Wood Exterior Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Built-Up Roofing With Ballast
	Metal Low-Slope Roofing
	Single Ply Roofing
<b>02 - Small Shed:</b>	Composition Shingle Roofing
<b>03 - Building 03:</b>	Composition Shingle Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors
	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System





<b>01 - Main Building:</b>	Suspended Acoustical Ceiling Tile
	Non-Painted Plaster/Gypsum Board Ceiling
	Metal Panel Ceilings
	Ceramic Tile Wall
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Epoxy Coated Flooring
	Carpet
	Athletic/Sport Flooring
<b>02 - Small Shed:</b>	Wood Ceilings
	Interior Wall Painting
	Wood Flooring
<b>03 - Building 03:</b>	Wood Ceilings
	Interior Wall Painting
	Wood Flooring

## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	4,200 MBH Cast Iron Steam Boiler
	1,275 MBH Cast Iron Water Boiler
	Steam to Water Heat Exchanger
	Steam Condensate Receiver, Tank and Pump
	Gas Heating Unit Vent
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	Pneumatic Heating System Controls
	3 Ton Ductless Split System
	10 Ton Outside Air Cooled Condenser
	Window Units
	Make-up Air Unit
	10 HP Pump
	2-Pipe Hot Water Hydronic Distribution System
	5,000 CFM Interior AHU
	10,000 CFM Interior AHU
	Ductwork
	10 Ton DX Gas Roof Top Unit
	25 Ton DX Gas Roof Top Unit



<b>01 - Main Building:</b>	Supply Fan
	4'x8' Ventilator/Relief Vent
	Wall Exhaust Fan
	Roof Exhaust Fan
	Laboratory Fume Hood
	Fire Sprinkler System

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	1,000 Gallon Water Storage Tank
	2" Backflow Preventers
	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Sump Pump
	Air Compressor (5 hp)

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	150 kW Emergency Generator
	Automatic Transfer Switch
	1,200 Amp Switchgear
	1,600 Amp Switchgear
	3,000 Amp Switchgear
	1600 Amp Distribution Panel
	600 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



# Facility Condition Assessment

South Kingstown - South Kingstown High School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$1,511	\$1,381,060	\$939,696	\$2,322,267	11.97 %
Roofing	-	\$3,056,871	-	-	-	\$3,056,871	15.76 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$2,323,895	\$1,053	-	-	\$2,324,949	11.99 %
Interior	-	-	\$1,405,913	\$1,413,750	\$909,723	\$3,729,387	19.23 %
Mechanical	-	\$3,802,939	\$302,997	\$310,479	\$3,130	\$4,419,545	22.78 %
Electrical	\$12,710	\$295,096	\$7,016	-	\$112,500	\$427,323	2.20 %
Plumbing	-	-	-	\$125,473	\$165,051	\$290,524	1.50 %
Fire and Life Safety	\$881,701	-	-	-	-	\$881,701	4.55 %
Technology	-	-	\$1,391,060	-	-	\$1,391,060	7.17 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$18,253	\$406,810	\$128,344	\$553,407	2.85 %
<b>Total</b>	<b>\$894,411</b>	<b>\$9,478,802</b>	<b>\$3,127,804</b>	<b>\$3,637,572</b>	<b>\$2,258,443</b>	<b>\$19,397,032</b>	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$4,419,545
Interior	-	\$3,729,387
Roofing	-	\$3,056,871

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$114,209	\$169,794	-	\$284,004
Barrier to Accessibility	-	-	\$5,704	-	-	\$5,704
Capital Renewal	-	\$9,478,802	\$1,597,066	\$2,950,713	\$904,766	\$14,931,347
Code Compliance	\$687,759	-	-	-	-	\$687,759
Educational Adequacy	\$206,652	-	\$46,774	\$456,111	\$1,353,678	\$2,063,215
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$60,953	-	\$60,953
Technology	-	-	\$1,362,539	-	-	\$1,362,539
Traffic	-	-	\$1,511	-	-	\$1,511
<b>Total</b>	<b>\$894,411</b>	<b>\$9,478,802</b>	<b>\$3,127,804</b>	<b>\$3,637,572</b>	<b>\$2,258,443</b>	<b>\$19,397,032</b>

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$2,322,267	\$0	\$0	\$0	\$124,372	\$541,392	\$665,764	\$2,988,031
Roofing	\$3,056,871	\$0	\$0	\$0	\$0	\$0	\$0	\$3,056,871
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$2,324,949	\$0	\$0	\$0	\$16,647	\$5,995	\$22,642	\$2,347,591
Interior	\$3,729,387	\$0	\$0	\$0	\$6,636	\$1,321	\$7,957	\$3,737,344
Mechanical	\$4,419,545	\$0	\$0	\$0	\$109,553	\$2,103,277	\$2,212,830	\$6,632,375
Electrical	\$427,323	\$0	\$0	\$0	\$70,047	\$1,702,911	\$1,772,958	\$2,200,281
Plumbing	\$290,524	\$0	\$0	\$0	\$23,570	\$1,449	\$25,019	\$315,543
Fire and Life Safety	\$881,701	\$0	\$0	\$0	\$0	\$0	\$0	\$881,701
Technology	\$1,391,060	\$0	\$0	\$0	\$0	\$0	\$0	\$1,391,060
Conveyances	\$0	\$0	\$0	\$0	\$0	\$570,418	\$570,418	\$570,418
Specialties	\$553,407	\$0	\$0	\$0	\$0	\$0	\$0	\$553,407
<b>Total</b>	<b>\$19,397,032</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$350,825</b>	<b>\$4,926,763</b>	<b>\$5,277,588</b>	<b>\$24,674,620</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$84,564,000. For planning purposes, the total 5-year need at the South Kingstown High School is \$24,701,149 (Life Cycle Years 1-5 plus the FCI deficiency cost). The South Kingstown High School facility has a 5-year FCI of 29.18%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.





## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 1,270 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the South Kingstown High School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



## Summary of Findings

The South Kingstown High School comprises 234,900 square feet and was constructed in 1954. Current deficiencies at this school total \$19,423,561. Five year capital renewal costs total \$5,277,588. The total identified need for the South Kingstown High School (current deficiencies and 5-year capital renewal costs) is \$24,701,149. The 5-year FCI is 29.18%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
South Kingstown High School Totals	234,900	1954	\$19,423,561	\$5,277,588	\$24,701,149	29.18%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Crosswalk Requires Repainting <b>Note:</b> Repaint crosswalks at end of school driveways	Traffic	2	Ea.	3	\$1,511	9305
Asphalt Paving Requires Replacement <b>Note:</b> Per LEA review - all asphalt should be replaced.	Capital Renewal	114	CAR	4	\$374,631	54851
Asphalt Paving Requires Replacement <b>Note:</b> Per LEA review - all asphalt should be replaced.	Capital Renewal	270	CAR	4	\$887,285	54852
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28591
Fencing Requires Replacement (8' Chain Link Fence) <b>Note:</b> Fence is rusted and falling.	Capital Renewal	1,360	LF	4	\$90,814	8460
School has insufficient # of tennis courts. <b>Note:</b> School has insufficient # of tennis courts.	Educational Adequacy	1	Ea.	5	\$161,597	29044
School has insufficient baseball fields. <b>Note:</b> School has insufficient baseball fields.	Educational Adequacy	1	Ea.	5	\$207,745	28329
School has insufficient football/soccer fields. <b>Note:</b> School has insufficient football/soccer fields.	Educational Adequacy	1	Ea.	5	\$94,430	28199
School has insufficient softball fields. <b>Note:</b> School has insufficient softball fields.	Educational Adequacy	1	Ea.	5	\$151,087	28373
School lacks a competition track. <b>Note:</b> School lacks a competition track.	Educational Adequacy	1	Ea.	5	\$324,837	28274
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$2,322,267</b>	
<b>Sub Total for School and Site Level</b>		<b>10</b>	<b>items</b>		<b>\$2,322,267</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Built-up Roofing With Aggregate Ballast Requires Replacement <b>Note:</b> Per LEA review feedback - school needs new roof	Capital Renewal	60,000	SF	2	\$2,281,673	54853
The Metal Roof Structural Roof Covering Requires Replacement <b>Note:</b> Per LEA review - school needs new roof	Capital Renewal	2,160	SF	2	\$82,140	54854
The Single-Ply Membrane Roof Covering Requires Replacement <b>Note:</b> Roof is leaking at the new addition and science wing.	Capital Renewal	54,000	SF	2	\$693,058	8495
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$3,056,871</b>	

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement <b>Note:</b> Per LEA review - replace windows	Capital Renewal	13,704	SF	2	\$2,319,047	54855
The Concrete Pre-Cast Panel Requires Replacement (Bldg SF) <b>Note:</b> Foundation concrete wall corner is damaged. <b>Location:</b> Northwest corner by secondary entrance	Capital Renewal	30	SF	2	\$4,849	8496
The Metal Panel Exterior Requires Repair <b>Location:</b> Wood shop	Capital Renewal	100	SF Wall	3	\$1,053	8462
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$2,324,949</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Entry Door Does Not Have Required Power Assist Device <b>Note:</b> Power assist mechanism is not functioning properly and should be replaced.	Barrier to Accessibility	2	Ea.	3	\$5,704	8474



# Facility Condition Assessment

South Kingstown - South Kingstown High School

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement <b>Note:</b> Doors are scratched and/or broken throughout main building.	Capital Renewal	37	Door	3	\$170,603	8463
The Athletic Sport Flooring Requires Replacement <b>Note:</b> Athletic floor is aged and worn. <b>Location:</b> Small gym	Capital Renewal	4,430	SF	3	\$151,617	8473
The Carpet Flooring Requires Replacement <b>Note:</b> Carpet is worn and stained throughout the building.	Capital Renewal	16,500	SF	3	\$358,977	8464
The Vinyl Composition Tile Requires Replacement <b>Note:</b> VCT worn, chipped, and peeling.	Capital Renewal	54,000	SF	3	\$619,474	8465
The Wood Flooring Requires Replacement <b>Note:</b> Wood floor is scratched and worn at stage. <b>Location:</b> Auditorium stage	Capital Renewal	3,000	SF	3	\$99,538	8466
Ceiling Grid Requires Replacement <b>Note:</b> Ceiling tiles are stained and sagging at the main building classrooms, library, cafeteria, offices, and kitchen.	Capital Renewal	98,458	SF	4	\$1,167,761	8492
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - each)	Hazardous Material	1	Ea.	4	\$285	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	600	SF	4	\$5,704	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	84	Ea.	4	\$23,958	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	271	LF	4	\$6,183	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	2,611	SF	4	\$24,823	Rollup
Room Is Excessively Reverberant <b>Note:</b> Main gym & small gym	Acoustics	7,600	SF	4	\$169,794	19725
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	400	SF	4	\$15,242	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	5	Ea.	5	\$11,408	Rollup
Interior Walls Require Repainting (Bldg SF)	Capital Renewal	135,957	SF	5	\$898,315	Rollup
<b>Sub Total for System</b>		<b>16</b>	<b>items</b>		<b>\$3,729,387</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductless Split System AC Requires Replacement <b>Note:</b> Units are aged. Condensers are rusting and evaporative units are molded.	Capital Renewal	6	Ea.	2	\$46,694	8489
Package Roof Top Unit Requires Replacement <b>Note:</b> RTU is aged and heat exchanger is rusted.	Capital Renewal	1	Ea.	2	\$29,808	8482
Package Roof Top Unit Requires Replacement <b>Note:</b> Unit is aged and rusted.	Capital Renewal	1	Ea.	2	\$72,674	8485
Replace Unit Vent <b>Note:</b> Units are aged and have not been maintained. <b>Location:</b> Gym	Capital Renewal	9	Ea.	2	\$152,233	8493
Replace Unit Vent <b>Note:</b> Units are aged. Many are not operational with failed motors.	Capital Renewal	17	Ea.	2	\$287,552	8494
Replace Unit Vent <b>Note:</b> Updated per LEA review	Capital Renewal	119	Ea.	2	\$2,012,861	54857
The Air Handler HVAC Component Requires Replacement <b>Note:</b> Air handler is aged and rusted with corroded connections. <b>Location:</b> Auditorium	Capital Renewal	1	Ea.	2	\$119,484	8480
The Exterior Condenser Requires Replacement <b>Note:</b> Condenser is old and the heat exchanger is rusted.	Capital Renewal	1	Ea.	2	\$16,342	8481
The Steam Condensate Receiver Requires Replacement <b>Note:</b> Pumps and seals are rusted and leaking.	Capital Renewal	3	Ea.	2	\$1,055,274	8486
The Window AC Unit Component Requires Replacement <b>Note:</b> Units are aged and beginning to fail. Plastic casing is cracked and coils are clogged.	Capital Renewal	3	Ea.	2	\$10,017	8479



# Facility Condition Assessment

South Kingstown - South Kingstown High School

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Large Diameter Exhausts/Hoods Require Replacement <b>Note:</b> Boiler room supply fan is not functioning.	Capital Renewal	1	Ea.	3	\$13,893	8469
The Make Up Air Equipment Requires Replacement <b>Note:</b> Units are aged, connections are corroded, cases are rusted. <b>Location:</b> Library, gyms, locker rooms, boiler room	Capital Renewal	11	Ea.	3	\$174,894	8475
Unit Ventilators Are Excessively Noisy <b>Location:</b> All learning spaces	Acoustics	18	Ea.	3	\$114,209	27972
Exhaust Fan Ventilation Requires Replacement	Capital Renewal	1	Ea.	4	\$2,678	8470
Lab lacks an appropriate fume hood.	Educational Adequacy	14	Ea.	4	\$307,801	Rollup
Remove Abandoned Equipment <b>Note:</b> Fuel storage tank has been abandoned in place and needs to be removed.	Capital Renewal	1	Ea.	5	\$3,130	8488
<b>Sub Total for System</b>		<b>16</b>	<b>items</b>		<b>\$4,419,545</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room last power shut-off valves for utilities	Educational Adequacy	9	Ea.	1	\$12,710	Rollup
Switchgear Is Needed Or Requires Replacement	Capital Renewal	1	Ea.	2	\$82,102	8478
Switchgear Is Needed Or Requires Replacement <b>Note:</b> Switchgear is old with broken breakers and is being used improperly as a disconnect.	Capital Renewal	1	Ea.	2	\$69,059	8487
The Distribution Panel Requires Replacement <b>Note:</b> Panel is old and breakers are cracking.	Capital Renewal	1	Ea.	2	\$51,908	8461
The Panelboard Requires Replacement <b>Note:</b> Panelboards are old, cases are damaged, and breakers are cracked.	Capital Renewal	13	Ea.	2	\$63,031	8483
The Panelboard Requires Replacement <b>Note:</b> Panels are aged, cases are damaged, and masonite panels are falling apart.	Capital Renewal	5	Ea.	2	\$28,996	8484
The Mounted Building Lighting Requires Repair	Capital Renewal	15	Ea.	3	\$7,016	8467
Remove Abandoned Equipment <b>Note:</b> Abandoned emergency generator should be removed.	Capital Renewal	1	Ea.	5	\$3,321	8468
Room Has Insufficient Electrical Outlets	Educational Adequacy	220	Ea.	5	\$109,178	Rollup
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$427,323</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Non-Refrigerated Drinking Fountain Requires Replacement <b>Note:</b> Units are aged, corroded, and non-functional.	Capital Renewal	9	Ea.	4	\$91,980	8471
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Service sinks are stained and rusting.	Capital Renewal	13	Ea.	4	\$33,493	8472
Room lacks a drinking fountain.	Educational Adequacy	3	Ea.	5	\$3,308	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	107	Ea.	5	\$161,742	Rollup
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>		<b>\$290,524</b>	

## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Alarm Is Missing Or Inadequate (NFPA 72 and NFPA 101, Section 9.6) <b>Note:</b> Updated per LEA review	Code Compliance	234,650	SF	1	\$687,759	54856
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	17	Ea.	1	\$193,942	Rollup
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$881,701</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	5	Ea.	3	\$28,521	Rollup
Technology: Auditorium AV/Multimedia system is in need of minor improvements.	Technology	1	Room	3	\$95,070	13163



# Facility Condition Assessment

South Kingstown - South Kingstown High School

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	482	Ea.	3	\$229,118	13176
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	28	Ea.	3	\$266,195	13159
Technology: Instructional spaces do not have local sound reinforcement.	Technology	30	Ea.	3	\$142,605	13177
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	10	Ea.	3	\$53,239	13166
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13169
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13170
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13171
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13172
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13173
Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13174
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$16,732	13168
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	10	Ea.	3	\$47,535	13167
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13165
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$21,676	13164
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	96	Ea.	3	\$41,070	13160
Technology: Network system inadequate and/or near end of useful life	Technology	30	Ea.	3	\$142,605	13162
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	96	Ea.	3	\$45,633	13161
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	6	Ea.	3	\$28,521	13175
<b>Sub Total for System</b>		<b>20</b>	<b>items</b>		<b>\$1,391,060</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$18,253	Rollup
Replace Cabinetry In Classes/Labs	Capital Renewal	27	Room	4	\$302,071	8490
<b>Note:</b> Laminate chipped or faded on main building cabinetry.						
Walk In Cooler/Freezer Is Required	Educational Adequacy	1	Ea.	4	\$90,316	Rollup
Welding Bays Are Required	Educational Adequacy	2	Ea.	4	\$10,838	Rollup
Work Tables Are Required	Educational Adequacy	1	Ea.	4	\$3,585	Rollup
Room lacks an appropriate refrigerator.	Educational Adequacy	15	Ea.	5	\$128,344	Rollup
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$553,407</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>79</b>	<b>items</b>		<b>\$17,074,765</b>	
<b>Total for Campus</b>		<b>89</b>	<b>items</b>		<b>\$19,397,032</b>	



## **Buildings with no reported deficiencies**

02 - Small Shed

03 - Building 03



## South Kingstown High School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (8 Ft)	1,850	LF	\$124,372	4
Parking Lot Lighting	Pole Mounted Fixtures (Ea.)	8	Ea.	\$61,879	5
Pedestrian Pavement	Sidewalks - Concrete	23,460	SF	\$479,513	5
		<b>Sub Total for System</b>		<b>3 items</b>	<b>\$665,764</b>
		<b>Sub Total for Building -</b>		<b>3 items</b>	<b>\$665,764</b>

### Building: 01 - Main Building

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Air Distribution	Make-up Air Unit	6	Ea.	\$95,397	4
<b>Note:</b> Shop classrooms, kitchen, and cafeteria					
Decentralized Heating Equipment	Heating Unit Vent - Gas	1	Ea.	\$14,156	4
Exhaust Air	Laboratory Fume Hood	5	Ea.	\$142,605	5
Exhaust Air	Roof Exhaust Fan	62	Ea.	\$322,655	5
Exhaust Air	Ventilator/Relief Vent (4'x8')	4	Ea.	\$53,026	5
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	234,650	SF	\$1,584,991	5
		<b>Sub Total for System</b>		<b>6 items</b>	<b>\$2,212,829</b>

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)	34	Ea.	\$50,748	4
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)	14	Ea.	\$19,299	4
Packaged Generator Assemblies	Emergency Generator (150 KW)	1	Ea.	\$123,591	5
Lighting Fixtures	Light Fixtures (Bldg SF)	234,650	SF	\$1,394,257	5
Electrical Service	Switchgear - Main Dist Panel (3000 Amps)	2	Ea.	\$185,063	5
		<b>Sub Total for System</b>		<b>5 items</b>	<b>\$1,772,957</b>

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Compressed-Air Systems	Air Compressor (5 hp)	2	Ea.	\$23,570	4
Building Support Plumbing System Supplementary Components	Sump Pump	1	Ea.	\$1,449	5
		<b>Sub Total for System</b>		<b>2 items</b>	<b>\$25,019</b>

#### Conveyances

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Elevators	Hydraulic (Passenger Elev)	2	Ea.	\$570,418	5
		<b>Sub Total for System</b>		<b>1 items</b>	<b>\$570,418</b>
		<b>Sub Total for Building 01 - Main Building</b>		<b>14 items</b>	<b>\$4,581,223</b>

### Building: 03 - Building 03

#### Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Wood	2	Door	\$16,647	4
Exterior Wall Veneer	Wood Siding - Bldg SF basis	200	SF	\$5,995	5
		<b>Sub Total for System</b>		<b>2 items</b>	<b>\$22,642</b>

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wood Flooring	Wood Flooring - All Types	200	SF	\$6,636	4
Wall Painting and Coating	Painting/Staining (Bldg SF)	200	SF	\$1,321	5
		<b>Sub Total for System</b>		<b>2 items</b>	<b>\$7,957</b>
		<b>Sub Total for Building 03 - Building 03</b>		<b>4 items</b>	<b>\$30,599</b>
		<b>Total for: South Kingstown High School</b>		<b>21 items</b>	<b>\$5,277,586</b>






**Supporting Photos**



Abandoned Generator



Science Room



Auditorium AHU



Failing Window Unit



# Facility Condition Assessment

South Kingstown - South Kingstown High School



Music Room



Typical Classroom




Main Building Exterior



Drop Off Exterior



Damaged Metal Panel Wall



Worn Wood Door



Non-Functional Drinking Fountain



Corroded Make-Up Air Unit



Damaged Door And Frame



Gym Heater



Heating Unit



Wall Exhaust Fan



# Facility Condition Assessment


South Kingstown - South Kingstown High School



Cafeteria



Condenser



Aged Panelboard



Corroded Utility Sink



25 Ton RTU



Aged 225 Amp Panelboard



Chipped And Curling VCT



Rusted Condensate Receiver



Worn Wood Floor



Rusted And Falling Fence



Chipped Art Classroom Cabinetry



Worn And Stained Carpet



# Facility Condition Assessment

South Kingstown - South Kingstown High School



Peeling Paint



Chipped VCT



Storage



Concrete Wall Corner



1,200 Amp Switchgear



Rusted And Molding Split System



# Facility Condition Assessment

South Kingstown - South Kingstown High School



Stained And Sagging Ceiling Tiles



Worn Gym Paint



Worn Athletic Flooring



Peeling Paint In Storage



Site Aerial



Building Mounted Light



Small Gym Interior



Marquee



Library



Main Gym





# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool

June 2017

1157 South Road, Wakefield, RI 02879





## Introduction

South Kingstown Inclusionary Preschool, located at 1157 South Road in Wakefield, Rhode Island, was built in 1964. It comprises 37,350 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

South Kingstown Inclusionary Preschool serves grades PK, has 21 instructional spaces, and has an enrollment of 110. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for South Kingstown Inclusionary Preschool is 165 with a resulting utilization of 67%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For South Kingstown Inclusionary Preschool the 5-year need is \$6,908,139. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of South Kingstown Inclusionary Preschool



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the South Kingstown Inclusionary Preschool campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Asphalt Pedestrian Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Storefront Entrance Doors
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Built-Up Roofing With Ballast
	Canopy Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Interior Wall Painting
	Concrete Flooring
	Quarry Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Carpet



## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	1,275 MBH Cast Iron Water Boiler
	3,264 MBH Cast Iron Water Boiler
	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	Pneumatic Heating System Controls
	1 Ton Ductless Split System
	3 Ton Ductless Split System
	Window Units
	Make-up Air Unit
	1 HP or Smaller Pump
	2-Pipe Hot Water Hydronic Distribution System
	5,000 CFM Interior AHU
	Ductwork
	Kitchen Exhaust Hoods
	Roof Exhaust Fan

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	2" Backflow Preventers
	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Sump Pump
	Air Compressor (2 hp)
	550 Gallon Above Ground Fuel Oil Storage Tank

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	50 kW Emergency Generator
	Automatic Transfer Switch
	400 Amp Distribution Panel
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool

<b>01 - Main Building:</b>	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$45,478	\$410,780	-	\$456,258	9.08 %
Roofing	-	-	-	-	-	\$0	0.00 %
Structural	-	-	-	\$3,423	-	\$3,423	0.07 %
Exterior	-	\$515,795	-	\$893	-	\$516,688	10.28 %
Interior	-	-	\$141,576	\$658,014	\$47,915	\$847,506	16.87 %
Mechanical	-	\$1,050,204	\$15,899	\$325,307	\$12,519	\$1,403,930	27.94 %
Electrical	-	\$162,120	\$24,468	\$12,407	\$39,701	\$238,696	4.75 %
Plumbing	-	-	\$9,304	\$279,851	\$46,651	\$335,805	6.68 %
Fire and Life Safety	\$15,964	-	-	-	-	\$15,964	0.32 %
Technology	-	-	\$825,043	-	-	\$825,043	16.42 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$86,704	\$294,455	-	\$381,158	7.59 %
<b>Total</b>	\$15,964	\$1,728,120	\$1,148,472	\$1,985,129	\$146,786	\$5,024,471	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$1,403,930
Interior	-	\$847,506
Technology	-	\$825,043

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies





## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool

The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	-	-	\$0
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	\$15,964	\$1,728,120	\$232,192	\$1,327,115	\$12,519	\$3,315,910
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$189,379	\$652,911	\$134,267	\$976,557
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$5,103	-	\$5,103
Technology	-	-	\$722,368	-	-	\$722,368
Traffic	-	-	\$4,533	-	-	\$4,533
<b>Total</b>	\$15,964	\$1,728,120	\$1,148,472	\$1,985,129	\$146,786	\$5,024,471

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$456,258	\$0	\$0	\$0	\$27,798	\$66,429	\$94,227	\$550,485
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Structural	\$3,423	\$0	\$0	\$0	\$0	\$0	\$0	\$3,423
Exterior	\$516,688	\$0	\$0	\$0	\$0	\$0	\$0	\$516,688
Interior	\$847,506	\$0	\$0	\$0	\$590,936	\$221,053	\$811,989	\$1,659,495
Mechanical	\$1,403,930	\$0	\$0	\$0	\$100,261	\$544,341	\$644,602	\$2,048,532
Electrical	\$238,696	\$0	\$0	\$221,928	\$0	\$0	\$221,928	\$460,624
Plumbing	\$335,805	\$0	\$0	\$0	\$0	\$1,449	\$1,449	\$337,254
Fire and Life Safety	\$15,964	\$0	\$0	\$109,473	\$0	\$0	\$109,473	\$125,437
Technology	\$825,043	\$0	\$0	\$0	\$0	\$0	\$0	\$825,043
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$381,158	\$0	\$0	\$0	\$0	\$0	\$0	\$381,158
<b>Total</b>	<b>\$5,024,471</b>	<b>\$0</b>	<b>\$0</b>	<b>\$331,401</b>	<b>\$718,995</b>	<b>\$833,272</b>	<b>\$1,883,668</b>	<b>\$6,908,139</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$13,072,500. For planning purposes, the total 5-year need at the South Kingstown Inclusionary Preschool is \$6,908,139 (Life Cycle Years 1-5 plus the FCI deficiency cost). The South Kingstown Inclusionary Preschool facility has a 5-year FCI of 52.84%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 208 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the South Kingstown Inclusionary Preschool cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



## Summary of Findings

The South Kingstown Inclusionary Preschool comprises 37,350 square feet and was constructed in 1964. Current deficiencies at this school total \$5,024,471. Five year capital renewal costs total \$1,883,668. The total identified need for the South Kingstown Inclusionary Preschool (current deficiencies and 5-year capital renewal costs) is \$6,908,139. The 5-year FCI is 52.84%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
South Kingstown Inclusionary Preschool Totals	37,350	1964	\$5,024,471	\$1,883,668	\$6,908,139	52.84%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Walks Require Replacement <b>Note:</b> Play area asphalt is cracked and splitting.	Capital Renewal	4,824	SF	3	\$40,945	8656
Traffic Signage Is Required <b>Note:</b> Add flashing beacons to school zone speed limit signs	Traffic	2	Ea.	3	\$4,533	9315
Asphalt Paving Requires Replacement <b>Note:</b> Paving cracked and splitting.	Capital Renewal	105	CAR	4	\$345,055	8655
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt has pot holes and cracks.	Capital Renewal	20	CAR	4	\$65,725	9228
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>		<b>\$456,258</b>	
<b>Sub Total for School and Site Level</b>		<b>4</b>	<b>items</b>		<b>\$456,258</b>	

## Building: 01 - Main Building

### Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Steel Beam Requires Repainting <b>Note:</b> Paint is peeling on the steel beams at canopies.	Capital Renewal	300	SF	4	\$3,423	8676
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$3,423</b>	

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement <b>Note:</b> Windows in original building are single pane with damaged caulk.	Capital Renewal	3,048	SF	2	\$515,795	8658
Exterior Door Requires Repair <b>Note:</b> Hardware should be repaired.	Capital Renewal	8	Ea.	4	\$893	10975
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$516,688</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Doors Require Replacement	Capital Renewal	11	Door	3	\$50,720	8659
The Carpet Flooring Requires Replacement <b>Location:</b> Former library space	Capital Renewal	3,536	SF	3	\$76,930	8660
The Vinyl Composition Tile Requires Replacement <b>Location:</b> Conference room and offices next to former library	Capital Renewal	1,214	SF	3	\$13,927	8661
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each)	Hazardous Material	13	Ea.	4	\$3,708	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet)	Hazardous Material	32	LF	4	\$730	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	70	SF	4	\$665	Rollup
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	17,135	SF	4	\$652,911	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	21	Ea.	5	\$47,915	Rollup
<b>Sub Total for System</b>		<b>8</b>	<b>items</b>		<b>\$847,506</b>	

### Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Requires Replacement (SF Basis)	Capital Renewal	4,482	SF	2	\$65,891	9227
Replace Unit Vent	Capital Renewal	11	Ea.	2	\$186,063	8688
The Radiant Heat HVAC Component Requires Replacement <b>Note:</b> Corrosion at connections and coils clogged.	Capital Renewal	104	Ea.	2	\$791,573	8690
The Window AC Unit Component Requires Replacement <b>Note:</b> Window AC units are non-functional.	Capital Renewal	2	Ea.	2	\$6,678	8677
The Make Up Air Equipment Requires Replacement <b>Note:</b> Gym make up air unit has corroded connections, clogged coils, and no filters.	Capital Renewal	1	Ea.	3	\$15,899	8673
Existing Controls Are Inadequate And Should Be Replaced With DDC Controls <b>Note:</b> Original pneumatic controls are leaking.	Capital Renewal	29,880	SF	4	\$201,831	8683



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Small HVAC Circulating Pump Requires Replacement <b>Note:</b> Pumps are leaking and rusting.	Capital Renewal	8	Ea.	4	\$61,027	8691
The Exhaust Hood Requires Replacement	Capital Renewal	12	Ea.	4	\$62,449	8687
Remove Abandoned Equipment <b>Note:</b> Fuel oil system abandoned in place. Underground fuel oil tank, piping, pumps, and all equipment should be removed.	Capital Renewal	4	Ea.	5	\$12,519	8692
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$1,403,930</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Generator Requires Replacement	Capital Renewal	1	Ea.	2	\$76,056	8664
The Distribution Panel Requires Replacement <b>Note:</b> Kelex panels with replacement parts no longer available.	Capital Renewal	2	Ea.	2	\$51,338	8682
The Electrical Disconnect Requires Replacement <b>Note:</b> Case is rusting on disconnect.	Capital Renewal	1	Ea.	2	\$1,833	8665
The Panelboard Requires Replacement	Capital Renewal	1	Ea.	2	\$4,849	8678
The Panelboard Requires Replacement <b>Note:</b> Kelex panel with replacement parts no longer available.	Capital Renewal	1	Ea.	2	\$4,849	8679
The Panelboard Requires Replacement <b>Note:</b> Kelex panelboards with replacement parts no longer available.	Capital Renewal	4	Ea.	2	\$23,197	8680
The Mounted Building Lighting Requires Replacement	Capital Renewal	14	Ea.	3	\$20,896	8663
Transfer Switch Requires Replacement <b>Note:</b> Contacts are burned and the unit is non-functional.	Capital Renewal	100	Amps	3	\$3,572	8686
The Canopy Lighting Requires Replacement	Capital Renewal	9	Ea.	4	\$12,407	8662
Room Has Insufficient Electrical Outlets	Educational Adequacy	80	Ea.	5	\$39,701	Rollup
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$238,696</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Urinal Plumbing Fixtures Require Replacement	Capital Renewal	7	Ea.	3	\$9,304	8674
Non-Refrigerated Drinking Fountain Requires Replacement <b>Location:</b> Classrooms	Capital Renewal	15	Ea.	4	\$153,300	8669
Non-Refrigerated Drinking Fountain Requires Replacement <b>Location:</b> Corridor	Capital Renewal	1	Ea.	4	\$10,220	8670
The Classroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Classroom lavatories are rusted and stained.	Capital Renewal	15	Ea.	4	\$40,785	8657
The Custodial Mop Or Service Sink Requires Replacement	Capital Renewal	3	Ea.	4	\$7,729	8671
The Refrigerated Water Cooler Requires Replacement <b>Note:</b> Compressor in drinking fountain is non-functional.	Capital Renewal	1	Ea.	4	\$7,377	8675
The Restroom Lavatories Plumbing Fixtures Require Replacement	Capital Renewal	13	Ea.	4	\$41,353	8666
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Kitchen lavatories are non-functional.	Capital Renewal	6	Ea.	4	\$19,086	8667
Room lacks a drinking fountain.	Educational Adequacy	19	Ea.	5	\$20,953	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	17	Ea.	5	\$25,697	Rollup
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$335,805</b>	

## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Kitchen Exhaust Hood <b>Note:</b> Kitchen hood is rusting and is missing filters.	Capital Renewal	1	Ea.	1	\$15,964	8681
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$15,964</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	18	Ea.	3	\$102,675	Rollup





# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	48	Ea.	3	\$22,817	13151
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	17	Ea.	3	\$339,399	13154
Technology: Instructional spaces do not have local sound reinforcement.	Technology	19	Ea.	3	\$90,316	13158
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13149
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$37,648	13148
Technology: Network system inadequate and/or near end of useful life	Technology	2	Ea.	3	\$15,211	13156
Technology: Network system inadequate and/or near end of useful life	Technology	13	Ea.	3	\$61,795	13157
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	48	Ea.	3	\$22,817	13152
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	37,350	SF	3	\$63,915	13155
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$54,190	13153
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$7,606	13150
<b>Sub Total for System</b>		<b>12</b>	<b>items</b>		<b>\$825,043</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	19	Ea.	3	\$86,704	Rollup
Replace Cabinetry In Classes/Labs <b>Note:</b> Laminate is peeling and chipped and doors are missing on casework.	Capital Renewal	25	Room	4	\$279,695	8685
The Metal Student Lockers Require Replacement <b>Note:</b> Lockers rusting at bottom.	Capital Renewal	30	Ea.	4	\$14,760	8684
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$381,158</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>56</b>	<b>items</b>		<b>\$4,568,213</b>	
<b>Total for Campus</b>		<b>60</b>	<b>items</b>		<b>\$5,024,471</b>	



## South Kingstown Inclusionary Preschool - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)	430	LF	\$27,798	4
Pedestrian Pavement	Sidewalks - Concrete	3,250	SF	\$66,429	5
		<b>Sub Total for System</b>		<b>\$94,227</b>	
		<b>Sub Total for Building -</b>		<b>\$94,227</b>	

### Building: 01 - Main Building

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Resilient Flooring	Vinyl Composition Tile Flooring	30,000	SF	\$344,152	4
Wall Painting and Coating	Painting/Staining (Bldg SF)	37,350	SF	\$246,784	4
Interior Door Supplementary Components	Door Hardware	65	Door	\$203,925	5
Interior Swinging Doors	Steel	4	Door	\$17,128	5
		<b>Sub Total for System</b>		<b>\$811,989</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Ductless Split System (3 Ton)	2	Ea.	\$15,565	4
Decentralized Cooling	Ductless Split System (1 Ton)	6	Ea.	\$84,696	4
Facility Hydronic Distribution	2-Pipe Water System (Hot)	29,880	SF	\$230,321	5
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	7,470	SF	\$50,458	5
HVAC Air Distribution	Ductwork (Bldg.SF)	17,928	SF	\$263,562	5
		<b>Sub Total for System</b>		<b>\$644,601</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	37,350	SF	\$221,928	3
		<b>Sub Total for System</b>		<b>\$221,928</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Building Support Plumbing System Supplementary Components	Sump Pump	1	Ea.	\$1,449	5
		<b>Sub Total for System</b>		<b>\$1,449</b>	

#### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	37,350	SF	\$109,473	3
		<b>Sub Total for System</b>		<b>\$109,473</b>	
		<b>Sub Total for Building 01 - Main Building</b>		<b>\$1,789,440</b>	
		<b>Total for: South Kingstown Inclusionary Preschool</b>		<b>\$1,883,667</b>	



## Supporting Photos



Renovation Plaque



Gymnasium



Classroom Lavatory



Original Single Pane Windows



# Facility Condition Assessment


South Kingstown - South Kingstown Inclusionary Preschool



Scratched Doors



Worn Carpet



Separating And Worn VCT



Broken Canopy Light



Non-Functional Canopy Light




Aged Building Mounted Light



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool



Generator



Restroom Lavatory



Kitchen Lavatory



Classroom Drinking Fountain



Non-Functional Drinking Fountain



Stained Service Sink



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool



Make Up Air Unit



Typical Urinal



Refrigerated Drinking Fountain



Paint Peeling At Canopies



Non-Functional Window Unit



100 Amp Panel



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool



Rusting Kitchen Hood



Aged Distribution Panel



Pneumatic System



Rusting Lockers



Damaged Casework



Non-Functional Transfer Switch



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool



Unit Vent Heater Coils Clogged



Radiant Fin Tube Heater



Pumps



Abandoned Equipment



Site Aerial



Cracked Asphalt





# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool



Cracked Asphalt Play Area



Elevation



Play Area



Marquee



Site Signage



Typical Classroom



# Facility Condition Assessment

South Kingstown - South Kingstown Inclusionary Preschool



Former Library



Entrance



# Facility Condition Assessment

South Kingstown - Wakefield Elementary School

June 2017

101 High Street, Wakefield, RI 02879





## Introduction

Wakefield Elementary School, located at 101 High Street in Wakefield, Rhode Island, was built in 1964. It comprises 34,004 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Wakefield Elementary School serves grades KG - 4, has 22 instructional spaces, and has an enrollment of 253. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Wakefield Elementary School is 326 with a resulting utilization of 78%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Wakefield Elementary School the 5-year need is \$6,680,887. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Wakefield Elementary School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Wakefield Elementary School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	Aluminum Exterior Windows
	Storefront / Curtain Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Built-Up Roofing With Ballast
----------------------------	-------------------------------

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Ceramic Tile Wall
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Quarry Tile Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Carpet

### Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	1,275 MBH Cast Iron Water Boiler
	3,264 MBH Cast Iron Water Boiler



<b>01 - Main Building:</b>	Steam/Hot Water Heating Unit Vent
	Fin Tube Water Radiant Heater
	Infrared Electric Radiant Heater
	Pneumatic Heating System Controls
	2 Ton Ductless Split System
	Window Units
	Make-up Air Unit
	1 HP or Smaller Pump
	2-Pipe Hot Water Hydronic Distribution System
	2,000 CFM Interior AHU
	Ductwork
	Kitchen Exhaust Hoods
	Roof Exhaust Fan

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Gas Piping System
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Toilets
	Urinals
	Sump Pump
	Air Compressor (2 hp)
	550 Gallon Above Ground Fuel Oil Storage Tank

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	50 kW Emergency Generator
	Automatic Transfer Switch
	800 Amp Switchgear
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.





# Facility Condition Assessment

South Kingstown - Wakefield Elementary School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$106,472	\$288,167	-	\$394,639	9.22 %
Roofing	-	-	\$25,811	-	-	\$25,811	0.60 %
Structural	-	-	-	\$3,423	-	\$3,423	0.08 %
Exterior	-	\$722,587	-	-	-	\$722,587	16.89 %
Interior	-	-	\$471,331	\$210,008	\$5,761	\$687,100	16.06 %
Mechanical	-	\$1,079,977	\$15,899	\$139,089	\$9,389	\$1,244,354	29.08 %
Electrical	-	\$129,010	\$3,572	-	\$41,686	\$174,268	4.07 %
Plumbing	-	-	\$8,094	\$261,155	\$27,005	\$296,253	6.92 %
Fire and Life Safety	-	-	-	-	-	\$0	0.00 %
Technology	-	-	\$532,064	-	-	\$532,064	12.43 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$9,127	\$189,829	-	\$198,955	4.65 %
<b>Total</b>	\$0	\$1,931,573	\$1,172,371	\$1,091,670	\$83,841	\$4,279,455	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$1,244,354
Exterior	-	\$722,587
Interior	-	\$687,100

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$34,225	-	\$34,225
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$1,931,573	\$629,669	\$853,333	\$25,551	\$3,440,125
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	-	-	\$20,535	\$113,796	\$58,290	\$192,621
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$90,316	-	\$90,316
Technology	-	-	\$520,656	-	-	\$520,656
Traffic	-	-	\$1,511	-	-	\$1,511
<b>Total</b>	\$0	\$1,931,573	\$1,172,371	\$1,091,670	\$83,841	\$4,279,455

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



### Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$394,639	\$0	\$0	\$0	\$201,820	\$23,205	\$225,025	\$619,664
Roofing	\$25,811	\$0	\$0	\$0	\$0	\$0	\$0	\$25,811
Structural	\$3,423	\$0	\$0	\$0	\$0	\$0	\$0	\$3,423
Exterior	\$722,587	\$0	\$0	\$0	\$0	\$0	\$0	\$722,587
Interior	\$687,100	\$0	\$0	\$208,158	\$501,494	\$216,474	\$926,126	\$1,613,226
Mechanical	\$1,244,354	\$0	\$0	\$229,687	\$273,162	\$140,924	\$643,773	\$1,888,127
Electrical	\$174,268	\$0	\$202,047	\$0	\$0	\$11,598	\$213,645	\$387,913
Plumbing	\$296,253	\$0	\$0	\$273,592	\$17,259	\$0	\$290,851	\$587,104
Fire and Life Safety	\$0	\$0	\$0	\$99,666	\$0	\$0	\$99,666	\$99,666
Technology	\$532,064	\$0	\$0	\$0	\$0	\$0	\$0	\$532,064
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$198,955	\$0	\$0	\$0	\$0	\$0	\$0	\$198,955
<b>Total</b>	<b>\$4,279,455</b>	<b>\$0</b>	<b>\$202,047</b>	<b>\$811,103</b>	<b>\$993,735</b>	<b>\$392,201</b>	<b>\$2,399,086</b>	<b>\$6,678,541</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$11,901,400. For planning purposes, the total 5-year need at the Wakefield Elementary School is \$6,680,887 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Wakefield Elementary School facility has a 5-year FCI of 56.12%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 189 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Wakefield Elementary School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



## Summary of Findings

The Wakefield Elementary School comprises 34,004 square feet and was constructed in 1964. Current deficiencies at this school total \$4,281,801. Five year capital renewal costs total \$2,399,086. The total identified need for the Wakefield Elementary School (current deficiencies and 5-year capital renewal costs) is \$6,680,887. The 5-year FCI is 56.12%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Wakefield Elementary School Totals	34,004	1964	\$4,281,801	\$2,399,086	\$6,680,887	56.12%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement <b>Note:</b> Concrete walkways are cracked and spalling and aggregate is exposed.	Capital Renewal	5,170	SF	3	\$104,961	4561
Crosswalk Requires Repainting <b>Note:</b> Repaint crosswalk leading across parking lot at north side of building	Traffic	1	Ea.	3	\$755	9297
Crosswalk: Needs to be added <b>Note:</b> Install crosswalk across West entrance to school	Traffic	1	Ea.	3	\$755	9298
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt is old, cracked, and alligatored.	Capital Renewal	62	CAR	4	\$203,747	4560
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28590
Fencing Requires Replacement (8' Chain Link Fence) <b>Note:</b> Fence is rusting and falling.	Capital Renewal	840	LF	4	\$56,091	4559
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$394,639</b>	
<b>Sub Total for School and Site Level</b>		<b>6</b>	<b>items</b>		<b>\$394,639</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Gutters Require Replacement <b>Note:</b> Gutters are leaking.	Capital Renewal	275	LF	3	\$13,072	4573
The Metal Downspouts Require Installation or Replacement <b>Note:</b> Downspouts are damaged and leaking.	Capital Renewal	200	LF	3	\$12,739	4564
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$25,811</b>	

### Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Steel Beam Requires Repainting <b>Note:</b> Painted beams are peeling.	Capital Renewal	300	SF	4	\$3,423	4578
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$3,423</b>	

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Aluminum Window Requires Replacement <b>Note:</b> Caulking has failed and air leaks in through the single pane windows on the north side of the building.	Capital Renewal	4,270	SF	2	\$722,587	4563
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$722,587</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Carpet Flooring Requires Replacement	Capital Renewal	10,800	SF	3	\$234,967	8714
The Vinyl Composition Tile Requires Replacement <b>Note:</b> Vinyl flooring throughout the building is peeling, faded, and chipped.	Capital Renewal	20,604	SF	3	\$236,364	4565
Caulking - significant areas of broken pieces &/or deteriorating caulk	Hazardous Material	400	LF	4	\$7,606	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	220	Ea.	4	\$62,746	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	750	LF	4	\$17,113	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	300	SF	4	\$2,852	Rollup
Room Is Excessively Reverberant (Install Fiberglass Wall Panel) <b>Note:</b> Gym	Acoustics	600	SF	4	\$34,225	19730
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	2,243	SF	4	\$85,467	Rollup
Classroom Door Requires Vision Panel	Educational Adequacy	1	Ea.	5	\$2,282	Rollup





# Facility Condition Assessment

South Kingstown - Wakefield Elementary School

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,480	Rollup
<b>Sub Total for System</b>		<b>10</b>	<b>items</b>		<b>\$687,100</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Replace Unit Vent <b>Note:</b> Units are aged and the coils and blowers are clogged.	Capital Renewal	6	Ea.	2	\$101,489	4591
Replace Unit Vent <b>Note:</b> Coils are clogged and the intakes are blocked.	Capital Renewal	3	Ea.	2	\$50,744	4592
The Air Handler HVAC Component Requires Replacement <b>Note:</b> Unit is aged, corroded, and rusted.	Capital Renewal	1	Ea.	2	\$43,137	4581
The Infrared Electric Radiant Heater Requires Replacement <b>Note:</b> Oil filled electric radiant heater is damaged.	Capital Renewal	1	Ea.	2	\$1,698	4585
The Radiant Heat HVAC Component Requires Replacement <b>Note:</b> Units are aged and the coils are packed and not circulating.	Capital Renewal	116	Ea.	2	\$882,909	4593
The Make Up Air Equipment Requires Replacement <b>Note:</b> Make up air unit has clogged coils and no filters. <b>Location:</b> Gym/cafetorium	Capital Renewal	1	Ea.	3	\$15,899	4575
Small HVAC Circulating Pump Requires Replacement <b>Note:</b> Pumps are rusted and leaking.	Capital Renewal	8	Ea.	4	\$61,027	4594
The Exhaust Hood Requires Replacement <b>Note:</b> Exhaust fans are aged and the blowers are packed full of dirt.	Capital Renewal	15	Ea.	4	\$78,062	4590
Remove Abandoned Equipment <b>Note:</b> Remove oil tank, pumps, and piping.	Capital Renewal	3	Ea.	5	\$9,389	4579
<b>Sub Total for System</b>		<b>9</b>	<b>items</b>		<b>\$1,244,354</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Generator Requires Replacement <b>Note:</b> Generator is old and seals are leaking.	Capital Renewal	1	Ea.	2	\$76,056	4566
Switchgear Is Needed Or Requires Replacement <b>Note:</b> Aged and rusted switchgear.	Capital Renewal	1	Ea.	2	\$23,482	4595
The Panelboard Requires Replacement <b>Note:</b> Panelboards are old and breakers are cracked.	Capital Renewal	4	Ea.	2	\$23,197	4583
The Panelboard Requires Replacement <b>Note:</b> Panelboard is aged and has previously been repaired improperly. It should be replaced.	Capital Renewal	1	Ea.	2	\$6,275	4584
Transfer Switch Requires Replacement <b>Note:</b> Transfer switch is old and contacts are burned.	Capital Renewal	100	Amps	3	\$3,572	4589
Room Has Insufficient Electrical Outlets	Educational Adequacy	84	Ea.	5	\$41,686	Rollup
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$174,268</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Sump Pump Requires Replacement <b>Note:</b> Sump pump and motor are corroded and non-functional.	Capital Renewal	1	Ea.	3	\$1,449	4580
The Urinal Plumbing Fixtures Require Replacement <b>Note:</b> Urinals are aged and stained.	Capital Renewal	5	Ea.	3	\$6,645	4576
Non-Refrigerated Drinking Fountain Requires Replacement <b>Note:</b> Drinking fountains are aged and clogged with calcium deposits. Valves are not functioning. <b>Location:</b> Classrooms and hallway	Capital Renewal	15	Ea.	4	\$153,300	4570
The Classroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Classroom lavatories are aged and stained.	Capital Renewal	14	Ea.	4	\$38,066	4562
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Custodial sinks are aged, stained, and rusted.	Capital Renewal	2	Ea.	4	\$5,153	4572



# Facility Condition Assessment

South Kingstown - Wakefield Elementary School

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Refrigerated Water Cooler Requires Replacement <b>Note:</b> Non-functional compressor on refrigerated drinking fountain.	Capital Renewal	1	Ea.	4	\$7,377	4577
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Restroom lavatories are aged, stained, and corroded.	Capital Renewal	12	Ea.	4	\$38,172	4567
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Kitchen lavatories are old and leaking.	Capital Renewal	6	Ea.	4	\$19,086	4568
Above Ground Fuel/Oil Storage Tank Requires Replacement <b>Note:</b> Rusting fuel storage tank.	Capital Renewal	1	Ea.	5	\$16,162	4586
Room lacks a drinking fountain.	Educational Adequacy	2	Ea.	5	\$2,206	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	8	Ea.	5	\$8,637	Rollup
<b>Sub Total for System</b>		<b>11</b>	<b>items</b>		<b>\$296,253</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,408	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	96	Ea.	3	\$45,633	13140
Technology: Instructional spaces do not have local sound reinforcement.	Technology	21	Ea.	3	\$99,823	13147
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,655	13138
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$21,676	13137
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	57	Ea.	3	\$24,385	13141
Technology: Network system inadequate and/or near end of useful life	Technology	2	Ea.	3	\$15,211	13145
Technology: Network system inadequate and/or near end of useful life	Technology	25	Ea.	3	\$118,837	13146
Technology: Number of current, up to date, network switch ports are insufficient to support campus technology.	Technology	144	Ea.	3	\$68,450	13142
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	34,004	SF	3	\$58,190	13144
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$54,190	13143
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1	Ea.	3	\$7,606	13139
<b>Sub Total for System</b>		<b>12</b>	<b>items</b>		<b>\$532,064</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	2	Ea.	3	\$9,127	Rollup
Replace Cabinetry In Classes/Labs <b>Note:</b> Cabinets are old and laminate is fading and peeling.	Capital Renewal	16	Room	4	\$179,005	4588
The Metal Student Lockers Require Replacement	Capital Renewal	22	Ea.	4	\$10,824	4587
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$198,955</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>55</b>	<b>items</b>		<b>\$3,884,816</b>	
<b>Total for Campus</b>		<b>61</b>	<b>items</b>		<b>\$4,279,455</b>	



## Wakefield Elementary School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Parking Lot Pavement	Asphalt	61	CAR	\$201,820	4
	<b>Note:</b> Paved play area				
Parking Lot Lighting	Pole Mounted Fixtures (Ea.)	3	Ea.	\$23,205	5
	<b>Note:</b> Mounted on utility poles facing parking lot				
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>	<b>\$225,024</b>	
<b>Sub Total for Building -</b>		<b>2</b>	<b>items</b>	<b>\$225,024</b>	

### Building: 01 - Main Building

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	31,504	SF	\$208,158	3
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	24,004	SF	\$284,699	4
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	24,004	SF	\$216,795	4
Interior Door Supplementary Components	Door Hardware	69	Door	\$216,474	5
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>	<b>\$926,126</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	34,004	SF	\$229,687	3
Decentralized Cooling	Window Units	3	Ea.	\$10,017	4
Decentralized Cooling	Ductless Split System (2 Ton)	1	Ea.	\$6,832	4
Heat Generation	Boiler - Cast Iron - Water (3264 MBH)	1	Ea.	\$181,009	4
	<b>Note:</b> 2,400 MBH - updated per LEA review				
Heat Generation	Boiler - Cast Iron - Water (1275 MBH)	1	Ea.	\$75,304	4
	<b>Note:</b> Updated per LEA review				
HVAC Air Distribution	Ductwork (Bldg.SF)	8,500	SF	\$124,960	5
Exhaust Air	Kitchen Exhaust Hoods	1	Ea.	\$15,964	5
<b>Sub Total for System</b>		<b>7</b>	<b>items</b>	<b>\$643,772</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)	34,004	SF	\$202,047	2
Power Distribution	Panelboard - 120/208 225A	1	Ea.	\$5,799	5
Power Distribution	Panelboard - 120/208 225A	1	Ea.	\$5,799	5
	<b>Note:</b> 200 amp				
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$213,645</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)	34,004	SF	\$273,592	3
Plumbing Fixtures	Classroom Lavatories	4	Ea.	\$10,876	4
Compressed-Air Systems	Air Compressor (2 hp)	1	Ea.	\$6,383	4
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>	<b>\$290,851</b>	

#### Fire and Life Safety

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	34,004	SF	\$99,666	3
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$99,666</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>18</b>	<b>items</b>	<b>\$2,174,060</b>	
<b>Total for: Wakefield Elementary School</b>		<b>20</b>	<b>items</b>	<b>\$2,399,084</b>	



**Supporting Photos**



Cracked Parking Lot Asphalt



Hallway Drinking Fountain



Site Aerial



Falling Fence



Signage




Cracked Concrete Walkway



Failed Caulking At Windows



Classroom Lavatory



Chipped VCT



Leaking Downspout



# Facility Condition Assessment

South Kingstown - Wakefield Elementary School



Restroom Lavatory




Aged Generator



Classroom Drinking Fountain



Kitchen Lavatory



Leaking Gutter



Stained Custodial Sink



Typical Urinal Fixture




Gym Make Up Air Unit



Paint Peeling



Refrigerated Drinking Fountain



Aged AHU



Non-Functional Sump Pump



400 Amp Panel With Improper Repairs



Panelboard With Cracked Breakers



Rusting Fuel Tank



Damaged Radiant Heater



Faded Faculty Lounge Cabinetry



Lockers





Transfer Switch With Burned Contacts



Damaged Classroom Cabinets



Damaged Heating Unit



Aged Heating Unit



Pumps Rusted And Leaking - New Section



Radiant Heater



Switchgear



Pumps Rusted And Leaking - Old Section



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School

June 2017

3119 Ministerial Road, West Kingston, RI 02892





## Introduction

West Kingston Elementary School, located at 3119 Ministerial Road in West Kingston, Rhode Island, was built in 1975. It comprises 43,552 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

West Kingston Elementary School serves grades KG - 4, has 28 instructional spaces, and has an enrollment of 265. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for West Kingston Elementary School is 376 with a resulting utilization of 70%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For West Kingston Elementary School the 5-year need is \$7,114,760. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of West Kingston Elementary School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the West Kingston Elementary School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

<b>Site</b>	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Metal Steep Slope Roofing
	Built-Up Roofing With Ballast

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Interior Demountable Partitions
	Foldable Interior Partition
	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Interior Door Hardware
	Door Hardware
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Wood Wall Paneling
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
	Wood Flooring
	Vinyl Composition Tile Flooring
	Epoxy Coated Flooring
	Carpet



## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Electric Heating Unit Vent
	Infrared Electric Radiant Heater
	Pneumatic Heating System Controls
	1 Ton Ductless Split System
	2 Ton Ductless Split System
	Make-up Air Unit
	Ductwork
	Roof Exhaust Fan
	Kitchen Exhaust Hoods

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	2" Backflow Preventers
	Gas Piping System
	75 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories
	Mop/Service Sinks
	Non-Refrigerated Drinking Fountain
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Air Compressor (5 hp)
	550 Gallon Above Ground Fuel Oil Storage Tank

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	800 Amp Switchgear
	112.5 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Panelboard - 277/480 400A
	Electrical Disconnect



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School

<b>01 - Main Building:</b>	Light Fixtures
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures





## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School

The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	\$369,968	\$718,439	-	\$1,088,407	18.84 %
Roofing	-	\$151,087	-	-	-	\$151,087	2.61 %
Structural	\$9,443	-	-	-	-	\$9,443	0.16 %
Exterior	-	\$235,838	-	-	-	\$235,838	4.08 %
Interior	-	-	\$888,801	\$408,788	\$3,541	\$1,301,130	22.52 %
Mechanical	-	\$1,177,531	\$110,547	\$67,198	-	\$1,355,276	23.46 %
Electrical	-	\$170,912	\$46,769	\$67,092	\$51,264	\$336,037	5.82 %
Plumbing	-	-	\$199,483	\$362,133	\$28,043	\$589,660	10.21 %
Fire and Life Safety	\$142,648	-	-	-	-	\$142,648	2.47 %
Technology	-	-	\$563,876	-	-	\$563,876	9.76 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,533	-	-	\$4,533	0.08 %
<b>Total</b>	\$152,091	\$1,735,368	\$2,183,976	\$1,623,651	\$82,849	\$5,777,934	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Mechanical	-	\$1,355,276
Interior	-	\$1,301,130
Site	-	\$1,088,407

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	\$174,695	\$28,329	-	\$203,023
Barrier to Accessibility	-	-	\$180,047	-	-	\$180,047
Capital Renewal	\$25,300	\$1,735,368	\$1,256,293	\$1,450,678	\$16,053	\$4,483,692
Code Compliance	\$126,791	-	-	-	-	\$126,791
Educational Adequacy	-	-	\$15,864	\$38,926	\$66,711	\$121,501
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$105,718	\$85	\$105,803
Technology	-	-	\$552,544	-	-	\$552,544
Traffic	-	-	\$4,533	-	-	\$4,533
<b>Total</b>	<b>\$152,091</b>	<b>\$1,735,368</b>	<b>\$2,183,976</b>	<b>\$1,623,651</b>	<b>\$82,849</b>	<b>\$5,777,934</b>

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,088,407	\$0	\$0	\$0	\$44,588	\$0	\$44,588	\$1,132,995
Roofing	\$151,087	\$0	\$0	\$0	\$0	\$0	\$0	\$151,087
Structural	\$9,443	\$0	\$0	\$0	\$0	\$0	\$0	\$9,443
Exterior	\$235,838	\$0	\$0	\$0	\$0	\$0	\$0	\$235,838
Interior	\$1,301,130	\$0	\$0	\$305,610	\$0	\$357,817	\$663,427	\$1,964,557
Mechanical	\$1,355,276	\$0	\$294,181	\$0	\$48,275	\$0	\$342,456	\$1,697,732
Electrical	\$336,037	\$0	\$0	\$0	\$20,250	\$258,780	\$279,030	\$615,067
Plumbing	\$589,660	\$0	\$5,845	\$0	\$0	\$0	\$5,845	\$595,505
Fire and Life Safety	\$142,648	\$0	\$0	\$0	\$0	\$0	\$0	\$142,648
Technology	\$563,876	\$0	\$0	\$0	\$0	\$0	\$0	\$563,876
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$4,533	\$0	\$0	\$0	\$0	\$0	\$0	\$4,533
<b>Total</b>	<b>\$5,777,934</b>	<b>\$0</b>	<b>\$300,026</b>	<b>\$305,610</b>	<b>\$113,113</b>	<b>\$616,597</b>	<b>\$1,335,346</b>	<b>\$7,113,280</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$15,243,200. For planning purposes, the total 5-year need at the West Kingston Elementary School is \$7,114,760 (Life Cycle Years 1-5 plus the FCI deficiency cost). The West Kingston Elementary School facility has a 5-year FCI of 46.67%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 242 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the West Kingston Elementary School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$0.



## Summary of Findings

The West Kingston Elementary School comprises 43,552 square feet and was constructed in 1975. Current deficiencies at this school total \$5,779,414. Five year capital renewal costs total \$1,335,346. The total identified need for the West Kingston Elementary School (current deficiencies and 5-year capital renewal costs) is \$7,114,760. The 5-year FCI is 46.67%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
West Kingston Elementary School Totals	43,552	1975	\$5,779,414	\$1,335,346	\$7,114,760	46.67%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

## Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

## LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.





## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Require Replacement <b>Note:</b> Cracked concrete sidewalks.	Capital Renewal	18,000	SF	3	\$365,435	9443
Traffic Signage Is Required <b>Note:</b> Add flashing beacon to school zone signs	Traffic	2	Ea.	3	\$4,533	11614
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt roadway is cracked and split.	Capital Renewal	101	CAR	4	\$331,910	9440
Asphalt Paving Requires Replacement <b>Note:</b> Alligatored asphalt paving.	Capital Renewal	80	CAR	4	\$262,899	9441
Asphalt Paving Requires Replacement <b>Note:</b> Play area pavement is cracked.	Capital Renewal	29	CAR	4	\$95,301	9442
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28593
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$1,088,407</b>	

### Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Pole Lighting Requires Replacement <b>Note:</b> Site lighting is aged, poles are corroded, and lenses are clouded.	Capital Renewal	3	Ea.	3	\$23,048	9444
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$23,048</b>	
<b>Sub Total for School and Site Level</b>		<b>7</b>	<b>items</b>		<b>\$1,111,456</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Built-up Roofing With Aggregate Ballast Requires Replacement <b>Note:</b> Per LEA review feedback roof was replaced in 2016 with the exception of 4,000 SF.	Capital Renewal	4,000	SF	2	\$151,087	9464
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$151,087</b>	

### Structural

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Foundation Study Recommended <b>Note:</b> Floor slab is cracked from the entrance lobby to the gym.	Capital Renewal	1	Job	1	\$9,443	9470
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$9,443</b>	

### Exterior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Metal Exterior Door Requires Replacement <b>Note:</b> Doors are rusted, corroded, and should be replaced.	Capital Renewal	37	Door	2	\$235,838	9447
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$235,838</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Classroom Entry Doors Provide Insufficient Sound Isolation <b>Note:</b> All classrooms	Acoustics	20	Ea.	3	\$174,695	19805
The Acoustical Ceiling Tiles Require Replacement <b>Note:</b> Ceiling tiles are aged and should be replaced.	Capital Renewal	15,000	SF	3	\$134,562	9448
The Carpet Flooring Requires Replacement <b>Note:</b> Carpet is old, faded, and stained. <b>Location:</b> Classrooms, library, teacher's lounge, various offices	Capital Renewal	15,000	SF	3	\$324,145	9449
The Vinyl Composition Tile Requires Replacement <b>Note:</b> VCT throughout the building is cracked and curling.	Capital Renewal	19,522	SF	3	\$222,443	9450
The Wood Flooring Requires Replacement <b>Note:</b> Stage flooring is faded and scratched.	Capital Renewal	1,000	SF	3	\$32,956	9451



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ceiling Grid Requires Replacement <b>Note:</b> Grid is broken and not in alignment. <b>Location:</b> Primary wing addition	Capital Renewal	11,200	SF	4	\$131,943	9484
Epoxy Flooring Requires Repair Or Replacement <b>Note:</b> Epoxy coating is worn and chipped. <b>Location:</b> Gym, kitchen, restrooms, mechanical rooms	Capital Renewal	7,000	SF	4	\$132,201	9471
Paint (probable pre-1978 in base (layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	319	Ea.	4	\$90,369	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	229	LF	4	\$5,190	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	638	SF	4	\$6,025	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - linear feet)	Hazardous Material	17	LF	4	\$385	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet)	Hazardous Material	309	SF	4	\$2,918	Rollup
Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet)	Hazardous Material	8	SF	4	\$76	Rollup
Paint (probable pre-1978 in base layer(s)) -large areas (> 10 sq. ft.)of peeling/damage & area in active use-adults only (measurement unit - square feet)	Hazardous Material	80	SF	4	\$755	Rollup
Partitions Provide Insufficient Sound Isolation <b>Note:</b> Classrooms adjacent to gym/library	Acoustics	1,000	SF	4	\$28,329	19806
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	280	SF	4	\$10,597	Rollup
Room lacks appropriate sound control.	Educational Adequacy	100	SF	5	\$3,456	Rollup
Wall/ceiling materials - area < 9 sq. ft. AND NOT in children-accessible area	Hazardous Material	9	SF	5	\$85	Rollup
<b>Sub Total for System</b>		<b>18 items</b>			<b>\$1,301,130</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ductwork Requires Replacement (SF Basis) <b>Note:</b> Ductwork is rusted and the insulation is damaged.	Capital Renewal	43,552	SF	2	\$635,953	9482
Replace Unit Vent <b>Note:</b> Heating units are aged and coils and blowers are clogged.	Capital Renewal	31	Ea.	2	\$435,877	9487
Replace Unit Vent <b>Note:</b> Heating units are aged and the coils and blowers are clogged. Air filters are missing or packed.	Capital Renewal	2	Ea.	2	\$28,121	9488
The Infrared Electric Radiant Heater Requires Replacement <b>Note:</b> Radiant heaters are aged and have clogged coils.	Capital Renewal	30	Ea.	2	\$50,595	9480
The Infrared Electric Radiant Heater Requires Replacement <b>Note:</b> Radiant heaters are aged with clogged coils.	Capital Renewal	16	Ea.	2	\$26,984	9481
The Make Up Air Equipment Requires Replacement	Capital Renewal	7	Ea.	3	\$110,547	9466
The Exhaust Hood Requires Replacement	Capital Renewal	4	Ea.	4	\$20,676	9485
The Exhaust Hood Requires Replacement <b>Note:</b> Exhaust fans are rusted and corroded.	Capital Renewal	9	Ea.	4	\$46,522	9486
<b>Sub Total for System</b>		<b>8 items</b>			<b>\$1,355,276</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Switchgear Is Needed Or Requires Replacement <b>Note:</b> Federal Pacific switchgear. Parts are no longer available.	Capital Renewal	1	Ea.	2	\$23,324	9489
The Electrical Disconnect Requires Replacement <b>Note:</b> Federal Pacific disconnect. Parts are no longer available.	Capital Renewal	1	Ea.	2	\$1,821	9454
The Electrical Transformer Requires Replacement <b>Note:</b> Federal Pacific transformer. Parts are no longer available.	Capital Renewal	1	Ea.	2	\$12,584	9472
The Panelboard Requires Replacement <b>Note:</b> Federal Pacific panels. Parts are no longer available.	Capital Renewal	2	Ea.	2	\$15,298	9473
The Panelboard Requires Replacement <b>Note:</b> Panelboard is aged and breaker panel is damaged.	Capital Renewal	1	Ea.	2	\$4,816	9474



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement <b>Note:</b> Federal Pacific panels. Parts are no longer available.	Capital Renewal	2	Ea.	2	\$11,520	9475
The Panelboard Requires Replacement <b>Note:</b> Federal Pacific panels. Parts are no longer available.	Capital Renewal	3	Ea.	2	\$18,697	9476
The Panelboard Requires Replacement <b>Note:</b> Federal Pacific panels. Parts are no longer available.	Capital Renewal	2	Ea.	2	\$35,336	9477
The Panelboard Requires Replacement <b>Note:</b> Federal Pacific panels. Parts are no longer available.	Capital Renewal	4	Ea.	2	\$47,517	9478
The Mounted Building Lighting Requires Replacement <b>Note:</b> Building mounted lights are aged. Fixtures are damaged and lenses clouded.	Capital Renewal	16	Ea.	3	\$23,721	9453
The Canopy Lighting Requires Replacement <b>Note:</b> Canopy lights are aged. The housings are rusted and deteriorated.	Capital Renewal	49	Ea.	4	\$67,092	9452
Room Has Insufficient Electrical Outlets	Educational Adequacy	104	Ea.	5	\$51,264	Rollup
<b>Sub Total for System</b>		<b>12</b>	<b>items</b>		<b>\$312,989</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Restroom Is Not ADA Compliant <b>Note:</b> Restroom does not have adequate ADA turning radius. <b>Location:</b> Lobby girl's restroom	Barrier to Accessibility	300	SF	3	\$83,099	9460
The Restroom Is Not ADA Compliant <b>Note:</b> Both faculty restrooms are missing an ADA stall.	Barrier to Accessibility	350	SF	3	\$96,949	9461
The Showers Plumbing Fixtures Require Replacement <b>Note:</b> Shower is old and the plumbing is corroded and stained.	Capital Renewal	1	Ea.	3	\$7,554	9458
The Urinal Plumbing Fixtures Require Replacement <b>Note:</b> Urinals are aged and stained.	Capital Renewal	9	Ea.	3	\$11,881	9467
Non-Refrigerated Drinking Fountain Requires Replacement <b>Note:</b> Drinking fountains are aged, stained, and corroded.	Capital Renewal	18	Ea.	4	\$182,721	9459
The Classroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Classroom lavatories are aged, stained, and corroded at connections.	Capital Renewal	20	Ea.	4	\$54,014	9446
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Service sinks are aged, rusted, corroded, and cracked.	Capital Renewal	5	Ea.	4	\$12,795	9462
The Refrigerated Water Cooler Requires Replacement <b>Note:</b> Drinking fountain is aged and the compressor is not functioning.	Capital Renewal	1	Ea.	4	\$7,328	9468
The Refrigerated Water Cooler Requires Replacement <b>Note:</b> Drinking fountain is aged and corroded.	Capital Renewal	1	Ea.	4	\$7,328	9469
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Lavatories are aged and stained and the support structures are degraded.	Capital Renewal	20	Ea.	4	\$63,192	9455
The Restroom Lavatories Plumbing Fixtures Require Replacement <b>Note:</b> Fixtures are aged, stained, and corroded at connections.	Capital Renewal	11	Ea.	4	\$34,756	9456
Above Ground Fuel/Oil Storage Tank Requires Replacement <b>Note:</b> Tank is aged and has no leak monitoring device.	Capital Renewal	1	Ea.	5	\$16,053	9483
Room lacks a drinking fountain.	Educational Adequacy	4	Ea.	5	\$4,382	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	7	Ea.	5	\$7,609	Rollup
<b>Sub Total for System</b>		<b>14</b>	<b>items</b>		<b>\$589,660</b>	

## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Alarm Is Missing Or Inadequate (NFPA 72 and NFPA 101, Section 9.6)	Code Compliance	43,552	SF	1	\$126,791	9465
Replace Kitchen Exhaust Hood <b>Note:</b> Kitchen exhaust hood is aged. Filters are clogged and the bearings are very noisy.	Capital Renewal	1	Ea.	1	\$15,857	9479
<b>Sub Total for System</b>		<b>2</b>	<b>items</b>		<b>\$142,648</b>	



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	2	Ea.	3	\$11,332	Rollup
Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Technology	120	Ea.	3	\$56,658	13242
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	12	Ea.	3	\$113,315	13245
Technology: Instructional spaces do not have local sound reinforcement.	Technology	12	Ea.	3	\$56,658	24968
Technology: Main Telecommunications Room ground system is inadequate or non-existent.	Technology	1	Ea.	3	\$6,610	13241
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$21,530	13240
Technology: Network system inadequate and/or near end of useful life	Technology	1	Ea.	3	\$7,554	13246
Technology: Network system inadequate and/or near end of useful life	Technology	23	Ea.	3	\$108,594	13248
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	43,522	SF	3	\$73,976	13247
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$53,825	13243
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1	Ea.	3	\$53,825	13244
<b>Sub Total for System</b>		<b>11</b>	<b>items</b>		<b>\$563,876</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1	Ea.	3	\$4,533	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$4,533</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>69</b>	<b>items</b>		<b>\$4,666,478</b>	
<b>Total for Campus</b>		<b>76</b>	<b>items</b>		<b>\$5,777,934</b>	



## West Kingston Elementary School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Playfield Areas	ES Playgrounds	1	Ea.	\$44,588	4
		<b>Sub Total for System</b>		<b>\$44,588</b>	
		<b>Sub Total for Building -</b>		<b>\$44,588</b>	

### Building: 01 - Main Building

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	39,052	SF	\$258,030	3
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	3,800	SF	\$45,070	3
		<b>Note:</b> Music addition			
Interior Demountable Partitions	Demountable Interior Partitions (Bldg SF)	100	SF	\$2,510	3
		<b>Note:</b> School office and vestibule			
Wall Paneling	Wood Panel wall	1,000	SF	\$9,127	5
Suspended Plaster and	Painted ceilings	1,000	SF	\$4,183	5
Interior Operable Partitions	Foldable partition (Bldg SF)	22	SF Wall	\$2,541	5
Interior Door Supplementary Components	Door Hardware	109	Door	\$341,966	5
		<b>Sub Total for System</b>		<b>\$663,426</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)	43,552	SF	\$294,181	2
Decentralized Cooling	Ductless Split System (1 Ton)	1	Ea.	\$14,116	4
Decentralized Cooling	Ductless Split System (2 Ton)	5	Ea.	\$34,159	4
		<b>Sub Total for System</b>		<b>\$342,455</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Panelboard - 120/208 100A	1	Ea.	\$4,849	4
Power Distribution	Panelboard - 277/480 100A	2	Ea.	\$15,401	4
Lighting Fixtures	Light Fixtures (Bldg SF)	43,552	SF	\$258,780	5
		<b>Sub Total for System</b>		<b>\$279,030</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 75 Gallons	1	Ea.	\$5,845	2
		<b>Sub Total for System</b>		<b>\$5,845</b>	
		<b>Sub Total for Building 01 - Main Building</b>		<b>\$1,290,756</b>	
		<b>Total for: West Kingston Elementary School</b>		<b>\$1,335,344</b>	



**Supporting Photos**



Alligatored Parking Pavement



Splitting Asphalt Pavement



Parking Lot Lighting



Cracked Concrete Walkway



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School



Site Aerial



Entrance



Exterior Finishes



Front Elevation



Gymnasium



Music Classroom



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School



Typical Classroom



Library



Plaque



Classroom At Original Building



Cafeteria



Site Signage






Stained Classroom Lavatory



Weathered And Corroded Exterior Doors



Rusted Exterior Metal Doors



Worn Carpet



Curling VCT Flooring



Cracked VCT



Worn Wood Floor At Stage



Canopy Mounted Fixture



Aged Building Mounted Light



Federal Pacific Disconnect



Typical Restroom Lavatories



Stained Drinking Fountain



# Facility Condition Assessment

South Kingstown - West Kingston Elementary School



Faculty Restroom With No ADA



Aged Service Sink



Aged Make Up Air Unit



Typical Urinals



Drinking Fountain With Non-Functional Compressor



Cracked Gym Floor



Cracked VCT Floor At Lobby



Worn Epoxy Floor



Worn Epoxy At Restroom



Federal Pacific Transformer



Federal Pacific Panelboard



Kitchen Exhaust



Aged Radiant Heater



Broken Ceiling Grid



Weathered Exhaust



Aged Heating Unit



Heating Unit Vent



Federal Pacific Switchgear