



Facility Condition Assessment

Newport - Rogers High School

June 2017

15 Wickham Road, Newport, RI 02840





Introduction

Rogers High School, located at 15 Wickham Road in Newport, Rhode Island, was built in 1957. It comprises 205,000 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Rogers High School serves grades 9 - 12, has 48 instructional spaces, and has an enrollment of 590. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Rogers High School is 1,000 with a resulting utilization of 59%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Rogers High School the 5-year need is \$51,435,651. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Rogers High School



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



System Summaries

The following tables summarize major building systems at the Rogers High School campus, identified by discipline and building.

Site

The site level systems for this campus include:

| | |
|------|------------------------------|
| Site | Asphalt Parking Lot Pavement |
| | Asphalt Roadway Pavement |
| | Asphalt Pedestrian Pavement |
| | Concrete Pedestrian Pavement |

Building Envelope

The exterior systems for the building(s) at this campus includes:

| | |
|----------------------------|---------------------------------|
| 01 - Main Building: | Brick Exterior Wall |
| | Metal Panel Exterior Wall |
| | Storefront / Curtain Wall |
| | Steel Exterior Entrance Doors |
| | Overhead Exterior Utility Doors |
| 02 - Building 02: | Brick Exterior Wall |
| | Stucco Exterior Wall |
| | Storefront / Curtain Wall |
| | Steel Exterior Entrance Doors |
| | Overhead Exterior Utility Doors |

The roofing for the building(s) at this campus consists of:

| | |
|----------------------------|--------------------------------|
| 01 - Main Building: | Cast In Place Concrete Roofing |
| | Single Ply Roofing |
| | Canopy Roofing |
| 02 - Building 02: | Single Ply Roofing |

Interior

The interior systems for the building(s) at this campus include:

| | |
|----------------------------|-----------------------------------|
| 01 - Main Building: | Wood Interior Doors |
| | Interior Door Hardware |
| | Suspended Acoustical Grid System |
| | Suspended Acoustical Ceiling Tile |
| | Adhered Acoustical Ceiling Tiles |
| | Painted Ceilings |
| | Metal Panel Ceilings |
| | Wood Wall Paneling |
| | Interior Wall Painting |



| | |
|----------------------------|-----------------------------------|
| 01 - Main Building: | Concrete Flooring |
| | Ceramic Tile Flooring |
| | Quarry Tile Flooring |
| | Wood Flooring |
| | Vinyl Composition Tile Flooring |
| | Terrazzo Flooring |
| | Epoxy Coated Flooring |
| | Carpet |
| 02 - Building 02: | Steel Interior Doors |
| | Interior Door Hardware |
| | Suspended Acoustical Grid System |
| | Suspended Acoustical Ceiling Tile |
| | Painted Ceilings |
| | Ceramic Tile Wall |
| | Interior Wall Painting |
| | Concrete Flooring |
| | Ceramic Tile Flooring |
| | Quarry Tile Flooring |
| | Vinyl Composition Tile Flooring |
| | Carpet |

Mechanical

The mechanical systems for the building(s) at this campus include:

| | |
|----------------------------|---|
| 01 - Main Building: | 4,200 MBH Cast Iron Steam Boiler |
| | 8,500 MBH Cast Iron Boiler |
| | Finned Wall Radiator |
| | 20 MBH Steam Unit Heater |
| | Pneumatic Heating System Controls |
| | 1 Ton Ductless Split System |
| | Window Units |
| | Make-up Air Unit |
| | 1 HP or Smaller Pump |
| | 2-Pipe Steam Hydronic Distribution System |
| | 2,000 CFM Interior AHU |
| | Ductwork |
| | 5 Ton DX Gas Roof Top Unit |
| | Roof Exhaust Fan |
| | Kitchen Exhaust Hoods |
| | Laboratory Fume Hood |
| | Fire Sprinkler System |
| 02 - Building 02: | 20 kW Electric Unit Heater |
| | 200 MBH Gas Unit Heater |



| | |
|--------------------------|-----------------------------------|
| 02 - Building 02: | Pneumatic Heating System Controls |
| | Make-up Air Unit |
| | 1 HP or Smaller Pump |
| | 5 Ton DX Gas Roof Top Unit |
| | Ductwork |
| | Roof Exhaust Fan |
| | Kitchen Exhaust Hoods |
| | Fire Sprinkler System |

Plumbing

The plumbing systems for the building(s) at this campus include:

| | |
|----------------------------|--------------------------------|
| 01 - Main Building: | 250 Gallon Water Storage Tank |
| 02 - Building 02: | 250 Gallon Water Storage Tank |
| 01 - Main Building: | 4" Backflow Preventers |
| | Gas Piping System |
| | 40 Gallon Gas Water Heater |
| 02 - Building 02: | 2" Backflow Preventers |
| | Gas Piping System |
| | 40 Gallon Gas Water Heater |
| 01 - Main Building: | Domestic Water Piping System |
| 02 - Building 02: | Domestic Water Piping System |
| 01 - Main Building: | Lavatories |
| | Mop/Service Sinks |
| | Refrigerated Drinking Fountain |
| | Restroom Lavatories |
| | Showers |
| | Toilets |
| | Urinals |
| 02 - Building 02: | Lavatories |
| | Mop/Service Sinks |
| | Refrigerated Drinking Fountain |
| | Toilets |
| 01 - Main Building: | Sump Pump |
| 02 - Building 02: | Air Compressor (1 hp) |

Electrical

The electrical systems for the building(s) at this campus include:

| | |
|----------------------------|------------------------------------|
| 01 - Main Building: | Electrical Service |
| | 225 KVA Transformer |
| | 1600 Amp Distribution Panel |
| | 800 Amp Distribution Panel |
| | Building Mounted Lighting Fixtures |



| | |
|----------------------------|------------------------------------|
| 01 - Main Building: | Canopy Mounted Lighting Fixtures |
| | Light Fixtures |
| 02 - Building 02: | Electrical Service |
| | 800 Amp Distribution Panel |
| | Light Fixtures |
| | Building Mounted Lighting Fixtures |
| | Canopy Mounted Lighting Fixtures |



Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – Mission Critical Concerns: Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

| System | Priority | | | | | Total | % of Total |
|----------------------|--------------------|---------------------|--------------------|--------------------|------------------|---------------------|------------|
| | 1 | 2 | 3 | 4 | 5 | | |
| Site | - | - | \$914,964 | \$56,658 | \$358,832 | \$1,330,454 | 3.51 % |
| Roofing | - | \$1,283,441 | \$513,376 | - | - | \$1,796,817 | 4.73 % |
| Structural | - | - | - | - | - | \$0 | 0.00 % |
| Exterior | - | \$9,824,849 | - | - | \$98,226 | \$9,923,075 | 26.15 % |
| Interior | - | - | \$1,100,424 | \$1,533,283 | \$81,603 | \$2,715,311 | 7.15 % |
| Mechanical | - | \$8,998,494 | \$15,899 | \$1,666,464 | - | \$10,680,858 | 28.14 % |
| Electrical | \$4,237 | \$613,604 | \$41,253 | \$52,279 | \$125,148 | \$836,520 | 2.20 % |
| Plumbing | - | - | \$2,477,809 | \$137,710 | \$58,659 | \$2,674,178 | 7.05 % |
| Fire and Life Safety | \$4,196,528 | - | - | - | - | \$4,196,528 | 11.06 % |
| Technology | - | - | \$3,256,269 | \$7,891 | - | \$3,264,160 | 8.60 % |
| Conveyances | - | - | - | \$22,817 | - | \$22,817 | 0.06 % |
| Specialties | - | - | \$18,253 | \$451,311 | \$42,781 | \$512,346 | 1.35 % |
| Total | \$4,200,765 | \$20,720,387 | \$8,338,248 | \$3,928,413 | \$765,250 | \$37,953,063 | |

*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

| | | |
|----------------------|---|--------------|
| Mechanical | - | \$10,680,858 |
| Exterior | - | \$9,923,075 |
| Fire and Life Safety | - | \$4,196,528 |

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



Facility Condition Assessment

Newport - Rogers High School



Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

| Category | Priority | | | | | Total |
|--------------------------|--------------------|---------------------|--------------------|--------------------|------------------|---------------------|
| | 1 | 2 | 3 | 4 | 5 | |
| Acoustics | - | - | \$482,754 | - | - | \$482,754 |
| Barrier to Accessibility | - | - | \$111,549 | - | - | \$111,549 |
| Capital Renewal | \$4,139,486 | \$20,720,387 | \$3,743,401 | \$2,563,744 | \$213,949 | \$31,380,969 |
| Code Compliance | - | - | - | - | - | \$0 |
| Educational Adequacy | \$61,279 | - | \$52,325 | \$134,277 | \$551,301 | \$799,181 |
| Functional Deficiency | - | - | \$19,689 | - | - | \$19,689 |
| Hazardous Material | - | - | - | \$1,230,392 | - | \$1,230,392 |
| Technology | - | - | \$3,222,197 | - | - | \$3,222,197 |
| Traffic | - | - | \$706,333 | - | - | \$706,333 |
| Total | \$4,200,765 | \$20,720,387 | \$8,338,248 | \$3,928,413 | \$765,250 | \$37,953,063 |

*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

| System | Current Deficiencies | Life Cycle Capital Renewal Projections | | | | | LC Yr. 1-5 Total | Total 5-Year Need |
|----------------------|----------------------|--|-------------|--------------------|--------------------|--------------------|---------------------|---------------------|
| | | Year 1 2017 | Year 2 2018 | Year 3 2019 | Year 4 2020 | Year 5 2021 | | |
| Site | \$1,330,454 | \$0 | \$0 | \$0 | \$85,084 | \$239,119 | \$324,203 | \$1,654,657 |
| Roofing | \$1,796,817 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,796,817 |
| Structural | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Exterior | \$9,923,075 | \$0 | \$0 | \$0 | \$2,129,561 | \$377,123 | \$2,506,684 | \$12,429,760 |
| Interior | \$2,715,311 | \$0 | \$0 | \$1,305,714 | \$2,661,657 | \$3,714,127 | \$7,681,498 | \$10,396,810 |
| Mechanical | \$10,680,858 | \$0 | \$0 | \$171,741 | \$50,031 | \$0 | \$221,772 | \$10,902,630 |
| Electrical | \$836,520 | \$0 | \$0 | \$59,258 | \$157,481 | \$971,375 | \$1,188,114 | \$2,024,634 |
| Plumbing | \$2,674,178 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$2,674,178 |
| Fire and Life Safety | \$4,196,528 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$4,196,528 |
| Technology | \$3,264,160 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$3,264,160 |
| Conveyances | \$22,817 | \$0 | \$0 | \$142,605 | \$0 | \$570,418 | \$713,023 | \$735,840 |
| Specialties | \$512,346 | \$0 | \$0 | \$0 | \$0 | \$837,557 | \$837,557 | \$1,349,903 |
| Total | \$37,953,063 | \$0 | \$0 | \$1,679,318 | \$5,083,814 | \$6,709,719 | \$13,472,851 | \$51,425,914 |

*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building’s health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$73,800,000. For planning purposes, the total 5-year need at the Rogers High School is \$51,435,651 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Rogers High School facility has a 5-year FCI of 69.68%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility’s disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 1,108 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Rogers High School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$1,890,734.



Summary of Findings

The Rogers High School comprises 205,000 square feet and was constructed in 1957. Current deficiencies at this school total \$37,962,800. Five year capital renewal costs total \$13,472,851. The total identified need for the Rogers High School (current deficiencies and 5-year capital renewal costs) is \$51,435,651. The 5-year FCI is 69.68%.

Table 4: Facility Condition by Building

| | Gross Sq Ft | Year Built | Current Deficiencies | LC Yr. 1-5 Total | Total 5 Yr Need (Yr 1-5 + Current Defs) | 5-Year FCI |
|---------------------------|-------------|------------|----------------------|------------------|---|------------|
| Rogers High School Totals | 205,000 | 1957 | \$37,962,800 | \$13,472,851 | \$51,435,651 | 69.68% |

**Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|----------|--------------|----------|--------------------|-------|
| Asphalt Walks Require Replacement | Capital Renewal | 5,000 | SF | 3 | \$42,439 | 2992 |
| Concrete Walks Require Replacement | Capital Renewal | 8,000 | SF | 3 | \$162,416 | 2993 |
| Note: Concrete is cracked and not level. | | | | | | |
| Install New Paving | Traffic | 34,000 | SF | 3 | \$706,333 | 4457 |
| Note: Extend west side parking lot to allow for more student parking | | | | | | |
| Parking Or Roadway Curbs Require Replacement | Capital Renewal | 50 | LF | 3 | \$3,777 | 2994 |
| Note: Concrete curbs in front of vocational building. | | | | | | |
| Backstops Require Replacement | Educational Adequacy | 1 | Ea. | 4 | \$28,329 | 28505 |
| Note: Backstops Require Replacement | | | | | | |
| Site Drainage Is Inadequate And Installation Of Drainage Piping | Capital Renewal | 150 | LF | 4 | \$28,329 | 2995 |
| Note: East side parking lot, the existing catch basin is clogged. | | | | | | |
| School has insufficient baseball fields. | Educational Adequacy | 1 | Ea. | 5 | \$207,745 | 28319 |
| Note: School has insufficient baseball fields. | | | | | | |
| School has insufficient softball fields. | Educational Adequacy | 1 | Ea. | 5 | \$151,087 | 28362 |
| Note: School has insufficient softball fields. | | | | | | |
| Sub Total for System | | 8 | items | | \$1,330,454 | |

Electrical

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|-----------------------|----------|--------------|----------|-----------------|------|
| The Pole Lighting Is Missing And Needed | Functional Deficiency | 1 | Ea. | 3 | \$19,689 | 1507 |
| Note: Install new fixture by parking/auditorium. | | | | | | |
| Sub Total for System | | 1 | items | | \$19,689 | |

Specialties

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|-----------------|-----------|--------------|----------|--------------------|------|
| High School Athletic Components Require Replacement | Capital Renewal | 1 | Ea. | 4 | \$449,885 | 1830 |
| Note: Current high school athletic fields are not usable due to sinkholes. May require relocation of fields. | | | | | | |
| Sub Total for System | | 1 | items | | \$449,885 | |
| Sub Total for School and Site Level | | 10 | items | | \$1,800,028 | |

Building: 01 - Main Building

Roofing

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|-----------------|----------|--------------|----------|--------------------|------|
| The Single-Ply Membrane Roof Covering Requires Replacement | Capital Renewal | 100,000 | SF | 2 | \$1,283,441 | 3035 |
| Note: Water coming in at interior gym/corridor wall. | | | | | | |
| Awning Or Canopy Metal Roofing System Requires Replacement | Capital Renewal | 9,000 | SF | 3 | \$513,376 | 2983 |
| Sub Total for System | | 2 | items | | \$1,796,817 | |

Exterior

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|-----------------|----------|--------------|----------|--------------------|------|
| The Storefront/Curtain Wall Requires Replacement (Bldg SF) | Capital Renewal | 120,000 | SF | 2 | \$9,674,293 | 2991 |
| Note: Seals failing, water actively migrating into building at gym entrance and main entry. | | | | | | |
| Sub Total for System | | 1 | items | | \$9,674,293 | |

Interior

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|--------------------------|-------|------|----------|-------------|------|
| Classroom Entry Doors Provide Insufficient Sound Isolation | Acoustics | 58 | Ea. | 3 | \$482,754 | 4727 |
| Note: All classrooms | | | | | | |
| Interior Doors Require Replacement | Capital Renewal | 8 | Door | 3 | \$36,887 | 2987 |
| Location: Gym and auditorium | | | | | | |
| The Access Is Not ADA Compliant And Requires A Doorway Access Power Assist Mechanism | Barrier to Accessibility | 2 | Door | 3 | \$41,831 | 2988 |
| Note: Main entry has power assist push button, but it is not connected to doors. | | | | | | |
| The Carpet Flooring Requires Replacement | Capital Renewal | 1,600 | SF | 3 | \$34,810 | 2985 |



Facility Condition Assessment

Newport - Rogers High School

Interior

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|-----------|--------------|----------|--------------------|--------|
| Adhered Acoustical Ceiling Tile Requires Replacement Note: Tiles are damaged or missing. | Capital Renewal | 8,000 | SF | 4 | \$86,751 | 2986 |
| Light Deterioration or Damage of 9x9 Asbestos Floor Tile is Present | Hazardous Material | 30,180 | SF | 4 | \$860,761 | Rollup |
| Moveable Partitions Require Replacement | Capital Renewal | 1,600 | SF Wall | 4 | \$184,816 | 2984 |
| Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet) | Hazardous Material | 460 | LF | 4 | \$10,496 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet) | Hazardous Material | 24,614 | SF | 4 | \$234,005 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - each) | Hazardous Material | 1 | Ea. | 4 | \$285 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - linear feet) | Hazardous Material | 110 | LF | 4 | \$2,510 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. AND NOT in children-accessible area (measurement unit - square feet) | Hazardous Material | 1,430 | SF | 4 | \$13,595 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - each) | Hazardous Material | 48 | Ea. | 4 | \$13,690 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - linear feet) | Hazardous Material | 370 | LF | 4 | \$8,442 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - damaged area < 9 sq. ft. OR overall worn AND in children-accessible area (measurement unit - square feet) | Hazardous Material | 9,050 | SF | 4 | \$86,038 | Rollup |
| Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use-adults only (measurement unit - square feet) | Hazardous Material | 60 | SF | 4 | \$570 | Rollup |
| Room Lighting Is Inadequate Or In Poor Condition. | Educational Adequacy | 805 | SF | 4 | \$30,674 | Rollup |
| Classroom Door Requires Vision Panel | Educational Adequacy | 1 | Ea. | 5 | \$2,282 | Rollup |
| The Metal Ceiling Tiles Require Replacement Location: Cafeteria kitchen | Capital Renewal | 600 | SF | 5 | \$57,042 | 2989 |
| Sub Total for System | | 19 | items | | \$2,188,238 | |

Mechanical

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|-----------|--------------|----------|--------------------|--------|
| Ductless Split System AC Requires Replacement Note: Visually failing and rusting away. | Capital Renewal | 1 | Ea. | 2 | \$14,116 | 1746 |
| Ductwork Requires Replacement (SF Basis) Note: Original to building. | Capital Renewal | 160,000 | SF | 2 | \$2,352,186 | 1502 |
| Gas Piping Requires Replacement (SF Basis) | Capital Renewal | 160,000 | SF | 2 | \$3,464,217 | 3009 |
| Steam/HW Unit Heater Requires Replacement Note: Outdated and should be replaced. Appears many of them are no longer functional. | Capital Renewal | 30 | Ea. | 2 | \$84,479 | 1462 |
| Steam/HW Unit Heater Requires Replacement | Capital Renewal | 15 | Ea. | 2 | \$42,239 | 1472 |
| The Air Handler HVAC Component Requires Replacement Note: AHUs are falling apart and patched with duct tape. They are original to 1957 install. | Capital Renewal | 9 | Ea. | 2 | \$388,232 | 1476 |
| The Cast Iron Water Boiler Requires Replacement | Capital Renewal | 1 | Ea. | 2 | \$431,626 | 3037 |
| The Fin Tube Water Radiant Heater Requires Replacement Note: Outdated and falling apart - recommend replacement. | Capital Renewal | 175 | Ea. | 2 | \$293,147 | 1470 |
| The Mechanical / HVAC Piping / System Is Beyond Its Useful Life Note: Piping and traps are failing. | Capital Renewal | 160,000 | SF | 2 | \$1,233,311 | 1485 |
| The Window AC Unit Component Requires Replacement Note: Window units no longer functioning. | Capital Renewal | 10 | Ea. | 2 | \$33,388 | 1503 |
| The Make Up Air Equipment Requires Replacement Note: Makeup air unit in room 425 is no longer functional. Location: Room 425 | Capital Renewal | 1 | Ea. | 3 | \$15,899 | 1480 |
| Existing Controls Are Inadequate And Should Be Replaced With DDC Controls | Capital Renewal | 160,000 | SF | 4 | \$1,080,752 | 2415 |
| Lab lacks an appropriate fume hood. | Educational Adequacy | 3 | Ea. | 4 | \$65,957 | Rollup |
| The Exhaust Hood Requires Replacement Note: Of the 40 total exhaust fan only 8 were running during occupied hours. | Capital Renewal | 40 | Ea. | 4 | \$208,165 | 1747 |
| Sub Total for System | | 14 | items | | \$9,707,716 | |



Electrical

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|-----------|--------------|----------|------------------|--------|
| Room last power shut-off valves for utilities | Educational Adequacy | 3 | Ea. | 1 | \$4,237 | Rollup |
| The Distribution Panel Requires Replacement | Capital Renewal | 1 | Ea. | 2 | \$51,908 | 1454 |
| The Electrical Disconnect Requires Replacement | Capital Renewal | 1 | Ea. | 2 | \$1,833 | 1455 |
| Location: Boiler room | | | | | | |
| The Electrical Service And Distribution Requires Replacement | Capital Renewal | 160,000 | SF | 2 | \$480,327 | 3010 |
| The Electrical Transformer Requires Replacement | Capital Renewal | 1 | Ea. | 2 | \$21,201 | 3011 |
| The Distribution Panel Requires Repair | Capital Renewal | 1 | Ea. | 3 | \$734 | 1463 |
| Note: 225KVA transformer, 208\120V. 800 Amps main. Preventive maintenance program. | | | | | | |
| Location: Auditorium basement | | | | | | |
| The Mounted Building Lighting Requires Replacement | Capital Renewal | 1 | Ea. | 3 | \$1,493 | 1510 |
| Location: Exterior gym wall | | | | | | |
| The Mounted Building Lighting Requires Replacement | Capital Renewal | 2 | Ea. | 3 | \$2,985 | 1512 |
| Location: Door 35 | | | | | | |
| The Mounted Building Lighting Requires Replacement | Capital Renewal | 3 | Ea. | 3 | \$4,478 | 1513 |
| Location: Doors 25 and 26 | | | | | | |
| The Mounted Building Lighting Requires Replacement | Capital Renewal | 1 | Ea. | 3 | \$1,493 | 1515 |
| Location: Door 24 | | | | | | |
| Wall Pack Lighting Requires Repair | Capital Renewal | 2 | Ea. | 3 | \$475 | 1516 |
| Location: By door 24 | | | | | | |
| Wall Pack Lighting Requires Repair | Capital Renewal | 1 | Ea. | 3 | \$238 | 1518 |
| Location: Across door 404 | | | | | | |
| The Incandescent Lighting Requires Replacement | Capital Renewal | 23 | Ea. | 4 | \$16,837 | 1459 |
| Location: Boiler room | | | | | | |
| The Incandescent Lighting Requires Replacement | Capital Renewal | 6 | Ea. | 4 | \$4,392 | 1461 |
| Location: Hallway between gym and auditorium | | | | | | |
| The Incandescent Lighting Requires Replacement | Capital Renewal | 32 | Ea. | 4 | \$23,425 | 1465 |
| Note: Emergency lighting system is old and needs replacement, battery indicator is in the discharged position. | | | | | | |
| Location: Auditorium makeup room. | | | | | | |
| The Incandescent Lighting Requires Replacement | Capital Renewal | 1 | Ea. | 4 | \$732 | 1519 |
| Location: Kitchen entry, door 19 | | | | | | |
| Remove Abandoned Equipment | Capital Renewal | 2 | Ea. | 5 | \$6,643 | 1490 |
| Note: Old condensate receiver tanks | | | | | | |
| Remove Abandoned Equipment | Capital Renewal | 2 | Ea. | 5 | \$6,643 | 1491 |
| Note: Hot water tanks in auditorium catwalk | | | | | | |
| Remove Abandoned Equipment | Capital Renewal | 2 | Ea. | 5 | \$6,643 | 1496 |
| Note: Old pumps | | | | | | |
| Remove Abandoned Equipment | Capital Renewal | 2 | Ea. | 5 | \$6,643 | 1497 |
| Note: Old fan motors | | | | | | |
| Remove Abandoned Equipment | Capital Renewal | 2 | Ea. | 5 | \$6,643 | 1498 |
| Note: Old fuel oil pumps | | | | | | |
| Remove Abandoned Equipment | Capital Renewal | 2 | Ea. | 5 | \$6,643 | 1499 |
| Note: Old boiler controls | | | | | | |
| Room Has Insufficient Electrical Outlets | Educational Adequacy | 152 | Ea. | 5 | \$75,432 | Rollup |
| Sub Total for System | | 23 | items | | \$732,077 | |

Plumbing

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|-----------------|---------|-----|----------|-------------|------|
| Sump Pump Requires Replacement | Capital Renewal | 2 | Ea. | 3 | \$2,898 | 1492 |
| The Gas Water Heater Requires Replacement | Capital Renewal | 2 | Ea. | 3 | \$6,225 | 1489 |
| Note: Water heater has failed. | | | | | | |
| The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life | Capital Renewal | 160,000 | SF | 3 | \$1,287,342 | 1744 |
| Note: Domestic water piping is beginning to fail per faculty manager. | | | | | | |
| The Sanitary Sewer Piping Requires Replacement | Capital Renewal | 750 | LF | 3 | \$116,765 | 1484 |
| The Showers Plumbing Fixtures Require Replacement | Capital Renewal | 60 | Ea. | 3 | \$456,335 | 1475 |
| Note: Showers are no longer functioning. | | | | | | |



Plumbing

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|-----------------|-----|----------|--------------------|--------|
| The Urinal Plumbing Fixtures Require Replacement Note: Original, failing. | Capital Renewal | 30 | Ea. | 3 | \$39,872 | 1474 |
| Water Storage Tank Requires Replacement Note: 200 gallon storage tanks | Capital Renewal | 2 | Ea. | 3 | \$45,253 | 3036 |
| The Custodial Mop Or Service Sink Requires Replacement Note: Original to building. Fixtures constantly failing or inoperable per custodian. | Capital Renewal | 10 | Ea. | 4 | \$25,764 | 1745 |
| The Refrigerated Water Cooler Requires Replacement Note: Majority of water fountains are not functioning. | Capital Renewal | 10 | Ea. | 4 | \$73,774 | 1743 |
| The Restroom Lavatories Plumbing Fixtures Require Replacement Location: Room 406 | Capital Renewal | 1 | Ea. | 4 | \$3,181 | 1481 |
| The Restroom Lavatories Plumbing Fixtures Require Replacement Location: Room 425 | Capital Renewal | 1 | Ea. | 4 | \$3,181 | 1483 |
| Room lacks a drinking fountain. | Educational Adequacy | 3 | Ea. | 5 | \$3,308 | Rollup |
| The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed | Educational Adequacy | 20 | Ea. | 5 | \$30,232 | Rollup |
| Sub Total for System | | 13 items | | | \$2,094,130 | |

Fire and Life Safety

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|----------------------|----------------|-----|----------|--------------------|--------|
| Emergency Lighting Is Inadequate Or Not Present And Should be Installed | Capital Renewal | 160,000 | SF | 1 | \$241,629 | 1460 |
| Fire Sprinkler System Requires Replacement (SF Basis) per NFPA 13 Note: Sprinkler system is original to building and should be replaced. | Capital Renewal | 160,000 | SF | 1 | \$3,042,230 | 1488 |
| Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) | Educational Adequacy | 5 | Ea. | 1 | \$57,042 | Rollup |
| Sub Total for System | | 3 items | | | \$3,340,901 | |

Technology

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|-----|-----|----------|-------------|--------|
| Room lacks Interactive White Board | Educational Adequacy | 2 | Ea. | 3 | \$11,408 | Rollup |
| Technology: Classroom AV/Multimedia systems are in need of improvements. | Technology | 1 | Ea. | 3 | \$9,507 | 4240 |
| Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life. | Technology | 76 | Ea. | 3 | \$1,517,312 | 4241 |
| Technology: Gymnasium sound system is nonexistent, inadequate, or near end of useful life. | Technology | 1 | Ea. | 3 | \$9,127 | 4246 |
| Technology: Instructional spaces do not have local sound reinforcement. | Technology | 76 | Ea. | 3 | \$361,265 | 4238 |
| Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$5,324 | 4221 |
| Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$5,324 | 4224 |
| Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$5,324 | 4227 |
| Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$5,324 | 4230 |
| Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$5,324 | 4233 |
| Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$5,324 | 4236 |
| Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate. | Technology | 1 | Ea. | 3 | \$45,253 | 4226 |
| Technology: Intermediate Telecommunications Room is not dedicated and/or inadequate. | Technology | 1 | Ea. | 3 | \$45,253 | 4232 |
| Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements. | Technology | 1 | Ea. | 3 | \$37,648 | 4220 |



Technology

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|-----------|--------------|----------|--------------------|--------|
| Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements. | Technology | 1 | Ea. | 3 | \$37,648 | 4223 |
| Technology: Intermediate Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements. | Technology | 1 | Ea. | 3 | \$37,648 | 4235 |
| Technology: Intermediate Telecommunications Room needs M/E improvements. | Technology | 1 | Ea. | 3 | \$24,338 | 4229 |
| Technology: Main Telecommunications Room ground system is inadequate or non-existent. | Technology | 1 | Ea. | 3 | \$6,655 | 4219 |
| Technology: Main Telecommunications Room is not dedicated and/or inadequate. | Technology | 1 | Ea. | 3 | \$50,197 | 4217 |
| Technology: Network system inadequate and/or near end of useful life | Technology | 12 | Ea. | 3 | \$91,267 | 4243 |
| Technology: Network system inadequate and/or near end of useful life | Technology | 205,000 | SF | 3 | \$58,468 | 4244 |
| Technology: Network system inadequate and/or near end of useful life | Technology | 62 | Ea. | 3 | \$294,716 | 4245 |
| Technology: PA/Bell/Clock system is inadequate and/or near end of useful life. | Technology | 205,000 | SF | 3 | \$350,807 | 4247 |
| Technology: Special Space AV/Multimedia system is inadequate. | Technology | 1 | Ea. | 3 | \$54,190 | 4239 |
| Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$7,606 | 4218 |
| Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$4,753 | 4222 |
| Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$4,753 | 4225 |
| Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$4,753 | 4228 |
| Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$4,753 | 4231 |
| Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$4,753 | 4234 |
| Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements. | Technology | 1 | Ea. | 3 | \$4,753 | 4237 |
| Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus. | Technology | 76 | Ea. | 3 | \$115,605 | 4249 |
| Technology: Telephone system is inadequate and/or non-existent. | Technology | 1 | Ea. | 3 | \$7,225 | 4248 |
| Sound and Video Recording Equipment is Required | Educational Adequacy | 1 | Ea. | 4 | \$7,891 | Rollup |
| Sub Total for System | | 34 | items | | \$3,241,497 | |

Conveyances

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|-----------------|----------|--------------|----------|-----------------|------|
| Elevator Electrical System Requires Cleaning And Inspection Note: One of the two elevators is not working. Location: Near main entry | Capital Renewal | 2 | Stop | 4 | \$22,817 | 1500 |
| Sub Total for System | | 1 | items | | \$22,817 | |

Specialties

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|----------------------|------------|--------------|----------|---------------------|--------|
| Room has insufficient writing area. | Educational Adequacy | 4 | Ea. | 3 | \$18,253 | Rollup |
| Backdrop is Required | Educational Adequacy | 1 | Ea. | 4 | \$1,426 | Rollup |
| Room lacks an appropriate refrigerator. | Educational Adequacy | 5 | Ea. | 5 | \$42,781 | Rollup |
| Sub Total for System | | 3 | items | | \$62,461 | |
| Sub Total for Building 01 - Main Building | | 113 | items | | \$32,860,945 | |



Building: 02 - Building 02

Exterior

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|-----------------|----------|--------------|----------|------------------|------|
| The Stucco Exterior Wall Requires Replacement (Bldg SF) | Capital Renewal | 4,500 | SF | 2 | \$150,556 | 2996 |
| The Exterior Soffit Requires Repair | Capital Renewal | 4,500 | SF | 5 | \$98,226 | 2997 |
| Sub Total for System | | 2 | items | | \$248,782 | |

Interior

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|--------------------------|----------|--------------|----------|------------------|--------|
| The Access Is Not ADA Compliant And Requires A Doorway Access Power Assist Mechanism | Barrier to Accessibility | 2 | Door | 3 | \$41,831 | 3001 |
| The Vinyl Composition Tile Requires Replacement Note: Tile is cracking and seams are lifting. | Capital Renewal | 40,300 | SF | 3 | \$462,311 | 2998 |
| The Concrete Flooring Requires Replacement Room lacks appropriate sound control. | Capital Renewal | 50 | SF | 4 | \$651 | 2999 |
| | Educational Adequacy | 100 | SF | 5 | \$3,456 | Rollup |
| The Gypsum Board Ceilings Require Repainting | Capital Renewal | 4,500 | SF | 5 | \$18,824 | Rollup |
| Sub Total for System | | 5 | items | | \$527,073 | |

Mechanical

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|-----------------|----------|--------------|----------|------------------|------|
| Ductwork Requires Replacement (SF Basis) | Capital Renewal | 45,000 | SF | 2 | \$661,552 | 2425 |
| Existing Controls Are Inadequate And Should Be Replaced With DDC Controls | Capital Renewal | 45,000 | SF | 4 | \$303,962 | 3006 |
| Small HVAC Circulating Pump Requires Replacement Note: Hot water circulator beginning to fail. Visible corrosion at piping connections. | Capital Renewal | 1 | Ea. | 4 | \$7,628 | 1752 |
| Sub Total for System | | 3 | items | | \$973,142 | |

Electrical

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|----------------------|----------|--------------|----------|-----------------|--------|
| The Distribution Panel Requires Replacement Location: Business office | Capital Renewal | 1 | Ea. | 2 | \$29,167 | 1527 |
| The Distribution Panel Requires Replacement Location: Wood shop | Capital Renewal | 1 | Ea. | 2 | \$29,167 | 1532 |
| The Mounted Building Lighting Requires Replacement Location: Doors 41 & 42 | Capital Renewal | 2 | Ea. | 3 | \$2,985 | 1538 |
| The Mounted Building Lighting Requires Replacement Location: Auto shop | Capital Renewal | 4 | Ea. | 3 | \$5,970 | 1540 |
| Wall Pack Lighting Requires Repair Location: Door 3 | Capital Renewal | 2 | Ea. | 3 | \$475 | 1535 |
| Wall Pack Lighting Requires Repair Location: Door 40 | Capital Renewal | 1 | Ea. | 3 | \$238 | 1536 |
| The Canopy Lighting Requires Replacement | Capital Renewal | 4 | Ea. | 4 | \$5,514 | 1534 |
| The Canopy Lighting Requires Replacement | Capital Renewal | 1 | Ea. | 4 | \$1,379 | 1541 |
| Room Has Insufficient Electrical Outlets | Educational Adequacy | 20 | Ea. | 5 | \$9,858 | Rollup |
| Sub Total for System | | 9 | items | | \$84,754 | |

Plumbing

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|--------------------------|--------|-----|----------|-------------|--------|
| The Gas Water Heater Requires Replacement | Capital Renewal | 1 | Ea. | 3 | \$3,113 | 2422 |
| The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life | Capital Renewal | 45,000 | SF | 3 | \$362,065 | 2423 |
| The Restroom Is Not ADA Compliant | Barrier to Accessibility | 100 | SF | 3 | \$27,887 | 3002 |
| The Sanitary Sewer Piping Requires Replacement Note: Sanitary piping is failing. | Capital Renewal | 750 | LF | 3 | \$116,765 | 1748 |
| The Urinal Plumbing Fixtures Require Replacement | Capital Renewal | 10 | Ea. | 3 | \$13,291 | 1751 |
| The Restroom Lavatories Plumbing Fixtures Require Replacement Note: Sinks are failing regularly. | Capital Renewal | 10 | Ea. | 4 | \$31,810 | 1749 |
| Room lacks a drinking fountain. | Educational Adequacy | 1 | Ea. | 5 | \$1,095 | Rollup |



Plumbing

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|----------------------|----------|--------------|----------|------------------|--------|
| The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed | Educational Adequacy | 16 | Ea. | 5 | \$24,023 | Rollup |
| Sub Total for System | | 8 | items | | \$580,049 | |

Fire and Life Safety

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|---|-----------------|----------|--------------|----------|------------------|------|
| Fire Sprinkler System Requires Replacement (SF Basis) per NFPA 13 | Capital Renewal | 45,000 | SF | 1 | \$855,627 | 2424 |
| Sub Total for System | | 1 | items | | \$855,627 | |

Technology

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|----------------------|------------|--------------|----------|---------------------|--------|
| Room lacks Interactive White Board | Educational Adequacy | 4 | Ea. | 3 | \$22,663 | Rollup |
| Sub Total for System | | 1 | items | | \$22,663 | |
| Sub Total for Building 02 - Building 02 | | 29 | items | | \$3,292,091 | |
| Total for Campus | | 152 | items | | \$37,953,063 | |



Rogers High School - Life Cycle Summary Yrs 1-5

Site Level Life Cycle Items

Site

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|---------------------------------|-----------------------------|----------|--------------|------------------|----------------|
| Parking Lot Lighting | Pole Lighting | 11 | Ea. | \$85,084 | 4 |
| Roadway Pavement | Asphalt | 50 | CAR | \$165,426 | 5 |
| Fences and Gates | Fencing - Chain Link (4 Ft) | 100 | LF | \$6,465 | 5 |
| | Note: Football field | | | | |
| Fences and Gates | Fencing - Chain Link (8 Ft) | 1,000 | LF | \$67,228 | 5 |
| | Note: Tennis courts | | | | |
| Sub Total for System | | 4 | items | \$324,202 | |
| Sub Total for Building - | | 4 | items | \$324,202 | |

Building: 01 - Main Building

Exterior

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------------|-------------------------------------|----------|--------------|--------------------|----------------|
| Exterior Wall Veneer | Metal Panel - Bldg SF basis | 22,400 | SF | \$2,129,561 | 4 |
| Exterior Window Wall | Storefront / Curtain Wall (Bldg SF) | 1,600 | SF | \$128,991 | 5 |
| | Note: Kalwall | | | | |
| Exterior Utility Doors | Overhead | 5 | Door | \$183,960 | 5 |
| Sub Total for System | | 3 | items | \$2,442,512 | |

Interior

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|--|-----------------------------------|-----------|--------------|--------------------|----------------|
| Resilient Flooring | Vinyl Composition Tile Flooring | 113,820 | SF | \$1,305,714 | 3 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Grid System | 127,400 | SF | \$1,511,028 | 4 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | 127,400 | SF | \$1,150,629 | 4 |
| Suspended Plaster and | Painted ceilings | 24,000 | SF | \$100,394 | 5 |
| Wall Paneling | Wood Panel wall | 8,000 | SF | \$73,014 | 5 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | 152,000 | SF | \$1,004,316 | 5 |
| Flooring Treatment | Concrete Floor - Finished | 1,600 | SF | \$20,832 | 5 |
| Tile Flooring | Quarry Tile | 1,600 | SF | \$72,861 | 5 |
| Wood Flooring | Wood Flooring - All Types | 1,600 | SF | \$53,087 | 5 |
| | Note: Gym | | | | |
| Fluid-Applied Flooring | Epoxy Coating | 6,400 | SF | \$121,689 | 5 |
| Interior Swinging Doors | Wood | 150 | Door | \$691,632 | 5 |
| Interior Door Supplementary Components | Door Hardware | 150 | Door | \$470,595 | 5 |
| Tile Flooring | Ceramic Tile | 1,600 | SF | \$42,966 | 5 |
| Sub Total for System | | 13 | items | \$6,618,757 | |

Mechanical

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|--------------------------------|------------------------------------|----------|--------------|-----------------|----------------|
| Facility Hydronic Distribution | Pump - 1HP or Less (Ea.) | 3 | Ea. | \$22,885 | 3 |
| | Note: Hot water circulators | | | | |
| HVAC Air Distribution | Roof Top Unit - DX Gas (5 Ton) | 3 | Ea. | \$58,194 | 3 |
| Sub Total for System | | 2 | items | \$81,079 | |

Electrical

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------------|---------------------------------|----------|--------------|--------------------|----------------|
| Lighting Fixtures | Building Mounted Fixtures (Ea.) | 18 | Ea. | \$26,867 | 3 |
| Lighting Fixtures | Canopy Mounted Fixtures (Ea.) | 17 | Ea. | \$23,435 | 3 |
| Lighting Fixtures | Light Fixtures (Bldg SF) | 160,000 | SF | \$950,697 | 5 |
| Sub Total for System | | 3 | items | \$1,000,998 | |

Conveyances

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------------|---|----------|--------------|------------------|----------------|
| Lifts | ADA Wheelchair lift | 3 | Ea. | \$142,605 | 3 |
| Elevators | Hydraulic (Passenger Elev) | 1 | Ea. | \$285,209 | 5 |
| | Note: Original elevator used as utility elevator | | | | |
| Elevators | Hydraulic (Passenger Elev) | 1 | Ea. | \$285,209 | 5 |
| Sub Total for System | | 3 | items | \$713,023 | |



Facility Condition Assessment

Newport - Rogers High School

Specialties

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------|---------------------|--|------|---------------------|----------------|
| Casework | Lockers | 1,300 | Ea. | \$639,581 | 5 |
| Casework | Fixed Cabinetry | 10 | Room | \$111,878 | 5 |
| | | Sub Total for System | | \$751,459 | |
| | | Sub Total for Building 01 - Main Building | | \$11,607,828 | |

Building: 02 - Building 02

Exterior

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-------------------------|-------------------------------|-----------------------------|------|-----------------|----------------|
| Exterior Entrance Doors | Steel - Insulated and Painted | 10 | Door | \$64,172 | 5 |
| | | Sub Total for System | | \$64,172 | |

Interior

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-------------------------------|-----------------------------------|-----------------------------|------|--------------------|----------------|
| Interior Swinging Doors | Steel | 40 | Door | \$171,278 | 5 |
| Suspended Plaster and | Painted ceilings | 9,000 | SF | \$37,648 | 5 |
| Tile Wall Finish | Ceramic Tile wall | 2,250 | SF | \$50,054 | 5 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | 42,750 | SF | \$282,464 | 5 |
| Tile Flooring | Quarry Tile | 450 | SF | \$20,492 | 5 |
| Flooring Treatment | Concrete Floor - Finished | 2,250 | SF | \$29,295 | 5 |
| Carpeting | Carpet | 1,800 | SF | \$39,161 | 5 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Grid System | 36,000 | SF | \$426,978 | 5 |
| Tile Flooring | Ceramic Tile | 200 | SF | \$5,371 | 5 |
| | | Sub Total for System | | \$1,062,741 | |

Mechanical

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|---------------------------------|--------------------------------|-----------------------------|-----|------------------|----------------|
| Decentralized Heating Equipment | Unit Heater Electric (20 KW) | 8 | Ea. | \$32,468 | 3 |
| HVAC Air Distribution | Roof Top Unit - DX Gas (5 Ton) | 3 | Ea. | \$58,194 | 3 |
| Decentralized Heating Equipment | Unit Heater Gas (200 MBH) | 7 | Ea. | \$50,031 | 4 |
| | | Sub Total for System | | \$140,694 | |

Electrical

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------|---------------------------------|-----------------------------|-----|------------------|----------------|
| Lighting Fixtures | Building Mounted Fixtures (Ea.) | 6 | Ea. | \$8,956 | 3 |
| Electrical Service | Electrical Service | 45,000 | SF | \$135,092 | 4 |
| Lighting Fixtures | Building Mounted Fixtures (Ea.) | 15 | Ea. | \$22,389 | 4 |
| Lighting Fixtures | Canopy Mounted Fixtures (Ea.) | 15 | Ea. | \$20,678 | 5 |
| | | Sub Total for System | | \$187,114 | |

Specialties

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------|---------------------|--|-----|---------------------|----------------|
| Casework | Lockers | 175 | Ea. | \$86,098 | 5 |
| | | Sub Total for System | | \$86,098 | |
| | | Sub Total for Building 02 - Building 02 | | \$1,540,818 | |
| | | Total for: Rogers High School | | \$13,472,849 | |



Supporting Photos



Site Aerial



Roof Exhaust



Typical Classroom



HVAC Pump




Typical Drinking Fountain



Library



Ceiling Unit Heater



Aged Panel



Abandoned Tanks



Failed Water Heater




Electrical Equipment




Typical Urinal Fixtures



Building Mounted Lighting



Cafeteria



Showers



Gymnasium



Corroded Custodial Sink



Settlement At Vocational Building



Main Entry



East Elevation



Auditorium



Science Classroom



School Plaque



Dome Roof



Northeast Elevation



Art Room



Music Room