



# Facility Condition Assessment

Westerly - Westerly High School

June 2017

23 Ward Avenue, Westerly, RI 02891





## Introduction

Westerly High School, located at 23 Ward Avenue in Westerly, Rhode Island, was built in 1937. It comprises 227,838 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

Westerly High School serves grades 9 - 12, has 60 instructional spaces, and has an enrollment of 851. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for Westerly High School is 1,100 with a resulting utilization of 77%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Westerly High School the 5-year need is \$18,247,342. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.




Figure 1: Aerial view of Westerly High School



## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

## Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

**Facility Condition Assessment:** Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

**Technology:** Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

**Hazardous Materials:** Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

**Traffic:** A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

**Acoustics:** Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

**Educational Program Space Assessment:** Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



## System Summaries

The following tables summarize major building systems at the Westerly High School campus, identified by discipline and building.

### Site

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement
	Asphalt Roadway Pavement
	Concrete Pedestrian Pavement

### Building Envelope

The exterior systems for the building(s) at this campus includes:

<b>01 - Main Building:</b>	Brick Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Storefront Entrance Doors
	Wood Exterior Doors
	Overhead Exterior Utility Doors
<b>02 - Field Light Shed:</b>	CMU Exterior Wall
	Vinyl Siding Exterior Wall
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors
<b>03 - New Bleachers/Press Box:</b>	Metal Panel Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
<b>04 - Concession Stand:</b>	CMU Exterior Wall
	Steel Exterior Entrance Doors

The roofing for the building(s) at this campus consists of:

<b>01 - Main Building:</b>	Slate Roofing
	EPDM Roofing
<b>02 - Field Light Shed:</b>	Composition Shingle Roofing
<b>03 - New Bleachers/Press Box:</b>	EPDM Roofing
<b>04 - Concession Stand:</b>	Composition Shingle Roofing

### Interior

The interior systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	Steel Interior Doors
	Aluminum/Glass Storefront Interior Doors
	Wood Interior Doors
	Overhead Interior Coiling Doors



<b>01 - Main Building:</b>	Interior Door Hardware
	Exposed Metal Structure Ceiling
	Suspended Acoustical Grid System
	Suspended Acoustical Ceiling Tile
	Painted Ceilings
	Ceramic Tile Wall
	Vinyl/Fabric Wall Covering
	Interior Wall Painting
	Concrete Flooring
	Ceramic Tile Flooring
	Wood Flooring
	Rubber Tile Flooring
	Vinyl Composition Tile Flooring
	Terrazzo Flooring
	Carpet
<b>02 - Field Light Shed:</b>	Wood Ceilings
	CMU Wall
	Interior Wall Painting
	Concrete Flooring
<b>03 - New Bleachers/Press Box:</b>	Wood Interior Doors
	Interior Door Hardware
	Painted Ceilings
	Vinyl/Fabric Wall Covering
	Vinyl Composition Tile Flooring
<b>04 - Concession Stand:</b>	Wood Ceilings
	Interior Wall Painting
	Concrete Flooring

## Mechanical

The mechanical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	400 MBH Cast Iron Water Boiler
	750 MBH Copper Tube Boiler
	Finned Wall Radiator
	Steam/Hot Water Heating Unit Vent
	20 kW Electric Unit Heater
	20 MBH Steam Unit Heater
	250 MBH Steam Unit Heater
	Radiant Water Heater
	DDC Heating System Controls
	1 Ton Ductless Split System
	5 Ton Heat Pump
	2-Pipe Hot Water Hydronic Distribution System



<b>01 - Main Building:</b>	1 HP or Smaller Pump
	5 HP Pump
	25 HP Pump
	VAV Boxes / Terminal Device
	2,000 CFM Interior AHU
	5,000 CFM Outdoor AHU
	Ductwork
	Kitchen Exhaust Hoods
	Roof Exhaust Fan
	Fire Sprinkler System
<b>03 - New Bleachers/Press Box:</b>	20 kW Electric Unit Heater
<b>04 - Concession Stand:</b>	Kitchen Exhaust Hoods

## Plumbing

The plumbing systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	250 Gallon Water Storage Tank
	4" Backflow Preventers
	Gas Piping System
<b>04 - Concession Stand:</b>	40 Gallon Electric Water Heater
<b>01 - Main Building:</b>	Domestic Water Piping System
<b>04 - Concession Stand:</b>	Domestic Water Piping System
<b>01 - Main Building:</b>	Classroom Lavatories
	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
<b>04 - Concession Stand:</b>	Lavatories
	Restroom Lavatories
	Toilets
<b>01 - Main Building:</b>	Air Compressor (1 hp)
	550 Gallon Above Ground Fuel Oil Storage Tank

## Electrical

The electrical systems for the building(s) at this campus include:

<b>01 - Main Building:</b>	
	480v Switch
	Automatic Transfer Switch
	1,200 Amp Switchgear
	3,000 Amp Switchgear
	600 Amp Switchgear



# Facility Condition Assessment

Westerly - Westerly High School

<b>01 - Main Building:</b>	225 KVA Transformer
	45 KVA Transformer
	500 KVA Transformer
	75 KVA Transformer
	Panelboard - 120/208 100A
	Panelboard - 120/208 125A
	Panelboard - 120/208 225A
	Panelboard - 120/208 400A
	Panelboard - 120/240 225A
	Panelboard - 277/480 100A
	Panelboard - 277/480 225A
	Panelboard - 277/480 400A
	Panelboard - 400+ Amps
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Light Fixtures
<b>02 - Field Light Shed:</b>	Panelboard - 120/208 400A
	Light Fixtures
<b>03 - New Bleachers/Press Box:</b>	Panelboard - 120/208 100A
	Light Fixtures
<b>04 - Concession Stand:</b>	Panelboard - 120/240 225A
	Light Fixtures



## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	Priority					Total	% of Total
	1	2	3	4	5		
Site	-	-	-	\$497,857	\$520,429	\$1,018,287	13.65 %
Roofing	-	-	\$41	-	-	\$41	0.00 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	-	-	-	-	\$0	0.00 %
Interior	-	-	\$16,693	\$808,893	\$1,364,108	\$2,189,694	29.36 %
Mechanical	-	\$1,263,625	-	\$109,929	-	\$1,373,554	18.42 %
Electrical	-	\$76,749	-	-	\$104,188	\$180,937	2.43 %
Plumbing	-	\$3,688	\$237,674	\$31,472	\$39,811	\$312,646	4.19 %
Fire and Life Safety	\$91,267	-	-	-	-	\$91,267	1.22 %
Technology	-	-	\$2,237,782	-	-	\$2,237,782	30.00 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$18,253	\$10,755	\$25,669	\$54,678	0.73 %
<b>Total</b>	<b>\$91,267</b>	<b>\$1,344,062</b>	<b>\$2,510,444</b>	<b>\$1,458,906</b>	<b>\$2,054,205</b>	<b>\$7,458,885</b>	

\*Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Technology	-	\$2,237,782
Interior	-	\$2,189,694
Mechanical	-	\$1,373,554

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



## Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- **Acoustics** deficiencies relate to room acoustics, sound insulation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- **Barrier to Accessibility** deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- **Capital Renewal** items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- **Code Compliance** deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- **Educational Adequacy** deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- **Functional Deficiencies** are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- **Hazardous Materials** include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- **Traffic** deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	Priority					Total
	1	2	3	4	5	
Acoustics	-	-	-	\$315,479	-	\$315,479
Barrier to Accessibility	-	-	-	-	-	\$0
Capital Renewal	-	\$1,344,062	\$254,408	\$501,694	\$1,360,589	\$3,460,753
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$91,267	-	\$35,366	\$184,983	\$693,616	\$1,005,232
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$456,750	-	\$456,750
Technology	-	-	\$2,220,670	-	-	\$2,220,670
Traffic	-	-	-	-	-	\$0
<b>Total</b>	\$91,267	\$1,344,062	\$2,510,444	\$1,458,906	\$2,054,205	\$7,458,885

\*Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



### Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

System	Current Deficiencies	Life Cycle Capital Renewal Projections					LC Yr. 1-5 Total	Total 5-Year Need
		Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021		
Site	\$1,018,287	\$0	\$0	\$3,630,646	\$0	\$510,990	\$4,141,636	\$5,159,923
Roofing	\$41	\$0	\$0	\$0	\$0	\$0	\$0	\$41
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$33,293	\$0	\$0	\$33,293	\$33,293
Interior	\$2,189,694	\$0	\$971,660	\$11,550	\$1,010,965	\$2,016,056	\$4,010,231	\$6,199,925
Mechanical	\$1,373,554	\$0	\$0	\$141,159	\$1,380,275	\$78,062	\$1,599,496	\$2,973,050
Electrical	\$180,937	\$0	\$0	\$0	\$0	\$69,059	\$69,059	\$249,996
Plumbing	\$312,646	\$0	\$0	\$0	\$0	\$59,019	\$59,019	\$371,665
Fire and Life Safety	\$91,267	\$0	\$0	\$0	\$0	\$0	\$0	\$91,267
Technology	\$2,237,782	\$0	\$0	\$0	\$0	\$0	\$0	\$2,237,782
Conveyances	\$0	\$0	\$0	\$0	\$0	\$285,209	\$285,209	\$285,209
Specialties	\$54,678	\$0	\$0	\$0	\$0	\$590,383	\$590,383	\$645,061
<b>Total</b>	<b>\$7,458,885</b>	<b>\$0</b>	<b>\$971,660</b>	<b>\$3,816,648</b>	<b>\$2,391,240</b>	<b>\$3,608,778</b>	<b>\$10,788,326</b>	<b>\$18,247,211</b>

\*Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast



## Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$82,021,680. For planning purposes, the total 5-year need at the Westerly High School is \$18,247,342 (Life Cycle Years 1-5 plus the FCI deficiency cost). The Westerly High School facility has a 5-year FCI of 22.25%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



## Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 1,232 students.

## Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the Westerly High School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$1,796,145.



### Summary of Findings

The Westerly High School comprises 227,838 square feet and was constructed in 1937. Current deficiencies at this school total \$7,459,016. Five year capital renewal costs total \$10,788,326. The total identified need for the Westerly High School (current deficiencies and 5-year capital renewal costs) is \$18,247,342. The 5-year FCI is 22.25%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
Westerly High School Totals	227,838	1937	\$7,459,016	\$10,788,326	\$18,247,342	22.25%

*\*Displayed totals may not sum exactly due to mathematical rounding*

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

### Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.

### LEA Feedback

As part of the assessment process, LEAs were given several opportunities to provide feedback on the data. Jacobs performed a thorough review of the comments provided relating to the Facilities Condition Assessment. Based on information provided, some adjustments were made to improve or refine the dataset. In other situations, enough information was not provided, item was out of scope, or evidence provided by assessment team did not align with the feedback and no adjustment was made. Finally, deficiency priorities, costs, and educational space/technology standards are consistent throughout the state.



## Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Paving Requires Replacement <b>Note:</b> Asphalt in the faculty, employee and visitors parking areas should be replaced.	Capital Renewal	64	CAR	4	\$210,319	2105
Backstops Require Replacement <b>Note:</b> Backstops Require Replacement	Educational Adequacy	1	Ea.	4	\$28,329	28625
Concrete Sidewalks Require Repair <b>Note:</b> Cracking in concrete walkways.	Capital Renewal	150	LF	4	\$259,209	2108
School has insufficient # of tennis courts. <b>Note:</b> School has insufficient # of tennis courts.	Educational Adequacy	1	Ea.	5	\$161,597	29054
School has insufficient baseball fields. <b>Note:</b> School has insufficient baseball fields.	Educational Adequacy	1	Ea.	5	\$207,745	28333
School has insufficient softball fields. <b>Note:</b> School has insufficient softball fields.	Educational Adequacy	1	Ea.	5	\$151,087	28376
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$1,018,287</b>	
<b>Sub Total for School and Site Level</b>		<b>6</b>	<b>items</b>		<b>\$1,018,287</b>	

## Building: 01 - Main Building

### Roofing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Roof Drains Require Cleaning <b>Note:</b> The roof drain on the east side is clogged and needs to be cleaned.	Capital Renewal	1	Ea.	3	\$41	2188
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$41</b>	

### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Rubber Flooring Requires Replacement <b>Note:</b> Seam in rubber tiled floor failing. <b>Location:</b> 1st W103 Science Room	Capital Renewal	100	SF	3	\$1,946	1944
The Ceramic Tile Flooring Requires Replacement <b>Note:</b> The ceramic tile floor in the 2010 girl's locker room is severely cracked.	Capital Renewal	100	SF	3	\$2,797	2033
The Vinyl Composition Tile Requires Replacement <b>Location:</b> Hallway staircase	Capital Renewal	1,000	SF	3	\$11,950	2032
Asbestos 9x9 Tile is Present. Limited Areas of Lifting or Broken Tiles Exist	Hazardous Material	140	SF	4	\$4,159	Rollup
Paint (probable pre-1978 in base (layers(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - each)	Hazardous Material	775	Ea.	4	\$230,247	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - linear feet)	Hazardous Material	950	LF	4	\$22,579	Rollup
Paint (probable pre-1978 in base layer(s)) - large areas (> 10 sq. ft.) of peeling/damage & area in active use - children (measurement unit - square feet)	Hazardous Material	17,000	SF	4	\$168,353	Rollup
Paint (probable pre-1978 in base layer(s)) -large areas (> 10 sq. ft.)of peeling/damage & area in active use-adults only (measurement unit - square feet)	Hazardous Material	3,100	SF	4	\$30,700	Rollup
Paint (probable pre-1978 in base layer(s)) -large areas(> 10 sq. ft.)of peeling/damage & area in active use-adults only (measurement unit - linear feet)	Hazardous Material	30	LF	4	\$713	Rollup
Room Is Excessively Reverberant <b>Location:</b> Gym	Acoustics	10,800	SF	4	\$251,341	27977
Room Is Excessively Reverberant <b>Location:</b> Cafeteria	Acoustics	2,756	SF	4	\$64,138	27978
Room Lighting Is Inadequate Or In Poor Condition.	Educational Adequacy	944	SF	4	\$35,970	Rollup
The Plaster Ceilings Require Replacement <b>Note:</b> Cafeteria ceiling requires repair where plywood is located.	Capital Renewal	100	SF	4	\$693	1945
Interior Doors Require Repainting <b>Location:</b> Steel hallway doors on first floor	Capital Renewal	9	Door	5	\$633	2031



# Facility Condition Assessment

Westerly - Westerly High School

## Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Walls Require Repainting	Capital Renewal	219,464	SF Wall	5	\$1,347,491	2030
Room lacks appropriate sound control.	Educational Adequacy	300	SF	5	\$10,439	Rollup
The Concrete Flooring Requires Repair Or Repainting <b>Note:</b> Crack in concrete outside of boy's locker room.	Capital Renewal	100	SF	5	\$792	1948
The Exposed Ceilings Require Repainting <b>Note:</b> Formerly boiler room and now pump room outside of auditorium has paint flaking from the ceiling. Recommend to remove old paint and repaint.	Capital Renewal	400	SF	5	\$4,753	1947
<b>Sub Total for System</b>		<b>18</b>	<b>items</b>		<b>\$2,189,694</b>	

## Mechanical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Electric Unit Heater Requires Replacement <b>Location:</b> Stair F, Floor 123	Capital Renewal	3	Ea.	2	\$12,683	2213
Electric Unit Heater Requires Replacement <b>Location:</b> Stair F, Floors 1-3	Capital Renewal	3	Ea.	2	\$12,683	2319
Outdoor Air Handler HVAC Component Required Replacement <b>Note:</b> Reznor units are breaking down and should be replaced. Unit on the middle roof has had fuses removed. Side panel is open which causes potential bird/rodent problem and heat loss.	Capital Renewal	5	Ea.	2	\$742,732	2194
Outdoor Air Handler HVAC Component Required Replacement <b>Note:</b> Trane units are breaking down.	Capital Renewal	3	Ea.	2	\$445,639	2195
Steam/HW Unit Heater Requires Replacement <b>Location:</b> Locker Rooms	Capital Renewal	6	Ea.	2	\$17,600	1923
The Steam/Hot Water Radiant Heater Requires Replacement <b>Note:</b> Original to building; recommend replacing.	Capital Renewal	6	Ea.	2	\$32,288	2204
Lab lacks an appropriate fume hood.	Educational Adequacy	5	Ea.	4	\$109,929	Rollup
<b>Sub Total for System</b>		<b>7</b>	<b>items</b>		<b>\$1,373,554</b>	

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Panelboard Requires Replacement <b>Note:</b> Replace original panel; equipment is obsolete.	Capital Renewal	1	Ea.	2	\$5,051	1925
The Panelboard Requires Replacement <b>Note:</b> Panels outdated and should be updated to newer equipment.	Capital Renewal	4	Ea.	2	\$40,009	2316
The Panelboard Requires Replacement <b>Note:</b> Electrical panels in kitchen are outdated and obsolete.	Capital Renewal	4	Ea.	2	\$20,202	2317
Remove Abandoned Equipment <b>Note:</b> Remove abandoned electrical equipment in attic and HVAC equipment on roof.	Capital Renewal	2	Ea.	5	\$6,920	2190
Room Has Insufficient Electrical Outlets	Educational Adequacy	196	Ea.	5	\$97,268	Rollup
<b>Sub Total for System</b>		<b>5</b>	<b>items</b>		<b>\$169,449</b>	

## Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Showers Plumbing Fixtures Require Replacement	Capital Renewal	30	Ea.	3	\$237,674	1922
The Custodial Mop Or Service Sink Requires Replacement <b>Note:</b> Mop sinks are beginning to fail per custodians.	Capital Renewal	6	Ea.	4	\$16,102	2318
The Refrigerated Water Cooler Requires Replacement <b>Note:</b> Water fountains in locker rooms no longer work. <b>Location:</b> Locker Rooms	Capital Renewal	2	Ea.	4	\$15,370	1924
Room lacks a drinking fountain.	Educational Adequacy	9	Ea.	5	\$9,925	Rollup
Room lacks a private shower area.	Educational Adequacy	1	Ea.	5	\$10,235	Rollup
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	Educational Adequacy	13	Ea.	5	\$19,651	Rollup
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>		<b>\$308,958</b>	



## Fire and Life Safety

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Educational Adequacy	8	Ea.	1	\$91,267	Rollup
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>		<b>\$91,267</b>	

## Technology

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room lacks Interactive White Board	Educational Adequacy	3	Ea.	3	\$17,113	Rollup
Technology: Auditorium AV/Multimedia system is in need of minor improvements.	Technology	1	Room	3	\$99,031	3677
Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	90	Ea.	3	\$891,278	3671
Technology: Instructional spaces do not have local sound reinforcement.	Technology	90	Ea.	3	\$445,639	3669
Technology: Intermediate Telecommunications Room ground system meets current industry standards/best practices.	Technology	1	Ea.	3	\$6,932	3661
Technology: Intermediate Telecommunications Room needs M/E improvements.	Technology	1	Ea.	3	\$25,352	3664
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,429	3660
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,429	3663
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,429	3665
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,429	3666
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,429	3667
Technology: Intermediate Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$17,429	3668
Technology: Main Telecommunications Room is not dedicated. Room requires partial walls and/or major improvements.	Technology	1	Ea.	3	\$44,366	3662
Technology: Main Telecommunications Room needs minor improvements.	Technology	1	Ea.	3	\$22,579	3659
Technology: Network cabling infrastructure is partially outdated and/or needs expansion.	Technology	180	Ea.	3	\$80,215	3672
Technology: Network system inadequate and/or near end of useful life	Technology	10	Ea.	3	\$79,225	3676
Technology: Special Space AV/Multimedia system is inadequate.	Technology	2	Ea.	3	\$112,895	3673
Technology: Special Space AV/Multimedia systems are in need of minor improvements.	Technology	8	Room	3	\$158,450	3670
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	90	Ea.	3	\$142,605	3674
Technology: Telephone system is inadequate and/or non-existent.	Technology	1	Ea.	3	\$7,526	3675
<b>Sub Total for System</b>		<b>20</b>	<b>items</b>		<b>\$2,237,782</b>	

## Specialties

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	4	Ea.	3	\$18,253	Rollup
Work Tables Are Required	Educational Adequacy	3	Ea.	4	\$10,755	Rollup
Room lacks an appropriate refrigerator.	Educational Adequacy	3	Ea.	5	\$25,669	Rollup
<b>Sub Total for System</b>		<b>3</b>	<b>items</b>		<b>\$54,678</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>61</b>	<b>items</b>		<b>\$6,425,423</b>	

## Building: 02 - Field Light Shed

### Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Lighting Branch Wiring Requires Replacement	Capital Renewal	500	SF	2	\$1,857	2440



# Facility Condition Assessment

Westerly - Westerly High School

## Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Lighting Fixtures Require Replacement <b>Note:</b> Update incandescent lights to LED.	Capital Renewal	500	SF	2	\$3,095	2441
The Panelboard Requires Replacement <b>Note:</b> Panelboard is outdated.	Capital Renewal	1	Ea.	2	\$6,536	2313
<b>Sub Total for System</b>		<b>3 items</b>			<b>\$11,488</b>	
<b>Sub Total for Building 02 - Field Light Shed</b>		<b>3 items</b>			<b>\$11,488</b>	

## Building: 04 - Concession Stand

### Plumbing

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
The Electric Water Heater Requires Replacement	Capital Renewal	1	Ea.	2	\$3,688	2315
<b>Sub Total for System</b>		<b>1 items</b>			<b>\$3,688</b>	
<b>Sub Total for Building 04 - Concession Stand</b>		<b>1 items</b>			<b>\$3,688</b>	
<b>Total for Campus</b>		<b>71 items</b>			<b>\$7,458,885</b>	

## Buildings with no reported deficiencies

03 - New Bleachers/Press Box



## Westerly High School - Life Cycle Summary Yrs 1-5

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Roadway Pavement	Asphalt	650	CAR	\$2,150,538	3
Parking Lot Pavement	Asphalt	247	CAR	\$817,205	3
Playfield Areas	HS Athletic Components	1	Ea.	\$452,935	3
Fences and Gates	Fencing - Chain Link (4 Ft)	2,000	LF	\$129,295	3
Fences and Gates	Fencing - Chain Link (8 Ft)	1,200	LF	\$80,673	3
Pedestrian Pavement	Sidewalks - Concrete	25,000	SF	\$510,990	5
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>	<b>\$4,141,636</b>	
<b>Sub Total for Building -</b>		<b>6</b>	<b>items</b>	<b>\$4,141,636</b>	

### Building: 01 - Main Building

#### Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Wood	4	Door	\$33,293	3
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$33,293</b>	

#### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Interior Door Supplementary Components	Door Hardware	29	Door	\$90,982	2
Interior Swinging Doors	Wood	191	Door	\$880,678	2
Interior Swinging Doors	Steel	1	Door	\$4,282	3
Wood Flooring	Wood Flooring - All Types	27,500	SF	\$912,431	4
Carpeting	Carpet	4,529	SF	\$98,534	4
Resilient Flooring	Vinyl Composition Tile Flooring	175,741	SF	\$2,016,056	5
<b>Sub Total for System</b>		<b>6</b>	<b>items</b>	<b>\$4,002,963</b>	

#### Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Ductless Split System (1 Ton)	10	Ea.	\$141,159	3
Decentralized Heating Equipment	Heating Unit Vent - Steam/Hot water	80	Ea.	\$1,353,184	4
Decentralized Heating Equipment	Unit Heater Steam/HW (250 MBH)	8	Ea.	\$27,091	4
Exhaust Air	Roof Exhaust Fan	15	Ea.	\$78,062	5
<b>Sub Total for System</b>		<b>4</b>	<b>items</b>	<b>\$1,599,496</b>	

#### Electrical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Electrical Service	Switchgear - Main Dist Panel (1200 Amps)	1	Ea.	\$69,059	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$69,059</b>	

#### Plumbing

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain	8	Ea.	\$59,019	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$59,019</b>	

#### Conveyances

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Elevators	Hydraulic (Passenger Elev)	1	Ea.	\$285,209	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$285,209</b>	

#### Specialties

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Casework	Lockers	1,200	Ea.	\$590,383	5
<b>Sub Total for System</b>		<b>1</b>	<b>items</b>	<b>\$590,383</b>	
<b>Sub Total for Building 01 - Main Building</b>		<b>15</b>	<b>items</b>	<b>\$6,639,422</b>	



## Building: 02 - Field Light Shed

### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	500	SF	\$3,304	3
		<b>Sub Total for System</b>		<b>\$3,304</b>	
		<b>Sub Total for Building 02 - Field Light Shed</b>		<b>\$3,304</b>	

## Building: 04 - Concession Stand

### Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	600	SF	\$3,964	3
		<b>Sub Total for System</b>		<b>\$3,964</b>	
		<b>Sub Total for Building 04 - Concession Stand</b>		<b>\$3,964</b>	
		<b>Total for: Westerly High School</b>		<b>\$10,788,327</b>	



**Supporting Photos**



Site Aerial



Main Building - Mop Sink



Main Building - Obsolete Panelboard



Cracked Concrete Walkway



# Facility Condition Assessment

Westerly - Westerly High School



Cracked Asphalt Paving



Building 02 - Exterior



Building 03 - Gypsum Ceiling



Main Building - Electrical Equipment In Attic



Main Building - Clogged Roof Drain



Main Building - Outdoor Air Handler



# Facility Condition Assessment

Westerly - Westerly High School



Main Building - Abandoned Equipment



Main Building - Original Radiant Heater



Main Building - Outdoor Air Handler



Building 03 - Interior Wood Doors



Building 04 - Exterior



Main Building - Worn Interior Metal Doors



# Facility Condition Assessment

Westerly - Westerly High School



Building 03 - Roofing



Main Building - Cracked Ceramic Tile Floor



Main Building - Paint Peeling



Main Building - Wood Shop



Main Building - Damaged VCT




Main Building - Curling Floor Seam



Main Building - 1996 Plaque



Main Building - Gymnasium



Main Building - Abandoned Restroom



Main Building - Cafeteria



Main Building - Kitchen



Main Building - Gymnasium



# Facility Condition Assessment


Westerly - Westerly High School




Main Building - Cafeteria Ceiling



Main Building - Crack In Concrete Floor



Main Building - Music Room



Main Building - Damaged Ceiling In Boiler Room



Main Building - Science Classroom



Building 04 - Back Bathroom Area



# Facility Condition Assessment

Westerly - Westerly High School



Main Building - Auditorium



Building 04 - Back Bathroom ADA



Site - Signage



Building 04 - Concession Stand



Building 03 - Announcer Box



Building 03 - Press Box



# Facility Condition Assessment

Westerly - Westerly High School



Building 03 - VCT Flooring



Site - Elevation



Main Building - Electric Unit Heater



Main Building - Aged Panelboard



Building 02 - Exterior



Main Building - Library



# Facility Condition Assessment

Westerly - Westerly High School



Building 02 - Outdated Panelboard



Building 03 - Exterior Steel Door



Main Building - Building Signage



Main Building - Auditorium Seating



Building 03 - Exterior Door